


MIDDLEBURG

SENIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
 3750 C.R. 220
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

9-20-05

INSPECTOR'S SIGNATURE _____ DATE _____

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fsg. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	58	No emergency light	X							FBC 423.17.1
1	26	Extension cord to strip to strip		X						NFPA 70 400-8
1	54	Return air grill blocked		X						
1	68	Evacuation sheet missing		X						FBC 423.14.2.4
1	71	Evacuation sheet missing		X						FBC 423.14.2.4
1	123	Hall ceiling tiles hanging down, track bent	X							NFPA 1 10 4.1
1	142	Chair prop open door with extension cord to fan		X						NFPA 70 400-8
1	142	Chair blocking doorway		X						FBC 423.20.1
1	136	Evacuation sheet		X						FBC 423.14.2.4
1	93	Bad balasts in lights	X							FBC 423.28.2 18.1
1	95	Ceiling tile missing		X						FBC 804.2.3
1	164	Door swings into room				X				FBC 423.13.1
1	164	No evacuation sheet		X						FBC 423.14.2.4
1	163	Storage to close to sprinkler ceiling		X						NFPA 13 13 8.5.3

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
 3750 C.R. 220
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

9-20-05

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Schedule d for Correctio n	Rule
1	148	Six lights out		X						FBC 423.28.2.18.1
1	148	Communication cables run across floor				X				FBC 423.28.2.18.1
1	187	Outlet by drinking fountain not marked GFI	X							FBC 423.28.2.18.1
1	178	Extension cord to extension cord to strip		X						NFPA 70 400-8
1	187	Junction box cover missing over fire alarm	X							NFPA 70 323.5
1	259	Evacuation sheet missing		X						FBC 423.14.2.4
1	263	Extension cords to sewing machines need tower		X						NFPA 70 400-8
1	226	Outlet needs to be moved for TV	X							FBC 423.28.2.18.1
1	241	Evacuation sheet		X						FBC 423.14.2.4
1	244	Information services directly in front of electrical panel				X				NFPA 70 110-26
1	245	Evacuation sheet		X						FBC 423.14.2.4
1	245	Extension cord around wall to strip		X						NFPA 70 400-8
1	239	Extension cord to tree decoration		X						NFPA 70 400-8
1	247	Plumbing access cover broken	X							
1	247	Two Ceiling tiles missing		X						FBC 804.2.3

FISCAL YEAR 2005-2006

DISTRICT: CLAY FACILITY # 0019

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**

FACILITY : MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

INSPECTOR'S SIGNATURE [Signature] DATE 9-20-05



Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	249	Emergency light not working		X						FBC 423.17.1
1	249	No cover over fluorescent light		X						NFPA 70 410-3
1	249	Storage in riser room		X						
1	197	Kitchen indirect drains need air gap (drains are down in floor)	X							FBC 423.28.2.18.1
1	215	Storage too close to sprinklers		X						NFPA 13 13.8.5.5.3
1	215	Tiles damaged		X						FBC 804.2.3
1	315	Grid/tiles damaged	X							NFPA 70 410.3
1	316	Light cover hanging; tiles damaged	X							NFPA 70 410.3
1	316A	Light cover missing								NFPA 70 410.3
1	326	Evacuation sheet missing		X						FBC 423.14.2.4
1	335	No evacuation sheet		X						FBC 423.14.2.4
1	335	Ceiling tile missing								FBC 804.2.3
1	335	Exit light not working		X						FBC 10106.3.1
1	335	Emergency light not working		X						FBC 423.12.1

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
 COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT CLAY FACILITY # 0019

FACILITY : MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

INSPECTOR'S SIGNATURE *[Signature]* DATE 9-20-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	312	Evacuation sheets missing		X						FBC 423.14.2.4
1	312	Wire for TV goes into ceiling		X						NFPA 70 400-8
1	313	Lights not working		X						FBC 423.28.2.18.1
1	313	Storage filling whole shower		X						
1	308	Storage too close to sprinkler		X						NFPA 13 8.5.5.3
1	296	Light cover missing		X						NFPA 70 410.3
1	249	Missing cover plate	X							NFPA 70 314.1
1	291	Exit light missing		X						FBC 10 16 3.1
1	291	Missing cover plate	X							NFPA 70 314.1
1	268	Light out in shower		X						FBC 423.28.2.18.1
1	270	Exit blocked; panel blocked with storage		X						FBC 423.20.1
1	357	Evacuation sheet missing		X						FBC 423.14.2.4
1	361A	Roof leak								
1	361A	No evacuation sheet		X						FBC 423.14.2.4
9		LP gas bottle stored in building		X						NFPA 1 21-3.3.5

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT CLAY FACILITY # 0019

FACILITY : MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

9-20-05

INSPECTOR'S SIGNATURE _____ DATE _____

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	7	No evacuation sheet		X						FBC 423.14.2.4
92	7	Emergency light not working		X						FBC 423.17.1
92	34	Hole in Wall by AC Unit	X							
92	47	Outlet cover plate broken	X							NFPA 70.314.2
92	47	No evacuation sheet		X						FBC 423.14.2.4
92	54-A	Emergency light not working		X						FBC 423.17.1
92	54 B	Emergency light not working		X						FBC 423.17.1
92	60	Evacuation sheet missing		X						FBC 423.14.2.4
92	60	No strobe light with alarm system	X							
92	60	Eave metal loose on roof	X							
92	70	No evacuation sheet		X						FBC 423.14.2.4
92	70	Mating wall not secure; bolts loose in ceiling			X					
92	70	New/recently moved classroom								
92	71	No evacuation sheet		X						FBC 423.14.2.4

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
 COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY # 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
 3750 C.R. 220
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

4-20-05

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency/Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	3	OK								
92	5	OK								
92	31	OK								
92	32	OK								
92	33	OK								
92	35	OK								
92	36	OK								
92	41	OK								
92	42	Evacuation sheet missing								FBC 423.14.2.4
92	43	OK								
92	44	OK								
92	45	OK								
92	46	OK								
92	51	OK								
92	52	OK								

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY # 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
 3750 C.R. 220
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: SEPTEMBER 20, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 9-20-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	72	No evacuation sheet		X						FBC 423.14.2.4
92	72	Ramp/sidewall tripping hazard			X					
92	72	Missing bolts in ceiling/newly moved classroom			X					
92	75	No evacuation sheet		X						FBC 423.14.2.4
92	77	No evacuation sheet		X						FBC 423.14.2.4
92	77	Emergency light not working		X						FBC 423.17.1
92	78	No evacuation sheet		X						FBC 423.14.2.4
92	78	Emergency light not working		X						FBC 423.17.1
92	79	No evacuation sheet		X						FBC 423.14.2.4
92	79	Emergency light not working		X						FBC 423.17.1
		**REPLACE WOOD RAMPS TO COMPLY WITH ADA REQ.								FBC 11-4.9.4