

SCHON
ARCONOMA
With the same of t

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FISCAL YEAR <u>2005-2006</u>

	DISTRICT: CLAY FACILITY #: 0003
	FACILITY: BANNERMAN LEARNING CENTER 608 MILL STREET GREEN COVE SPRINGS, FLORIDA 32043
	INSPECTION DATE: JANUARY 12, 2006
-	INSPECTOR'S SIGNATURE DATE

Rue		FBC 423.15.4	FBC 423.15.4	NFPA 70, 110-12	NFPA 70, 110-12		NFPA 70, 100-12		NFPA 70 552-41	NFPA 70:552-41	NFPA 70 110-12	
Scheduled for Correction	2000						Account of the second of the s					
Cost No. of times Def. Cited											***************************************	
Info Serv.												
Oper. Fac. "O" "C"						×		2-15-1 13-1 13-1 13-1 13-1 13-1 13-1 13-1				
Maint. "N"		×	×	X	×		×		×	X	×	
Deficiency Description and Corrective Action Required:	OK	EXTERIOR FANS WON'T STAY ON WITH LIGHTS HAVE SEPARATE SWITCH	EXTERIOR FANS WON'T STAY ON WITH LIGHTS HAVE SEPARATE SWITCH	FIRE ALARM COVER & INTERCOM COVER REMOVED	OUTSIDE BEHIND ROOM 207 & 208 CONDUIT COVER MISSING	LIGHTSOUT	ALARM "J" BOX COVERS MISSING	ROOFLEAK	GFCI TEST BUTTON NOT WORKING	GECLITEST BUTTON NOT WORKING	DIST. PANEL FENCED AREA BOX COVERS MISSING	
Room		205	206	208	208	218	218	220	310	311	320	
Building	_	2		2	2	2	2	2	က	8	ю	

"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

FACILITY #: DISTRICT: CLAY

0003

FACILITY: BANNERMAN LEARNING CENTER

608 MILL STREET GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: JANUARY 12, 2006

DATE

1-13.06

NSPERTOR'S SIGNATURE

nemany

							***************************************	A STATE OF THE STA
Building	Коош	Deficiency Description and Corrective Action Required:	Maint. Oper. "M" "O".	Fac. "C" S	Info. Cost Serv. "I.S."	No. of times Def. Cited	Scheduled for Correction	Rule
92	-	OK					South State of the	
. 92	- 5	OK						
62	3	OK						Control of the Contro
- 92	4	OK						
92	5	OK			And the second s			
- 62	. 6	OK						
92	7	OK						
92	8	ОК						
92	6	OK		77 N				
- 92	10	ОК						
92	11	OK						
92	12	OK						
92	13	ОК			The state of the s			
92	14	OK						

(BLC 2005-06 SREF INSPECTION REPORT.wpd)



FISCAL YEAR 2005-2006

"FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

FACILITY #: 0003 DISTRICT. CLAY

FACILITY: BANNERMAN LEARNING CENTER

608 MILL STREET GREEN COVE SPRINGS, FLORIDA 32043

JANUARY 12, 2006 INSPECTION DATE:

INSPECTOR'S SIGNATURE

DATE

1-12-06

					The state of the s	Control of the second of the second	Carlot Contract the Contract of the Contract o	The Carlotte Comment of the County of	とは 間の 門かり はりまるのう
Building	Коош	Deficiency Description and Corrective Action Required:	Maint Oper, C'm "O"	Fac. "C"	Info. Serv. "LS."	Soo	No. of times Def.	Scheduled for Correction	Rule
92	30	ОК		Control of the contro	The state of the s		S. S		
92	31	ОК							
92	32	ОК							
92	33	OK							
92	34	ОК		2 · C.					
92	35	OK							
92	36	OK							
-92	37	OK							
92	39	ОК					10 10 A SEA MARKET TO THE		
92	40	OK							
92	42	OK			2		A STATE OF THE STA		
92	43	OK							
92	50	OK				20 Pi			
92	52	ОК		1					

(BLC 2005-06 SREF INSPECTION REPORT.wpd)



FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

PISTRICT: CLAY FACILITY#: 0003

FACILITY: BANNERMAN LEARNING CENTER
608 MILL STREET
GREEN COVE SPRINGS, FLORIDA 32043


INSPECTION DATE: JANUARY 12, 2006

INSPECTION'S SIGNATURE

TURE DATE

30-61

	17.1		4.8			11.00	
Rule	FBC 423.17.1		FBC 11-4.8				
	FB(毘				
fuled							
Scheduled for Correction							
of def		bilati Tirli					
No. of times Def. Cited			i				
Cost							
Ö							
Info. Serv. "1.S."							
		day.					
Fac. "C"					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
/							
Oper. "O"							
Maint. "W"	×		×				
N				Wille			
iired:			≰				
on Requ			ET AD				
ve Acti			O ME				
отеси	5		IPS T				
n and C	SHO) RAIN				
scriptio) 		WOOL				
icy Des	GEN		ACE V				
Deficiency Description and Corrective Action Required:	EMERGENCY LIGHT OUT		REPLACE WOOD RAMPS TO MEET ADA REQUIREMENTS				
LECTION DESCRIPTION	38						
Room	, w	100 iii	GENERAL NOTE				
Building	92		GEN				
<u> </u>		i Phi				38 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	





COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: GREEN COVE SPRINGS JUNIOR HIGH SCHOOL 1220 BONAVENTURE AVENUE GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: JANUARY 17, 2006

1-17.06 DATE

INSPECTOR'S SIGNATURE

marran


								J		
Building	Коот	Deficiency Description and Corrective Action Required:	Main <u>t</u> "W"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
	, LECT	FIRE EXTINGUISHER NOT SIGNED		×						69A-36
GENERAL NOTE:	ii O	MANY EMERGENCY EVACUATION SHEETS MISSING		X						FBC 423.17.1
2	104	LIGHT IN ENTRANCE TO RESTROOM INOPERABLE		×						7.00
2	105	LIGHT IN ENTRANCE TO RESTROOM INOPERABLE		X						
4	424	EMERGENCY LIGHT OUT	×							FBC 1006.2
4	422	GAS GRILL STORED INSIDE:					1			NFPA 101-13
5	527	COVERS MISSING ON LIGHTS	×							NFPA 70
9	517	LIGHTS NOT WORKING		X						
5	535	NO EMERGENCY LIGHTS		×						FBC 1006.2
5	545	NO EMERGENCY LIGHTS.		X		E.				FBC 1006.2
5	530	EXIT LIGHT OUT		×				Angel Pill		FBC 423.17.1
7	701	MANY CAPACITY SIGNS MISSING	×				e /ale			FBC 423.14.2.2

FISCAL	COMPREHENSIVE SA STATE BOA ADMINISTRATIVE R	INSPECTION"

FISCAL YEAR 2005-2006 APREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION MINISTRATIVE RULES S.R.E.F. - CHAPTER 5 E SAFETY, CASUALTY SAFETY & SANITATIO INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICTCLAY FACILITY#: 0001
ORT	FACILITY: GREEN COVE SPRINGS JUNIOR HIGH SCHOOL
1	1220 BONAVENTURE AVENUE GREEN COVE SPRINGS, FLORIDA 32043
NO.	INSPECTION DATE: JANUARY 17, 2006
<i>></i> 3	INSPECTOR'S SIGNATURE DATE

				11/				
Building	Room	Deficiency Description and Corrective Action Required:	Waint. Oper. "W" "O"	Fac. Se	Info. Cost Serv: "I.S."	No. of times Def. Cited	Scheduled for Correction	Rule
82	02	OK						
-92	12	OK						
92	22	OK						
92	104	ОК						
92	105	OK						
92	106	УС						
92	107	ОК						
92	112	LEAK AT WASHER HOOK UP	X					
92	113	ОК						
NOTE	Ш	REPLACE WOOD RAMPS TO MEET ADA REQUIREMENTS	. ×					FBC 11-4.9.4





COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

 DISTRICT
 CLAY
 FACILITY #: 0014

 FACILITY:
 LAKESIDE JUNIOR HIGH SCHOOL

 2750 MOODY ROAD

 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: JANUARY 25, 2006

19an 25,

28 RC 30 RC 46 EN 46 EN 856 NV 56 NV	Deficiency Description and Corrective Action Required: ROOF LEAK ROOF LEAK ALARM J-BOX NO COVER EMERGENCY LIGHT NOT WORKING ACROSS FROM ROOM 44 EMERGENCY LIGHT INSIDE ROOM NOT WORKING NO EMERGENCY LIGHT	Maint.		S S S S S S S S S S S S S S S S S S S	7	No. of times Def. Cited	Scheduled Correction	Rule NFPA 70 FBC:423:17.1 FBC:423:17.1
	NO EMERGENCY LIGHT NO EMERGENCY LIGHT		××					FBC 423.17.1 FBC 423.17.1
ž	NO EMERGENCY LIGHT		××		200			FBC 423.17.1
ž ž	NO EMERGENCY LIGHT NO EMERGENCY LIGHT		×					FBC 423.17.1
71 NG	NO EMERGENCY LIGHT		×					FBC 423:17.1

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY #: 0014 FACILITY: LAKESIDE JUNIOR HIGH SCHOOL 2750 MOODY ROAD ORANGE PARK, FLORIDA 32073	
--	--

INSPECTION DATE: JANUARY 25, 2006

M. Lastan

INSPECTOR'S SIGNATURE

Jan 25,2006

			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	100 Cont. (100 March 100 Co.)	The second second second second	201 See 1928 See 1927	Company of the Company	Control of the second second second second	Control of the second state of the second	The second secon
Building	Room	Deficiency Description and Corrective Action Required:	Maint. «M»	Oper. "O"	Fac. "Ç"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	79	NO EMERGENCY LIGHT		×						FBC 423.17.1
3	80	NO EMERGENCY LIGHT		X						FBC:423.17.1
က	81	NO EMERGENCY LIGHT		×						FBC 423.17.1
3	74	EMERGENCY LIGHT NOT WORKING		×						FBC:423:17.1
5	110	EMERGENCY LIGHT NOT WORKING		×						FBC 423.17.1
9	.115	LIGHT: SWITCH & COVER BROKEN	X							NFPA-70
5	125	TWO WIRES NOT IN BOX - BOX OPEN	×							NFPA-70
9	135	COMMUNICATION BOX OPEN	×							NFPA-70
5	138	EMERGENCY LIGHT - BULB BROKEN		×						FBC 423.17.1
5	140	EMERGENCY LIGHT NOT WORKING		×						FBC 423.17.1
5	209	EXHAUST FAN NOT WORKING	×							FBC 423.15.4
2	234	EMERGENCY LIGHT NOT WORKING		×						FBC 423.17.1
5	231	EMERGENCY LIGHT NOT WORKING		×						FBC 423.17.1
.5	235	WIRE FROM PANEL NOT IN CONDUIT	X							NFPA-70

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0014	FACILITY: LAKESIDE JUNIOR HIGH SCHOOL 2750 MOODY ROAD ODANICE DABK EI ORIDA 32073	OLYMPIC L'AINI, I LOINDA SENTO
DISTRICT. CLAY	FACILITY: LAKESIDE JUN 2750 MOODY R ODANICE DARK	NING I TONIO

INSPECTION DATE: JANUARY 25, 2006

BATE

									The second second second	Control of the Contro
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	215	MISSING OCCUPANCY LOAD SIGN		×						FBC 423.14.2.2
8	804	EXIT LIGHT OUT.		×					151	FBC 1016.3.1
8	826	HEAT DETECTOR HANGING DOWN		×						The second secon
8	827	COPPER LINES NOT ISOLATED FROM GALVANIZED STRIPS	×							
8	828	COPPER LINES NOT ISOLATED FROM GALVANIZED STIPS	×							
8	830	CEILING TILE MISSING:		×						
o	901	EMERGENCY LIGHT OUT		×						FBC 423.17.1
6	918	EMERGENCY LIGHT OUT		×						FBC 423.17.1
6	922	EMERGENCY LIGHT OUT		×						FBC 423.17.1
Control of expendence										

(6)

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL 2750 MOODY ROAD ORANGE PARK, FLORIDA 32073	
7522(1824)	_

INSPECTION DATE: JANUARY 25, 2006

INSPECTOR'S SIGNATURE

Pem 25,2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint "W"	Oper. "O"	Fac. "C"	info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule	
in the second								2007 6			25 25 (12)(1
82	701	EMERGENCY LIGHT OUT		×		2		50 10 A A A A A A A A A A A A A A A A A A	**************************************	FBC 423.17.1	1.0
92	701	FIRE EXTINGUISHER NEEDS TO BE MOVED TO WITHIN 15 FT OF STOVE		×							MARKET AND
92	702	OK				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	20 Person 1978 207		2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		8
92	703	ОК									(E)
92	704	ОК						12 8 5 5 5 6 5 6 5 6 5 6 5 6 5 6 5 6 5 6 5			j.
- 92	705	OK									150
92	902	OK									9
92	707 A/B	OK									
92	208	ОК			2 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	200 mm			0 000 000 000 000 000 000 000 000 000		.55 .55
- 85	710	ОК									divid:
92	721	ОК			2.50		100 mm 10				: 6.
92	722	OK									
92	723	ОК				# P					35 35
.92	725	УО									

(LSJH 2005 SREF INSPECTION REPORT.wpd)

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT. CLAY FACILITY #: 0014
7	FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
1	2750 MOODY ROAD ORANGE PARK, FLORIDA 32073
ဂ္ O	INSPECTION DATE: JANUARY 25, 2006
	Land. 1.25.66
	0

		The state of the s			The second section of the second section of the second	The state of the s	The state of the s	CONTRACTOR CONTRACTOR	CONTRACTOR OF THE PROPERTY OF
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. Fac. "O" "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	733	OK			(A)			名のないでは、これには、日本のでは、	
92	735	ОК							
82	737	OK						The state of the s	
92	754 A/B	OK							
92	791	OK					2.20		And the fillest that is a state of the second section to the second section of the section of the second section of the section of the second section of the sectio
- 92	793	OK							
92	794	OK							
- 85	731	EMERGENCY LIGHT OUT		×					FBC 423.17.1
92	743	MISSING FIRE EXTINGUISHER		×					69A-36
	***	REPLACE WOOD RAMPS TO MEET ADA REQ.	×						FBC 4.9.4