
#### F **Z**





	DISTRICT: CLAY FACILITY.# 0013
PORT	FACILITY: CLAY HIGH SCHOOL
FR 5	GREEN COVE SPRINGS, FLORIDA 32043
ATION	INSPECTION DATE: SEPTEMBER 14, 2005
	Marsh 9-14.05
	ANSPECTOR'S SIGNATURE DATE

Rule	NFPA 804.2.3	NFPA 70 410.3	7 min (1) min	NFPA 70 410.3	FBC 423.20.1	FBC:804.2.3	NFPA 70 410.3	NFPA 70 410.3	FBC 423.20.1	FBC 423.17.1	FBC 423.7.3	FBC 423.17.1	FBC 804.2.3	FBC 804.2.3
Scheduled for Correction														
No. of times Def. Cited														
Cost														
Info. Serv. "I.S."														
"C"							i							
Oper. "O"	×	×	×		×				×		×	X	×	×
Maint. "W"				×		X	×	×		×				
Deficiency Description and Corrective Action Required:	Ceiling tile missing	Lense cover missing in electrical room	Light in shower not working	Lens cover missing	Storage in exit passage	Ceiling grid hanging down; tiles missing	Lense cover missing	Lense cover missing - round light incadescent	Equipment stored in exit in laundry	Missing emergency light	Missing extinguisher	Emergency light not working	Ceiling tiles broken	45 45 4 A
Коош	103	103A	116	110	110	132A	134	135	123	138	138	138F	138F	138A
Building			-	L	-		-	<b>J</b>			l			

( CHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)



	DISTRICT: CLAY FACILITY# 0013
PORT	FACILITY: CLAY HIGH SCHOOL
FER 5	GREEN COVE SPRINGS, FLORIDA 32043
FATION	INSPECTION DATE: SEPTEMBER 14, 2005
	Jan. M. 9-14.05
	/NSPECTOR'S SIGNATURE DATE
-3	

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M".	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
-	143	Ceiling tile & grid damages	×							FBC 804.2.3
\	144A	Missing 2 ceiling tiles		×						FBC 804.2.3
2	201	Emergency light not working - flow light not in		×						FBC 423.17.1
2	205	Ceiling tile missing/broken		×						FBC 804.2.3
2	Z09A	Missing ceiling tile		×			***************************************			FBC 804.2.3
2	209A	. Smoke defector hanging	X							FBC 423.7.7
2	209A	3 panel covers missing	×							NFPA 70 312.5
2	209A	Panel knockouts missing	X			100				NFPA 70 312.5
2	215	Duplex outlet cover missing on column	×							NFPA 70 312.5
2	233	Two celling tiles missing		×						FBC 804.2.3
3	301	Conduit for computers wiring not secured to wall				×				
ĸ.	304	Panduit covers missing each end of room				×				NFPA 312.5
3	304	Ceiling tiles missing/broken tiles		×						FBC 804.2.3
8	304	TV straps loose		×						



	DISTRICT: CLAY FACILITY#: 0013
ORT	FACILITY: CLAY HIGH SCHOOL
נט	GREEN COVE SPRINGS, FLORIDA 32043
NOI	INSPECTION DATE: SEPTEMBER 14, 2005
	Ja. 15.05
	MSPECTOR'S SIGNATURE DATE



#### "FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

GREEN COVE SPRINGS, FLORIDA 32043 0013 9./ DATE SEPTEMBER 14, 2005 FACILITY #: 2025 HIGHWAY 16 W. FACILITY: CLAY HIGH SCHOOL NSPECTOR'S SIGNATURE INSPECTION DATE: DISTRICT: CLAY FISCAL YEAR <u>2005-2006</u>

Building	Room	Deficiency Description and Corrective Action Required:	Maint ."M"	,co.,	Fac. 11. "C" S	Info. C Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
	382	Lens cover missing	×							NFPA 410.3
	395	TV to low; no padding		×						FBC 423.14.3
	405	Light cover missing	×							NFPA 70 410.3
	510B	Extension cords (2 cords together)		X						NFPA 70 400-8
	510A/B	Exit lights misleading - remove	×							FBC 1016.3.1
<ul> <li>■ + 1/4 + 1/4 / 3 / 3 / 3</li> </ul>	512	Two extension cords plugged together		X						NFPA 70 400-8
	512	Lens cover missing in storage room	×							NFPA 70 410.3
	517 A/B	Exit lights misleading - possibly remove	×					4		FBC 1016-3-1
	517B	Ceiling tile missing		×						FBC 804.2.3
	518	2 lens covers missing in storage room		X						NFPA 70 410.3
	803	Lights out		×						
	805	Lens cover missing		X						NFPA 70 410.3
	813	Fire extinguisher (K) missing		×				i i		NFPA 1-13.6.6.7
	830	Canvas backdrop needs to be removed		×						

(CHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)




PORT FACILITY: CLAY HIGH SCHOOL
2025 HIGHWAY 16 W.
GREEN COVE SPRINGS, FLORIDA 32043

-ATION INSPECTION PATE: SEPTEMBER 14, 2005

WASPECTOR'S SIGNATURE DATE

DATE

Rule	FBC 804.2.3	FBC 804.2.3	FBC 423.17.1	FBC 804.2.3	FBC 804.2.3			FBC 804.2.3		NFPA 70 312.5	NFPA 70 312.5		FBC 804.2.3		FBC 423.10.1
Scheduled for Correction	<u>u</u>				ш.			<u>.</u>			_		u-		
No. of times Def. Cited															
Cost															
Info. Serv. "LS."											×				
Fac. "C"			:												
Oper/ "O"	×	X		×	×	X	×	X	×					X	
Maint. "M"			×							X		X	×		×
Deficiency Description and Corrective Action Required:	Ceiling tile missing	Damaged ceiling tiles missing	Emergency light hanging down - high ceiling	Damaged ceiling tiles	Ceiling tiles lifted, missing, high ceiling	Return air duct very dirty - high ceiling	Cracked lens covers - high ceiling	Ceiling tiles missing	Ceiling tiles missing	Panel cover missing; electrical	Panel cover missing; computer	Door won't close	Scuttle hole in attic missing	Light not working	Fencing needed around septic pump section
Коош	830	83.1	831	833	1104	1104	1110	1110	1122	1129	1129	2	2	3	
Building	8	8	80	8	1	<u>\</u>	7	<b>\</b>	11	Σ	1	29	30	30	30




	DISTRICT: CLAY FACILITY#. 0013
L Z	FACILITY: CLAY HIGH SCHOOL
•	2025 HIGHWAY 16 W.
L	GREEN COVE SPRINGS, FLORIDA 32043
ဂ	
NO.	INSPECTION DATE: SEPTEMBER 14, 2005
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
<i>-</i> 2	INSPECTOR'S SIGNATURE DATE

Rule	NFPA 70-410.3		NFPA 10113.2.5.6.7	NFPA 70 312.5	NFPA 70 110.26	FBC 1013.9	NFPA 10-776.1.9	NFPA 110.26	FBC 4.9.4	
Scheduled for Correction	4		2	V	4	Ш.	2	4		
No. of times Def. Cited										
Info. Cost Serv. "I.S."										
Fac.			×							
Oper.	×	×			×	X	×	×		
Maint. "M"				X					×	
Deficiency Description and Corrective Action Required:	Lights out (6) lens covers missing	Brick on top of roll up door - high ceiling	Stadium handrails missing	Missing electrical box cover	Storage in front of panel	Replace non skid on ramp	Fire extinguisher not signed	Electrical panel access blocked	REPLACE WOOD RAMPS TO MEET ADA REQ.	
Коош				102	103	7	2	8	***	
Building	31	31	33	.35	35	- 25	92	92		

( CHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)

#### 





#### CO AD "FIR

FISCAL YEAR 2005-2006 DISTRICT CLAY FACILITY #: 0044	OMPREHENSIVE SAFETY INSPECTION REPORT  STATE BOARD OF EDUCATION  STATE BOARD OF EDUCATION  ORANGE PARK, FLORIDA 32003	SAFETY, CASUALTY SAFETY & SANITATION INSPECTION DATE: SEPTEMBER 23, 2005  INSPECTION IN COMPLIANCE WITH	/ INSPECTOR'S SIGNATURE D
FISCAL YEA	OMPREHENSIVE SAFETY INSPECT STATE BOARD OF EDUCA	IRE SAFETY, CASUALTY SAFETY IN COMPLIANC	F.S. 1013.12, 101

Building	Коот	Deficiency Description and Corrective Action Required:	Maint. Op "M" "C	Oper. / F	Fac. Info. "C" Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for for Correction	Rule
-	130	Expansion joint material torn	×				50 Mg 1 Mg		
	221	Ceiling tile missing	(	×					FBC 804.2.3
~	226	Expansion joint material torn	×				1 m m m m m m m m m m m m m m m m m m m		
	252	Expansion joint material tom	×	1.2.4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.					
-	253	Expansion joint material torn	×						
\	272	Cover on "J" box above panel 2BPH	×						NFPA 70 312.5
-	276	Hole in roof flashing	×						FBC 1503.2
	280	Floor drain cover missing	X						
-	274	(Hall) expansion material torn	×				7.77		
÷	291	No emergency evacuation sheet		×					FBC 423.14.2.4
_	281	Material too close to ceiling		×					NFPA 13 13.8.5.5.3
V	271	Expansion joint material torn	×						
-	298	Black mold on ceiling tile		×					The Control of the Co
۲	302	Cover plate under window	×						NFPA 70 314.1

( FHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)



#### FISCAL YEAR <u>2005-2006</u>

STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH COMPREHENSIVE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: HIGH SCH QUARE PAF FLORIDA 3. EMBER 23.
/ INSPECTOR'S SIGNATURE DATE

Ruie	NFPA 70- 527.2	FBC 423.14.2.4	NFPA 1 4.1.8.5	FBC 423.		NFPA 70 314:1	FBC 804.2.3		NFPA 1 4.4.3.1	NFPA 1 21.3.3.5	NFPA 1 21.3.3.5	NFPA 1 12:2:4:6.7	
Scheduled for Correction	Ż		岁	E		Ż	Ш_		Z	Z	岁	Ż	
No. of times Def.													
Info. Cost Serv. "1.S."					-								
ir Fac. "C"				22.2								×	
Maint. Oper. "M". "O".	×	×	×	×	×	X	×	×	×	×	×		
Deficiency Description and Corrective Action Required:	Surge protector's piggy backed	Emergency evacuation sheet missing	Entrance/exit door drags	Light fixture broken	Light fixture broken	East side switch cover	Ceiling tile missing	Black mold on ceiling	Excessive material stored	LP tank in room	Gas grill with LP tank in room	Stadium handrails	
Room	303	306	315	207	205	202	227	230	001	001	90	ļ ļ	
Building	_	Τ	-	2	2	2	2	2	40	40	40	SITE	

(FHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)

	DISTRICT CLAY FACILITY# 0044
I REPORT	FACILITY: FLEMING ISLAND HIGH SCHOOL
V APTER 5	ORANGE PARK, FLORIDA 32003
ANITATION	INSPECTION DATE: SEPTEMBER 23, 2005
E 5	19 man 11 12 3 3 3
-	/ ANSPECTÓR'S SIGNATURE DATE

Building	Коош	Deficiency Description and Corrective Action Required:	Maint Oper.	"Tao. "C."	Info. Cost Serv. "I.S."	No. of times Def. Cited	Scheduled for Correction	Rule
92	10	ОК						
92	-11	ЭОК						
92	12	ОК						
92	13	УО						
92	14	ОК						
92	15	ЖО						
92	20	OK						
92	21	ОК						
92	22	OK				1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
92	23	УО						
92	24	OK				The second secon	Single Property of the State of	
92	25	OK						
92	30	OK						
92	31	ЖО						

(FHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)

DISTRICT: CLAY FACILITY # 0044	FACILITY: FLEMING ISLAND HIGH SCHOOL  2233 VILLAGE SQUARE PARKWAY  ORANGE PARK, FLORIDA 32003	INSPECTION DATE: SEPTEMBER 23, 2005	INSPECTOR'S SIGNATURE DATE
FISCAL YEAR 2005-2006	COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE BILL ES & D. E. E. CHARDED &	"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH	F.S. 1013.12, 1013.20 & NFPA 101

5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Carlotte a second of the an		The second secon	20 SEC. SEC. SEC. SEC. SEC. SEC. SEC. SEC.	36 78	100	· · · · · · · · · · · · · · · · · · ·	おは、おは、日本のは、日本のでは、日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日
Building	Коош	Deficiency Description and Corrective Action Required:	Maint Oper. "M" "O".	Fac. "C"	Info. Cost Serv. "I.S."	tt No. of times Def Cited	Scheduled for Correction	Ruie
92	32	OK						
92	33	УО						
82	34	OK					7	** 1973 1973 1974 1974 1974 1974 1974 1974 1974 1974
92	35	ЭК						
92	40	ОК						
- 92	41	ЭК						
92	42	OK						
92	43	ОК						
92	44	ОК						
92	45	ОК						
92	46	ОК				The state of the s		
92	47	УО						
82	48	Emergency light out	×					FBC 423.17.1
92	49	OK						

( FHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)



#### FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

When a more
ALCOHOLD TO
12/2015/10/74
25 22236
of the second
医肾 福瓦克斯氏
L. CONTRACTOR
and the second second
C
水均含量等等等。
1000
100
역하고 보였다.
01 <b>- 1</b> 110 411
-7) <b>—</b> 9880.
"你在一块影响
FACILITY #
Territoria.
100 (100 (100))
True 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Sec. 25. 1.45
1. 满身运行物试证
a.经选择人所
# 55 8 M 10 18
医格朗伊斯诺
or special section
4.5.共成體 段 20
医克特氏管膜 医红线
<b>3.0 经股份</b> [15] 第
A-1889 1507
averies like
124 Miles
95,624,1 973
<ol> <li>Sept. 1967</li> </ol>
医性致尿性 医环
mark this pairs
18 8 8 6 TO 18
10 C 10 L 10 C
1017 1721 (61)
1792
. 0
200
1940/CF   Down
ن ا <b>نس</b> ان
(V)1-9
(*************************************
17 MARKET
法保护制 超点
45/0/G <b>1</b> - 43
946 7 42
: .d::
ř
K,
5
ા 5
<u> </u>
ZICT.
RICT.
RICT:
IRICT.
TRICT
TRICT
STRICT
STRICT:_
ISTRICT:_
OISTRICT
DISTRICT:_
DISTRICT:_
DISTRICT:_
DISTRICT: CLAY

0044

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY ORANGE PARK, FLORIDA 32003

INSPECTION DATE: SEPTEMBER 23, 2005

VSPECTOR'S SIGNATURE

DATE

				,				
Building	Коот	Deficiency Description and Corrective Action Required:	Maint Oper. / "M" "O"	Fac. Info. "C" Serv.	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	09	OK						
92	51	OK						
92	25	ОК						
92	53	OK						
92	09	ОК						
92		ОК		1111				
82	62	OK						
92	. 63	ОК						
65	02	Soil erosion by ramp	×				<u> </u>	FBC 423.27.2.1
92	7	УО						
92	72	Ceiling tile missing in restroom	×				出	FBC 804.2.3
- 92	73	OK						
82	80	Disconnect; wired improperly		×			Ż	NFPA 70 312.5
92	81	УО.						

(FHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)

DISTRICT. CLAY FACILITY#: 0044	PACILITY: FLEMING ISLAND HIGH SCHOOL  2233 VILLAGE SQUARE PARKWAY  ORANGE PARK, FLORIDA 32003	TION INSPECTION DATE: SEPTEMBER 23, 2005  G 35 - G  INSPECTION DATE  DATE	
FISCAL YEAR <u>2005-2006</u>	COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RILLES S. R. F. F. CHAPTER 5	"FIRE SAFETY, CASUALLY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101	

Room         Deficiency Description and Corrective Action Required:         Majnit.         Oper.         Fac.         Serv.         Infl.         Cos           90         OK         92         OK         I.1.5°         I.1.5°										Т
		Коот	Deficiency Description and Corrective Action Required		X (2.0.2.5)	Cost	No. of times Def. Cited	Scheduled for Correction	Rule	
		82	ОК							
		06	ОК							
		91	OK			 				T
	17,12,17,742,11	92	OK							
	170 U. J. Delete V. V.					A COLUMN				50 iene 10 iene
	12									nan e
						5 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)				
					I i					

(FHS 2005 SREF & FIRE SAFETY INSPECTION REPORT.wpd)