



FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY# 0009	
	FACILITY: MIDDLEBURG ELEMENTARY SCHOOL	
	3958 MAIN STREET	
	MIDDLEBURG, FLORIDA 32068	
Z	INSRECTION DATE: NOVEMBER 3, 2005	
	19	
	Normall #. Automan 11:5-03	
	Winspector's signature date	

Room Deficiency Description and Corrective Action Required:	Maint	Oper.	Fac.	Info	Cost	No. of	Scheduled	Rule
)	"1.S."		unies Dei.	Correction	
EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
EMERGENCY LIGHT MISSING	Χ							FBC 423 17:1
FIRE ALARM BOX COVER MISSING	×							NFPA-70 314.1
		X						FBC 10016.3.1
EXHAUST FAN NOT WORKING BOYS ROOM	×							FBC 423.15.4
FIRE ALARM COVER PLATE MISSING	X							NFPA-70.314.1
EXHAUST FAN NOT WORKING GIRLS ROOM	×	, , ,						FBC 423.15.4
ELECTRICAL BOX COVER MISSING	X							NFPA-70.314.1
		X						FBC 1016:1
	·	×						FBC 1016.1
7 FIRE ALARM COVER MISSING	X							NFPA-70 314.1
STORAGE IN FRONT OF ELECTRICAL PANEL		×						NFPA-70 110.26
· 是有情况,这一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个								



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: MIDDLEBURG ELEMENTARY SCHOOL
3958 MAIN STREET
MIDDLEBURG, FLORIDA 32068
INSPECTION DATE: NOVEMBER 3, 2005

MSPECTOR'S SIGNATURE

1.3.05 DATE

Scheduled Rule Tor- for Correction	FBC 423.17.1	NFPA-70.314.1	FBC 423.14.2.4	FBC 423/7.1	FBC 423.17.1	FBC 423.17.1	FBC 423.15.4	FBC 423.17.1			FBC 423.15.4	FBC 423.15.4	であっています。 これのであると、これではいいのはある。 の形式には開発しています。
Cost No. of times Def.													
Oper Fac Info. "O" "C" Serv.			×	X	×			***************************************					
Deficiency Description and Corrective Action Required: "Maint."	NO EMERGENCY LIGHTING WHOLE BUILDING X	MULT. COVERS MISSING(FIRE, ELEC., PHONE) X	EMERGENCY EVACUATION SHEET MISSING	EMERGENCY LIGHT OUT	EMERGENCY LIGHT OUT	30 NO EMERGENCY LIGHT	EXHAUST FAN NOT WORKING X	EXIT LIGHT OUT NEAR STAIRS 2" FLOOR	ROOF LEAK CEILING TILE MISSING X	EXHAUST FAN LOOSE	EXHAUST FAN NOT WORKING X	EXHAUST FAN NOT WORKING	TO A SECTION OF THE S
Room	****	4	18	10	20	30	31		6/	81	84	85	i di
Building	3		4					1					

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

ST FACILITY # 0009

FACILITY: MIDDLEBURG ELEMENTARY SCHOOL
3958 MAIN STREET
MIDDLEBURG, FLORIDA 32068

MIDDLEBURG, FLORIDA 32068

ON INSPECTION DATE: NOVEMBER 3, 2005
INSPECTOR'S SIGNATURE DATE

INSPECTOR'S SIGNATURE

DATE

							ANN Thur	10	giraj Mari			Ne.s
	6.2	2.3	17.1	2.3	14.1	1.2.4						
Rufe	FBC 423.16.2	FBC 804.2.3	FBC 423.17.1	FBC 804.2.3	NFPA-70 314.1	FBC 423.14.2.4		[34 14 14				
	FBC	FBC	FBC	FBC	VFPA	BC 4						
								,				
			l									
Scheduled for Correction												
Sc. Co.												
J.												
No. of times Def. Cited												
						Galle Sales Galles		1				
Cost								. 9			'	
V.P.AV., SATAVAR VARVO SAROV				通道: 超过				16 10 10 10		基礎 计值数		
Info. "1.S."								1				
		La Million		Beredikt Carries Carries				12	Albat Tigh			5. 1 1 1 3 3 3 4 1
Fac. "C".								100 (c)				
Oper.	×		×	X		×						
63		X	_									
Maint. "M"					×							
		開発						2				
Deficiency Description and Corrective Action Required:						EMERGENCY EVACUATION SHEET MISSING		1: 1: 1:				
Requ	(D				ניז	L MIS						
Action	SING				SSINC	HEE		i i				
ctive	MIS				S MIS	SNC		39				
Corre	OCCUPANCY LOAD SIGN MISSING	Q.		ව	ELECTRICAL BOX COVER MISSING	JATIC						
on and	OAD	ISSII	L	ISSI	χĊ	VAC			an Carl XVII			
scripti	Ω ΣΥ ΓΩ	LEM	50.	EM	\L B(ς V.E.		1. 1. 1. 1.				
Cy De	PAN	10	IGH.	IG TI	RIC/	GEN						
afficien	CCU	EILIN	EXIT LIGHT OUT	CEILING TILE MISSING	LECT	MER						
		ွသ			Ш					ANT The		
Room	10	107 CEILING TILE MISSING	110	114		115						
						14 ACM 17-124 17-114		7.5 7.5 8.5 7.5	46.5 18.15			
Building	တ											
								3				



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY # 0009

FACILITY: MIDDLEBURG ELEMENTARY SCHOOL
3958 MAIN STREET
MIDDLEBURG, FLORIDA 32068

INSPÉCTION DATE: NOVEMBER 3, 2005


INSPECTION DATE:

11.3.05 DATE

				_					
Bullding	Room	Deficiency, Description and Corrective Action Required:	Maint. Oper. "M" "O"	Fac. "C"	Info. Cost Serv. "I.S."	times Def. Cited	Scheduled for Correction	Rule	
92	23	OK				_			
	24)OK							
	25	OK YO							
	26	OK							
	53	OK							
	35	0K							
	36	OK						·	
	37	ОК							
	38	OK						1	
	39)Vo							
	40	OK							
	41	yo							
	42	OK.							
	43								

Rule 1.3.05 6000 NOVEMBER 3, 2005 FACILITY: MIDDLEBURG ELEMENTARY SCHOOL FACILITY #. MIDDLEBURG, FLORIDA 32068 Scheduled for Correction 3958 MAIN STREET MSPECTOR'S SIGNATURE No. of times Def. Cited INSPECTION DATE: DISTRICT. CLAY Cost Info. Serv. "LS." Fac. "FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 oper. INSPECTION" IN COMPLIANCE WITH Maint. "M" F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION FISCAL YEAR <u>2005-2006</u> Deficiency Description and Corrective Action Required: Š Š Š 웅 숭 엉 Коош 65 8 99 29 89 69 Building 92

(MBE 2005-06 SREF INSPECTION REPORT.wpd)



COMPRE	ADMINI "FIRE SA

FISCAL YEAR 2005-2006 PREHENSIVE SAFETY INSPECTION REPORSTATE BOARD OF EDUCATION MINISTRATIVE RULES S.R.E.F. - CHAPTER SAFETY, CASUALTY SAFETY & SANITATIONSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT CLAY FACILITY # 0018
PORT	FACILITY: MONTCLAIR ELEMENTARY SCHOOL
ER 5	ORANGE PARK, FLORIDA 32073
ATION	INSPECTION DATE: NOVEMBER 8, 2005
	ANSPECTOR'S SIGNATURE DATE

是这类人				ing in Benja	(40°4)	12.5		V VI	in the
	7	1	FBC 423.14.2.4			4.0 4.0 4.0 4.0 4.0 4.0 4.0	140,013 34, 35		
Rule	FBC 1016.1	FBC 1016.1	3.14						
₫	. SC 1	ည္က	42;						
	出	出	BC				7.7		
			1.1						
									Type of the second seco
					e e e e e e e e e e e e e e e e e e e	ent.			1944 1944
Scheduled for Correction									
chec fo orre									
န ၁					7847 7347 745				
— 6					100		233		4.54
No. of times Def. Cited									
				Diagram Table 45		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Balle.	
Cost									
3									
						786 72 - 937 85 - 877	37. 34.8.5	X(A)	Allera e Section
Info. Serv. "I.S."									
And Com				14.5		1876. J. Le 1841. 198	7.55		#54 <u>0</u>
					12 m		3.82		A. S. S.
				38177		J 19			39 To 4 Due Oek
Oper. "O"	×	×	×						
ō"			,		1 774 945 1				11.4%
1						111/25 147-611			100
Maint. "M"				×			# \\ \		
		47.74 2.77 2.77 2.77		04703 10475 11.662	\$444	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7.5	<u> </u>	1.54
							47. W. C.	Party. Patan	
			9				12 14 A		
iired			SSII	NG					
Requ		9496233 - 1.44	ĭ.	SSI					
tion			E	S MI					
e Ac			SHI	ERS				300	
ectiv			ON	MB		1.45% 1444a	light.		
Con			ATI	NC.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				1
and			CU	ING		1			
otion	5	5	EV/	[D]					
Scri	EXIT LIGHT OUT	<u> </u>	 	BU					
۲. ا	Œ.	뜐	ΉËΝ	_ IOR				(1,7.5) 1,743 474,90	
cienc	□		ERG	ER	BySec GCSD				l da filosofia. Serios
Deficiency Description and Corrective Action Required:	Ξ	EXIT LIGHT OUT	EMERGENCY EVACUATION SHEET MISSING	EXTERIOR BUILDING NUMBERS MISSING				174); 1797;	
				45.3	499	7.4 7.4 7.4	14.74 14.74		
Soom S	435a	436a	407	****					
Building Room	7	14. 3 % 13.3%		基金。 1		15 to 2 15 to 2	\$49.000 . 1404.000	第三 Seauti	1 4.024 44.43
l Gillo									
Barilli Barilli	4					10 st	the first		
[12] 1		19900			1995 L	18,85	[March	Mary.	48.5



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT CLAY FACILITY# 0018

FACILITY: MONTCLAIR ELEMENTARY SCHOOL

2398 MOODY ROAD ORANGE PARK, FLORIDA 32073

INSPECTION DATE:

INSPECTOR'S SIGNATURE

wand

NOVEMBER 8, 2005

NFPA-70 110.26 FBC 423.15.4 FBC 423.16.1 69A-36 Rule for Correction Scheduled No. of times Def. Cited Cost Info. Serv. "I.S." Fac. × × Maint. "M" × × × × NEWSPAPER STORED IN FRONT OF ELEC PANEL NO SIGNS FOR RESTROOMS BOY'S OR GIRL'S Deficiency Description and Corrective Action Required: FIRE EXTINGUISHER NOT HUNG BY DOOR SIDING BY AC UNIT "ROTTED" WATER LEAKS AT FOUNTAIN FANS NOT WORKING 숭 웅 욧 S Š 엉 ş 엉 25a,b 22 Room 35 23 26 28 21 27 3 32 33 34 36 Building 92 96




"FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

NOVEMBER 8, 2005 0018 FACILITY: MONTCLAIR ELEMENTARY SCHOOL 2398 MOODY ROAD ORANGE PARK, FLORIDA 32073 FACILITY #: INSPECTION DATE: DISTRICT: CLAY

NSPECTOR'S SIGNATURE

DÁTE

			-3.	35		·诗	(1) (2) (2)	1. 水道を含むして	
Building	Коош	Room Deficiency Description and Corrective Action Required:	Maint. «M"		Edc. Into "C" Serv. "I.S."	de Cost	No. of times Def. Cited	Scheduled for Correction	Kule
35	36	OK							
	37	ЖО							
	38	OK							
	39	EXHAUST FAN COVER MISSING		X					FBC:423.15.4
	40	OK							
	41	У О							
	44	OK							
	45	УО							
	46	OK		:					
	****	REPLACE ALL WOOD RAMPS TO MEET ADA REQ.	×						FBC 11-4.9.4
							3		





COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: ORANGE PARK ELEMENTARY SCHOOL

1401PLAINFIELD AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 10, 2005

Annulf home of

Building	Коош	Deficiency Description and Corrective Action Required:	Main Main Main	Oper. "O"	Fac. "C"	lhfo. Serv.	Cost	No. of Umes	Scheduled	Rui
						Ž		Cited		
~	10	MISSING CEILING TILE		×						FBC 804.2.3
	12	EMERGENCY LIGHT MISSING	×							FBG 423.17.11
~	13	ELECTRICAL BOX COVER MISSING	×							NFPA-70 314.
		EMERGENCY LIGHT MISSING	X							FBC 423 17.1
-	2	OCCUPANCY LOAD SIGN ON INSIDE OF ROOM		×						FBC 423.16.2
	810	810 TURN EXIT SIGN		X						FBC 1016
4	83	OCCUPANCY LOAD SIGN MISSING		×		<u></u>				FBC 423.16.2
7	84	CEILING TILE MISSING		X						FBC 804.2.3
4	84	SOUND SYSTEM PANEL NO COVER	×							NFPA-70 314.1
2	02	NO EMERGENCY LIGHTS	X							EBC 423.14.2.4
5	1.2	NO EMERGENCY LIGHTS	X							FBC 423.14.2.4
8	8	NO EMERGENCY LIGHTS	X							FBC 423.14.2.4
က	q6	NO EMERGENCY LIGHTS	×							FBC 423.14.2.4
8	96	****STEP-DOWN @ EXIT DOOR	X							FBC 11-4.13[8

SCHOOL STATE OF THE SCHOOL

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101


FACILITY: ORANGE PARK ELEMENTARY SCHOOL
1401PLAINFIELD AVENUE
ORANGE PARK, FLORIDA 32073

N INSPECTION DATE: NOVEMBER 10, 2005

INSPECTION DATE:

//. /0·05 DATE

		11-02	140000						in a de la constante de la con	Distr		4281
Section (Control of Control of Co	ω		2000 2000 000 000 000 000 000 000 000 0									
	FBC 11-4.13.8	FBC 423.17.1								####		
ar District of the second	4.	က်	100401									
Reference	7	42										
designation of the comment of the co	BC	BC										
property of the first land of the second of	ш											
The state of the s			200511 2011									
The second secon			e Carabado de Antonio Visa de Antonio de Caraba Visa de Antonio de Carabado Visa de Carabado de Carabado Visa de Carabado de C									
and the state of t		35555	400044-6-0 044048-6-0		Section 1		14444 14444		- Godden	Parties!		27-15-
Scheduled for Correction												
for rect			15 com and 16 com 15 co				349					
5 8												
			1000000 10000000 100000000 100000000		atha				The state of the s			
The state of the s					Medic				Table and the			
No. of times Def. Cited												
237 0										Company of the compan		
		45.5°	Control of the contro		sidazya. gridata		####		44513	 HERE		Wilder of
Sos			The second of th									
			The state of the s							1000		
7.274.00.00.00.00.00.00			10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1111711		Pist.		CONTR.	SERVE CONTRACTOR		hill this
Info. Serv.			State of the state									
= 0 =			925-7393. 22-32-32-3 27-32-32-3									
			ii ari		1602							
Č. Č.			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							Traffi Same		
												M
		pachdon VSVEV	\$25.00 25.00		65.5				341			374
"O"		×			de di							
KO 2		444										
			alia araba sa kata kata kata kata kata kata kata				285		sigt.			
Maint	×											
							MÖ		12011			Edition (
Jest Andrews (Print, 1844), and an experience of the print of the prin												
2												
be .												
5												
e Actio			1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1				26.2.2					
9	R											
orrect	8			—			E					
75	⊑	S		\geq								
2	$\widetilde{\mathbf{x}}$		The College of the Selection of the Sele	<u> </u>		! I						
	0	- 등		뜐								
	S	3		J								10.0
	0	<u> </u>		Š								
<u> </u>	٠-D	回	The state of the s	Ë			1985					filly.
2	8" STEP-DOWN @ EXIT DOOR	RG		EMERGENCY LIGHT OUT								
20	S	3		ME								
ŏ	<u></u>	EMERGENCY LIGHT OUT		Ш								
Room Deficiency Description and Corrective Action Required:			51.05 7376 6 2574 7							 THE REAL PROPERTY.		
E C	61a	7	227 13 14 14 14 14 14 14 14 14 14 14 14 14 14	22								
	9											
			70.4000 70.7000		Mil					THE STATE		A Section
Building	3		1000	92	121							
	,,	2		တ								
		3.416.5			THE TE		manuel.	ı	: Halings		l	1920/





COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY # 0024

FACILITY: ROBERT M. PATERSON ELEMENTARY SCHOOL
5400 PINE AVENUE
ORANGE PARK, FLORIDA 32003

INSPECTION DATE: NOVEMBER 15, 2005

STANKER

DATE

SPECTOR'S SIGNATURE

Building			က	2	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	92							
Коош	142	122	312	508	\$ 10 miles	-	2	ю	4	2	9	2	8
Deficiency Description and Corrective Action Required:	OCCUPANCY LOAD SIGN MISSING	CLASSROOM NOT BY DESIGN CHANGE DOOR SWING	CLASSROOM NOT BY DESIGN CHANGE DOOR SWING	EXIT LIGHT OUT	C. Della C. L. Sellen C. Carlotte Const	COVER MISSING EXT COMM. BOX	ОК	EXHAUST FAN NOT WORKING	OK	OK	OK	OK	EMERGENCY LIGHT OUT
Maint "M"		×	×		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			×					
Oper. "O"	×			X									X
Fac. Inf					a programme of the second	×							
Info. Cost. Serv. "I.S."													
t. No of times Def. Cited													
Scheduled for Correction					2. 2. 3. 4. 3. 4. 3. 4. 3. 4. 3. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.								
Rule	FBC 423.16.2	FBC 423	FBC 423	FBC 1016.3.1	ACTION POSTERIORES PARENTE PER A SALE			FBC 423.15.4					FBC 423.17.1



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: ROBERT M. PATERSON ELEMENTARY SCHOOL 5400 PINE AVENUE ORANGE PARK, FLORIDA 32003

INSPECTION DATE: NOVEMBER 15, 2005

INSPECTOR'S SIGNATURE DATE

Building		Room Deficiency Description and Corrective Action Required:	Maint C	Oper	Fac. "C".	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	11	OUTLET COVER MISSING BY SINK	×							NFPA 314.1
	13	DOOR CLOSER BROKEN @ BATHROOM	×							
	4	OK								
	15	OK								
	16	OK								
	17	00K					「大学」では 「大学」では 「大学」である。 「大学」である。			
	18	TRAILER HITCH NOT UNDER BUILDING	_	×						
	21)VC								
	22	OK								
	23	yo								
	24	EMERGENCY LIGHT OUT		×						FBC 423.17.1
	25	NO.						AACLE		
	26	OK	-							
	27	EXHAUST FAN NOT WORKING	X							FBC 423.15.4



FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY #: 0024

FACILITY: ROBERT M. PATERSON ELEMENTARY SCHOOL
5400 PINE AVENUE
ORANGE PARK, FLORIDA 32003

INSPECTION DATE: NOVEMBER 15, 2005

INSPECTION SIGNATURE
DATE

DATE

Building		Cost No. of	Rule
		.C" Serv. times "I.S." Def. Cited.	forrection
82	28	8 EMERGENCY LIGHT OUT X	FBC 423.17.1
	29	9 OK	FBC 423
	30	0 OK	FBC 423
	41		FBC-1016.3.1
	42	2 OK	FBC 423.16.2
	43	3 OK	
	44	4 OK	
	45	5. OK	
	46	S OK	
	47		
	48	3 OK	
	49	3 EMERGENCY LIGHT OUT	FBC423.17.1
	20	OK OK	
	51		


"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

FACILITY # 0024 FACILITY: ROBERT M. PATERSON ELEMENTARY SCHOOI 5400 PINE AVENUE ORANGE PARK, FLORIDA 32003

NOVEMBER 15, 2005 **TOR'S SIGNATURE** INSPECTION DATE:

DATE

* for the form		7 .955-1		a Secretary			 		38 _m [
										1965 (A. 1866 (A.	
	7	・では 対象数数						1111			
	FBC 423.16.2	က			4.					100	
Rule	33	FBC 423			FBC-4.9.4			12% 2.3			1124
Ž.	4	BC			ပ္က်				100		
	ĕ	ш.			世	热觀				7.544.E	
	ш								Hai		1.7
		建筑					1200				Lipid.
returni e e e e e e e e e e e e e e e e e e e		486566		48.4M		- 1965 -		(C)	1952 1952	2000 N	7.5% d 885 5 A
Scheduled for Correction											
or ecti							遺居		446	194	ANTENNA ANTENNA
5 5								150	. 700 159-5 1715	24 july 24 hours	## J. J. J
		37743				(Myaks	4/15/4/4	1.4	(.45); (20);	4.504	(4.)
ef. se						120 C		3	V4)		
No. of times Def. Cited								9-1			3/43
WAS CHARGE		据[广集] WF第一		ALTERY OF		option.	 を 100mm	93		3.34	
.							region of				100 (100) 100 (100)
Cost								40		7 10 mm	
		表现。						150		181a 300 1858 - T	
								. 137 203	erio Sal	11 March 11 March 12	443
Info. Serv. "I.S."								Ĝ.			
								154	934).		
MARKET CO.				16454 16454 16454		1.1	海融	95	V.		to fifth
දී දී								200	77.7		11,177
				特別			A. A.	W	541 540		
		年時か					跨順	152	eresa India	in min	nours.
0"	×								1999 1990	391	
0						144					
		\$37T		1979.5		1100	 TO AL	696	150	¥.£8	
Maint "M"		×			×	11000	\$Gg		roj Nak		
						1945	 Pilips	ta)		¥4.	
										iganai Lääää	
		(Pat)						1.3	40.7 F 3		
					EQ.						diele. Hegin
		回			R				(re.) C. (2) C. Vari		
		Š			Ϋ́			189	150E 150E		
2		BR			A	5.44.5 190 an	調道	1.47	016 616		
		巫			山		Name of	100 200	330		
<u>~</u>		8			¥						
		$\underline{\mathbf{Q}}$			ō						
₹					Η.					iller ja. Elita	
3		ΙğΙ		lagit Kiti Milippan	<u></u>			184 184	544 544	W.	. (13) 3 (13)
		生			Æ				950 3.4	#	(
8		₩			S.			100	egan Mak		
2					Ŏ						1. (3.47)
5		ō		新於	NO	1023		100			
基验验		H		學學科				. 54			
200		SC		76%	ΑF		柳鄉	17.7.5 \$7.48			
Q		5			끥			14 A	1974		7 A 1.
8		DOOR CLOSER ON BATHROOM DOOR BROKEN			REPLACE ALL WOOD RAMPS TO MEET ADA R		4.4.1			Milit	
2	¥	8	Ą		F.		A. A.				
Deficiency Description and Corrective Action Required:	Ş	Ā	0		쭚			1			
		THE STATE OF		Fig.		(Maries		1.00	H/GI	MAG	5465T
. E	52	53	54		****			100 No. 1 10. 1		W. C.	
Room	٠,		٦,		*			ĝ.		Mark	
as fill mental in the state of the second		955		A. A.		製まり	 Talling.	. 1) }	THE STATE	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Building	٥.							1.1.1 1.07	- 1.4 - 1.05		
	92							100 m			17. 18.02
a		Eig.		ZWY.		777					#4.5%





"FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

0043 FACILITY #: DISTRICT CLAY

FACILITY: RIDEOUT ELEMENTARY SCHOOL

3065 APALACHICOLA BOULEVARD MIDDLEBURG, FLORIDA 32068

INSPECTION DATE:

NOVEMBER 17, 2005

MSPECTOR'S SIGNATURE Mossen

Building	Room	Building Room Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fac. "C"	Info. Serv. "1.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
	120	DOOR CLOSURE COMING APART	×							
	134	134 ROOFLEAK								
	138	ROOF LEAK								
	223	EXIT LIGHT MISSING	X							FBC_1016.3.1
	224	LIGHT GRID BROKEN (CLIPS)		×						
	215	OCCUPANCY LOAD SIGN MISSING		X						FBC 423:16.2
	238	CONTROL WIRES NOT IN CONDUIT	×							
		*****BEHIND DUCT BACK RIGHT CORNER								
	302	OCCUPANCY LOAD SIGN MISSING		×						FBC 423.16.2
	311	311 ROOF LEAK	X							
	312	ROOF LEAK	×	-						
	301	ROOF LEAK	X							
	442	PAPER TREE DECORATION IN HALL "PAPER"		×						
	430	430 CEILING TILE MISSING		X						FBC 804.2.3



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: RIDEOUT ELEMENTARY SCHOOL
3065 APALACHICOLA BOULEVARD
MIDDLEBURG, FLORIDA 32068
INSPECTION DATE: NOVEMBER 17, 2005

INSPECTION DATE:

11.17.0 DATE

					_						
Bullding	Room	Deficiency Description and Corrective Action Required:	Waint	Oper.	Fac.	Serv.	Cost	No. of times Def. Cited	Scheduled for Correction	Rule	
-	413	ROOF LEAK	×								
	458	458 CEILING TILE MISSING		×						FBC 804.2.3	
					1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 /		1, c,	The state of the s	The state of the s		- / - / - / - / - /
		表现,更以所有企业,可以不是不是一个企业,但是不是一个企业,可以不是一个企业,可以不是一个企业,可以不是一个企业,可以不是一个企业,可以不是一个企业,不是一个企业,不是一个企业,不是一个企业,不是一个								のでは、「大きない」というでは、「大きない」というでは、「大きない」というです。 こうかん かんしょう しょうしゅう しゅうしゅう かんしゅう しゅうしゅう しゅう	
92	10	OK			_	_					
		y o									
	12	OK									
	13										
	14	ОК			·						
	50	HOOD NOT DUCTED TO EXTERIOR	X							FBC 423.24	
		FIRE EXTINGUISHER NOT WITHIN 15ft OF STOVE		×						69A-36	
	21	21 HOOD NOT DUCTED TO EXTERIOR	X								
		FIRE EXTINGUISHER NOT WITHIN 15ft OF STOVE		×						69A-36	
	22	YO	E S.								



FISCAL YEAR <u>2005-2006</u>


COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT CLAY FACILITY#. 0043
RT	FACILITY: RIDEOUT ELEMENTARY SCHOOL
: :	3065 APALACHICOLA BOULEVARD
70	MIDDLEBURG, FLORIDA 32068
NOI	INSPECTION DATE: NOVEMBER 17, 2005
	Jurust . Avenue 11.17.05
9	INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Waint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "1.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Ruie
92	23	HOOD NOT DUCTED TO EXTERIOR	×							
	24	OK								
	25	OK								
	26	OK								
	27	OK								
	28	OK								
	59	OK								
	.30	OK								
	31	OK								
	32	OK								
	33	OK								
	34	OK								
	40	OK								
	41	OK								

(ROE 2005-06 SREF INSPECTION REPORT.wpd)

NOVEMBER 17, 2005 0043 3065 APALACHICOLA BOULEVARD ĎATE FACILITY: RIDEOUT ELEMENTARY SCHOOL MIDDLEBURG, FLORIDA 32068 FACILITY #: INSPECTOR'S SIGNATURE INSPECTION DATE: DISTRICT CLAY "FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION **FISCAL YEAR 2005-2006**





FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: RIDGEVIEW ELEMENTARY SCHOOL
421JEFFERSON AVENUE
ORANGE PARK, FLORIDA 32065

N INSPECTION DATE: November 22, 2005

INSPECTOR'S SIGNATURE

DATE

DATE

Eac. Info. Cost. No. or Scheduled Rule "C". Serv. Imes for Servection	FBC 423.14.2.4	69A-36	FBC 1016.1	69A-36	69A-36	69A-36	. 69A-36	694-36	69A-36	EBC 423:14.2.4		69A-36	
Maint Oper.	×	×	×	15f	×	Stf. X	5ft X	5ft X	Sft X	X		×	
Deficiency Description and Corrective Action Required:	EMERGENCY EVACUATION SHEETS MISSING	FIRE EXTINGUISHERS NOT SIGNED	EXIT LIGHT OUT	FIRE EXTINGUISHER NOT BY COOKTOP max	FIRE EXTINGUISHERS NOT SIGNED	601 FIE EXTINGUISHER NOT BY COOKTOP max 1	FIE EXTINGUISHER NOT BY COOKTOP max 18	FIE EXTINGUISHER NOT BY COOKTOP max 1	FIE EXTINGUISHER NOT BY COOKTOP max 18	EMERGENCY EVACUATION SHEET MISSING		FIRE EXTINGUISHERS NOT SIGNED	NO.
Room	****	****	129	108	****	601	602	603	604	708	新疆	****	7
Building	~				9					2		92	

(RVE 2005-06 SREF INSPECTION REPORT.wpd)

FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

	PISTRICT: CLAY FACILITY #: 0020 FACILITY: RIDGEVIEW ELEMENTARY SCHOOL 421JEFFERSON AVENUE ORANGE PARK, FLORIDA 32065
	INSPECTION DATE: November 22, 2005
•	INSPECTOR'S SIGNATURE DATE

Building	Room	Room Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	"Ç".	Info. Serv. "I.S."	Oost	No. of times Def. Cited	Scheduled for Correction		Rule
92	712	OK				-					
24.00	713	FIRE ALARM WIRES NOT CONNECTED BATHROOM	×								
	714	FIRE ALARM WIRES NOT CONNECTED BATHROOM	×								
	715	OK									
	716	OK									
	718)N									
	728	CEILING DAMAGED FROM LEAK	×								
	729	ЖО									
	730	OK		_							
	731	ХO									
	732	ОК									
	733	XO.									
	734	DOOR SWINGS WRONG WAY	×							FBC 4	FBC 423.16.1
	735	BATHROOM VENT NOT WORKING.	×							FB(FBC 423

(RVE 2005-06 SREF INSPECTION REPORT.wpd)



"FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

11: 22-05 DATE FACILITY #: 0020 FACILITY: RIDGEVIEW ELEMENTARY SCHOOL November 22, 2005 421JEFFERSON AVENUE ORANGE PARK, FLORIDA 32065 INSPECTION DATE: DISTRICT CLAY

MSPECTOR'S SIGNATURE

Building Room 92 736 737 741 742 743	Deficiency Description and Corrective Action Required: TV NOT SECURED TO BOOKCASE LOUD EXHAUST FAN REPLACE NON SKID ON RAMIP OK	Maint.		 Serv. S. "S."	<u> </u>	Villines Littled Def Cited	Scheduled Correction	FBC 1013.9 FBC 1013.9 FBC 1013.9 FBC 1013.9	
747 748 749	REPLACE NON SKID ON RAMP SIGNAGE BOY'S RESTROOM REPLACE NON SKID ON RAMP OK		×××					FBC/1013:9 FBC/1013.9	
750 751 752	OK LENS COVER MISSING OK		×						

(RVE 2005-06 SREF INSPECTION REPORT.wpd)



"FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

FACILITY #____0020 FACILITY: RIDGEVIEW ELEMENTARY SCHOOL ORANGE PARK, FLORIDA 32065 **421JEFFERSON AVENUE** DISTRICT CLAY

November 22, 2005 MSPECTOR'S SIGNATURE INSPECTION DATE:

1.22.0

DATE

FBC 423.17.1 FBC 11-4.9.4 69A-36 Rule Scheduled Correction No. of times Def. Cited Cost Info. Serv. "I.S." C. Lac ...0, ...0, × × Maint. "M" × REPLACE WOOD RAMPS TO MEET ADA REQ. Deficiency Description and Corrective Action Required: FIRE EXTINGUISHER NOT SIGNED **EMERGENCY LIGHT OUT** 엉 숭 엉 엉 Š Š ş ð 774 Кооп 754 758 772 753 755 756 **** 757 760 Building 92

(RVE 2005-06 SREF INSPECTION REPORT.wpd)