



FISCAL YEAR 2005-2006 COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT. CLAY FACILITY#. 0012
E	FACILITY: S. BRYAN JENNINGS ELEMENTARY SCHOOL
ι.	ORANGE PARK, FLORIDA 32073
NO	INSPECTION DATE: DECEMBER 1, 2005
	James 15-1-05
	INSPECTOR'S SIGNATURE DATE

Building	Коош	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
	29a	COMMUNICATION PANEL - NO COVER	×							NFPA 70 314.1
X	30a	PANEL - NO COVER	X							NFPA 70 314.1
~	30a	10" HOLES IN WALL TO BOILER ROOM	×							
<u> </u>	33	ELECTRICAL PANEL COVER REMOVED	X							NFPA 70 314.1
-	33	LIGHT OUT		×						FBC 1006.2
_	34d	INCANDESCENT LIGHT HAS NO COVER	X							
-	34e	INCANDESCENT LIGHT HAS NO COVER	×							
<u> </u>	332b	INCANDESCENT BULBS / FLOOD FIXTURES?		×						
3	42	RETURN AIR VENT FILLED WITH TRASH		×			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	to 20 VCP () Systematics	Control of the contro	
3	44	RETURN AIR VENT FILED WITH TRASH		×						
င	43	ELECTRICAL BOX MISSING KNOCKOUT	×							NFPA-70, 314.1
က	48a	LIGHTOUT		×						FBC 1006.2
4	*	NO EMERGENCY LIGHTS IN CLASSROOMS		×						FBC 1006.2



FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY S. BRYAN JENNINGS ELEMENTARY SCHOOL
215 CORONA DRIVE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: DECEMBER 1, 2005

INSPECTOR'S SIGNATURE
DATE
DATE

									The state of the s	Committee and the second secon
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "W"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rute
5	**	NO EMERGENCY LIGHTS IN CLASSROOMS		×						FBC 1006.2
	50	LIGHT OUT		X						FBC 1006.2
	80	LIGHT OUT		×					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	FBC 1006.2
	- 8d	LIGHTOUT		×						EBC 1006.2
9	*	NO EMERGENCY LIGHTS IN CLASSROOMS		×						FBC 1006.2
	P6	LIGHTS OUT		×						FBC 1006.2
	12c	LIGHTS OUT		×						FBC 1006.2
	*	NO EMERGENCY LIGHTS IN CLASSROOMS		×						FBC 1006.2
8	*	NO EMERGENCY LIGHTS IN CLASSROOMS		×						FBC 1006.2
6.	*	NO EMERGENCY LIGHTS IN CLASSROOMS		×						EBC 1006.2
2	17a	EMERGENCY LIGHT OUT		×						FBC 1006.2
6	22d	EXIT FAN NOT WORKING	×							
	21e	COVER TO TV BOX MISSING	×				AL TO A COLUMN STATE OF			金田県「東京の東京の東京のできる。

(SBJ 2005-06 SREF INSPECTION REPORT.wpd)

"FIRE SAFETY, CASUALTY SAFETY & SANITATION COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 INSPECTION" IN COMPLIANCE WITH STATE BOARD OF EDUCATION FISCAL YEAR <u>2005-2006</u>

 DISTRICT:
 CLAY.
 FACILITY:#: 0012

 FACILITY:
 S. BRYAN JENNINGS ELEMENTARY SCHOOL

 215 CORONA DRIVE
 ORANGE PARK, FLORIDA 32073

MSPECTOR'S SIGNATURE

F.S. 1013.12, 1013.20 & NFPA 101

DECEMBER 1, 2005

INSPECTION DATE:

DATE

									The second secon	the state of the s
Building	Room	Deficiency Description and Corrective Action Required:	Maint. C	Oper. "O"	.C. C.	Info. Serv.: "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
0	23d	EXIT FAN NOT WORKING	×							
	24a	EXTENSION CORD THROUGH DOORWAY		×						NFPA 527.2
							troffeed day grants of home of the			
- 85	26	ELECTRICAL PANEL BLOCKED BY FILE CABINET		×						NFPA 70, 26.1
92	27	ОК					100		Production of the second of th	
. 92	28	ЭОК								
92	29	ОК						A CONTRACTOR AND A CONT		
- 65	30	ЭК								
92	32	ОК								
- 65	33	УО				1111	4172			
92	34	EMERGENCY LIGHT OUT		×						FBC 1006.2
- 92	35	NO EXIT SIGN	X							
92	36	NO EXIT SIGN	×							では、日本の
92	38	NO EXIT SIGN	×							
92	39	NO EXIT SIGN	×							



FISCAL YEAR 2005-2006 COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION

INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101


FACILITY: S. BRYAN JENNINGS ELEMENTARY SCHOOL
215 CORONA DRIVE
ORANGE PARK, FLORIDA 32073

ANSPECTOR'S SIGNATURE

INSPECTION DATE: DECEMBER 1, 2005

15-1-6 DATE

				\ 					Control of the contro
Building	Коош	Deficiency Description and Corrective Action Required:	Waint: Oper. "ען" "ס"	Tac. Cac	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
82	43	NO EXIT SIGN	×						
92	37	OK							
92	42	OK			5000			200 200 200 200 200 200 200 200 200 200	
- 62	4	OK							
92	45	OK							
. 92	49	ОК							
92	90	ОК					STATE OF THE STATE	Expression and the state of	The Control of the Co
-92	75	OK							
92	92	ОК			2.5	The state of the s	**************************************		AND COMPANY OF THE PROPERTY OF
92	<u> </u>	ОК							
92	78	OK							
92	79	EMERGENCY LIGHT OUT	X						FBC 1006.2
92	80a/b	B-SIDE AC COVER FALLING	×				Trigger visit party		
- 85	81	OK							
	****	REPLACE WOOD RAMPS TO MEET ADA REQ.	×						FBC4.9.4





FISCAL YEAR 2005-2006 COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY#. 0053
	FACILITY: SWIMMING PEN CREEK ELEMENTARY SCHOOL
	1630 WOODPECKER LANE
	MIDDLEBURG, FLORIDA 32068
_	
_	INSPECTION DATE: JANUARY 19, 2006

INSPECTOR'S SIGNATURE

DATE

Scheduled Rule for	Correction	NFPA 10	FBC 423.17.1				FBC 423.13.1	FBC 423.13.1	FBC 423.13.1		FBC 423.12.3	
Info. Cost No. of times	S." Def. Cited											
Oper. Fac. Im			X	×	X	×	X	×	X	×	X	
Maint. "M"		×					· exit	' EXIT	EXIT		627.1S	E-1000
Deficiency: Description and Corrective. Action Required:		FIRE ALARM PANEL TAG NOT CURRENT	CLASSROOM NOT BY DESIGN; DOOR SWING CHANGE	CEILING TILE MISSING	EMERGENCY LIGHT NOT WORKING	CEILING TILE MISSING	CLASSROOM NOT BY DESIGN - SECONDARY REQUIRED	CLASSROOM NOT BY DESIGN - SECONDARY REQUIRED	CLASSROOM:NOT BY DESIGN - SECONDARY REQUIRED.	EXIT LIGHT COVER MISSING	ROOM NUMBER SIGN NOT CORRECT; SAYS 630	
Room		102	203	212	228	434	433	533	627	617	630	
Building			2	2	7	4	4	5	9	9		

FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

INSPECTION DATE: JANUARY 19, 2006

A Called January 19, 2006

MSPECTOR'S SIGNATURE D

Lan 19,2006 DATE

				-				
Building	Коот	Deficiency Description and Corrective Action Required:	Maint. Oper.	Fac. "C"	Info. Cc Serv. "I.S."	Cost No. of times Def. Cited	Scheduled for Correction	Rule
92	701	ОК						
76	702	ЭО					Y., Y.	
85	705	ОК						
92	206	OK						
92	202	ОК						
92	208	УО						
92	805	ОК						
92	808	УО						
92	810	ОК						
92		TEACHER COMPLAINT OF MOLD & AIR QUALITY	×					
92	704	ROOF LEAK - MOLD OVER STOVE	×					
92	801	FIRE EXTINGUISHER NOT CURRENT	X					NFPA 10
92	803	LENS COVER MISSING	×					
- 35	804	EMERGENCY LIGHT NOT WORKING	X					FBC:423.17.1

|--|

FISCAL YEAR <u>2005-2006</u>

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101


	DISTRICT; CLAY	CLAY #: 0053
	FACILITY:	FACILITY: SWIMMING PEN CREEK ELEMENTARY SCHOOL
		1630 WOODPECKER LANE
		MIDDLEBURG, FLORIDA 32068
_		

INSPECTION DATE: JANUARY 19, 2006

INSPECTOR'S SIGNATURE

John 19,200C

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "W"	Oper. "O"	Fac. "C"	Info. Serv. "1.S."	Cost No. of times Def. Cited	of Scheduled is for ited Correction	Rule
92	804	FIRE EXTINGUISHER NOT CURRENT		×					NFPA 10
92	908	EMERGENCY LIGHT NOT WORKING		X			# 141 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		FBC 423:17.1
92	807	EMERGENCY LIGHT NOT WORKING		×					FBC 423.17.1
- 82	809	TV NOT ON BRACKET		×					
							3.75 2.75 2.75 2.75 2.75 2.75 2.75 2.75 2		



DISTRICT. CLAY FACILITY #: 0042	FACILITY: THUNDERBOLT ELEMENTARY SCHOOL 2020 THUNDERBOLT ROAD ORANGE PARK, FLORIDA 32003	INSPECTION DATE: DECEMBER 8, 2005 Off December 8, 2005 Off December 8, 2005 INSPECTOR'S SIGNATURE DATE
FISCAL YEAR <u>2005-2006</u>	COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RIII ES S. R. F. F. CHAPTER 5	"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
Ψ-	262	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
	247	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
_	231	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
1	236	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
1	239	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
1	240	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
<u> </u>	244	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
1	245	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
82	701	ОК								
92	702	ЭК								
92	705	ОК								
92	706	OK								
92	707	ОК						3		
92	703	LENSE COVER MISSING RESTROOM	×							
92	704	LIGHT OUT IN RESTROOM		×						

(TBE 2005-06 SREF INSPECTION REPORT.wpd)



	FISCAL YEAR <u>2005-2006</u>		DIS	DISTRICT: CLAY	LAY	FAC	FACILITY #	0042
	COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RIII ES S.R. F. F. CHAPTER 5	A REPORT A APTER 5		FACILITY: THUNDERBOLT ELEMENTARY SCHOOL 2020 THUNDERBOLT ROAD ORANGE PARK, FLORIDA 32003	UNDERBO O THUND ANGE PA	THUNDERBOLT ELEMENTA 2020 THUNDERBOLT ROAD ORANGE PARK, FLORIDA 32	THUNDERBOLT ELEMENTARY S 2020 THUNDERBOLT ROAD ORANGE PARK, FLORIDA 32003	SCHOOL
	"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101	ANITATION ITH		INSPECTION DATE: DECEMBER 8, 2005	DATE: D	ECEMBE 7 JRE	R 8, 2005	De 8,2005 DATE
uilding Room	n Deficiency Description and Corrective Action Required:	Waint. O	Oper. Fac.	info. Serv.	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92 704	4 DOOR CLOSURE BROKEN	×						
92 708	B AC UNIT NEEDS PADDING BY RAMP	X						FBC 1003.2
100		>						

Building	Коот	Deficiency Description and Corrective Action Required:	Maint. Oper. "M" "O"	."C".	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	704	DOOR CLOSURE BROKEN	×						
92	708	AC UNIT NEEDS PADDING BY RAMP	×						FBC 1003.2
92	708	ROOF LEAK DAMAGE	×						
92	709	RAMP NEEDS ADJUSTMENT "BOUNCES"	X						
62	710	RAMP NEEDS ADJUSTMENT "BOUNCES"	×						
92	721	ELECTRICAL PANEL COVERED WITH POSTERS	X		W. 7				NFPA 70, 26.1
92	722	ОК							
- 82	723	ЮК							
92	724	ОК							
92	725	ОК							
92	726	OK							
- 92	727	ОК							
92	728	ОК							
92	729	УО						ab	

(TBE 2005-06 SREF INSPECTION REPORT.wpd)

			FISC	FISCAL YEAR <u>2005-2006</u>	R 2005-	2006			DISTE	DISTRICT: CLAY	LAY	FA	FACILITY #	0042	15	
		COM	COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	HENSIVE SAFETY INSPECTION STATE BOARD OF EDUCATION STRATIVE RULES S.R.E.F CHA	Y INSPI OF EDU S S.R.E.	CATION F CF	ISPECTION REPORT EDUCATION R.E.F CHAPTER 5	ORT 8.5	FACIL	-1 TY : TH 202	UNDERE O THUN ANGE P	THUNDERBOLT ELEMENTA 2020 THUNDERBOLT ROAD ORANGE PARK, FLORIDA 33	FACILITY: THUNDERBOLT ELEMENTARY SCHOOL 2020 THUNDERBOLT ROAD ORANGE PARK, FLORIDA 32003	/ SCHO	OF	
		"FIRE	"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101	RETY, CASUALTY SA SPECTION" IN COMP F.S. 1013.12, 1013.20	Y SAFE JMPLIA 3.20 & N	FETY & SAN LIANCE WIT & NFPA 101	ANITAI VITH 01	NOI	INSPE	INSPECTION DATE: DECE	DATE:	DECEMBI TURE	DECEMBER 8, 2005 TURE DA	Sec E	005 Dec 8,2005 DATE	
Building	Коош	Deficiency Det	Deficiency Description and Corrective Action Required:	ive Action Requ	uired:		Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction		Rule	
92	730	OK														
92	731	OK														
92	732	OK														

(TBE 2005-06 SREF INSPECTION REPORT.wpd)