


TRYNES

ELEMENTARY SCHOOL



FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0040

FACILITY: TYNES ELEMENTARY SCHOOL
 1550 TYNES BOULEVARD
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: DECEMBER 14, 2005

INSPECTOR'S SIGNATURE: *Samuel J. ...* DATE: 12-14-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		HANDICAPPED ACCESS FROM PARKING TO BUILDING BLOCKED		X						FBC 11.24
1	111	ROOF LEAK	X							
1	112	ROOF LEAK	X							
1	144	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2.2
1	152	ROOF LEAK	X							
1	143	ROOF LEAK	X							
2	208	ROOF LEAKS - 3	X							
2	233	AC/CONTROL PANEL ABANDONED								
2	238	STORAGE AROUND WATER HEATER - MOVE								NFPA 70
3	324	ROOF LEAK	X							
5	534	ROOF LEAK	X							
6	617	ROOF LEAK	X							
3	330	ROOF LEAK	X							
5	528	ROOF LEAK	X							

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0040

FACILITY: TYNES ELEMENTARY SCHOOL
 1550 TYNES BOULEVARD
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: DECEMBER 14, 2005

INSPECTOR'S SIGNATURE: *Sammy F. Burton* DATE: 12-14-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
***		TRANSFORMER OUTSIDE BUILDING HAS VEGETATION GROWN AROUND IT - MOVE		X						NFPA 70
92	1	OK								
92	2	OK								
92	3	OK								
92	4	OK								
92	5	OK								
92	6	OK								
92	7	OK								
92	10	OK								
92	22	OK								
92	23	OK								
92	24	OK								
92	25	OK								

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0040

FACILITY: TYNES ELEMENTARY SCHOOL
 1550 TYNES BOULEVARD
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: DECEMBER 14, 2005

INSPECTOR'S SIGNATURE: *Henry F. Johnston* DATE: 12-14-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	26	OK								
92	27	OK								
92	28	OK								
92	29	OK								
92	30	OK								
92	41	OK								
92	43	OK								
92	61	OK								
92	62	OK								
92	63	OK								
92	64	OK								
92	65	OK								
92	66	OK								

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0040

FACILITY: TYNES ELEMENTARY SCHOOL
 1550 TYNES BOULEVARD
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: DECEMBER 14, 2005


David D. Johnson
 INSPECTOR'S SIGNATURE

12-14-05
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	67	OK								
92	68	OK								
92	8	LIGHT COVERS MISSING IN RESTROOM		X						
***		GENERAL NOTE: REPLACE WOOD RAMPS TO MEET ADA REQUIREMENTS	X							FBC 11.25

W. E. CHERRY

ELEMENTARY SCHOOL



FISCAL YEAR 2005-2006

DISTRICT: CLAY FACILITY #: 0006

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**



FACILITY: W. E. CHERRY ELEMENTARY SCHOOL
420 EDSON DRIVE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: DECEMBER 12, 2005

INSPECTOR'S SIGNATURE: *Russell A. Johnson*
DATE: 12-12-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	47	EMERGENCY LIGHT OUT		X						FBC 423.17.1
2	53	WHEEL CHAIR LIFT NOT CERTIFIED	X							
2	75	EXIT LIGHT OUT		X						FBC 423.17.1
2	75	CEILING TILE OUT, WIRES EXPOSED	X							FBC 804.2.3
3	55	OCCUPANT LOAD SIGN MISSING		X						FBC 423.16.2
3	55B	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
3	64	EMERGENCY LIGHT OUT		X						FBC 423.17.1
4	15	FIRE EXTINGUISHER MISSING		X						69A-36
4	14	FIRE EXTINGUISHER MISSING		X						69A-36
4	71	LENS MISSING ON LIGHT FIXTURES		X						NFPA 70

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0006

FACILITY: W. E. CHERRY ELEMENTARY SCHOOL
 420 EDSON DRIVE
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: DECEMBER 12, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 12-12-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	26	OK								
92	27	OK								
92	29	OK								
92	30	OK								
92	31	OK								
92	32	OK								
92	33	OK								
92	34	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	36	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	37	GRILL MISSING								NFPA 70 314.1
92	38	LIGHT FIXTURE LOOSE		X						
92	39	OK								
92	40	OK								
92	41	OK								

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY # 0006

FACILITY: W. E. CHERRY ELEMENTARY SCHOOL
 420 EDSON DRIVE
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: DECEMBER 12, 2005


Dorothy A. Swinton
 INSPECTOR'S SIGNATURE

DATE
 12-12-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Schedule d for Correctio n	Rule
92	42	OK								
92	43	GLOBE MISSING ON CLOSET FIXTURE		X						FBC 423.17.1
92	47	OK								
92	48	STEP EXCEEDS MAXIMUM RISE - ADD STEP	X							FBC 11-4.13.8
92	49	OK								
92	50	OK								
92	51	OK								
92	54	WIRE STICKING OUT OF HEAT DETECTOR	X							NFPA 70 314.1
92	54	GLOBE MISSING ON CLOSET FIXTURE		X						
92	54	EMERGENCY LIGHT INOPERABLE	X							FBC 423.17.1
	****	REPLACE WOOD RAMPS TO MEET ADA REQ.								FBC 4.9.4

WILLKINSON

ELEMENTARY SCHOOL



FISCAL YEAR 2005-2006

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY #: 0026

FACILITY: J.L. WILKINSON ELEMENTARY SCHOOL
4965 C.R. 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 10, 2006

INSPECTOR'S SIGNATURE: *John S. McArthur* DATE: *Jan 10, 2006*

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	102	ROOF LEAK	X							
1	126	PHONE PANEL - NO COVER, BIG MESS				X				NFPA 70 110-12
1	127	EXTENSION CORD - NEEDS ELECTRICAL OUTLET		X						NFPA 70 400-8
2	209	CEILING TILES MISSING		X						FBC 804.2.3
2	226	EXIT LIGHT OUT		X						FBC 1016.3.1
2	230	LIGHT OUT		X						
2	234	LENSE COVER MISSING		X						
20	R2	EMERGENCY LIGHT OUT		X						FBC 423.17.1
3	305	EXIT NOT WITHIN 15FT RANGE		X						NFPA 10
4	400	DOOR BUMPERS NEED TO BE REPLACED	X							
4	412	ROOF LEAKS	X							
4	430	EXTERIOR FAN NOT WORKING	X							FBC 423.15.4
4	427	LENSE COVER MISSING		X						FBC 804.2.3
5	511	EMERGENCY LIGHT OUT		X						FBC 423.17.1

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0026

FACILITY: J.L. WILKINSON ELEMENTARY SCHOOL
 4965 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 10, 2006

INSPECTOR'S SIGNATURE: *J.L. Swartz*

DATE: *Jan 10, 2006*

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	500	LENSE COVER MISSING		X						FBC 804.2.3
5	525	EXTERIOR FAN NOT WORKING	X							FBC 423.17.1
5	504	EXTERIOR FAN NOT WORKING	X							FBC 423.17.1
5	507	EXTERIOR FAN NOT WORKING	X							FBC 423.17.1
5	518	EXTERIOR FAN NOT WORKING	X							FBC 423.17.1
5	530	EXTERIOR FAN NOT WORKING	X							FBC 423.17.1
92	1	OK								
92	2	OK								
92	3	OK								
92	4	OK								
92	6	OK								
92	18	OK								
92	19	OK								

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0026

FACILITY: J.L. WILKINSON ELEMENTARY SCHOOL
 4965 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 10, 2006

Lead Inspector
 INSPECTOR'S SIGNATURE

Jan 10, 2006
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	20	OK								
92	31	OK								
92	37	OK								
92	38	OK								
92	39	OK								
92	40	OK								
92	49	OK								
92	51	OK								
92	66	OK								
92	7	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
92	5	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
92	8	REPLACE NON SKID		X						FBC 11-4.8
92	9	EXTERIOR FANS NOT WORKING	X							FBC 423.17.1
92	10	RAMP IN POOR CONDITION	X							FBC 11 4.8

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0026

FACILITY: J.L. WILKINSON ELEMENTARY SCHOOL
 4965 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 10, 2006

Jed Swearingin
 INSPECTOR'S SIGNATURE

Jan 10, 2006
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	11	RAMP IN POOR CONDITION	X							FBC 11.4.8
92	12	ROOF LEAK	X							
92	12	REPLACE RAMP; IN POOR CONDITION	X							FBC 11.4.8
92	13	REPLACE RAMP; IN POOR CONDITION	X							FBC 11.4.8
92	14	OK								
92	15	OK								
92	16	OK								
92	17	OK								
92	42	OK								
92	43	OK								
92	44	OK								
92	45	OK								
92	46	OK								
92	47	OK								

FISCAL YEAR 2005-2006



**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**

DISTRICT: CLAY FACILITY #: 0026

FACILITY: J.L. WILKINSON ELEMENTARY SCHOOL
4965 C.R. 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 10, 2006

INSPECTOR'S SIGNATURE: *Tom Sweetland* DATE: Jan 10, 2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	48	OK								
92	50	OK								
92	52	OK								
92	33	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	34	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	34	WALLBOARD BEHIND TOILET DAMAGED	X							
92	35	CONCRETE BEING POURED AT RAMP/FORMED BUT NOT POURED			X					
92	36	BATHROOM LIGHT COVER MISSING		X						
92	41	ROOF LEAK	X							
92	61	EMERGENCY LIGHT BUTTON NOT WORKING		X						FBC 423.17.1
92	62	CONCRETE BEING POURED	X							
92	63	CONCRETE BEING POURED	X							
92	64	EXTERIOR FAN NOT WORKING	X							
92	65	CONCRETE BEING POURED	X							FBC 423.15.4

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0026

FACILITY: J.L. WILKINSON ELEMENTARY SCHOOL
 4965 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 10, 2006

Zed Swectlow
 INSPECTOR'S SIGNATURE

Jan 10, 2006
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	67	CONCRETE BEING POURED			X					
92	68	MATING TRIM MISSING	X							
92		CAN SEE DAYLIGHT AT CANOPY END	X							
GENERAL NOTE		REPLACE WOOD RAMPS TO MEET ADA REQUIREMENTS	X							FBC11-4.8