



SENIOR HIGH SCHOOLS



Clay

High School



FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

DISTRICT: CLAY FACILITY #: 0013

FACILITY: CLAY HIGH SCHOOL
2025 HIGHWAY 16 WEST
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: OCTOBER 2, 2008

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2


INSPECTOR'S SIGNATURE

10.2-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 1 | 130 | LIGHTS NOT WORKING | X | | | | | | | FBC 1006.3 |
| 1 | 134 | EQUIPMENT BLOCKING EXIT | | X | | | | | | FBC 423.20.1 |
| 1 | 143 | LENS COVER ON LIGHT MISSING | | X | | | | | | NFPA 70 |
| 1 | 144A | EMERGENCY LIGHT OUT | X | | | | | | | FBC 423.17.1 |
| 2 | 202 | FIRE SUPPRESSION INSPECTION ON HOOD OUT OF DATE | X | | | | | | | |
| 2 | 209 | EXIT LIGHT OUT | X | | | | | | | FBC 1006.3.1 |
| 3 | 325 | WIRE EXPOSED IN CEILING | X | | | | | | | |
| 3 | 328 | LENS COVER MISSING ON LIGHT | | X | | | | | | NFPA 70 |
| 3 | 342B | NO EVACUATION SHEET | | X | | | | | | FBC 423.14.2.4 |
| 3 | 389A | NO EMERGENCY LIGHT | X | | | | | | | FBC 423.17.1 |
| 3 | 389B | NO EMERGENCY LIGHT | X | | | | | | | FBC 423.17.1 |
| 3 | 383 | EMERGENCY LIGHT OUT | X | | | | | | | FBC 423.17.1 |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

DISTRICT: CLAY FACILITY #: 0013

FACILITY: CLAY HIGH SCHOOL
2025 HIGHWAY 16 WEST
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: OCTOBER 2, 2008

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2


INSPECTOR'S SIGNATURE

10-2-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 3 | 383 | SMOKE DETECTOR ON CEILING LOOSE | X | | | | | | | NFPA 70 110.12 |
| 7 | 730 | LIGHT IN FRONT OF DOOR LOOSE | X | | | | | | | NFPA 70 110.12 |
| 8 | 828 | SMOKE DETECTOR HANGING FROM CEILING | X | | | | | | | NFPA 70 110.12 |
| 8 | 830 | TEAR IN STAGE CURTAIN | X | | | | | | | |
| 8 | 830 | RETURN AIR GRILL NEEDS CLEANING | | X | | | | | | |
| 8 | 831 | ELECTRICAL OUTLET STRIP ON WALL BROKEN | X | | | | | | | |
| 8 | 831 | EMERGENCY LIGHT HANGING FROM CEILING | X | | | | | | | NFPA 70 110.12 |
| 8 | 835 | WIRES HANGING FROM CEILING | X | | | | | | | NFPA 70 110.12 |
| 8 | 835 | EMERGENCY LIGHT LOOSE FROM CEILING | X | | | | | | | NFPA 70 110.12 |
| 11 | 1129 | NO PANEL COVERS ON PANEL | X | | | | | | | NFPA 70 |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

DISTRICT: CLAY FACILITY #: 0013

FACILITY: CLAY HIGH SCHOOL
2025 HIGHWAY 16 WEST
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: OCTOBER 2, 2008

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2



INSPECTOR'S SIGNATURE

10-2-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|------------------|
| 92 | 43 | RANGE HOOD NOT DUCTED TO OUTSIDE | X | | | | | | | |
| 92 | 46 | DOOR STICKS ON RAMPSIDE | X | | | | | | | FBC 423.28.2.9.1 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Fleming Island

High School



FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12, 1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0044

FACILITY: FLEMING ISLAND HIGH SCHOOL
2233 VILLAGE SQUARE PARKWAY
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 7, 2008

Ed Swettow
INSPECTOR'S SIGNATURE

10-7-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|-------------------|
| 1 | 66 | EMERGENCY EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 1 | 173 | EMERGENCY EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 1 | 141 | OCCUPANCY LOAD SIGN MISSING | | X | | | | | | FBC 423.14.2.2 |
| 10 | 1026 | EMERGENCY EVACUATION SHEETS MISSING | | X | | | | | | FBC 423.14.2.4 |
| 2 | 202 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 2 | 258 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 31 | 001 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 31 | 04 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 31 | 04 | REMOVE GAS BOTTLES | | X | | | | | | NFPA 1.21.1.3.3.5 |
| 40 | 01 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: √ NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0044

FACILITY: FLEMING ISLAND HIGH SCHOOL
2233 VILLAGE SQUARE PARKWAY
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 7, 2008


Bob Sweatt
INSPECTOR'S SIGNATURE

10-7-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|---|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|--------------|
| 92 | 10 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 22 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 51 | EXTENSION CORD USED FOR OVERHEAD PROJECTOR; REMOVE ALL WIRES/CABLES | | X | | | | | | |
| 92 | 52 | RAMP DOOR STICKS, MAY NEED SHORING @ FLOOR | X | | | | | | | |
| 92 | 85 | EMERGENCY LIGHT MISSING LENSE COVER @ RAMP DOOR | | | | | | | | NFPA 70 |
| 92 | 91 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Middleburg

High School



FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: √ NUMBER OF DRILLS PERFORMED: 1

DISTRICT: CLAY FACILITY #: 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG , FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

10-14-08

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 1 | | SPRINKLER HEADS NEED TO BE ADJUSTED TO BELOW CEILING TILES – CURRENTLY THEY ARE TOO HIGH | X | | | | | | | NFPA 13 |
| 1 | 1 | REMOVE ALL HOMECOMING DECORATIONS | | X | | | | | | NFPA 101 |
| 1 | 1 | REMOVE EXTENSION CORD TO DISPLAY LIGHTS | | X | | | | | | NFPA 70,400.8 |
| 1 | 67 | SPRINKLER HEADS ABOVE CEILING | X | | | | | | | NFPA 13 |
| 1D | 144 | EXCESSIVE DECORATIONS FOR HOMECOMING | | X | | | | | | NFPA 101 |
| 1D | 164 | EXTENSION CORD FROM HALL INTO CLASSROOM | | X | | | | | | NFPA 70.400.8 |
| 1F | 239 | NO EMERGENCY EVACUATION SHEET | | X | | | | | | FBC 423.14.2.4 |
| 1F | 227 | REMOVE FLAMABLE STORAGE AND FERTILIZERS OR CHANGE LIGHT TO EXPLOSION LIGHT | | X | | | | | | NFPA101 |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: √ NUMBER OF DRILLS PERFORMED: 1

DISTRICT: CLAY FACILITY #: 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG , FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

[Handwritten Signature]

10-14-08

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|---|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|-----------------|
| 1F | 230 | ADD EXTINGUISHER BY STOVE | | X | | | | | | 69A-58 |
| 1H | 285 | OCCUPANCY LOAD SIGN MISSING (1800 MAX OCCUPANCY FOR ROOM) | | X | | | | | | FBC 1004.3 |
| 1H | 284A | DOORS CHAINED AFTER SCHOOL - REMOVE | | X | | | | | | |
| 1J | 339 | SPRINKLERS TO HIGH ESCUTCHEON | X | | | | | | | NFPA 13 |
| 35 | | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 35 | | GAS BOTTLE STORED IN BUILDING | | X | | | | | | NFPA 1.2-3.3.5 |
| 10 | | REMOVE ALL GAS BOTTLES | | X | | | | | | NFPA 1.21-3.3.5 |
| 10 | | ELECTRICAL PANEL NEEDS KNOCKOUT | X | | | | | | | NFPA 70 110.26 |
| 10 | | ELECTRICAL JUNCTION BOX - NO COVER | | X | | | | | | NFPA 70 110.26 |
| 9 | | ELECTRICAL PANEL BLOCKED BY SHELF | | X | | | | | | NFPA 70 110. |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 1

DISTRICT: CLAY FACILITY #: 0019

FACILITY: MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG , FLORIDA 32068


INSPECTION DATE: OCTOBER 14, 2008

[Signature]
INSPECTOR'S SIGNATURE 10-14-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|--------------|
| 92 | 41 | EMERGENCY LIGHTS NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 53 | EMERGENCY LIGHTS NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 55 | EMERGENCY LIGHTS NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 88 | EMERGENCY LIGHTS NOT WORKING | | X | | | | | | FBC 423.17.1 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Orange Park

High School



FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0007

FACILITY: ORANGE PARK HIGH SCHOOL
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

Tom Sweatt
INSPECTOR'S SIGNATURE 10-30-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|-------------------|
| 1 | 100 | EXTINGUISHER OVERCHARGED – REPLACE | | X | | | | | | NFPA 14 |
| 1 | 118 | NO EMERGENCY EVACUATION SHEET | | X | | | | | | FBC 423.14.2.4 |
| 1 | 104 | GATES LOCKED WHILE OCCUPIED | | X | | | | | | NFPA 101/FBC 1003 |
| 1 | 126 | EMERGENCY LIGHT OUT – ELEC. ROOM | | X | | | | | | FBC 423.17.1 |
| 1 | 126 | FIRE ALARM BOX OPEN | | X | | | | | | NFPA 70 |
| 1 | 226 | REPLACE OLD EXTINGUISHER | | X | | | | | | FAC 69A-58 |
| 1 | 252 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 1 | 204 | EMERGENCY LIGHT – NOT WORKING – BULBS REMOVED | | X | | | | | | FBC 423.17.1 |
| 3 | 3 | EMERGENCY LIGHT BROKEN – NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 4 | 1 | MAX OCCUPANCY SIGN MISSING 1350 | | X | | | | | | |
| 4 | 9 | EXTINGUISHER MISSING | | X | | | | | | FAC 69A-58 |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12, 1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0007

FACILITY: ORANGE PARK HIGH SCHOOL
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

Ted Smeathart
INSPECTOR'S SIGNATURE 10-30-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 4 | 5 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 4 | 6 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 4 | 7 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 4 | 18 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 4 | 19 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 10 | 100 | OCCUPANCY LOAD SIGN MISSING | | X | | | | | | FBC 423.14.2.2 |
| 10 | 122 | WRENCH MISSING SPRINKLER BOX | | X | | | | | | |
| 10 | 111 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 10 | 114 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 19 | 9 | EXCESSIVE PAPER ON WALLS 20% MAX | | X | | | | | | |
| 20 | 16 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 20 | 18A | CLEAR ISLE TO EXIT | X | | | | | | | |
| 22 | 5 | EXIT LIGHT OUT | | X | | | | | | FBC 1016.3.1 |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: √ NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0007

FACILITY: ORANGE PARK HIGH SCHOOL
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

Ted Sweatt
INSPECTOR'S SIGNATURE 10-30-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 25 | 22 | NO EVACUATION SHEET | | X | | | | | | FBC 423.14.2.4 |
| 25 | 23 | ATV PARKED IN BLDG. - MOVE OUT | | X | | | | | | |
| 27 | 2 | EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 27 | 3 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 27 | 7 | PAINT STORED IN BUILDING | | X | | | | | | NFPA - 101 |
| 47 | 1 | REMOVE LP GAS BOTTLES - STORE OUTSIDE | | X | | | | | | NFPA 1 |
| 51 | 8 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 12 | 132 | LP TANKS STORED IN BID - REMOVE | | X | | | | | | NFPA 1 |
| 12 | 152 | 2X4 WOOD ON FIRE SPRINKLER LINE - REMOVE WOOD | X | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0007

FACILITY: ORANGE PARK HIGH SCHOOL
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008


Tom Sweetman
INSPECTOR'S SIGNATURE

10-30-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 92 | 26 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 30 | EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 92 | 44 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 47 | EMERGENCY EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 92 | 51 | EMERGENCY LIGHT NOT ATTACHED TO WALL | | X | | | | | | FBC 423.17.1 |
| 92 | 52 | EXCESSIVE COMBUSTIBLES ON WALL - REMOVE | | X | | | | | | NFPA 101 |
| 92 | 55 | EMERGENCY EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 92 | 56 | EMERGENCY EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| | | | | | | | | | | |
| | | | | | | | | | | |

Ridgerview

High School



FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL
466 MADISON AVENUE
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

[Signature]
INSPECTOR'S SIGNATURE

11-4-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 1 | 107 | ADD FIRE EXTINGUISHER | | X | | | | | | |
| 1 | 149 | OCCUPANCY LOAD SIGN MISSING | | X | | | | | | FBC 423.14.2.3 |
| 2 | 218 | MATERIAL STORED IN ELECTRICAL ROOM | | X | | | | | | NFPA 70 |
| 2 | 227 | EXIT LIGHT COBER BROKEN | X | | | | | | | FBC 1016.3.1 |
| 2 | 224 | LIGHT COVER MISSING | X | | | | | | | NFPA 70 401.3 |
| 3 | 333 | NO EMERGENCY EVACUATION SHEET | | X | | | | | | FBC 14.2.4 |
| 6 | 688 | EXIT LIGHT OUT | X | | | | | | | FBC 423.17.1 |
| 6 | 658 | EXTENSION CORD THROUGH ATTIC | | X | | | | | | NFPA 70 |
| 6 | 657 | EXTENSION CORD THROUGH ATTIC | | X | | | | | | NFPA 70 |
| 6 | 632 | FIRE ALARM PANEL OPEN | X | | | | | | | NFPA 70 110.26 |
| 9 | 914 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 9 | 915 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 9 | 913 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL
466 MADISON AVENUE
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

[Signature]
INSPECTOR'S SIGNATURE 11-4-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|-----------------|
| 9 | 930 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 9 | 933 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 9 | 941 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 9 | 941 | OUTLET COVER BROKEN | | X | | | | | | NFPA 70 410.1.2 |
| 10 | | EXTERIOR BUILDING # MISSING "O" | X | | | | | | | |
| 10 | 1021 | FIRE EXTINGUISHER MISSING | X | | | | | | | |
| 11 | 1103 | EMERGENCY LIGHT OUT | X | | | | | | | FBC 423.17.1 |
| 12 | 1201 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 12 | 1202 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 12 | 1203 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL
466 MADISON AVENUE
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

[Handwritten Signature]
INSPECTOR'S SIGNATURE

11/4/08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 92 | 1 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 3 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 8 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 11 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 13 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 14AB | EMERGENCY LIGHTS OUT X2 | X | | | | | | | FBC 423.17.1 |
| 92 | 27 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 28 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 29 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 32 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 41 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 41 | NO EVACUATION SHEET | | X | | | | | | FBC 423.14.2.4 |
| 92 | 42 | MENS ROOM EXPOSED WIRES ON THERMOSTAT | X | | | | | | | |

FISCAL YEAR 2008-2009

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12, 1013.20 & RULE 69A-58**

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL
466 MADISON AVENUE
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

[Signature]
INSPECTOR'S SIGNATURE 11-4-08
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 92 | 47 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 49 | LENS COVERS MISSING ON LIGHTS | X | | | | | | | NFPA 70 401.3 |
| 92 | 50 | EXCESSIVE COMUSTIBLES ON WALLS/CEILING | | X | | | | | | NFPA 70 110.28 |
| 92 | 61 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 66 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 69 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 81 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 83 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 86 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 89 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| 92 | 92 | EMERGENCY LIGHTS OUT | X | | | | | | | FBC 423.17.1 |
| | | | | | | | | | | |