

		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT TION CHAI INSP	PTER ECTIC	5 5 1 N77 IN	ACILITY SPECTI	BANI 608 M GREE	VERMAN IILL STR EN COVE	LEARNING EET SPRINGS, F VEMBER 6, 2	LORIDA 32043
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	ALL	ОК					THE PROVIDE LAR.	Color of Patrice Sector		
2	ALL	OK								
3	ALL	OK								

		FISCAL YEAR <u>2008-200</u>	9		D	ISTRICT		(FACILITY	′ #: <u>0003</u>
		COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	ion Chai Insp	PTER ECTIC	5 DN7 II		$\frac{608 \text{ M}}{\text{GREE}}$	ILL STR IN COVE	SPRINGS, F	LORIDA 32043
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	ОК	신같은 전 전 전 가수나 			48 - 2017-12 (2017-12 1		dryf as of shift (1629)		
92	2	OK								
92	3	ок	and the second second							
92	4	ОК								
92	5	ок								
92	6	ОК								
92	7	ок								
92	8	OK								
92	9	RAMP EXCEEDS 1/12 SLOPE	х					2		FBC 11-4.8
92	. 10	ок								
92	11	ОК								
92	12	OK .								

	<u></u>	FISCAL YEAR <u>2008-200</u>	9		D	ISTRICT	: <u>CLA</u> `	Y	FACILITY	′#: 0003
A TANK		COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH	'ION Chai INSP	PTER ECTI(5		608 N GREE	IILL STR EN COVE		ELORIDA 32043
		F.S. 1013.12, 1013.20 & NFP	a 101		A II) My SPEC/T	DR'S SI	GNATUR	RE	 DATE
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	14	ОК	<u>i ser da suande</u>		engelen bei Dieleigen von d	<u>a. ///ikababa</u>				
92	30	OK								
92	31	ОК		Sector production and the	and a second second	1		The second section of sector sectors		
92	32	ОК								
92	33	LIGHT FLICKERS		X	anto Studence	3			and a second second second second second	
92	34	οκ								
92	35	ΟΚ		动机的空中的	addraitheas	19	10000000404			
92	36	OK								
92	37	ΟΚ	and so the second second			w Hitcher		antinda tinda		
92	38	ÖK								
92	39	ОК								
92	40	ок								
92	42	OK		<u> </u>						

BANNERMAN LEARNING CENTER 2008-09 SREF REPORT

A CONTRACTOR		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT FION - CHAI INSP	PTER ECTIC	5)N" II		BANI 608 M GREE ON DAT	NERMAN IILL STR IN COVE	LEARNING EET SPRINGS, F VEMBER 6, 2	LORIDA 32043
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	43	ОК								
92	50	ОК								
92	52	OK		and the second of the second				interitation.		
	and the second	e for interferent versen en e		1999 - 2019 - 1999 (1999) 1999 - 1999 - 1999 (1999) 1999 - 1999 - 1999 (1999)	1999-1999 1999-1999 1999-1999	unte como tribude y desta	(whither \$12,5)		2019 - 1424 - 1444 - 1460 - 1470 - 1490 - 1570 - 1470 - 1470 - 1470 - 1470 - 1470 - 1470 - 1470 - 1470 - 1470 -	n an
Angele Park 215 - 21										
PANNEPM/		JING CENTER 2008-09 SREF REPORT	<u> </u>	1		l]	J	<u> </u>	



		FISCAL YEAR <u>2008-2009</u>	<u>9</u>		DIS	STRICT:	CLAY		_ FACILITY	#. 0001
		COMPREHENSIVE SAFETY & SAI INSPECTION REPORT STATE BOARD OF EDUCAT	ION			CILITY:	1220 E	BONAVE	NTURE AVE	INIOR HIGH SCHOOL NUE LORIDA 32043
	J	ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP.	INSPI		N77 INS	Tod.	wer	E: <u>NOV</u> <i>Unv</i> SNATUR	<u>/EMBER 13,</u> > E	2008 <u>][-]3-08</u> DATE
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	800	EXIT SIGN MISSING FOR ROOM 802	X	20000	an de la desta	n andre strand strate	an Cain Cainealaistean		n sana dina dina di kana da kana di kana kana kana kana kana kana kana kan	LANGSBOWER'S DELY ABLE SALARSHINGAR
: 1 · · ·	17	CEILING TILES MISSING		X				K.		FMC 804.2.3
1	12	OVERHEAD PROJECTOR - SECURE PROPERLY		x						
2	800	EMERGENCY LIGHT OUT IN CORRIDOR		x						FBC 423.17.1
2	112	MOVE TABLE BY DOOR	x							
	103	CEILING TILE MISSING		X						FMC 804.2.3
3			1			1		I		FBC 423.14.2.4
4	415	EVACUATION SHEET MISSING		X						1 00 423.14.2.4
	415 424	EVACUATION SHEET MISSING PROJECTOR – SECURE PROPERLY		X X						1 DO 423.14.2.4
4										FBC 423.14.2.2

GREENCOVE SPRINGHS JUNIOR HIGH SCHOOL 2008-09 SREF INSPECTION

		FISCAL YEAR 2008-2009 COMPREHENSIVE SAFETY & SAP INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH	NITAT ION CHAP INSPE	TER	5	ACILITY:	GREE 1220 I GREE	NCOVE BONAVE N COVE	NTURE AVE	INIOR HIGH SCHOOL NUE LORIDA 32043
		F.S. 1013.12, 1013.20 & NFP			M	SPECTO	Wea DR'S SIG	(fand) GNATUR	E	<u> - 3-08</u> date
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	70	ОК								
92	71	ок								
92	104	EMERGENCY LIGHT OUT		х						FBC 423.17.1
92	105	ОК								
92	106	LENSE COVER MISSING		х						NFPA 70
92	106	OVERHEAD PROJECTOR INSTALLED INCORRECTLY		× X		x				FBC 1003
92	107	EMERGENCY LIGHT OUT		x						FBC 423.17.1
92	112	EMERGENCY LIGHT OUT		x						FBC 423.17.1
92	113	ОК								
		THS JUNIOR HIGH SCHOOL 2008-09 SREF INSPECTION								<u> </u>

GREENCOVE SPRINGHS JUNIOR HIGH SCHOOL 2008-09 SREF INSPECTION



		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT ION CHAI INSP	PTER Ectic	5)N" IN	SPECTI	N DAT	STONE H S.W. OR(STONE H	TOBER 24, 2	H SCHOOL JE DRIDA 32656
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	167	STORAGE IN ELECTRICAL ROOM – REMOVE		X	e esta de stillada esta est	<u> </u>		, af a chiair an thai sha a th		NFPA 70
1	173	STORAGE IN ELECTRICAL ROOM – REMOVE		x						NFPA 70
1	188	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
1	192	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
2	63	LIGHT OUT IN CHEMICAL STORAGE		х						
2	65	REMOVE EXTENSION CORD ABOVE CEILING		x						NFPA 70
2	65	HAVE MAINTENANCE PUT IN OUTLET	х	1						
2	802	PROTECT GAS LINES OUTSIDE BUILDING		x						
2	70	EMERGENCY LIGHT OUT		х						FBC 423.17.1
4	401	ELECTRICAL BOX/OUTLET NOT COVER		x						NFPA 70
4	408	RE-ARRANGE DESKS – CLEAR PATH TO EXIT		X						FBC 1003.3.2
-				·····		1	+	1	1	

		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFF	nitat fion - Chai Insp	PTER	5)N"		: <u>KEYS</u> 2900 KEYS ON DAT	<u>STONE H</u> S.W. OR TONE H TE: <u>OC</u>	<u>tober 24, 2</u>	H SCHOOL JE ORIDA 32656
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	501	THREE EXTENSION CORDS GO INTO CEILING REMOVE & HAVE OUTLETS INSTALLED	<u>, ki a 1, 5, 45 i</u>	X					<u>a a serie de la companya de la comp</u>	NFPA 70
5	550	REMOVE STORAGE FROM ELECTRICAL ROOM		x						NFPA 70
5	501	CEILING TILES MISSING BY ROOM 507		х						FMC 804.2.3
5	549	AIR HANDLER #15 FREEZING UP	x							
5	548	REMOVE PAPER RECORDS FROM ELECTRICAL ROOM		х						NFPA 70
5	539	DO NOT STORE LP GAS BOTTLES IN BUILDING		X						NFPA 1
6	607A	COMMUNICATION BOX OPEN – CLOSE		х						
6	610	CEILING TILE MISSING		x			an a			FMC 804.2.3
7	713	DESKS STORED IN CORRIDOR – REMOVE		Х						FBC 1003.3.2
7	725	DESKS STORED IN MECHANICAL ROOM – REMOVE		X						NFPA - 1
7	725	GOLF CART STORED IN MECHANICAL ROOM – REMOVE S HIGH 2008-09 SREF REPORT		x						NFPA – 1

		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	nitat Tion - Chai Inspi	PTER	5)N" II	ACILITY	• <u>KEYS</u> 2900 <u>KEYS</u> ON DAT	STONE H S.W. OR STONE H TE: OC	<u>TOBER 24, 2</u>	H SCHOOL JE ORIDA 32656
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9	911	REMOVE ALL EQUIPMENT FROM CORRIDOR		Х			alle and diffe	ing and the state of the state	an an an tha Bhailean Bhailean an a	FBC 1003.3.2
9	906	OCCUPANCY SIGN MISSING -1,500 MAX. OCCUPANCY		Х						BC 423.14.2.2
9	909	KNOCKOUT MISSING ELECTRICAL PANEL – RP		Х						NFPA 70
9	909	COVER MISSING SURGE PROTECTOR NEXT TO PANEL		X						
9	906	TWO EXIT LIGHTS OUT		х						FBC 1016.3.1
20	22	OPEN ELECTRICAL BOX		X						NFPA 70
										a service de la service de Reference de la service de l Reference de la service de l
				1.000 A						

KEYSTONE HEIGHTS HIGH 2008-09 SREF REPORT


		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT FION CHAI INSP	PTER	5	FACILITY	: <u>KEYS</u> 2900 KEYS	TONE H S.W. OR TONE H TE: <u>OC</u>	<u>TOBER 24, 2</u>)	H SCHOOL JE DRIDA 32656
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac "C"		Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	ОК		<u>.</u>		<u> </u>				<u>an an a</u>
92	2	ок								
92	3	EVACUATION SHEET MISSING		X					·····	FBC 423.14.2.4
92	4	RAMP EXCEEDS 1/12 SLOPE	X					2		FBC 11-4.8
92	5	EMERGENCY LIGHT NOT WORKING - EXT. ON FLOOR		X						FBC 423.17.1
92	6	οκ								
92	7	ОК								
92	. 11	ОК								
92	12	EMERGENCY LIGHT NOT WORKING		x						FBC 423.17.1
92	13	EMERGENCY LIGHT NOT WORKING		x						FBC 423.17.1
92	14	ОК								
92	15	ΟΚ								
92	16	OK	1	1	1					

		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFF	nitat fion - Chai I Insp	PTER Ectic	5		KEYS 2900 KEYS ON DAT	STONE H S.W. OR STONE H	TOBER 24, 2	H SCHOOL JE DRIDA 32656
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac "C"	rv.	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	17	ОК	i si ikazart			 	<u>i la da seu </u>		an shekara ta safat ka sa	
92	18	RAMP EXCEEDS 1/12 SLOPE		x				2		FBC 11.4.8
92	18	EMERGENCY LIGHTS NOT WORKING		X		 				FBC 423.17.1
92	19	ок								
92	20	ок								
92	21	FIRE EXTINGUISHER TAG MISSING		x						69A-58
92	22	ок								
92	23	ОК				• • •				
92	24	RAMP EXCEEDS 1/12 SLOPE		x				2		FBC 11.4.8
92	25	EMERGENCY EVACUATION SHEET MISSING		x		<u>}</u> -				FBC 423.14.2.4
92	26	ОК								
92	27	EMERGENCY EVADCUATION SHEET MISSING		x						FBC 423.14.2.4
92	28	WOOD RAMP TRIP HAZARD AT END		X						FBC 1003

		FISCAL YEAR <u>2008-200</u>	9			DISTRICT	CLA	Y		(#:<u>0011</u>
		COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F.	TION - CHAI	PTER	5		2900 KEYS	<u>S.W. OR</u> TONE H		JE DRIDA 32656
		CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFF			-		Jure	GNATUR	<u>TOBER 24, 2</u> 	2008 <u>10 - 24-08</u> DATE
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	29/30	ОК					i e setto de la secto.			
92	50	ΟΚ								
92	51	ОК				<u> </u>			· · · · · ·	
92	52	ОК								
92	53	ОК								
92	54	ОК								
92	55	COMPUTER WIRE FROM ROOM 55 TO ROOM 57				X				NFPA 70 – 760
92	56	ОК						1		
92	57	COMPUTER WIRE FROM ROOM 57 TO ROOM 55				x				NFPA 70 – 760
92	58	ОК								
92	59	ОК								
92	60	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
92	61	ОК					1			

	Required:"M"9262EMERGENCY LIGHT NOT WORKING9263OK9264SIDING BAD NEAR CORNER AND RAMPX9265POSSIBLE TERMITE AT DOOR FRAMEX9272OK9274OK						ILITY:	2900 S KEYS	TONE H S.W. OR TONE H	EIGHTS HIG CHID AVENU EIGHTS, FLC TOBER 24, 2	H SCHOOL IE DRIDA 32656
Building	Room	Deficiency Description and Corrective Action Required:		Oper. "O"	Fac. "C"	: s	Info. Serv. 'I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	62	EMERGENCY LIGHT NOT WORKING		Х							FBC 423.17.1
92	63	ОК			an a						
92	64	SIDING BAD NEAR CORNER AND RAMP	х								
92	65	POSSIBLE TERMITE AT DOOR FRAME	X								
92	72	ОК									
92	74	ΟΚ									
92	76	ок									
92	78	ОК									
92	80	ОК									
92	82	ΟΚ									
92	90	ОК									
92	91	ОК			an an Airtean an						
EYSTONE	HEIGHT	S HIGH 2008-09 SREF REPORT									





		FISCAL YEAR <u>2008-2009</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT	PTER	5 5 1 1	ACILITY NSPECTI	: <u>LAKE</u> 2851 <u>GREE</u> ON DA	E ASBUR SANDRII EN COVE	DGE ROAD SPRINGS, I VEMBER 18	IGH SCHOOL FLORIDA 32043
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	390	ок								
92	391	ROOF LEAKS/ CEILING TILE STAINED	x							FBC 804.2.3
92	392	ОК				**				
92	393	OK								
92	394	NOT TIED DOWN			X	1. Carlos de Servicio en en 19	1111-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	1.2. anna 1.2.		
92 -	401	ок								
92	402	ОК			11.11 STORE AND MEDICAL	ter constant to story (1993)		-11-53, 20, 73, 75, 75, 75, 75, 75, 75, 75, 75, 75, 75		
92	403	DOOR STICKS IN STORAGE ROOM	X							FBC 423.28.2.9.1
92	404	ОК		ತೆಂತುಗೆ ಡಾ.ಎಎ	ive sugers some filse	211 x 3.4 210 20 44	and the second			
92	405	CEILING TILE MISSING		<u>x</u>						FBC 804.2.3
92	406	ОК		tive statistical in a	and the second second	ana ing kabupatèn ka	1 1 47 G Martin			an a
92	407	EXTINGUISHER NEEDS TO BE RECHARGED	X							


		FISCAL YEAR <u>2008-2009</u> COMPREHENSIVE SAFETY & SAU INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT ION CHAP INSPE	TER	5 N7 IN:	SPEQTIC	LAKE 2851 S GREE ON DAT	ASBUR SANDRIE N COVE	Y JUNIOR H DGE ROAD SPRINGS, F /EMBER 18,	#: <u>0025</u>
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	408	ОК								
92	409	ОК								
92	410	ОК								
92	421	RAMP EXCEEDS 1/12 SLOPE	X					2		FBC 11-4.8
92	422	ОК								
92	423	ок					a. Second			
92	424	RAMP EXCEEDS 1/12 SLOPE	x					2		FBC 11-4.8
92	425	STORAGE ROOM LIGHT COVER MISSING	x							NFPA 70 401.3
92	426	RAMP EXCEEDS 1/12 SLOPE	x					2		FBC 11-4.8
92	427	RAMP EXCEEDS 1/12 SLOPE	X					2		FBC 11-4.8
92	427	STORAGE ROOM LIGHT COVER MISSING	x				<u> </u>			NFPA 70 401.3


		FISCAL YEAR <u>2008-2009</u> COMPREHENSIVE SAFETY & SAI INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT ION CHAP INSPE	TER ECTIO	5 FA	CILITY: SPECTIC	LAKE 2851 S GREE ON DAT	ASBUR SANDRIE N COVE	OGE ROAD SPRINGS, F /EMBER 18,	GH SCHOOL
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost .	No. of times Def. Cited	Scheduled for Correction	Rulė
92	428	ОК			nin dina di si bisi di penglik	n tig Contraction and	49912439-1920 (1960)		relian der angere versioning in der	
92	430	ОК								
		OR HIGH SCHOOL 2008-09 SREF INSPECTION								

.

.









		FISCAL YEAR <u>2008-2009</u>)		DIS	STRICT:	CLAY		_ FACILITY	#:0014
		COMPREHENSIVE SAFETY & SAP INSPECTION REPORT STATE BOARD OF EDUCAT		ION	FA	CILITY:	2750 N	/IOODY F	NIOR HIGH S ROAD K, FLORIDA	
		ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP		N7 IN:	[od]	hve		/ <u>EMBER 20,</u>	2008 11-20-C8 DATE	
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	ALL	ALL EMERGENCY LIGHTS OUT IN CLASSROOMS	X	i de ser de la company.	and a start of the second	1-11000-19408-4140		the reaction of the second		FBC 423.17.1
1	12	EMERGENCY LIGHT OUT IN CORRIDOR		X						
1	10	EMERGENYC EVACUATION SHEET MISSING	<u>er a sedera instatus par</u>	Х						FBC 423.14.2.4
e 1	11	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
1	29	ROOF LEAK – STAINED CEILING TILES	х							
1	30.	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
2	31	PROJECTOR INSTALLED IMPROPERLY				x				
2	35	EMERGENCY LIGHT OUT		x						FBC 423.17.1
2	40	PROJECTOR INSTALLED IMPROPERLY				x				
2	40	LIGHT WITH EXTENSION CORD INOT CEILING - REMOVE		X						NFPA 70
2	40	EMERGENCY LIGHT OUT		x						FBC 423.17.1

A LA		FISCAL YEAR <u>2008-2009</u> COMPREHENSIVE SAFETY & SAP INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F	NITAT ION CHAP	TER	F4		LAKE 2750 ORAN	Side Ju Moody Ige Par	K, FLORIDA	SCHOOL 32073
Building	Room	CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP		Oper. "O"		[d	Swā	Mont GNATUR No. of times Def.	VEMBER 20, E Scheduled for Correction	2008 <u>[]-20-08</u> DATE Rule
								Cited	Correction	
2	ALL	EMERGENCY LIGHTS OUT IN ALL CLASSROOMS	X		an-anatai					FBC 423.17.1
3	ALL	EMERGENCY LIGHTS OUT IN ALL CLASSROOMS	<u> </u>							FBC 423.17.1
3	66	EMERGENCY EVACUATION SHEET MISSING		X		ia mananisia		in and the second		FBC 423.14.2.4
3	61	EMERGENCY LIGHT OUT		X -						FBC 423.17.1
3	59	EXIT BLOCKED – REMOVE TABLE	tine and all the	X			and a state of the			FBC 1003
3	80	DESK IN FRONT OF SECOND EXIT – MOVE		X						FBC 1003
3	80	ROOF LEAKS	X		No. 10 and 10 and 10 and 10 and	ng 199 yan kasaran	Th Concept Disease Actor		e - en standen men gesonen andere andere andere	
3	80	EMERGENCY EVACUATION SHEET MISSING		<u> </u>						FBC 423.14.2.4
3	72	EXIT BLOCKE3D – MOVE TABLE		X						FBC 1003
5	112	EXTINGUISHER TAG MISSING		X						FAC 691-58
5	116	HALF EMERGENCY LIGHTS OUT - NORTHWEST		x						FBC 423.17.1

		FISCAL YEAR <u>2008-2009</u> COMPREHENSIVE SAFETY & SAU INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	TER	5 N ⁷⁷ INS	CILITY: SPECTIC	LAKE 2750 M ORAN ON DAT	<u>Side Jui Moody F</u> Ige Par	<u>K, FLORIDA</u>	SCHOOL 32073	
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	124	EMERGENCY LIGHT OUT	i <u>destruites</u> tati	X		an tara ang ang ang ang ang ang ang ang ang an	and a start of the		andarah ing pangkanang pangkanang pangkanang pangkanang pangkanang pangkanang pangkanang pangkanang pangkanang	FBC 423.17.1
5	138	HALF OF EMERGENCY LIGHTS OUT		X						FBC 423.17.1
5	213	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
5	217	REMOVE STORAGE FROM EXIT		X						FBC 1003
5	215	REMOVE EXTENSION CORD ON SHELF TO CLOCK		х						NFPA 70
5	215	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2.2
5	233	FIRE EXTINGUISHER NOT SIGNED		x						FAC 69A-58
5	239	ROOF LEAK - REPLACE TILES		X						
8		FIRE EXTINGUISHER NOT SIGNED		x						FAC 69A-58
	804	OUTLET COVER CRACKED – CRACKS IN MASONRY		x						NFPA 70







		FISCAL YEAR <u>2008-2009</u>	-		DI	STRICT:	CLAY		_ FACILITY	#: 0014
		COMPREHENSIVE SAFETY & SAN INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F	ion Chap	TER (5		2750 M ORAN	<u>IOODY I</u> GE PAR	K, FLORIDA	32073
		"CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP		CTIO		Tod)	hve		/EMBER 20,	2008 11-20-c8 Date
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	ALL	ALL EMERGENCY LIGHTS OUT IN CLASSROOMS	х							FBC 423.17.1
1	:12	EMERGENCY LIGHT OUT IN CORRIDOR		X						
1	10	EMERGENYC EVACUATION SHEET MISSING	1	Х						FBC 423.14.2.4
1	11	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
1	29	ROOF LEAK – STAINED CEILING TILES	x							
1	30	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
2	31	PROJECTOR INSTALLED IMPROPERLY				X				
- 2	35	EMERGENCY LIGHT OUT		X		Sector (deg)				FBC 423.17.1
2	40	PROJECTOR INSTALLED IMPROPERLY				x				
2	40	LIGHT WITH EXTENSION CORD INOT CEILING - REMOVE		×						NFPA 70
2	40	EMERGENCY LIGHT OUT		x						FBC 423.17.1


		FISCAL YEAR 2008-2009 COMPREHENSIVE SAFETY & SAF INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	NITAT ION CHAP INSPE	TER	5 N7 IN	ACILITY: SPECTIC Isd	LAKE 2750 I ORAN ON DAT	<u>Side Ju</u> Moody Ige Par	K, FLORIDA	SCHOOL 32073
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	ALL	EMERGENCY LIGHTS OUT IN ALL CLASSROOMS	X							FBC 423.17.1
- 3	ALL	EMERGENCY LIGHTS OUT IN ALL CLASSROOMS	x							FBC 423.17.1
3	66	EMERGENCY EVACUATION SHEET MISSING	11 Martines Address	X	<u></u>					FBC 423.14.2.4
3	- 61 · ·	EMERGENCY LIGHT OUT		X						FBC 423.17.1
3	59	EXIT BLOCKED – REMOVE TABLE		X						FBC 1003
3	80	DESK IN FRONT OF SECOND EXIT MOVE		x						FBC 1003
3	80	ROOF LEAKS	х							
3	80	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
3	72	EXIT BLOCKE3D – MOVE TABLE		x						FBC 1003
5	112	EXTINGUISHER TAG MISSING		- X						FAC 691-58
5	116	HALF EMERGENCY LIGHTS OUT - NORTHWEST		X						FBC 423.17.1

		COMPREHENSIVE SAFETY & SAF INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	ION Chap Inspe	TER	5 N7 IN	SPECTIC Tod	$\frac{2750 \text{ M}}{\text{ORAN}}$	ige par	<u>K, FLORIDA</u>	32073
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	124	EMERGENCY LIGHT OUT		X					analan tan Artsanata	FBC 423.17.1
5	138	HALF OF EMERGENCY LIGHTS OUT		x						FBC 423.17.1
5	213	EMERGENCY LIGHT OUT		х						FBC 423.17.1
5	217	REMOVE STORAGE FROM EXIT		X						FBC 1003
5	215	REMOVE EXTENSION CORD ON SHELF TO CLOCK		X						NFPA 70
5	215	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2.2
5	233	FIRE EXTINGUISHER NOT SIGNED		x						FAC 69A-58
5	239	ROOF LEAK - REPLACE TILES		X						
8		FIRE EXTINGUISHER NOT SIGNED		Х						FAC 69A-58
8	804	OUTLET COVER CRACKED – CRACKS IN MASONRY WALL?		x						NFPA 70

		FISCAL YEAR <u>2008-2009</u>	9			DISTRICT	CLAY	<u>, </u>	FACILITY	#:
		COMPREHENSIVE SAFETY & SAI INSPECTION REPORT STATE BOARD OF EDUCAT	ION			FACILITY:	2750	NOODY	NIOR HIGH S ROAD K, FLORIDA	
	BuildingRoomDeficiency Description and Corrective Action Required:92732OK92733EMERGENCY EVACUATION SHEET MISSING92734LENS COVER MISSING		INSPI	ectio			wea	Hand	<u>VEMBER 20,</u>) E	<u>2008</u> <u>11-20-08</u> Date
Building	Room		Maint. "M"	Oper. "O"	Fac "C		Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	732	ОК			1 VIEW 1 0010400				<u>, 1997 - 1997 - 1997 - 1997 - 1997 - 1997</u>	n den franziel en zonen endezig in den fabrie de sind system fabrie de system. Transformen
92	733	EMERGENCY EVACUATION SHEET MISSING		x						FBC 423.14.2.2
92	734	LENS COVER MISSING		x						NFPA 70
92	735	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	735	RAMP EXCEEDS 1/12 SLOPE	х					2		FNC 11-4.8
92	737	CEILING HANGING	x							
92	745	А&ВОК								
92	791	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	791	PLUMB. CLEAN-OUT – OPEN BY RAMP		x						
92	793	ОК								
92	794	ок								

		FISCAL YEAR <u>2008-2009</u>	9		DI	STRICT:	CLAY		FACILITY	#:0014
		COMPREHENSIVE SAFETY & SAI INSPECTION REPORT STATE BOARD OF EDUCAT	ION			CILITY:	2750	NOODY I	NIOR HIGH S ROAD K, FLORIDA	
		ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	INSPI		N77 IN	Tod	Swe	E: <u>NOV</u> E BNATUR	<u>√EMBER 20,</u> ∕ E	2008 11-20-09 DATE
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	701	ОК	<u> 1990/003-177992*</u>			<u> </u>		n en de la serve de la serv Internet de la serve de la s		
92	702	ок								
92	703	ОК								
92	704	OK								
92	705	ОК						The back of the state		
92	706	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	708	ок	a second to the second	and an occurrent of the	wax en eus too Hee		1			
92	710	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	721	RAMP DOOR STICKS	- 1970 (1970) 1970 - 1977 (1970)	X	netwyc gawli erwyddiad	a national terms	New York and a second	2417,0022,002445,00240		
92	721	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	722	ОК	1 at 31-73 Wo 14			•) (* • • » . * . /•.	en ante antes	in a state the second state		
92	731	OK								





ORANGE PARK JUNIOR HIGH 2008-09 SREF INSPECTION

		FISCAL YEAR <u>2008-2009</u>			D	DISTRICT <u>:</u>	CLAY		_ FACILITY	#. 0016
A CONTRACTOR	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION					ACILITY:	1500	GANO A		IIGH SCHOOL
ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101 INSPECTOR'S SIGNATURE									-	008
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	501	EMERGENCY LIGHT NOT WORKING		X		oon haaroon aanaa		no fotologija je 100 m doch je		FBC 423.17.1
92	503	ОК								
92	505	ОК								
92	507	RAMP EXCEEDS 1/12 SLOPE	X							FBC 11-4.8
92	509 A & B	EMERGENCY LIGHT NOT WORKING		х						FBC 423,17,1
92	-511	EMERGENCY LIGHT NOT WORKING		<u>х</u>						FBC 423.17.1
92	516	ОК								·
92	513	ОК								
92	514	ОК								
92	504	ОК								
92	506	ок								
92	508	OK	1000年1月2日日本	Constant States	ing ang ang ang ang ang ang ang ang ang a		1 ALCONTRACTOR	1. ····································		一般的 化的 医结肠的 化合金化合金化合金化合金化合金化合金

BuildingRoomDeficiency Description and Corrective Action Required:Maint "M"Oper "C"Fac. "C"Info. Serv. "C."Scheduled for CorrectionScheduled for CorrectionRule92510WOOD RAMP DETERIORATINGXIII<			FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFF	NITAT FION - CHAF I INSPI	TER	5 N"		ORA 1500 ORAI	NGE PAI GANO A NGE PAI	VENUE RK, FLORID/ CEMBER 2, 2	HIGH SCHOOL
92 703 OK Image: Constraint of the second sec	Building	Room	Deficiency Description and Corrective Action Required:		Oper. "O"		Serv.	Cost	times Def.	for	Rule
92 704 OK Image: Constraint of the second sec	92	510	WOOD RAMP DETERIORATING	X	1.197 (10.201) (10.202)		(1999) (* 1999) 1997) - 1997)				
92 705 OK Image: Constraint of the second sec	92	703	OK								
92 706 EMERGENCY LIGHT NOT WORKING X Image: Constraint of the state of	92	704	ОК								
92 707 OK Image: Constraint of the second sec	92	705	OK								
92 708 OK 92 710 OK	92	706	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
92 7:10 OK	92	707	OK								
	92	708	ОК	100 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110 - 110				-40200000000	personal and second a second		
92 712 EMERGENCY LIGHT NOT WORKING X Image: Constraint of the second sec	92	710	ОК								
	92	712	EMERGENCY LIGHT NOT WORKING		X	Competitive Armstration					FBC 423.17.1

ORANGE PARK JUNIOR HIGH 2008-09 SREF INSPECTION





		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	5 5 7 7 7 1	DISTRICT: CLAY FACILITY #: 0017 FACILITY: WILKINSON JUNIOR HIGH SCHOOL 5025 C.R. 218 MIDDLEBURG, FLORIDA 32068 INSPECTION DATE: DECEMBER 5, 2008 MUM Mum Mum Mum Mum Mum Mum Mum Mum Mum Mu							
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule	
1		ОК			A SACARA SACARA						
2		ok									
3		ок									
4		ок									
5		ок									
6		OK									
7	777	AC/CONTROL BOXES OPEN/MISSING COVERS	x								
8	804	OUTLET COVERS BROKEN OR MISSING		X						NFPA 70	
8	814	AC GRILLS DIRTY – NEED LIFT TO CLEAN		х						FMC	
8	814	OUTLET COVERS BROKEN OR MISSING		x						NFPA 70	
9	917	CEILING TILES MISSING OR BROKEN		x						FMC 80	
9	906	TWO EMERGENCY LIGHTS NOT WORKING		x						FBC 423.17.1	
9	901	EMERGENCY LIGHT NOT WORKING		x						FBC 423.17.1	

		FISCAL YEAR 2008-200	9		DI	STRICT	CLA	(_ FACILITY	#:0017				
		COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT	ECTION REPORT ARD OF EDUCATION					TY: <u>WILKINSON JUNIOR HIGH SCHOOL</u> 5025 C.R. 218 MIDDLEBURG, FLORIDA 32068						
		ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101					INSPECTION DATE: DECEMBER 5, 2008							
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Орег. "О"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule				
92	2	RAMP EXCEEDS 1/12 SLOPE	X	<u>(19)103998887</u>		। संस्थेत राज्य में साथ 		2		FBC 11-4.8				
92	3	TRIP HAZARD AT BASE OF RAMP	x							FBC 1003				
92	4	RAMP EXCEEDS 1/12 SLOPE	х					2		FBC 11-4.8				
92	5	OK												
92	6	ОК												
92	- 7	ОК												
92	8	ОК												
92	- .9	OK												
92	10	RAMP EXCEEDS 1/12 SLOPE	x					2		FBC 11-4.8				
92 -	11	ОК												
92	12	ОК	- And		a second a second s	1 Mary Control Street Bill	- 111112/10/04 2 (% T		ne konstructus (1990), Marcandona					
92	17	OK												
92	18	ОК												

WILKINSON JUNIOR HIGH 2008-09 SREF REPORT





		FISCAL YEAR 2008-200	9		DI	STRICT	: <u>CLA</u>	<u>(</u>	_ FACILITY	/# : <u>0017</u>				
		COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT	FA	FACILITY: <u>WILKINSON JUNIOR HIGH SCHOOL</u> 5025 C.R. 218 MIDDLEBURG, FLORIDA 32068										
		ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101					INSPECTION DATE: DECEMBER 5, 2008							
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule				
<u>1</u>		ΟΚ			Alexandra Alexandra	<u> 2009.02323</u>								
2		OK												
3	1986) - Aritz (2007) 1997	ОК	na na sana na s	add dollard, ?"										
4		OK												
5		ок												
. 6		ОК												
7	777	AC/CONTROL BOXES OPEN/MISSING COVERS	х											
8	804	OUTLET COVERS BROKEN OR MISSING		X						NFPA 70				
8	814	AC GRILLS DIRTY – NEED LIFT TO CLEAN		х						FMC				
.8	814	OUTLET COVERS BROKEN OR MISSING		X						NFPA 70				
9	917	CEILING TILES MISSING OR BROKEN		Х						FMC 80				
9	906	TWO EMERGENCY LIGHTS NOT WORKING		X						FBC 423.17.1				
	901	EMERGENCY LIGHT NOT WORKING					1	1						

		FISCAL YEAR <u>2008-200</u>	9		DI	STRICT	CLA	ŕ.	_ FACILITY	′#:0017					
		INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F. "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101					FACILITY: WILKINSON JUNIOR HIGH SCHOOL 5025 C.R. 218 MIDDLEBURG, FLORIDA 32068 INSPECTION DATE: DECEMBER 5, 2008 1059ECTOR'S SIGNATURE DATE							
Building	Room	Deficiency Description and Corrective Action Required:	Maint. " <u>M</u> "	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule					
92	2	RAMP EXCEEDS 1/12 SLOPE	Х			<u> अनुसंदे</u> स हम र जिल्ला थे।	And South Street	2		FBC 11-4.8					
92	3	TRIP HAZARD AT BASE OF RAMP	x							FBC 1003					
92	4	RAMP EXCEEDS 1/12 SLOPE	X	i se titteljen nem prejekter i na filje		A A ALL DESIGNATION	And Providence of Coldent	2	<u>na la constante de la constante</u>	FBC 11-4.8					
92	5	ОК													
92	6	ок													
92	7	ОК													
92	8	ОК													
92	9	ОК —													
92	10	RAMP EXCEEDS 1/12 SLOPE	х					2		FBC 11-4.8					
92	11	ОК						249 249 249							
92	12	ОК													
92	17	OK													
the part of the second second second									7						

•

		FISCAL YEAR <u>2008-200</u> COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	5 5 7 1 N	DISTRICT: CLAY FACILITY #: 0017 FACILITY: WILKINSON JUNIOR HIGH SCHOOL 5025 C.R. 218 MIDDLEBURG, FLORIDA 32068 INSPECTION DATE: DECEMBER 5, 2008 INSPECTION DATE: DECEMBER 5, 2008 INSPECTOR'S SIGNATURE DATE							
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule	
92	21	ОК		10100000000000		1 4354					
92	22	ок									
92	23	ок									
92	24	ОК									
92	25	ОК									
92	26	OK									
92	27	ОК									
92	30	OK									
92	40A	LENS COVER MISSING		x				· · · · · · · · · · · · · · · · · · ·		NFPA 70	
92	40B	LENS COVER MISSING		X						NFPA 70	
92	41	ОК				1 100 10 100 10 ¹ 10		Second Second			
92							 Alexandra 			• A Andrew Land 2018年1月17日1月1日月月1日日日本市场建築市场市场工作	
92	42	OK									

		FISCAL YEAR 2008-200 COMPREHENSIVE SAFETY & SA INSPECTION REPORT STATE BOARD OF EDUCAT ADMINISTRATIVE RULES S.R.E.F "CASUALTY SAFETY & SANITATION IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFP	DISTRICT: CLAY FACILITY #: 0017 FACILITY: WILKINSON JUNIOR HIGH SCHOOL 5025 C.R. 218 MIDDLEBURG, FLORIDA 32068 MIDDLEBURG, FLORIDA 32068 INSPECTION DATE: DECEMBER 5, 2008 Autor 13 - 5 - c8 INSPECTOR'S SIGNATURE DATE							
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	44	ОК	o janut an dan		, have standaktoris	energian (annera) e cheanna			i z 1999. je stanosti regularna predstala.	
92	46	ОК								
92	48	ОК								
92	96	ок								
	LIUNIOR	HIGH 2008-09 SREF REPORT								