



State Fire Marshal - Inspection Report -SCHOOL

PDF version is recommended for printing and requires Adobe Reader

District:

Clay

School:

CLAY HIGH SCHOOL

Address:

2025 HIGHWAY 16 W

Inspection Date: April 23, 2010

Note:

N/A

Inspectors present

State: No District: Yes Local: No

Violation **Building** Anticipated Cite Reference Code Room Compliance Date N/A 0803 **EXTENSION CORD NOT** 0-833 Apr 23, 1 Building 2010 RATED FOR USE N/A ---See notes N/A 0211 BLOCKED/LOCKED EXITS 0-325 Apr 23, 1, Building 2010 N/A --See notes N/A 0808 IMPROPER STORAGE IN 0-328 Apr 23, 1 **ELECT/MECH ROOMS** Building 2010 N/A --See notes N/A 0301 UNPROTECTED 328 Apr 23, 1 Building **VERTICAL OPENING** 2010 N/A --See

			notes			ŗ
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0- Building N/A See	756	Apr 23, 2010	1
N/A	0211	BLOCKED/LOCKED EXITS	notes 0- Building N/A See notes	749	Apr 23, 2010	1
N/A	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	0- Building N/A See notes	128	Apr 23, 2010	1
N/A	0506	EXTINGUSHER MISSING FROM LOCATION	0- Building N/A See notes	128	Apr 23, 2010	1,
N/A	0301	UNPROTECTED VERTICAL OPENING	0- Building N/A See notes	130b	Apr 23, 2010	1,
N/A	0211	BLOCKED/LOCKED EXITS	0- Building N/A See notes	134	Apr 23, 2010	1
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0- Building N/A See notes	138b	Apr 23, 2010	1
N/A	0301	UNPROTECTED VERTICAL OPENING	0- Building N/A See notes	142	Apr 23, 2010	1
N/A	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	0- Building N/A See notes	123	Apr 23, 2010	1
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0- Building	125	Apr 23, 2010	1

							'
***************************************				N/A See notes			
	N/A	0803	EXTENSION CORD NOT RATED FOR USE	0- Building N/A See notes	228	Apr 23, 2010	1,
	N/A	0504	EXTINGUSIHER ACCESS OBSTRUCTED	0- Building N/A See notes	212	Apr 23, 2010	1
*************************	N/A	0211	BLOCKED/LOCKED EXITS	0- Building N/A See notes	1114	Apr 23, 2010	1
	N/A	0807	MISSING/BRÓKEN RECEPTACLE/FACEPLATE	0- Building N/A See notes	1102	Apr 23, 2010	1
	N/A	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0- Building N/A See notes	p33	Apr 23, 2010	1
	N/A	0199	GENERAL REQUIREMENTS	0- Building N/A See notes	404	Apr 23, 2010	1
	N/A	0803	EXTENSION CORD NOT RATED FOR USE	0- Building N/A See notes	514	Apr 23, 2010	1

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F!S.

I hereby certify that the required fire drills have been completed as of this inspection date.

Or

Acknowledgement N/A.

!

Primary inspector: Additional inspector:

Raul Feliciano

N/A

Powered by eGroupWare's CSS Design and the Bureau of Economic and Business Research.



State Fire Marshal - Inspection Report - SENIOR HIGH

PDF version is recommended for printing and requires Adobe Reader

District:

Clay

School:

FLEMING ISLAND SENIOR HIGH

Address:

2233 VILLAGE SQUARE PARKWAY

Inspection

April 19, 2010

Date:

Note:

School in good shape. Areas of concern, Fire extinguishers throughout the school

missing monthly inspection's.

Inspectors present

State: Yes	District:	No Local: No		•		· r
Reference	Code	Violation	Building	Room	Anticipated Compliance Date	Cited
N/A	0100	GENERAL REQUIREMENTS	1- PERMANENT	121	Apr 19, 2010	0 ,
N/A	0800	UTILITIES	2- PERMANENT	gym	Apr 19, 2010	0

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

Or

Acknowledgement N/A.

Primary inspector:

randy brunson

Additional inspector:

N/A

Powered by eGroupWare's CSS Design and the Bureau of Economic and Business Research.



State Fire Marshal - Inspection Report -SENIOR HIGH

PDF version is recommended for printing and requires Adobe Reader

District:

Clay

School:

MIDDLEBURG SENIOR HIGH

Address:

3750 STATE ROAD 220

Inspection Date: April 19, 2010

Note:

N/A

Inspectors present

State: No

District: Yes

Local: No

Reference	Code	Violation	Building	Room	Anticipated Compliance Date	C
N/A	0809	OPEN ELECTRICAL JUNCTION BOX	0-Building N/A See notes	144	Apr 19, 2010	1
N/A	0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	0-Building N/A See notes	62 ·	Apr 19, 2010	, 1
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	161	Apr 19, 2010	1
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0-Building N/A See notes	151	Apr 19, 2010	1
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0-Building N/A See notes	242	Apr 19, 2010	1
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0-Building N/A See notes	p66	Apr 19, 2010	1

N/A	0210	EXIT ACCESS NOT MAINTAINED	0-Building N/A See notes	p63 [.]	Apr 19, 2010	, 1
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0-Building N/A See notes	p86	Apr 19, 2010	1
N/A	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0-Building N/A See notes	p5a5b	Apr 19, 2010	1 1
N/A	0211	BLOCKED/LOCKED EXITS	12- PERMANENT	12 .	Apr 19, 2010	1
N/A	1300	OUTSIDE STRUCTURE	0-Building N/A See notes	building3	Apr 19, 2010	['] 1

Statements acknowledged

hereby certify that the district has complied with section 1013.12(1)(b), F.S.

hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F,S.

hereby certify that the required fire drills have been completed as of this inspection date.

Or

Acknowledgement N/A.

Primary inspector:

Raul Feliciano

Additional inspector:

N/A

Powered by eGroupWare's CSS Design and the Bureau of Economic and Business Research.

http://app.bebr.ufl.edu/SFM/public/showReport.php?d=10&s=570&did=10&i%5B%5D=3... 4/23/2010



N/A

No

State Fire Marshal - Inspection Report - ORANGE PARK SENIOR HIGH

PDF version is recommended for printing and requires Adobe Reader

District:

Clay

School: Address: ORANGE PARK SENIOR HIGH 2300 KINGSLEY AVENUE

Inspection Date: January 4, 2010

N/A Note:

Inspectors present

State: No District: Yes Local: No

Reference	Code	Violation	Building	Room	Anticipated Compliance Date	Cited	Notes
N/A	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	0-Building N/A See notes	5	Jan 4, 2010	0	Building 16 A- wing
N/A	0507	TRAVEL DISTANCE TO EXTINGUISHER EXCEEDED	0-Building N/A See notes	hallway	Jan 4, 2010	0	Building 17 B-Wing
N/A	0211	BLOCKED/LOCKED EXITS	19- PERMANENT	D3	Jan 4, 2010	0	N/A
N/A	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	19- PERMANENT	D2	Jan 4, 2010	0	N/A
N/A	0211	BLOCKED/LOCKED EXITS	20- PERMANENT	EAdmanistration	Jan 4, 2010	0	N/A
N/A	0901	IMPROPER STORAGE	22- PERMANENT	9B	Jan 4, 2010	0	N/A
N/A	0803	EXTENSION CORD NOT RATED FOR USE	22- PERMANENT	H6	Jan 4, 2010	0	N/A
N/A	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	22- PERMANENT	H5	Jan 4, 2010	0	N/A
N/A	0506	EXTINGUSHER MISSING FROM LOCATION	22- PERMANENT	Hallway	Jan 4, 2010	0	N/A
N/A	0211	BLOCKED/LOCKED EXITS	22- PERMANENT	ALLClassroom	Jan 4, 2010	0	All class rooms secondary exits are blocked.
N/A	0010	IMMINENT HAZARD	3-PERMANENT	51	Jan 4, 2010	0	storage of flammable combustible liquids are not in approved flame cabinet
N/A	0901	IMPROPER STORAGE	51- PERMANENT	11	Jan 4, 2010	0	N/A
N/A	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	51- PERMANENT	boyslockerroom	Jan 4, 2010	0	N/A
N/A	0211	BLOCKED/LOCKED	51-	17	Jan 4, 2010	0	N/A

		EXITS	PERMANENT				
N/A	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	51- PERMANENT	7	Jan 4, 2010	0	N/A
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	604	Jan 4, 2010	0	Building 600
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	605	Jan 4, 2010	0	Building 600
N/A	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	4-PERMANENT	7	Jan 4, 2010	0	N/A
N/A	0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	4-PERMANENT	boyslockerrm	Jan 4, 2010	0	N/A
N/A	0399	PROTECTION OTHER	10- PERMANENT	outsiderear	Jan 4, 2010	0	must install placards adressing diesel fuel
N/A	0405	SMOKE DETECTORS INOPERABLE/MISSING	10- PERMANENT	131	Jan 4, 2010	0	N/A
N/A	0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT	114	Jan 4, 2010	0	N/A
N/A	0901	IMPROPER STORAGE	10- PERMANENT	122	Jan 4, 2010	0	fire riser rm
N/A	0901	IMPROPER STORAGE	10- PERMANENT	126	Jan 4, 2010	0	N/A
N/A	0506	EXTINGUSHER MISSING FROM LOCATION	10- PERMANENT	126B	Jan 4, 2010	0	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	10- PERMANENT	125C	Jan 4, 2010	0	N/A
N/A	0211	BLOCKED/LOCKED EXITS	10- PERMANENT	125	Jan 4, 2010	0	N/A
N/A	0299	MEANS OF EGRESS OTHER	10- PERMANENT	2ndflhallway	Jan 4, 2010	0	door operation
N/A	0901	IMPROPER STORAGE	10- PERMANENT	256	Jan 4, 2010	0	N/A
N/A	0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT	186	Jan 4, 2010	0	N/A
N/A	0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT	180F	Jan 4, 2010	0	N/A
N/A	0204	EMERG LIGHTS NOT OPERATIONAL	10- PERMANENT	admanistrationhallway	Jan 4, 2010	0	N/A
N/A	0010	IMMINENT HAZARD	12- PERMANENT	159	Jan 4, 2010	0	not an emergency exit
N/A	0901	IMPROPER STORAGE	0-Building N/A See notes	142	Jan 4, 2010	0	Auto repair shop
N/A	0301	UNPROTECTED VERTICAL OPENING	0-Building N/A See notes	142	Jan 4, 2010	0	N/A
N/A	0504	EXTINGUSIHER ACCESS OBSTRUCTED	91- RELOCATABLE	VP2	Jan 4, 2010	0	N/A
N/A	0504	EXTINGUSIHER ACCESS OBSTRUCTED	91- RELOCATABLE	VP1	Jan 4, 2010	0	N/A
N/A	0204	EMERG LIGHTS NOT OPERATIONAL	91- RELOCATABLE	L2	Jan 4, 2010	0	N/A
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	K17	Jan 4, 2010	0	Portable
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	40	Jan 4, 2010	0	portable 40
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	K16	Jan 4, 2010	0	N/A
N/A	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0-Building N/A See notes	K12	Jan 4, 2010	0	portable

rimary ins Additional	spector: inspector:	Raul Feliciano					
-	igement N/	A.					Yes
hereby ce r	rtify that th	e required fire drills have been	completed as of this in	spection date.			
hereby ce	ertify that th	e local authority having jurisdic	ction has complied with	n section 1013.12(2)	(b), F.S.		No
hereby ce	ertify that th	e district has complied with sec	tion 1013.12(1)(b), F.S	S .			No
tatemen	its acknow	vledged					
		EMERGENCY MODE					
V/A	0203	EXIT LIGHTS INOPERABLE	0-Building N/A See notes	portable58	Jan 4, 2010	0	N/A
		INOPERABLE EMERGENCY MODE	See notes		vair 1, 2010	Ŭ	portuoio
I/A	0203	EXIT LIGHTS	0-Building N/A	K7	Jan 4, 2010	0	amount of 20% allowable artwork portable
I/A	0399	PROTECTION OTHER	0-Building N/A See notes	K24	Jan 4, 2010	0	portable exceeded
I/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	K23	Jan 4, 2010	0	portable
I/A	0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	0-Building N/A See notes	K11	Jan 4, 2010	0	portable
/A	0504	EXTINGUSIHER ACCESS OBSTRUCTED	0-Building N/A See notes	K11	Jan 4, 2010	0	portable

Powered by $\underline{eGroupWare} \text{'s CSS Design and the } \underline{Bureau \text{ of Economic and Business Research}}.$



State Fire Marshal - Inspection Report -SENIOR HIGH

PDF version is recommended for printing and requires Adobe Reader

District:

Clay

School:

RIDGEVIEW SENIOR HIGH

Address:

466 MADISON AVENUE

Inspection Date: April 23, 2010

Note:

N/A

Inspectors present

State: No

District: Yes

Local: No

Reference	Code	Violation	Building	Room	Anticipa Complia Date
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	3-PERMANENT	3	Apr 23, 2010
N/A	0405	SMOKE DETECTORS INOPERABLE/MISSING	3-PERMANENT	328	Apr 23, 2010
N/A	0408	MANUAL PULL STATION MISSING/INOPERABLE	5-PERMANENT	5	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	6-PERMANENT	649	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	6-PERMANENT	650	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	6-PERMANENT	651	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	6-PERMANENT	652	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	6-PERMANENT	653668	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	8-PERMANENT	822	Apr 23, 2010

N/A	0408	MANUAL PULL STATION MISSING/INOPERABLE	0-Building N/A See notes	941	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	90- RELOCATABLE	p4	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	0-Building N/A See notes	p12	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	0-Building N/A See notes	p2122	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	0-Building N/A See notes	p26	Apr 23, 2010
N/A	0411	HORN/STROBE DEVICE INADEQUATE/INOPERABLE	0-Building N/A See notes	p42	Apr 23, 2010
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	602	Apr 23, 2010
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0-Building N/A See notes	649	Apr 23, 2010
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	302	Apr 23, 2010
N/A	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	217	Apr 23, 2010
N/A	0803	EXTENSION CORD NOT RATED FOR USE	0-Building N/A See notes	233	Apr 23, 2010
N/A	0211	BLOCKED/LOCKED EXITS	10- PERMANENT	1036	Apr 23, 2010
N/A	0010	IMMINENT HAZARD	0-Building N/A See notes	01	Apr 23, 2010
1					

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

Or

Acknowledgement N/A.

Primary inspector:

Raul Feliciano

Additional inspector:

N/A

Powered by eGroupWare's CSS Design and the Bureau of Economic and Business Research.