

# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY	FACILITY: 0013
	FACILITY: CLAY HIGH S  2025 HIGHW	
	INSPECTION DATE: 00	
<b>177</b>	Mor Edition BATE:	**************************************

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac: "C"	Înfo. Serv: "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	10Z	CONDUITS NEED TO BE RE-SECURED AFTER SOUND PANEL INSTALL.			x					NFPA 70-110.1.2
1	. 103∞	FIRE ALARM BOX OPEN	X	可能的 建模数:						NEPA 70-110.12
1	102	ELECTRICAL PLUG NOT ATTACHED TO BOX BY VENDING MACHINE		Х						NFPA 70-210
1	115	EMERGENCY LIGHT OUT		X						FBC 423.17.1
. 1	132A	LIGHT COVER MISSING		Х						NFPA 70-410.85
1	127	SANITARY TILE BROKEN	X							
1	132	SANITARY TILE BROKEN	X							
1	128	CEILING TILE MISSING		X						FBC 804:2:3
1	132B	HOLE IN CONCRETE BY STAIR ON LANDING		Х						
43	"中的现在分别的特别为各种	THE PROPERTY OF THE PROPERTY O	THE PURPLE STREET	FF 55 55	ENGRE MIN	175000000000000000000000000000000000000	<b>延伸指指</b>	AUXONOUTE A		
1966	134	MOTION SENSOR COVER MISSING		i X			建筑特别			
1	134 143	MOTION SENSOR COVER MISSING  MOTION SENSOR LOOSE		X						
	N. J. State (N. J. Patrick									



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT:_	CLAY	FAC	ILITY:_	0013	
	FACILITY:		H SCHOOL	ГОТ		
			HWAY 16 W OVE SPRIN		RIDA 32043	······································
į	INSPECTIO	N DATE:	OCTOBER	11, 201	1	****

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S:"	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3A	226	STORAGE TO HIGH 18" FROM CEILING		Х						NFPA 1
3A-	333	ÜRINAL BROKEN	X						10 C C	
3A	333	ONE BULB OUT, EMERGENCY LIGHT		Х				_		FBC 423.17.1
3B	308	STORAGE TOO HIGH 18 " FROM CEILING		X						NEPA 1, 12-1
3B	309	STORAGE TOO HIGH - 18" FROM CEILING		X						NFPA 1, 12-1
3C.	364	EXHAUST FAN COVER MISSING/WORKING		- X						and the second s
3C	353	BOXES TOO HIGH		Х						NFPA 1. 12-1
-3C	343	PLUG ABOVE CEILING TO PROJECTOR			X		tanillaretsey Turkey Turkey			NEPA 70-110.12
3C	344	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-110.12
3C	338	OUTLET STRIPS DAISY CHAINED TOGETHER		X						NFPA 70-400.8
3D	382	TILE SANITARY BASE BROKEN	Х							
3D	396	J-BOX NO COVER		- X-						NEPA 70-110.26
3D	396	ELECTRICAL PANEL NOT LABELED P3A-1	Х							NFPA 70-110.12



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY: 0013
	FACILITY: CLAY HIGH SCHOOL  2025 HIGHWAY 16 WEST  GREEN COVE SPRINGS, FLORIDA 32043
,	INSPECTION DATE: OCTOBER 11, 2011

NSPECTOR'S SIGNATURE DAT

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Pac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rulé
3D	395	WOOD FRAMED WALL – REMOVE KNOCK OUT MISSING J-BOX ABOVE EXIT DOOR		Х	·					NFPA 70 110.12
3D	389	EMERGENCY LIGHT OUT		X						FBC 423:17:1
4		OK								
5	518	STORAGE TOO HIGH IN CLOSET		×					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NFPA 1-12.1
5	510A	CEILING TILE MISSING		Х						FBC 802.3
5	510B	EXIT SIGN OVER TWO WAY DOOR		X						FBC 1016.3
6	601	EXTENSION CORD ABOVE CEILING TO PROJECTOR - NEEDS ELECTRICAL PLUG ADDED ABOVE CEILING			X					NFPA 70-400.8
7A	706	PLUG ABOVE CEILING PROJECTOR			Χ					NEPA 70-400.8
7A	709	PLUG ABOVE CEILING PROJECTOR			Х					NFPA 70-400.8
7B	714	PLUG ABOVE CEILING PROJECTOR			X	V araile				NFPA 70-400.8
7B	718	PLUG ABOVE CEILING PROJECTOR			Х					NFPA 70-400.8



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0013

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

**GREEN COVE SPRINGS, FLORIDA 32043** 

INSPECTION DATE: OCTOBER 11, 2011

INSPECTOR'S SIGNATURE

10-11-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
7A	718	PLUG ABOVE CEILING PROJECTOR			Х					NFPA 70-400.8
7A	719	PLUG ABOVE CEILING PROJECTOR			Χ					NFPA 70-400.8
7A	723	PLUG ABOVE CEILING PROJECTOR			Х					NFPA 70-400.8
7A .	728	PLUG ABOVE CEILING PROJECTOR		(4) (4)	X					NFPA 70-400.8
7A	710	STORAGE TOO HIGH		Х					:	NFPA 1-12.1
7A	717	STORAGE TOO HIGH		X						NFPA 1-12.1
7A 1	722	STORAGE TOO HIGH		Х						NFPA 1-12.1
7A	726	STORAGE TOO HIĞH		X						NFPA 1-12.1
7A	727	STORAGE TOO HIGH		Х						NFPA 1-12.1
7A	739	STORAGE TOO HIGH		X						NEPA 1-12.1
7B	762	PLUG ABOVE CEILING PROJECTOR			×					NFPA 70-400.8
7B	.758	PLUG ABOVE CEILING PROJECTOR			X					NFPA 70-400.8
7B	756	PLUG ABOVE CEILING PROJECTOR			×	:				NFPA 70-400.8



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0013

FACILITY: <u>CLAY HIGH SCHOOL</u>

2025 HIGHWAY 16 WEST


**GREEN COVE SPRINGS, FLORIDA 32043** 

INSPECTION DATE: OCTOBER 11, 2011

MSPECTOR'S SIGNATURE

10-11-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Pac. "C"	Info. Serv. "I.S."	Cost	No. of times Def, Cited	Scheduled for Correction	Rüle
7B	752	PLUG ABOVE CEILING PROJECTOR			X					NFPA 70-400.8
7B	747	PLUG ABOVE CEILING PROJECTOR			×					NFPA 70-400.8
, 7B	748	STORAGE TOO HIGH IN CLOSET		Х						NFPA 1-12.1
7B.	749	STORAGE TOO HIGH IN CLOSET		X						NFPA 1-12:1
7B	754	STORAGE TOO HIGH IN CLOSET		Х						NFPA 1-12.1
7B	760	STORAGE TOO HIGH IN CLOSET		X						NFPA 1-12:1
7B	752	OUTLET COVER PLATE MISSING		Х						NFPA 70-110.12
7B	791	CEILING TILE STAINED		X						FBC 804.2.3.
8	802	BROKEN FLOOR TILE BY ROOM 805	Х							FBC 804.2.3
8	803	PAINT PEELING OFF WALLS	X							
- 8	801	J BOX MISSING KNOCKOUT		Х						NFPA 70-110.12
. 8	801	EXIT LIGHT OUT FAR NORTH ENTRANCE		X						FBC:1006.3.1
8	841	COVER PLATE MISSING		Х						NFPA 70 110.12



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0013
FACILITY:	CLAY HIGH S	SCHOOL	
FACILITY:	CLAY HIGH S 2025 HIGHW	SCHOOL VAY 16 WEST	

INSPECTION DATE: OCTOBER 11, 2011

Lad Weatland 10-11-11

NSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Mäint: "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
8	835	CEILING TILES MISSING		Х						FBC 804.2.3
8	835	SPRINKLER TAG MISSING METAL	X							NFPA 13
, 8	825	EXIT LIGHT OUT		Х						FBC 1006.3.1
-8	829	ON SIDEWALK BEHIND ROOM 829 EXHAUST FAN HAS NO COVER		X						
8	837	J BOX COVER REMOVED	×							NFPA 70 110.12
9	906	PLUG ABOVE CEILING PROJECTOR			X					NFPA 70-400.8
9	912	PLUG ABOVE CEILING PROJECTOR			Х					NFPA 70-400.8
9	915	PLUG ABOVE CEILING PROJECTOR			X					NFPA 70-400.8
9	922	PLUG ABOVE CEILING PROJECTOR			X					NFPA 70-400.8
9	907	STORAGE TOO HIGH	2 - 21 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	Х		a de vis				NFPA 1 12.1
9	911	STORAGE TOO HIGH		Х						NFPA 1 12.1
9	916	STORAGE TOO HIGH		X						NFPA 1 12.1
9	921	STORAGE TOO HIGH		Х						NFPA 1 12.1



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY: 0013	
	FACILITY: CLAY HIGH SCHOOL 2025 HIGHWAY 16 WEST	
	GREEN COVE SPRINGS, FLORIDA 32043	
i	INSPECTION DATE: OCTOBER 11, 2011	
	118	

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper "O"	Pac. "C"	Info. Serv! "I.S!"	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
11	1122	BROKEN/MISSING CEILING TILES		Х						FBC 804.2.3
11	1129	DOORS REMOVED FROM ELECTRICAL PANELS	X							NFPA-70.110
26	1	TWO J BOXE COVERS MISSING	×							NFPA 70.110
35		OK	2000年 - 新基本 1000年 - 新基本							
29		ок								
				1.200分件 1.200分件						
			-795 12							



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0013
FACILITY:	CLAY HIGH SCH		
	2025 HIGHWAY	16 WEST	
	<b>GREEN COVE S</b>	PRINGS, FLO	ORIDA 32043

Tal Sweathere	10-11-11
NŠPECTŎR'S SIGNATURE	DATE

INSPECTION DATE: OCTOBER 11, 2011

Building.	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	5 A/B	ОК								
92.	7	ЮK								
92	8	ОК								
92	17	OK								
92	18	ОК								
92	19	OK								
92	20	ОК								
92	31	ΘK								
92	32	ОК								
92	33	OK								
92	40	ОК	1.00.00.00.00.00.00.00.00							
92	41	ok								



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLA	Y FACILITY:	0013
FACILITY: CLAY	HIGH SCHOOL HIGHWAY 16 WEST	

**GREEN COVE SPRINGS, FLORIDA 32043** 

INSPECTION DATE: OCTOBER 11, 2011

SPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Pac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	42	ОК								
92	43	RANGE HOOD NOT DUCTED THROUGH WALL	X							FBC 423.15.4
92	44	ок					·			
92	45	OK								
92	46	ок								
92	.47	OK								
92	48	ОК								
92	49	οK								
92	51	ок								
92	54	oK								
92	58	ок								
92	50	STORAGE BUILDING OK:								

### FIRE SAFETY INSPECTION REPORT FOR EDUCATIONAL FACILITIES FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58

ANNUAL PERMANENT INSPECTION ANNUAL RELOCATABLE INSPECTION	INSPECTION DATE:	OCTOBER 11, 2011
FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED:	INSPECTOR'S SIGNA	TURE D

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	115	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
3A -	226	STORAGE TOO HIGH 18" FROM CEILING		X						NFPA 1-12.1
3B	308	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
3B	309	STORAGE TOO HIGH 18" FROM CEILING		Χ						NFPA 1-12.1
3C	353	BOXES TOO HIGH		Х						NFPA 1-12.1
3C	343	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-110.12
3C	344	PLUG ABOVE CEILING TO PROJECTOR			х					NFPA 70-110.12
3C	338	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-110.12
3D	395	WOOD FRAMED WALL - REMOVE		Х						FBC 423.5
3D	389	EMERGENCY LIGHT OUT		×				NAALYI SADAA		FBC 423.17.1
6	601	EXTENSION CORD ABOVE CEILING TO PROJECTOR								

DISTRICT: CLAY FACILITY: 0013

2025 HIGHWAY 16 WEST

**GREEN COVE SPGS., FLORIDA 32043** 

FACILITY: CLAY HIGH SCHOOL

### FIRE SAFETY INSPECTION REPORT FOR EDUCATIONAL FACILITIES FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58

ANNUAL PERMANENT INSPECTION	1	ANNUAL RELOCATABLE INSPECTION	
FIRE DRILL LOG:√	NUME	BER OF DRILLS PERFORMED: 2	

DISTRICT:_	CLAY	FACILITY	0013
FACILITY:	<b>CLAY HIGH SC</b>	HOOL	
-	2025 HIGHWAY		
	GREEN COVE	SPGS., FLO	RIDA 32043
INSPECTIO	N DATE: OCT	OBER 11, 20	11
[ad	Sweethon	<u> </u>	Oct 11, 2011
INSPECTO	R'S SIGNATURE		DATE


Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
7A	710	STORAGE TOO HIGH – 18" FROM CEILING		Х					<u></u>	NFPA 1-12.1
7A	717	STORAGE TOO HIGH 18" FROM CEILING		Х						NFPA 1-12.1
7A	722	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
7A	726	STORAGE TOO HIGH 18" FROM CEILING		X						NFPA 1-12.1
. 7A	727	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
7A	739	STORAGE TOO HIGH - 18" FROM CEILING		Х						NFPA 1-12.1
7B	748	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
7B	749	STORAGE TOO HIGH - 18" FROM CEILING		X						NFPA 1-12.1
7B	754	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
7B	760	STORAGE TOO HIGH 18" FROM CEILING		X						NFPA 1-12.1
8	801	EXIT LIGHT OUT @ FAR NORTH ENTRANCE		Х						FBC 1006.3.1

### FIRE SAFETY INSPECTION REPORT FOR EDUCATIONAL FACILITIES FLORIDA STATUTES 1013.12,1013.20 & RULE 69A-58

ANNUAL PERMANENT INSPECTION	1	ANNUAL RELOCATABLE INSPECTION	
FIRE DRILL LOG:	NUME	BER OF DRILLS PERFORMED:2_	

DISTRICT:_	CLAY	FACILITY:_	0013
FACILITY:	CLAY HIGH SC 2025 HIGHWAY GREEN COVE	16 WEST	RIDA 32043
INSPECTIO	N DATE: OCT	OBER 11, 20	)11
Tod	Sweathon		Oct 11, 2011
INSPECTO	R'S SIGNATURE		DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9	907	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
9	911	STORAGE TOO HIGH - 18" FROM CEILING		X						NFPA 1-12.1
9	916	STORAGE TOO HIGH – 18" FROM CEILING		Х						NFPA 1-12.1
9	921	STORAGE TOO HIGH - 18" FROM CEILING		X						NFPA 1-12-1
										A. A
										70



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	4.5	FACILITY: 0044	
· 10	4: 1 1	di Tere di C		


FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY FLEMING ISLAND, FLORIDA 32003

INSPECTION DATE: OCTOBER 18, 2011

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Ореі. "О	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rulė
1	183	BROKEN OUTLET COVER BY GALLERY		Х						NFPA 70-110.12
1	36	TV NOT SECURED TO BRACKET		X						69A-58
1	84	ELEVATOR MOTOR COVER REMOVED	Х							NFPA 70-110.12
1	165	COVER PLATE MISSING AT CEILING		Х						NFPA 70 110.12
1	147	EXTENSION CORD THROUGH CEILING/REMOVE		Х						NFPA 70 400.8
1.	146	BROKEN LENSE COVER		Х						NFPA 708 401.3
1	146	CEILING TILE MISSING		Х						FBC 804.2.3
1.	143	REPAIR DRYWALL CEILING	X							FBC 804:2.3
1	103	TWO TV'S NEED TO BE SECURED		Х						69A-58
1.	226	PROJECTORS WITH PLUG ABOVE CEILING			X					NFPA 70-110.12
1	222	PROJECTORS WITH PLUG ABOVE CEILING			Х					NFPA 70-110.12
1	225	PROJECTORS WITH PLUG ABOVE CEILING			X					NFPA 70-110.12
1	260	PROJECTORS WITH PLUG ABOVE CEILING			х					NFPA 70-110.12



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DICTRICT	CLAV	FACILITY.	0044	
DISTRICT	 ULAT	FACILII I.	 0044	

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY FLEMING ISLAND, FLORIDA 32003

INSPECTION DATE: OCTOBER 18, 2011

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	261	PROJECTORS WITH PLUG ABOVE CEILING			×					NFPA 70-110.12
1.5	265	PROJECTORS WITH PLUG ABOVE CEILING			X					NFPA 70-110.12
1	274	PROJECTORS WITH PLUG ABOVE CEILING			х					NFPA 70-110.12
1	275	PROJECTORS WITH PLUG ABOVE CEILING			X					NFPA 70-110.12
1	289	PROJECTORS WITH PLUG ABOVE CEILING			×					NFPA 70-110.12
1.0	290	PROJECTORS WITH PLUG ABOVE CEILING			X					NFPA 70-110.12
1	233	EMERGENCY EVACUATION SHEET MIWSING		х						FBC 423.14.2.4
1	256	STORAGE TOO HIGH		- X.						NFPA 1-12.1
1	279	SWITCH COVER MISSING		Х						NFPA 70-110.2
1	301	STORAGE TOO HIGH		X						NFPA 1-12:1
2	202	REMOVE EXTENSION CORD UP HIGH BY STAGE		Х						NFPA 70-400.B
2	202	REMOVE TV CABLES FROM FIRE HOSE CONNECTION		Χ						



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0044

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY FLEMING ISLAND, FLORIDA 32003

INSPECTION DATE: OCTOBER 18, 2011

MSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Pac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	204	REMOVE STORED PAINT		Х						NFPA 1
2	227	CEILING TILES MISSING		- X		110.00				FBC 804.2.3
2	262	REMOVE EXTENSION CORD; ADD OUTLET		Х						NFPA 70-400.8
2	255	CEILING TILE MISSING		X						FBC 804.2.3
2	267	EXCESSIVE STORAGE		Х						NFPA 101-14
. 10	1006	CHANGE SIGN TO READ EMERGENCY EXIT ONLY (DO NOT ENTER)		Χ						FBC 1006.3:1
10	1028	J-BOX COVER MISSING		Х						NFPA 70-110.12
10	1021A	GATE LOCKED/EXIT LIGHT OUT		X						FBC 23.20.1
10	1025	PLUG TO PROJECTOR ABOVE CEILING			x					NFPA 70-400.8
31	- 5	TOILET SEAT BROKEN		Х	2.2					
31	2/3	NOT SCHOOLS LOCKS – CHANGE		Х						
31	2/3	EXIT LIGHTS NOT WORKING (RIGHT)		X						FBC 1006.3.1
40	1	ANTS UNDER 3 COMPARTMENT SINKS		Х						

### FISCAL YEAR <u>2011-2012</u>



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0044
FACILITY: F	LEMING ISL	AND HIGH SCHO	OOL
		E SQUARE PAR	
	FLEMING ISL	AND, FLORIDA	32003
-			
INSPÉCTION	DATE: O	CTOBER 18, 201	1
INOI/LOTION	DAIL	OTOBLIC 10, 201	
$\mathcal{T}$	/ <sub>2</sub>		la carel
1 trall			10-18-11

INSPECTOR'S SIGNATURE

Building.	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Pac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
41	6	TOILET SEAT BROKEN/HANDICAPPED		Х						
1000					-		7.7			
							Z.F.			



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	:CLAY	FACILITY: 0044	
FACILITY	: FLEMING ISLAN	ID HIGH SCHOOL	
		SOLIARE PARKWAY	

FLEMING ISLAND, FLORIDA 32003

INSPECTION DATE: OCTOBER 18, 2011

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	10	ОК								
92	11	OK								
92	12	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	12	IMPROPER PROJECTOR		Χ						NFPA 70-400.8
92	13	IMPROPER PROJECTOR		Х						NFPA 70-400.8
92	13	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	14	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	15	PLUG ABOVE CEILING TO PROJECTOR			X					NFPA 70-400:8
92	20	ОК								
. 92	- 21	NO EMERGENCY EVADUATION SHEET		Х						FBC 423.14.2.4
92	22	ОК								
92	23	PLUG ABOVE CEILING TO PROJECTOR			X					NFPA 70-400.8
92	24	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-400.8



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

INSPECTION DATE: OCTOBER 18, 2011

2233 VILLAGE SQUARE PARKWAY FLEMING ISLAND, FLORIDA 32003

DISTRICT: CLAY FACILITY: 0044

FACILITY: FLEMING ISLAND HIGH SCHOOL

Dan I be	10-18-11
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac: "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	25	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-400.8
92 -	25	EMERGENCY LIGHT OUT		<b>X</b> -						FBC 423.17.1
92	27	MIRROR MISSING		Х						
92	27	CEILING TILE MISSING		X						FBC 804.2.3
92	30	EXTENSION CORD ACROSS EXIT PATH		Х						NFPA 101
92	- 31	EMERGENCY LIGHT OUT		X	1 P 1 P 1 P 1 P 1 P 1 P 1 P 1 P 1 P 1 P					FBC 423 17.1
92	32	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	33	OK								
92	34	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	35	OK .								
-92	40	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-400.8
92	41	OK								
92	42	ОК								



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

			4		and the second		
DISTRICT	•	CLAY	F	ACILIT	<b>Y</b> :	0044	
	***************************************	21,244				1 1	<u> </u>

FACILITY: FLEMING ISLAND HIGH SCHOOL
2233 VILLAGE SQUARE PARKWAY
FLEMING ISLAND, FLORIDA 32003

INSPECTION DATE: OCTOBER 18, 2011

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	43	ок								
92	44	OK								
92	45	PLUG ABOVE CEILING TO PROJECTOR			Х					NFPA 70-400.8
92	46	OK								
92	47	ок								
92	48	OK		1 1 1 1 1 1 1						
92	49	ок								
92	50	PLUG ABOVE CEILING TO PROJECTOR			X					NFPA 70-400.8
92	51	EMERGENCY LIGHT NOT WORKING		Х	L					FBC 423.17.1
92	52.	EMEGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	52	EXTENSION CORD ABOVE CEILING		Х						NFPA 70-400.8
92	52	IMPROPER PROJECTOR HANGER		- X						NFPA 101
92	52	TWO CEILING TILES MISSING		х						FBC 804.2.3



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:0044	<u> </u>
EACH ITV	ELERAINIC ISLA	AND HIGH SCHOOL	
FACILITY.			
	2233 VILLAGE	SQUARE PARKWAY	
	FI FMING ISLA	AND FLORIDA 32003	

INSPÉCTION DATE: OCTOBER 18, 2011

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I:S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	53	ОК								
. 92	61	OK								
92	71	ОК								
92	73 .	OK								
92	60	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
. 92	62	LOTS OF STANDING WATER		X						
92	63	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	64	OK								
92	70	RAMP BOUNCY; MISSING BOLT HALFWAY UP	X					:		
92	72	EMERGENCY LIGHT OUT		Χ-						FBC 4223.17.1
92	72	CEILING TILE MISSING IN CLOSET		Х						FBC 804.2.3
92	. 80	NO SMOKE DETECTOR IN CLOSET	X							NFPA 101:3
92	81	NO SMOKE DETECTOR IN CLOSET	Х							NFPA 101-13



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	<b>FACILITY</b> :0044
FACILITY:	FLEMING ISLA	ND HIGH SCHOOL
•	2233 VILLAGE	SQUARE PARKWAY
	FLEMING ISLA	AND, FLORIDA 32003

NSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def, Cited	Scheduled for Correction	Rule
92	81	MISSING CEILILNG TILE IN CLOSET		Х						FBC 804.2.3
. 92	82	OK								
92	83	COVER PLATE MISSING IN CLOSET		Х						NFPA 20-110.12
92	83	NO SMOKE DETECTOR IN CLOSET	X		4					NEPA 101-13
92	84	NO SMOKE DETECTOR IN CLOSET	х							NFPA 101-13
92	85	OK	10 To 10 To 20							
92	86	EXIT LIGHT MISSING AT RAMP DOOR	Х							FBC 423.17.1
. 92	87	FILING CABINET TOO CLOSE TO DOOR		X		t et sent				FBC 1004
92	90	ОК								
92	91	OK								
92	93	ОК								
92	95	OK								
92	96	ОК								



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:0044
FACILITY:	FLEMING ISL	AND HIGH SCHOOL
-		SE SQUARE PARKWAY
	****	LAND, FLORIDA 32003
INSPECTIO	N DATE: <u> </u>	CTOBER 18, 2011

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	87	ок								
92	. 92	CEILING DROOPS IN MIDDLE OF ROOM	X							69A-58
92	94	EXCESSIVE PAPER WALLS / CEILING		Х						69A-58
	SPANIS GARAGE		201000000000000000000000000000000000000			JPE-PARTE CONTROL OF CASE	Jaconerus sevesos	3040000 TVS	ny tropica. Normal rose and constitution	
				Land South Can			detherna e sauc	FOR CHARLES		
Decaded and State State St	and the second s				Index (1)	(Star 1)			ISS STATES STATES AND STATES	
227										



ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY F	FACILITY:	0011
------------------	-----------	------

FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL 2900 S.W. ORCHID AVENUE

**KEYSTONE HEIGHTS, FLORIDA 32656** 

INSPECTION DATE: OCTOBER 13, 2011

INSPECTOR'S SIGNATURE

0-/3-/1

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper: "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No∷of times Def. Cited	Scheduled for Correction	Rule
1	130	CEILING TILE OUT		Х						FBC 804.2.3
1//	143	CEILING TILE OUT		X						FBC 804.2.3
1	149	PROJECTOR OUTLET ABOVE CEILING			Х					NFPA 70 110.12
1	157	HOSE BIB NEEDS ANTI SYPH		X						
1	158	HOSE BIB NEEDS ANTI-SYPH		X						
1	163	CEILING TILES OUT		Х						FBC 804.2.3
1	164	CEILING TILES OUT		Х						FBC 804.2.3
1	172A	CEILING TILES OUT		X						FBC 804.2.3
1	172	ADD CEILING OUTLET	×							-
1.	190	MATERIAL STORED TOO CLOSE TO CEILING		X						NFPA 1-12-1
2	171	OPEN "J" BOXES THREE LOCATIONS	Х							NFPA 70-110.26
4	401	OPEN "ا" BOXES	Χ.							NFPA 70-110.26





### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

<b>FACILITY:</b>	KEYSTONE HEIGHTS HIGH SCHOOL	
	2900 S.W. ORCHID AVENUE	
	KEYSTONE HEIGHTS, FLORIDA 32656	

INSPECTION DATE: OCTOBER 13, 2011

| Aug | | 10 - | 3 - | |
INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
4	403	KNOCK OUTS OPEN ON ELECTRIC PANEL	X							NFPA 70-110.26
4	412	OPEN "J" BOX	X							NFPA 70-110.26
4	402	TYPICAL OF ALL STORAGE ROOMS; ALL MATERIAL STORED TOO CLOSE TO CEILING		Х						NFPA 70-110.26
5	509	MATERIAL STORED TOO CLOSE TO CEILING		X	######################################					NEPA 70-110.26
5	518	REMOVE PROPANE TANKS		X						NFPA 1.21.3.3.5
6		ALL STORAGE ROOMS - MATERIALS STORED TOO CLOSE TO CEILING		×						NFPA 70-110.26
7	700	EXIT LIGHT OUT	Х							FBC 1016.3.1
8		OK								
9	906	CEILING TILES MISSING		Х						FBC 802.3
9	906	LIGHT BURNED OUT		X	A. William					FBC 1016.3.1



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	CLAY	_ FACILITY:_	0011
FACILITY:	KEYSTONE HEI	<u> SHTS HIGH S</u>	CHOOL
	2000 S W OPCL	IID VAEVITE	

**KEYSTONE HEIGHTS, FLORIDA 32656** 

INSPECTION DATE: OCTOBER 13, 2011

SPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
20		FRONT AND REAR HOSE BIBS WITHOUT VACUUM BREAK		Х						
20	20	ENTRY LIGHT LOOSE	X							
20	2	OUTLET COVER MISSING		Х						NFPA 70 410.1.2
35	2	REMOVE PROPANE BOTTLE		X		2. 人。 中国建筑				NEPA 1:21.3.3.5
		The second of th								
							DVE SE			
			33.3.2.2.3.							
			ALL ALL MANUFACTURES		A TO THE PROPERTY OF THE PARTY	20.000			eministrativa (il distribution antibalistici di silatici), s	



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRIC	T: CLAY	FACILITY: 0011	
FACILITY	2900 S.W. O	HEIGHTS HIGH SCHOOL PRCHID AVENUE HEIGHTS, FLORIDA 32656	

INSPECTION DATE: OCTOBER 13, 2011

NSPECTOR'S SIGNATURE

10 77

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac.	Info. Serv. "I.S."	Cost	No. of times Def Cited	Scheduled for Correction	Rule
92	1	ОК								
92	2	ок								
92	3	ок								
92	4	OK								
92	5	ок								
92	6	OK								
92	7	ок								
92	8	OK								
92	. 9	ок								
92	10	ok								
92	11	ОК								
92	12	OK:								



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0011

FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL
2900 S.W. ORCHID AVENUE
KEYSTONE HEIGHTS, FLORIDA 32656

INS	PE	¢TIC	DHAC	AT	E:	OCTOBER 13, 2011

/NSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper: "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	13	ок .							·	
92	14	OK								
92	15	ОК						·		
92	16	ОК				avs.			STATES TANK	
92	17	ок								
92	18:	EMERGENCY LIGHT OUT		X						NEPA 101.7.9
92	19	ок								
92	20	LOOSE BOARDS ON RAMP	Х							FBC 1006
92	21	ок								
92	22	OK	740							
92	23	ок								
92	24	GAP AT END OF RAMP	X							FBC 1006



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:_	0011	
FACILITY:	KEYSTONE	HEIGHTS HIGH S	CHOOL	
	2900 S.W. C	ORCHID AVENUE		
	KEVETONE	HEIGHTS ELOPI	DA 32656	

INSPECTION DATE: OCTOBER 13, 2011

// 5//

Building	Room	Deficiency:Description and Corrective Action Required:	Maint: "M"	Oper: "O"	Fac. "G"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	25	PROJECTOR OUTLET ABOVE CEILING			Х					NFAP 70-400.8
92	25	SINK DRIPS	X							
. 92	25	HANDRAIL ON RAMP DOESN'T EXTEND TO LANDING	X							FBC 11
92	'26	NO EVACUATION SHEET		- X						FBC 423 14.2.4
92	27	HANDRAIL DOESN'T EXTEND TO LANDING	×							FBC 11
92	27	OUTLET FOR PROJECTOR ABOVE CEILING	X							NEPA-70-400.8
92	28	RAMP IN POOR CONDITION	Х							FBC 11
92	28	TOP STEP & STAIR	X							
92	29	POWER STRIP TO POWER STRIP		Х						NFPA 70-400.8
92	29.	SPEAKER WIRE ON FLOOR		×						NFPA 70 110.12



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0011
2.0	9-11		

FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL 2900 S.W. ORCHID AVENUE

**KEYSTONE HEIGHTS, FLORIDA 32656** 

INSPECTION-DATE: OCTOBER 13, 2011

rus //	10.13-11
PECTOR'S SIGNATURE	ĎАТЕ

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	50	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
.92	51	oK								
92	52	ok								
92	53	ROOF LEAK BY AC UNIT	Χ							
92	54	ок								
. 92	55	oK								
92	56	OUTLET FOR PROJECTOR ABOVE CEILING	Х							NFPA 70-400.8
92	.57	οK								
92	58	ок								
92	59	οK								
92	60	ок								
92	61	EMERGENCY LIGHT OUT	Χ							FBC 423,17.1



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0011

FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL 2900 S.W. ORCHID AVENUE

**KEYSTONE HEIGHTS, FLORIDA 32656** 

NSPECTION DATE:	OCTOBER 13, 2011
////	

INSPECTOR'S SIGNATURE

10-13-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Opër. "O"	Fác. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	61	LANDING DOOR TO LOW	X							
92	62	οK								
92	63	SECOND EXIT BLOCKED		Х						FBC 423.20.1
92	64	оK								
92	65	ок								
92 .	72	OK		Full Comment	7.20 to					
92	74	ОК								
92	76	OK'		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1						
92	78	ОК								
92	- 80	OK								
92	82	NO HEAT DETECTOR IN CLOSET	Х							
92	82	STORAGE TOO HIGH IN CLOSET		X						NFPA 1-12.1



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:_	0011						
			····						
FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL									
	2900 S.W. ORG								

**KEYSTONE HEIGHTS, FLORIDA 32656** 

INSPECTION DATE: OCTOBER 13, 2011

PECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	84	LIGHT AT RAMP OUT	Х							FBC 1006.1
92	90	OK								
92	91	ОК								
						·				



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY	FACILITY: 0019
--	----------------	----------------

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION	N DATE:	OCTOBER 20	, 2011

INSPECTOR'S SIGNATURE

1070-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	27	HOLE IN CEILING		Х						NFPA 101
1.3	-28	HOLE IN CEILING		Х						NFPA 101
1	49	EXTENSION CORD THROUGH CEILING		Х						NFPA 70-400.8
1	133	MISSING FIRE ALARM COVER	X							NFPA 70
1	134	EXHAUST FAN NOT WORKING	X							
1	111	WATER DAMAGED ABOVE CEILING	X							FBC 804.2.3
1	139	EXTENSION CORD ABOVE CEILING		Х						NFPA 70-400.8
1	142	EXTENSION CORD ABOVE CEILING		Х						NFPA 70-400.8
1	161	DIMMER SWITCH HOT	Х							NFPA 110
1	247	HOLE IN:CEILING		X						NFPA 101
1	241	POWER STRIP DAISY CHAINED		Х						NFPA 70-400.8
1	210	BATHROOM NOT FINISHED			X					
1	271	HOLE IN CEILING		Х						NFPA 101



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:	0019

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

INSPECTOR'S SIGNATURE

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 20, 2011

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "1.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	279	HOLE IN CEILING		Х						NFPA 101
1	281	HOLE IN CEILING		X						NEPA 101
1	281B	HOLE IN CEILING		Х						NFPA 101
1	285	OUTLET BOX BROKEN	X							NFPA 70 410.1.2
1	307	NO FIRE ALARM STROBE	×							
1	309	NO FIRE ALARM STROBE	X							
1	291A	HOLE FROM FIRE ALARM	Х							NFPA 101
1	301	HOLE IN CEILING	12 mg	X					and the same of th	NFPA 101
1	317	HOLE IN CEILING		X						NFPA 101
1	318	HOLE IN CEILING		Χ						NFPA 101
1	363	HOLE IN CEILING		Х						NFPA 101
1.5	366	HOLE IN CEILING		Χ						NEPA 101
1	372	HOLE IN CEILING		Х						NFPA 101
1.	371	HOLE IN CEILING		X						NEPA 101



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY: 0019
FACILITY: MIDDLEBURG	G HIGH SCHOOL
3750 C.R. 22	0
MIDDLEBUR	G. FLORIDA 32068

INSPECTION DATE: OCTOBER 20, 2011

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	001	SMOKE DETECTOR NOT FASTENED AT CEILING	Х							NFPA 1(03) 10.4.1
92	.001	STAIR NOT FASTENED TO BUILDING	X						THE STATE OF THE S	
92	5	ок								
.92	7	OK								
92	9	ок								
92	31	oK								
92	32	ок								
92	33	ЮK								
92	41	PROJECTOR NOT WIRED PROPERLY	Х							NFPA 70-110.12
92	34	OK								
92	35	ок								
92	36	OK								
92	42	ок								



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	_ FACILITY:_	0019
FACILITY:	MIDDLEBURG H	IIGH SCHOOL	
	3750 C.R. 220		
-	MIDDLEBURG	FLORIDA 320	38

INSPECTION DATE: OCTOBER 20, 2011

| Sery | 10 20-//
INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	43	Ok								2.00
92	44	PROJECTOR NOT WIRED PROPERLY	X							NFPA 70-110.12
92	45	ОК								
92	46	ОК				ight.				
92	47	PROJECTOR NOT WIRED PROPERLY	Х							NFPA 70-110.12
92	51	PROJECTOR NOT WIRED PROPERLY	X							NFPA 70-110.12
92	52	TEMPORARY WALL – REMOVE		Х						
92	53	PROJECTOR NOT WIRED PROPERLY	X							NFPA 70-110.12
92	54	ок								
92	55	EMERGENCY LIGHT OUT	X							NFPA:101.7.9
92	60	ок								
92	61	ок				24. 115.00 27.12 2.13				
92	62	ок								



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0019

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 20, 2011

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper "O"	Fac. "C"	Infö. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	63	ОК								
92	64	ОК								
92	65	ОК								
92	66 .	ок								
92	67	ОК								
92	69	ок								
92	70	ОК								
92	71	ОК								
92	72	ОК								
92	73	FRONT PANEL OFF DRY WALL	×			ya.				
92	73	EMERGENCY LIGHT OUT	X							NFPA 101.7.9
92	74	ŎΚ								
92	75	ОК								



**COMPREHENSIVE SAFETY & SANITATION** INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

> IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	_ FACILITY:_	0019	
FACILITY:	MIDDLEBURG H	IGH SCHOOL		

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 20, 2011

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	76	ОК								
92	77	OK								
92	78	COVER MISSING ON "J" BOX ABOVE ELECTRICAL PANEL	×							NFPA 70
92	79	OK								
92	80	ок								
92	81	OK								
92	82	HANDRAILS NEED TO EXTEND AT BASE	Х							
-92	. 83	OK								
92	84	ОК								
92	-85	HANDRAILS NEED TO EXTEND AT BASE	X							
92	87	ОК								

(8)	
	239/

### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: C	LAY	FACILITY:	0019						
	FACILITY: MIDDLEBURG HIGH SCHOOL									
	3750 C.R. 220 MIDDLEBURG, FLORIDA 32068									
59	INSPECTION D	APE: OCTO	DBER 20, 201	1						

INSPECTOR'S SIGNATURE

Info.
Serv. Cost times Scheduled Rule

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	88	ОК								
92	89	ОК								
							Visit			



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY F	FACILITY:	0052
------------------	-----------	------

FACILITY: OAKLEAF HIGH SCHOOL

4035 PLANTATION OAKS BOULEVARD ORANGE PARK, FLORIDA 32065

**INSPECTION DATE: NOVEMBER 1, 2011** 

INSPECTOR'S SIGNATURE

ATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper "O"	Fac: "E"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled för Gorrection	Rùle
1		STAIRWELL DOORS PROPPED OPEN		Х			•	,		FBC 1008.1.3.7
3	300	NO MAX. OCCUPANCY SIGN		×						FBC 423.14.2.2
3	300A	DOORS PROPPED OPEN	,	Х						FBC 1008.1.3.7
3	300B	DOORS SWING IN - ROOM USED AS A CLASSROOM NOW			X					
3	314H	CARDBOARD STORED IN ROOM CLEARLY MARKED "NO STORAGE."		Х						NFPA 1 -12-1.1
3	314	EXTENSION CORD ABOVE CEILING - REMOVE		X						
3	314	ADD OR MOVE EXTINGUISHER TO WITHIN 15 FT. OF STOVE		X				•		69A-58
3	340	LIGHT IN EXHAUST HOOD BURNED OUT		X						
5	530B	EXIT LIGHT OUT		Х					,	FBC 1006.3.1
5	521	PAINT STORED - MOVE TO BUILDING 6		X	75) 1/1 15) 10/1					
6	601	MOVE FLAMMABLE TO ROOM 602		X						FBC 1004



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0052	

FACILITY: OAKLEAF HIGH SCHOOL

4035 PLANTATION OAKS BOULEVARD

ORANGE PARK, FLORIDA 32065

INSPÉCTION DATE:	NOVEMBER 1, 20	)11
	1)	
Damy H		11-1-11
INSPECTOR'S SIGNA	TURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled för Correction	Rúle
6	1106	HEAT DETECTOR MISSING – COVER	X							NFPA 1
6	1103	HEAT DETECTOR MISSING - COVER	X						1	PE NEPA 1
6	1110	PROPANE GAS BOTTLES STORED IN BUILDING – REMOVE				·				NFPA 1.21.3.3.5
7	703A	PROPANE GAS BOTTLES STORED IN BUILDING = REMOVE		X						NEPA 1.21.3.3.5
				•						
					•					



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY: 0003
	FACILITY: ORANGE PARK HIGH SCHOOL  2300 KINGSLEY AVENUE  ORANGE PARK, FLORIDA 32073
19	INSPECTION DATE: OCTOBER 25, 2011

Building	Rōom	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rulé
1	180B	FIRE ALARM – ANNUNCIATOR PANEL NOT WORKING	×							NFPA-101.9.6
1	100	FIRE ALARM DETECTOR DAMAGED @ FIRE DOORS WEST OF MEDIA CENTER	X							NFPA 101-9:6
1	107	NO EMERGENCY EVACUATION SHEEET		Χ.						FBC 423.14.2.4
1	214	IMPROPER PROJECTOR HANGER - REMOVE & ADD PROPER CEILING MOUNT		Χ						
1	207	SIGN SAYS PULL STATION INSIDE BUT PULL STATION HAS BEEN MOVED -REMOVE SIGN		Х						
1	219B	EMERGENCY/LIGHT OUT "		X						FBC-423.17.1
1	233	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
1.	225	EXIT LIGHT OUT		X						FBC 423.17.1
1	- 229	EXTENSION CORD ABOVE CEILING-REMOVE		Х			-			NFPA 70 400.8
11	221	EXTENSION CORD ABOVE CEILING-REMOVE		X		is it is				NEPA 70 400.8
1	227	EXTENSION CORD ABOVE CEILING-REMOVE		Х						NFPA 70 400.8



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY: 0003
	FACILITY: ORANGE PARK HIGH SCHOOL  2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	•
<del>5</del> 9	INSPECTION DATE: OCTOBER 25, 2011
	1100 -1) 0-0

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper.	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	228	EXTENSION CORD ABOVE CEILING-REMOVE		Х		:				NFPA 70 400.8
1	226	MAGNETIC DOOR CLOSER SCREW MISSING		X						
1	224	CEILING TILE MISSING		Х						FBC 804.2.3
1	229	FAUCET NOT SECURED TO SINK		Х						
1	254	CEILING NEEDS REPAIR	X							
2	4	STORED MATERIAL TOO CLOSE TO CEILING		×						NFPA 1-12:1
3		ок								
4	5	OPEN ELECTRICAL J-BOX IN CEILING	×							NFPA 70-110.26
4	5	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
4	17C	EMERGENCY LIGHT OUT	a Lind	Χ		1				FBC 423.17.1
4	19B	FIRE ALARM PANE NOT CERTIFIED	Х							NFPA 72-10.6.2
4	17C	LIGHT FIXTURE COVER MISSING	77-1457 (and 17) 13 (2) (3) (3)	Х	il i diana	CAGAN Tagan				NEPA 70-410.85
4	19B	FIRE ALARM PANEL NOT CERTIFIED	Х							NFPA 72 10.6.2



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY:_	0003
----------------	------------	------

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

**ORANGE PARK, FLORIDA 32073** 

INSPECTION DATE: OCTOBER 25, 2011

NSPECTOR'S SIGNATURE

Oct 25, 2011

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Орет. "О"	Pac. °C'	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rulė
4	15	BULBS NOT PROTECTED		Х						NFPA 70-410.8.5
4	13	SWITCH BROKEN		X						NEPA 70 110.12
4	19C	EXTERIOR HOSE BIBBS NEEDS VACUUM BREAK		Х						FPC 300
10	-100	MAX OCCUPANCY SIGN MISSING		X						FBC 423.14.2.2
10	116	REMOVE FLAMMABLE FROM STAGE		Х						
10	122	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
10	103	EMERGENCY LIGHT OUT		Х				•		FBC 423.17.1
10	104	EMERGENCY LIGHT OUT		Х						FBC 423:17:1
12		FIRE EXTINGUISHER NOT SIGNED		Х						69A-58
12	112	NO SIGNS ON RESTROOM DOORS		X						FBC 423.14.2.3
12	132	IMPROPER STORAGE IN ELECTRIAL/MECHANICAL ROOM		Х						NFPA 1
12	135	NO EVACUATION SHEET		Χ						FBC 423:14.2.4
12	141	NO EVACUATION SHEET		Х						FBC 423.14.2.4



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY: 0003
FACILITY: ORANGE PARK HIGH SCHOOL 2300 KINGSLEY AVENUE ORANGE PARK, FLORIDA 32073
INSPECTION DATE: OCTOBER 25, 2011

INSPECTOR'S SIGNATURE

Oct 25, 2011 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
16		ОК								
.18	A STATE OF THE STA	OK						Fr 1180 (20)		
21		ОК								
27		NO BULB PROTECTION	e wit die	Х						NFPA 70-410.85
27	6	PAINT IN CLASSROOM CLOSET – REMOVE		Х						NFPA 1
27	8	PAINT IN CLASSROOM CLOSET — REMOVE		X						NFPA 1
24		NO EMERGENCY EVACUATION SHEET								FBC 423.14.2.4
24	26	BROKEN GLASS @ DOOR	Χ							
24	1	CEILING PANEL LOOSE	Х							FBC 804 2.3
41	1	EMERGENCY LIGHT OUT		X						FBF 423.17 1
41	1 .	GAS CANS STORED IN BUILDING – REMOVE		Х						NFPA 1
41	1.	GAS POWERED TRENCHER - REMOVE		Х						NFPA 1
41	1	GAS CANS/EQUIP – REMOVE		Х						NFPA 1



### **COMPREHENSIVE SAFETY & SANITATION** INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CL/	\Y F	ACILITY:	0003
		KINGSLEY A	VENUE	
	ORA	NGE PARK, F	LORIDA 320	773
3	INSPECTION DA	TE: OCTOE	BER 25, 2011	
1.	Joel Su	really		201.25,201
	INSPECTOR'S SI	GNATURE		ATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Gost	No. of times Def. Cited	Scheduled for Correction	Rule
41	2	TOILET LEAKING ON FLOOR – NO VACUUM BREAK.HOSE BIB UNDER SINK	х							
.51	12	EMERGENCY LIGHT BROKEN		Х						FBC 423.17.1
51	13	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
51	17	REMOVE PADLOCK FROM EXIT DOOR		X						FBC 1001
51	17	PLUMBING PIPE BROKEN ON TOP OF WALL	×							
51	21	EMERGENCY LIGHT BROKEN		X						FBC 423.17:1
SOMenskovski vasa.	and the state of the state of									
				154 3 (24) 154 3 (24)						
									**************************************	
Silvener landest ver 19		the state of the s					٠.			

DATE



### **COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT** STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLA	Y FACILIT	Y: 0003	_							
	FACILITY: ORANGE PARK HIGH SCHOOL										
	2300 KINGSLEY AVENUE ORANGE PARK, FLORIDA 32073										
			<u> </u>	-							
7	INSPECTION DA	TE: OCTOBER 25,	2011	_							

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	13	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	35	ÖK:								
92	35	ОК								
92	37	EMERGENCY LIGHT OUT		Χ						FBC 423.17.1
92	38	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
.92	39	ÖK								
92	40	OK .								
92	45	ОК								
92	51	ОК								
92 '	52	OK								
92	56	ОК							-	
92	60	ΘK								
92	61	ОК								



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY: 0003
	FACILITY: ORANGE PARK HIGH SCHOOL  2300 KINGSLEY AVENUE  ORANGE PARK, FLORIDA 32073
7	INSPECTION DATE: OCTOBER 25, 2011

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
. 92	62	ОК				17	0122 47 310			
92	63	ΘK								
92	64	ОК								
92	- 65	ОК				型规则				
92	48	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	50	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	53	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	54	PROJECTOR INSTALLED INCORRECTLY		X						NFPA 70
92	54	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
92	55	EMERGENCY LIGHT OUT		Х						FBC 423.14.2.1
96	58	OK - RESTROOMS		Х						
.92	-59	EXCESSIVE PAPER ON WALLS		Х			i de la companya de l			NFPA 101
92	66	TRIP HAZARD AT BASE OF RAMP	Х							FBC 1005
92	67	ÉMERGENCY LIGHT OUT		X						FBC 423.17.1



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

Administrative rules S.R.E.F. - Chapter 5
"Casualty Safety & Sanitation Inspection"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0022
------------	------	------------	------

FACILITY: RIDGEVIEW HIGH SCHOOL


466 MADISON AVENUE

**O9RANGE PARK, FLORIDA 32043** 

INSPECTION DATE: OCTOBER 28, 2011

Newford 1028-11
INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	64	HEAT DETECTOR LOOSE IN CEILING	Х							NFPA 1-10.4.1
1	124	STAINED CEILING TILE	Sign.	Χ.						FBC 804.2.3
1	135	EXIT LIGHT OUT	X							FBC 1006.3.1
1	157	DOOR BROKEN	X		7.1					
1	149	PROJECTOR PLUG ABOVE CEILING	X							NFPA 70-110.2
1	149	EXIT LIGHT OUT	X							FBC 1006.3.1
2	204	LIGHT SWITCH BROKEN	×							NFPA 70
2	201	OPEN ELECTRICAL BOX	Χ							NFPA 70 110.26
2	207	FIRE ALARM BOX/COVER MISSING	X							NFPA 70 110.26
2	234	OPEN ELECTRICAL BOX	×				14. 15. 14. 17. 14. 18. 17. 15. 14. 11. 14.			NFPA 70 110.26
2	201	BROKEN GLASS IN DOOR	,		,					
. 2	220	EXCESSIVE MATERIAL STORED		Х						NEPA 70 110.26
2	216	LENS COVER MISSING		Х						NFPA 708 401.3



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	<b>FACILITY</b> :0022
	DIDOEVIEW	HIGH SOURCE
FACILITY:	RIINTEVIEW	HIGH SCHOOL
FACILITY: _	466 MADISC	HIGH SCHOOL  ON AVENUE

INSPECTION DATE: OCTOBER 28, 2011

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info: Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Řule
2	211	EXTERIOR DOOR – DEADBOLT; CANNOT UNLOCK FROM INSIDE	Х				: .			NFPA 14.5.2
2	215	DOOR HANDLE BROKEN	Х							
2	211	CEILING TILES MISSING		Х						FBC 804.2.3
3	302	MOLD ON CEILING		X						
3	309	MATERIAL STORED TOO HIGH		Х						NFPA 13.8.5.5.3
3	307	CEILING VENT COVER MISSING	×							
3	313	CEILING TILES MISSING		Х						FBC 804.2.3
3	315	CEILING TILES MOLDY		Х						
3	315	SWITCH_COVER MISSING		Х						NFPA 70
3	320	CEILING TILE STAINED		X	Tall the best of the second of					FBC 804:2.3
3	326	LIGHT BULB EXPOSED	Х							NFPA 708 401.3
3.	332	EXPOSED WIRES	Χ			1.174 1.174	nin yangi y			NEPA 70-312.5
3	329	OUTLET COVER MISSING		Х						NFPA 70 410.1.2



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0022

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

O9RANGE PARK, FLORIDA 32043

INSPECTION DATE: OCTOBER 28, 2011

INSPECTOR'S SIGNATURE

1028.11

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	333	NO EMERGENCY EVACUATION SHEET		· X						FBC 423.14.2.4
3	340	GEILING TILES MISSING		X						FBG 804.2.3
3	347	CEILING TILES STAINED		Х						FBC 804.2.3
3	346	CEILING TILES MISSING		X						FBC 804.2.3
5	502	EXIT LIGHT BROKEN	X :							FBC 1006.3.1
5'	501	STAINED CEILING TILES	X							FBC 804.2.3
5	509	PROJECTOR OUTLET ABOVE CEILING	, X							NFPA 70-110.2
5	510	CLEAN OUT - COVER MISSING	Х							NEPA 70
5	528	NO EMERGENCY EVACUATION SHEET	-	Х						FBC 423.2.4
5	530	PROJECTOR OUTLET ABOVE CEILING	X							NEPA 70-110.2.4
5	530	TWO OUTLETS WITHOUT COVER	Х							NFPA 70
5	530	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
5	534	STAINED CEILING TILE		: X :						FBC 804.2.3



## COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0022	
FACILITY:	RIDGEVIEW H	IIGH SCHOOL		
	AGE MADISON	LAVENHE		

**O9RANGE PARK, FLORIDA 32043** 

NSPECTION DATE: OCTOBER 28, 2011

INSPECTOR'S SIGNATURE

1000

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "О"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	540	VINYL BASE MISSING	X							
5	544	ALL POWER STRIPS LOOPED TOGETHER		Χ						NFPA 70 400.8
5	544	CLEAN AIR FILTERS		Х						
6	633	CEILING TILES MISSING		X						FBC 804.2.3
6	605	LIGHT OUT		Х						FBC 1006.3.1
6	612	BROKEN SWITCH COVER		X						NFPA 70-410.12
6	630	OPEN ELECTRICAL BOX	Х							NFPA 70
6	630	ROOF LEAK	×							
6	638	DRINKING FOUNTAIN OUT OF ORDER	Х							
6	689	NO EMERGENCY EVACUATION SHEET		X					・ 開発する場合。 は高速度は2000と	FBC 423.14.2.4
6	697	TOILET OUT OF SERVICE	X.							
6	679	PROJECTOR OUTLET ABOVE CEILING	Χ					7.13 (a. 7.1		NFPA 70-110.2.4
6	668	BROKEN LENS ON LIGHTS		Х						NFPA 708 401.3



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

ַוטואונטו:	CLAT	FACILITY	0022	
FACILITY:	RIDGEVIEW HIG	SH SCHOOL		
	466 MADISON A	AVENUE		
	OODANCE DAD	K ELODIDA	22042	

INSPÉCTION DATE: OCTOBER 28, 2011

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
6	667	CEILING TILE MISSING		Х	·					FBC 804.2.3
7	714	NO EVACUATION SHEET		X						FBC 423.14.2.4
7	710	MOLD IN CEILING TILE		Х						FBC 804.2.3
8	801	STAINED & MISSING CEILING TILE		X						FBC 804.2.3
8	828	FOUR WHEELER STORED IN MECHANICAL ROOM		Х						NFPA 1
9	903	FIRE EXTINGUISHER MISSING		Χ						NFPA 1(03) 13.6.3.6
9	904	LOCK MISSING SCREWS		Х						
9	924	SWITCH PLATE COVER BROKEN		Χ			na in La secona di la	· included and the control of the co		NFPA 70
9	924	LENS COVER MISSING		Х						NFPA 708 401.3
9	938	ÇELINĞ TILE MISSING		. X						FBC 804.2.3
9	950	LIGHT OUT - NO EMERGENCY LIGHT	Х							FBC 423.17.1
9	930	EMERGENCY LIGHT OUT	X							FBC 423.17.1
9	928	SWITCH COVER MISSING		Х						NFPA 70



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:_	0022
FACILITY:	RIDGEVIEW HIG	H SCHOOL	
	466 MADISON A	VENUE	
	O9RANGE PAR	K FLORIDA 3	2043

INSPECTION DATE: OCTOBER 28, 2011

INSPECTOR'S SIGNATURE

10-28-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9	914	OUTLET COVER MISSING		X						NFPA 70
10	1012	REMOVE TV BRACKET		X	±.,					
10	1008	J-BOX OPEN		Х						NFPA 70
10	1008	CEILING TILE MISSING		Х						FBC 804.2.3
10	1006	IMPROPER PROJECTOR BRACKET	Χ .							
10	1,004	CEILING TILE MISSING		X						FBC 804.2.3
. 10	1017	FLOOR TILE BROKEN		X						
. 10	1072	LADIES RESTROOM NEEDS SIGN	Χ.							



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILIT	Y: 0022					
FACILITY:	RIDGEVIEW HIGH	H SCHOO	)I					
	FACILITY: RIDGEVIEW HIGH SCHOOL  466 MADISON AVENUE							
	O9RANGE PARK	, FLORID	A 32043					
INSPECTIO	N DATE OCTO	RFR 28	2011					

INSPECTOR'S SIGNATURE

10-28-/1 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	ОК								
92	2	OPEN JUNCTION BOX @ ENTRY	X							NEPA 70
92	3	OK								
92	'4	EMERGENCY LIGHT OUT	×							FBC 423:17:1
, 92	. 5	ОК								
92	6	OK								
92	7	ОК								
92	8.	OK								
92	9	PROJECTOR NOT WIRED PROPERLY	Х							NFPA 70-110.2.4
92 .	10	OK								
92	11	ОК								
92	12	EMERGENCY LIGHT OUT	Χ							FBC 423:17:1



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY: 0022
----------------	----------------

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

**O9RANGE PARK, FLORIDA 32043** 

INSPECTION	ON DATE:	OCTOBER	28, 201	1

INSPECTOR'S SIGNATURE

1028.11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	13	LENS COVER MISSING ON LIGHTS		Х						NFPA 708 401.3
92	14	OK					1. j			
92	21	ОК								
92	22	OK								
92	23	ок								
.92	24	OK		-						
92	25	PROJECTOR NOT WIRED PROPERLY	Х							NFPA 70-110.2.4
92	26	OK		400		11 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
92	27	ок								
92	28	ΟĶ	1	e e e e e e e e e e e e e e e e e e e						
92	29	ок								
92	30	οK					72.1 1.1 1.2 1.3 1.3 1.3 1.3 1.3 1.3 1.3 1.3 1.3 1.3			
92	31	ок								



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0022	
FACILITY:	RIDGEVIEW HIG 466 MADISON A			
	<b>O9RANGE PAR</b>	K, FLORIDA 3	32043	

INSPECTION DATE: OCTOBER 28, 2011

/ Vicef / Linspector's SIGNATURE

10.28-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper "O"	Fac. "G"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	32	ОК								
92	33	ÖK								
92	34	ок								
92	41	οK								
92	42	ОК								
92	43	OK								
92	44	OK								
92	45	OK								
92	46	OK ·								
92	47	OK								
92	48	ок								
92	49	PROJECTOR NOT WIRED PROPERLY	X							NFPA 70-110.2.4
92	50	EXCESSIVE MATERIAL ON WALLS		X						NFPA 70 110.26



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY:_	0022
----------------	------------	------

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

O9RANGE PARK, FLORIDA 32043

INSF	ÆCTI.	ÒΝ	DATE:	OCTOBER	28,	2011

ECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac: "C"	Info: Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	51	ок								
92	52	OK								
92	53	ОК								
92	54	OK								· · · · · · · · · · · · · · · · · · ·
92	61	ОК	,							
92	62	OK								
92	63	EMERGENCY LIGHT OUT	×							FBC 423.17.1
92	64	ÖK								
92	65	ок								
92	66	OK								
92	67	ОК								
92	68	PROJECTOR WIRED IMPROPERLY	X			24 13 6 A		7.17		NFPA 70-110.2.4
92	68	ACCESS TO ELECTRICAL PANEL		Х						NFPA 70 110.26
92	69	OK					in a superior			



### COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	_ FACILITY:_	0022	
FACILITY:	RIDGEVIEW HI			

**O9RANGE PARK, FLORIDA 32043** 

INSPECTION DATE: OCTOBER 28, 2011

ECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	70	ок								
92	71	ÖK								
92	72	ОК								
92	73	OK								
92	74	EMERGENCY LIGHT OUT	Х							FBC 423.14.2.3
92	81	OK								
92	82	PROJECTOR WIRED IMPROPERLY	Х							NFPA 70-110.2.4
92	83	PROJECTOR WIRED IMPROPERLY	Х							NFPA 70-110.2.4
92	84	PROJECTOR WIRED IMPROPERLY	X							NFPA 70-110.2.4
92	85	ОК								
92	86	ок								
92	87	ок								
92	88	ОК	,							



# COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:_	0022
FACILITY:	RIDGEVIEW I	HIGH SCHOOL	
_	466 MADISO	N AVENUE	
•	OORANGE P	ARK, FLORIDA	32043

INSPECTION DATE: OCTOBER 28, 2011

Type 10:28-1/
INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	89	PROJECTOR WIRED IMPROPERLY	Х							NFPA 70-110.2.4
.92	90	ОК								
92	92	ОК								
92	92	ОК								
92	101	ОК								
92	102	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	103	PROJECTOR WIRED IMPROPERLY	×							NFPA 70-110.2.4
	·									
			i	,						