


ORANGE PARK

JUNIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
 1500 GANO AVENUE
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: JANUARY 24, 2006

Darryl H. Brown
 INSPECTOR'S SIGNATURE

DATE: 1-24-06

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "G" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|----------------|
| 1 | 122 | OCCUPANCY LOAD SIGN MISSING | | X | | | | | | FBC 423.14.2.2 |
| 1 | 179 | OCCUPANCY LOAD SIGN MISSING | | X | | | | | | FBC 423.14.2.2 |
| 2 | 215 | EXIT LIGHT LOOSE | | X | | | | | | |
| 3 | *** | ANTI-SYPHON DEVICE MISSING ON HOSE BIBS | | X | | | | | | |
| 3 | *** | ANTI-SYPHON DEVICE MISSING ON HOSE BIBS | | X | | | | | | |
| 3 | 317A | LENS COVER MISSING | | X | | | | | | |
| 4 | *** | MISSING ANTI-SYPHON DEVICE | | X | | | | | | |
| 4 | 465 | ROOF LEAK | X | | | | | | | |
| 4 | 458 | EMERGENCY EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 5 | 501 | EMERGENCY LIGHT OUT/HANGING | | X | | | | | | FBC 1016.3.1 |
| 5 | 522 | EMERGENCY LIGHT OUT/HANGING | | X | | | | | | FBC 1016.3.1 |
| 5 | 517A | EMERGENCY LIGHT OUT/HANGING | | X | | | | | | FBC 1016.3.1 |
| 6 | 610 | EXTENSION CORDS RUN THROUGH DOORWAY | | X | | | | | | NFPA-70 800-4 |

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
 1500 GANO AVENUE
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: JANUARY 24, 2006

INSPECTOR'S SIGNATURE: *Darryl J. Swanson* DATE: 1-24-06

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|-----------------------|------|--------------------|--------------------------|------|
| 92 | 501 | OK | | | | | | | | |
| 92 | 508 | OK | | | | | | | | |
| 92 | 510 | OK | | | | | | | | |
| 92 | 513 | OK | | | | | | | | |
| 92 | 703 | OK | | | | | | | | |
| 92 | 704 | OK | | | | | | | | |
| 92 | 705 | OK | | | | | | | | |
| 92 | 715 | OK | | | | | | | | |
| 92 | 716 | OK | | | | | | | | |
| 92 | 717 | OK | | | | | | | | |
| 92 | 718 | OK | | | | | | | | |
| 92 | 720 | OK | | | | | | | | |
| 92 | 721 | OK | | | | | | | | |
| 92 | 722 | OK | | | | | | | | |

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT CLAY FACILITY # 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1500 GANO AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: JANUARY 24, 2006

INSPECTOR'S SIGNATURE [Signature] DATE 1-24-06

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|--------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|--------------|
| 92 | 723 | OK | | | | | | | | |
| 92 | 724 | OK | | | | | | | | |
| 92 | 725 | OK | | | | | | | | |
| 92 | 726 | OK | | | | | | | | |
| 92 | 503 | CABINET IN FRONT OF ELECTRIC PANEL | | X | | | | | | NFPA-70 |
| 92 | 504 | RAMP HAS SOME LOOSE BOARDS | X | | | | | | | FBC 11-8.4 |
| 92 | 505 | RAMP DAMAGED AT LANDING - LEANING | X | | | | | | | |
| 92 | 505 | CEILING NEEDS SOME REPAIR | X | | | | | | | FBC 804.2.3 |
| 92 | 507 | FIRE EXTINGUISHER NOT BY THE EXIT | | X | | | | | | 69S-36 |
| 92 | 509A/B | STAIRS IN POOR SHAPE | X | | | | | | | |
| 92 | 511 | FIRE EXTINGUISHER NOT BY EXIT | | X | | | | | | 69A-36 |
| 92 | 512 | CEILING PEELING | X | | | | | | | |
| 92 | 514 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 514 | DOOR HANDLE BROKEN | X | | | | | | | |

FISCAL YEAR 2005-2006

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1500 GANO AVENUE
ORANGE PARK, FLORIDA 32073


INSPECTION DATE: JANUARY 24, 2006

INSPECTOR'S SIGNATURE: *David L. Brown* DATE: 1-24-06

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|---------|--|------------|-----------|----------|--------------------|------|-------------------------|--------------------------|--------------|
| 92 | 515 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | |
| 92 | 516 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 516 | GLOBES MISSING ON LIGHT FIXTURE | | X | | | | | | |
| 92 | 702 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 706 | NO FIRE EXTINGUISHER BY COOK TOP | | X | | | | | | 69A-36 |
| 92 | 707/A/B | EMERGENCY LIGHT NOT IN "B" SIDE | | X | | | | | | FBC 423.17.1 |
| 92 | 708 | NO FIRE EXTINGUISHER BY COOK TOP | | X | | | | | | 69A-36 |
| 92 | 709 | RAMP SETTLE/MISSING SPINDLE | X | | | | | | | 69A-36 |
| 92 | 710 | NO FIRE EXTINGUISHER BY COOK TOP | | X | | | | | | |
| 92 | 711 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 92 | 712 | NO FIRE EXTINGUISHER BY COOK TOP | | X | | | | | | 69A-36 |
| 92 | 719 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| | **** | REPLACE WOOD RAMPS TO MEET ADA REQ. | X | | | | | | | FBC 4.9.4 |

WILLKINSON

JUNIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION
INSPECTION" IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY #: 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
5025 C.R. 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 26, 2006

Tom Swadlow
INSPECTOR'S SIGNATURE

Jan 26, 2006
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|--------------------------|------|-------------------------------|--------------------------------|--------------|
| 2 | 211 | EXIT LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 2 | 211 | COVER MISSING ON J BOX, NW DOOR | X | | | | | | | |
| 2 | 220 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 2 | 220 | COVER MISSING ON ENTRY LIGHT | X | | | | | | | |
| 3 | 301 | OCCUPANCY SIGN MISSING | | X | | | | | | FBC 1004.3 |
| 3 | 311 | DOOR SWING, CLASSROOMS NOT BY DESIGN | | | X | | | | | |
| 4 | 407 | EMERGENCY EVACUATION SIGN MISSING | | X | | | | | | |
| 6 | 600 | EXIT LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 9 | 901B | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 9 | 906B | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 9 | 906B | ROOM NUMBER 901 SHOULD BE 906B | | X | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
 5025 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 26, 2006

INSPECTOR'S SIGNATURE: *Ted Spivey*
 DATE: *Jan 26, 2006*

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|--------------------------|------|-------------------------------|--------------------------------|--------------|
| 92 | 2 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 2 | FIRE EXTINGUISHER MISSING | | X | | | | | | |
| 92 | 3 | OK | | | | | | | | |
| 92 | 4 | OK | | | | | | | | |
| 92 | 5 | OK | | | | | | | | |
| 92 | 6 | HOLES IN EXTERIOR WALL AT RAMP | X | | | | | | | |
| 92 | 7 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 7 | AV CORD RUNNING OVERHEAD | | | X | | | | | |
| 92 | 8 | OK | | | | | | | | |
| 92 | 9 | OK | | | | | | | | |
| 92 | 10 | OK | | | | | | | | |
| 92 | 11 | GLOBE IN CLOSET MISSING | X | | | | | | | |
| 92 | 12 | OK | | | | | | | | |
| 92 | 17 | OK | | | | | | | | |

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
 5025 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 26, 2006

Paul Sw-cattone
 INSPECTOR'S SIGNATURE

Jan 26, 2006
 DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|--------------------------|------|-------------------------------|--------------------------------|----------------|
| 92 | 18 | OK | | | | | | | | |
| 92 | 21 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 21 | EVACUATION SHEET MISSING | | X | | | | | | FBC 423.14.2.4 |
| 92 | 22 | OK | | | | | | | | |
| 92 | 23 | OK | | | | | | | | |
| 92 | 24 | OK | | | | | | | | |
| 92 | 25 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 26 | OK | | | | | | | | |
| 92 | 27 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 30 | OK | | | | | | | | |
| 92 | 40 | OK | | | | | | | | |
| 92 | 41 | OK | | | | | | | | |
| 92 | 42 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 92 | 43 | OK | | | | | | | | |

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION
 INSPECTION" IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
 5025 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 26, 2006

1-26-06

INSPECTOR'S SIGNATURE DATE

[Handwritten Signature]

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|-----------------------|------|-------------------------|--------------------------|-----------|
| 92 | 45 | OK | | | | | | | | |
| 92 | 46 | OK | | | | | | | | |
| 92 | 48 | OK | | | | | | | | |
| 92 | 96 | OK | | | | | | | | |
| | **** | REPLACE WOOD RAMPS TO MEET ADA REQ. | X | | | | | | | FBC 4.9.4 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |