SCHOOL DISTRICT OF CLAY COUNTY CHANGE ORDER NO. __4_

SDCC PROJECT NAME:	Middleburg	Elementary	School	Building	1	Remodel
SDCC PROJECT NO: <u>C-25</u>	i-09/10					
The Owner authorized the March 17, 2011.	Contractor to r	make the follow	ving chang	ge(s) in the	e con	tract dated
REVISED CONTRACT		DRIGINAL CON PREVIOUS CH				549,400.00 501,077.68
Change(s) and reason(s) for and valley repair – see attack	-	Order: <u>Drywall</u>	, tile, isola	tion valves	, roof	sheathing,
Additional Time needed for Completion date is October 2	this Change O 25, 2011. Fina	rder is <u>six (6)</u> Completion da	calendar o ite is <u>Nove</u>	days. Con mber 24, 2	tract <u>011</u> .	Substantial
For these changes: Add to the Contract the sum of: Fou						
	CURR	ENT CONTRA	IUOMA TO	NT:	\$50	01,077.68
	ADDIT	ION TO CONT	RACT:	National		14,291.00
	DEDU	CTION TO CO	NTRACT:	Terror dista	·	\$0.00
	REVIS	ED CONTRAC	T AMOUN	T:	\$51	15,368.68
ARCHITECT/ENGINEER CI Architect/Engineer, the price the proper ratio to the cost of	s quoted in thi	s Change Orde	er are both	fair and re	eason	able and in
Signature: Architect/Engin		the	Da	ate: <u>8 </u>	31-1	<u>-</u>
By execution of this Chang compensation and time have the work identified in this Ch	e been resolve					
ACCEPTED: Signature:	ontractor		Da	ate: 🔗 . 🥏	31.	//_
Signature: S	Buce DCC Project M	<i>COliv</i> anager	Da	ate: <u>& - 3</u>	1-1,	<u>!</u>
APPROVED: Signature:	sheel Board Cl		Da	ate:		
MIS15010	chool Board Cl	iairman				

SCHOOL DISTRICT OF CLAY COUNTY CHANGE ORDER #4

SDCC PROJECT NAME: Middleburg Elementary School Building 1 Remodel

SDCC PROJECT NUMBER: C-25-09/10

ADDITIONAL INFORMATION

The additive changes are for:

1.	Remove existing plaster/ceramic tile in rooms 112 and 125 and install new drywall. The original intent was to keep the existing tile and drywall in place, however, this is not feasible with the demolition of plumbing and walls in the immediate area.	\$5,	360.00
2.	Install new tile wainscot in rooms 112 and 125. The original intent was to keep the existing tile and drywall in place, however, this is not feasible with the demolition of plumbing and walls in the immediate area.	\$4,	413.00
3.	Install isolation valves to isolate break room sink and refrigerator.	\$	352.00
4.	Replace rotten roof sheathing.	\$3	,200.00
5.	Repair damaged valley at Main entrance.	<u>\$</u>	966.00

\$14,291.00

Addition of six (6) days to the Contract.

TOTAL CHANGE ORDER AMOUNT:

A time extension is required for additional labor to complete these changes.