


Bowling

Learning Goals





FISCAL YEAR 2007-2008

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**

DISTRICT: CLAY FACILITY #: 0003

FACILITY: BANNERMAN LEARNING CENTER
608 MILL STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 8, 2007

Dawlett Burton
INSPECTOR'S SIGNATURE

11-8-07
DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		OK								
2		OK								
3		OK								




FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0003

FACILITY: BANNERMAN LEARNING CENTER
608 MILL STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 8, 2007


 INSPECTOR'S SIGNATURE 11-8-07
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	OK								
92	2	OK								
92	3	OK								
92	4	OK								
92	5	OK								
92	6	OK								
92	7	OK								
92	8	OK								
92	9	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11-4.8
92	10	OK								
92	11	OK								
92	12	OK								
92	13	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11-4.8
92	14	OK								



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
 COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY # 0003

FACILITY: BANNERMAN LEARNING CENTER
 608 MILL STREET
 GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 8, 2007

Samuel H. Brown
 INSPECTOR'S SIGNATURE DATE 11-8-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	30	OK								
92	31	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11-4.8
92	32	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11-4.8
92	33	OK								
92	34	OK								
92	35	OK								
92	36	OK								
92	37	OK								
92	38	OK								
92	39	OK								
92	40	OK								
92	42	OK								
92	43	OK								
92	50	OK								



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0003

FACILITY: BANNERMAN LEARNING CENTER
608 MILL STREET
GREEN COVE SPRINGS, FLORIDA 32043


INSPECTION DATE: NOVEMBER 8, 2007

[Signature]
 INSPECTOR'S SIGNATURE DATE 11-8-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	52	OK								

Green Gate Springs

Junior High School





FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: _____

FACILITY: GREEN COVE SPRINGS JUNIOR HIGH SCHOOL
1220 BONAVENTURE AVENUE
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 7, 2007

INSPECTOR'S SIGNATURE: *Dewalt Jura* DATE: 11-7-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	27	DOOR STICKS	X							NFPA 14.5.2
5	545	EXPOSED WIRES	X							NFPA 70 110.12
5	501	LIGHTS OVER BLEACHERS NOT PROTECTED	X							NFPA 70 401.3
5	527	LIGHTS NOT PROTECTED	X							NFPA 70 401.3
5	525	LIGHTS NOT PROTECTED	X							NFPA 70 401.3
5	517	LIGHTS NOT PROTECTED	X							NFPA 70 401.3
5	511	LIGHTS NOT PROTECTED	X							NFPA 70 401.3
5	415A	LENS CRACKED	X							NFPA 70 401.3



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: _____


FACILITY: GREEN COVE SPRINGS JUNIOR HIGH SCHOOL
1220 BONAVENTURE AVENUE
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 7, 2007 DATE
Jerry H. [Signature]
INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	70	OK								
92	104	OK								
92	105	OK								
92	106	OK								
92	107	OK								
92	112	OK								
92	113	OK								

Lake Forest

Junior High School





FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0025

FACILITY: LAKE ASBURY JUNIOR HIGH SCHOOL
2851 SANDRIDGE ROAD
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 6, 2007

[Signature]
 INSPECTOR'S SIGNATURE DATE 11-6-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		OK								
2		OK								
3		OK								
5		OK								
6		OK								
7		OK								
8		OK								



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0025

FACILITY: LAKE ASBURY JUNIOR HIGH SCHOOL
2851 SANDRIDGE ROAD
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 6, 2007

[Signature]
 INSPECTOR'S SIGNATURE
 DATE 11-6-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	401	OK								
92	402	OK								
92	403	OK								
92	404	OK								
92	405	OK								
92	406	OK								
92	407	OK								
92	408	OK								
92	409	OK								
92	410	OK								
92	421	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11.4.8
92	422	OK								
92	423	OK								
92	424	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11.4.8



FISCAL YEAR 2007-2008

**COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**

DISTRICT: CLAY FACILITY #: 0025

FACILITY: LAKE ASBURY JUNIOR HIGH SCHOOL
2851 SANDRIDGE ROAD
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 6, 2007

[Signature]
INSPECTOR'S SIGNATURE

11-6-07
DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	425	OK								
92	426	RAMP EXCEEDS 1-12 SLOPE		X						FBC 11.4.8
92	427	RAMP EXCEEDS 1-12 SLOPE		X						FBC 11.4.8
92	428	RAMP EXCEEDS 1-12 SLOPE		X						FBC 11.4.8

Library

Junior High School





FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
2750 MOODY ROAD
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2007

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 10.30.07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	105	LIGHT COVERS MISSING		X						NFPA 70 401.3
5	115	STAINED CEILING TILES		X						FBC 804.2.3
5	116	AIR CURTAINS NOT WORKING	X							
5	116A	ACCESS HOLE MISSING COVER		X						NFPA 70
5	116A	STAIR BLOCKED		X						FBC 423.17.1
5	124	EMERGENCY LIGHT OUT	X							FBC 423.17.1
5	125	DOOR BLOCKED		X						
5	142	TILE BROKEN		X						FBC 804.3.2
5	208	ROOF LEAK	X							
5	211	UNPROTECTED BULB		X						
5	245	UNPROTECTED BULB		X						
5	216	EMERGENCY LIGHT TEST BUTTON BROKEN	X							FBC 423.17.1
5	215	ROOF LEAK	X							



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
 COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
 2750 MOODY ROAD
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2007

Deborah Brown
 INSPECTOR'S SIGNATURE DATE 10-30-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	242	ROOF LEAK	X							
5	221	EMERGENCY LIGHT OUT	X							FBC 423.17.1
5	233	ROOF LEAK	X							
5	238	EMERGENCY LIGHT OUT	X							FBC 423.17.1
1		EMERGENCY LIGHT OUT IN ALL CLASSROOMS	X							FBC 423.17.1
1	216	NO EMERGENCY LIGHT	X							FBC 423.17.1
1	8	NO EMERGENCY LIGHT	X							FBC 423.17.1
1	30	ROOF LEAK	X							
1	21	CEILING TILE BROKEN		X						FBC 804.2.3
2	35	HOLE IN CEILING (REPAIR LEAK)		X						FBC 804.2.3
2	31	EMERGENCY LIGHT OUT	X							FBC 423.17.1
2	40	EMERGENCY LIGHT OUT	X							FBC 423.17.1
2	45	EMERGENCY LIGHT OUT	X							FBC 423.17.1
2	45	NO EVACUATION SHEET		X						FBC 423.14.2



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
 COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
 2750 MOODY ROAD
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2007

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 10.30.07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	49	WALL ORDER REPAIR	X							
2	55	ROOF LEAK	X							
2	55	CEILING TILES OUT		X						
2	54	EMERGENCY LIGHT OUT	X							FBC 423.17.1
2	53	EMERGENCY LIGHT OUT	X							FBC 423.17.1
2	53	NO EVACUATION SHEET		X						FBC 423.14.2
3		EMERGENCY LIGHT OUT (GENERAL)	X							FBC 423.17.1
3	59	CEILING TILE OUT		X						
3	70	NO EVACUATION SHEET		X						FBC 423.14.2
3	80	ROOF LEAK	X							
3	77	ROOF LEAK	X							
7		EXTERIOR ROTTED WOOD EAST GABLE, PLUMBING VENT BOOTS DETERIORATED	X							
8	828	LIGHTS OUT		X						FBC 1006.3.1
9	901	RISER AND SEAT BOARDS BROKEN - BOTH SIDES	X							



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
 2750 MOODY ROAD
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2007

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 10-30-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	701	OK								
92	702	OK								
92	703	RAMP NOT LEVEL AT TRANSITION	X							FBC 11.4.8
92	704	NO EVACUATION SHEET		X						FBC 423.14.2
92	705	OK								
92	706	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	708	OK								
92	710	OK								
92	722	OK								
92	731	OK								
92	733	OK								
92	735	WOOD RAMP EXCEEDS 1-12 SLOPE	X							FBC 11.4.8
92	737	CEILING DAMAGED	X							
92	745	GATE TO TRANSFORMER UNLOCKED		X						



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
2750 MOODY ROAD
ORANGE PARK, FLORIDA 32073


INSPECTION DATE: OCTOBER 30, 2007

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 10-30-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	791/92	EXTERIOR PLUMBING CLEANOUT OPEN	X							
92	792/92	TV BLOCKING ELECTRICAL PANEL		X						
92	791/92	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	791/92	TRANSFORMER AT EXTERIOR NOT FENCED	X							
92	793	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	794	OK								

Orange 1917

Junior High School





FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
 1550 GANO AVENUE
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 15, 2007

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 11-15-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	160	CEILING TILE MISSING		X						FBC 804.2.3
2	206	FIRE EXTINGUISHER NOT SIGNED BY STOVE		X						FAC 69A-53
2	202	ELECTRICAL SHUNT TRIPS NOT LABELED	X							NFPA 70
2	252	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
2	253	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
2	254	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
2	255	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
2	256	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
2	257	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
2	258	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
3	352	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
3	353	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
3	354	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
3	355	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1550 GANO AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 15, 2007

Doretha J. ...
 INSPECTOR'S SIGNATURE DATE 11-15-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	356	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
3	357	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
3	358	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	416	EXIT LIGHT OUT		X						FBC 1006.3.1
4	452	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	453	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	454	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	455	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	456	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	457	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
4	458	EMERGENCY EXIT LABEL MISSING ON DOORS		X						FBC 423.13.1
5	510	EMERGENCY LIGHT OUT		X						FBC 423.17.1
5	506A	EMERGENCY LIGHT OUT		X						FBC 423.17.1
5	517A	EMERGENCY LIGHT OUT		X						FBC 423.17.1



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
 COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1550 GANO AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 15, 2007

[Signature]
 INSPECTOR'S SIGNATURE
11.15.07
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	517C	EMERGENCY LIGHT OUT		X						FBC 423.17.1
6	604	LENSE COVER HANGING FROM CEILING		X						
6	609	CEILING TILE MISSING		X						FBC 804.2.3



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
 1550 GANO AVENUE
 ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 15, 2007

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 11.15.07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	501	OK								
92	503	EMERGENCY LIGHT OUT								
92	504	OK								
92	505	OK								
92	506	OK								
92	507	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	508	OK								
92	509A&B	OK								
92	510	OK								
92	511	OK								
92	513	OK								
92	514	OK								
92	515	OK								
92	507	RAMP EXCEEDS 1-12 SLOPE			X					FBC 11-4.8



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1550 GANO AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 15, 2007

[Signature]
 INSPECTOR'S SIGNATURE DATE 10-25-07

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	516	RAMP IN POOR CONDITION	X							FBC 11-4.8
92	703	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	704	OK								FBC 804.2.3
92	705	OK								
92	706	OK								
92	707A/B	OK								
92	708	OK								
92	710	MISSING FIRE EXTINGUISHER		X						
92	712	OK								

Williamson

Junior High School





FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY # 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
 5025 C.R. 218
 MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: NOVEMBER 27, 2007

Ed McArthur
 INSPECTOR'S SIGNATURE

Nov 27, 2007
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	220	REMOVE BROKEN LIGHT	X							
3	311	DOORS SWING IN WRONG DIRECTION - USED AS A CLASSROOM	X							
3	314A	COVER MISSING ON AC CONTROL		X						NFPA 70 419.12
4	409	LIGHT OUT		X						FBC 1006.3.1
4	407	EXCESSIVE COMBUSTIBLES ON WALLS		X						NFPA 70 210
5	503	FIRE ALARM COVER REMOVED		X						NFPA 70 419.12
6	612	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
7	790	FIRE ALARM COVER REMOVED		X						NFPA 70 419.12



FISCAL YEAR 2007-2008

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY # 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
5025 C.R. 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: NOVEMBER 27, 2007 DATE
[Signature]
 INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	2	RAMP EXCEEDS 1-12 SLOPE	X							FBC 11.4.8
92	3	TRIP HAZARD @ BASE OF RAMP	X							
92	4	RAMP EXCEEDS 1-12 SLOPE	X							FBC 11.4.8
92	5	ROTTED WOOD TREAD @ ENTRANCE	X							
92	41	WOOD SPINDLES MISSING	X							FBC 1013.7
92	40	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	41	EMERGENCY LIGHT OUT	X							FBC 423.17.1