


High School





FISCAL YEAR 2006-2007

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY	Ý#: <u>0013</u>
FACILITY: <u>CLAY HIGH SCHOOL</u> 2025 HIGHWAY 16 WEST	
GREEN COVE SPRINGS,	
INSPECTION DATE: OCTOBER 10.	2006
lod Sweatland	Oct 10,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S:"	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	102	MAXIMUM OCCUPANCY SIGN MISSING		Х						FBC 1004.3
1		NO EMERGENCY EVACUATION SHEETS		Χ.::						FBC 423.14.2.4
1	111	NO EMERGENCY EVACUATION SHEETS		Х						FBC 423.14.2.4
1	113	EMERGENCY LIGHT COVER BROKEN								FBC 423.17.1
1	118	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
1	127	EMERGENCY LIGHT NOT WORKING, BROKEN WIRES EXPOSED	X							FBC 423.17.1
1	132A	CEILING TILE MISSING		Х						FBC 804.2.3
1	135	EMERGENCY LIGHT OUT		X						FBC 423.17.1
1	127B	JUNCTION BOX LOOSE		Х						NFPA 70 410.12
1	138	EMERGENCY LIGHT OUT		X						FBC 423.17.1
1	142	CEILING TILES MISSING		Х						FBC 804.2.3
2	211	EMERGENCY LIGHT OUT		Х						FBC 423.17.1



FISCAL YEAR 2006-2007

DISTRICT; CLAY FAGILI	TY#: 0013
FACILITY: CLAY HIGH SCHOOL	
2025 HIGHWAY 16 WES GREEN COVE SPRINGS	
INSPECTION DATE: OCTOBER 10.	, 2006
Tod Swestland	Oct 10, 2006
INSPECTOR'S SIGNATURE	DATE

⊪ Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled : for Correction	Rule
3	301	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
3	302	NO EMERGENCY EVACUATION SHEET	1225 4	Х						FBC 423.14.2.4
3	302	MOVE EMERGENCY LIGHT TO LIGHT UP ROOM	Х			-				FBC 423.17.1
3	312A	ADD EMERGENCY LIGHT	×							FBC 423.17.1
3	318	NO EMERGENCY LIGHT	Х							FBC 423.17.1
3	300B	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
3	379	CEILING TILES MISSING		Х						FBC 804.2.3
3	381	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
3	361	EMERGENCY EVACUATION SHEETS MISSING		Х						FBC 423.14.2.4
3	344	HALF OF THE EMERGENCY LIGHTS NOT WORKING (BULB)		X						FBC 423.17.1
3	341	AV WIRES UP WALL ACROSS CEILING				Х				NFPA 70 870.52
3	389	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
3	329	CEILING TILES MISSING		Х						FBC 804.2.3
5	-504	LENSE COVER MISSING		X						



DISTRICT: CLAY FACILIT	「Y# : 0013
FACILITY: CLAY HIGH SCHOOL 2025 HIGHWAY 16 WEST	
GREEN COVE SPRINGS.	
INSPECTION DATE: OCTOBER 10,	2006
Toll Walland	Oct 10,2006
TNSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	510A	EXIT LIGHT COVER MISSING		Х						FBC 423.17.1
5	517A	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17,1
_ 5	518	LENSE COVER MISSING		Х						FBC 423.17.1
6	601	NO EMERGENCY EVACUATION SHEET		×						FBC 423.14.2.4
7	782	OCCUPANCY LOAD SIGN MISSING		Х						FBC 1004.3
7	788	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
8	801	EMERGENCY LIGHT COVER MISSING		Х						FBC 423.17.1
- 8	802	EMERGENCY LIGHT COVER MISSING		X						FBC 423:17:1
8	805	LENSE COVER MISSING		Х						FBC 423.17.1
- 8	810	NO EMERGENCY EVACUATION								FBC 423.14.2.4
8	812	EXIT LIGHT TO HIGH CANNOT BE SEEN NORTHWEST CORNER	х							FBC 423.17.1
8	831	REPLACE DAMAGED CEILING TILES		X						FBC 804.2.3
8	835	LIGHTS NOT BRIGHT ENOUGH FOR CLASSROOM	x							FBC 1205.3



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CI	_AY F#	ACILITY#: 00	13

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: OCTOBER 10, 2006

INSPECTOR'S SIGNATURE

Oct 10, 2006

DATE


Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac: "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
8	822	EXIT LIGHT OUT		Х						FBC 423.17.1
8	825	EXIT LIGHT OUT		Х						FBC 423.17.1
8	838	EMERGENCY LIGHT NOT WORKING OUT		Х						FBC 423.17.1
- 8	837	ONE BULB OUT - EMERGENCY LIGHT		x						FBC 423.17.1
9	914	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
11	1104	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
11	1109	WIRES THROUGH EXIT – ACROSS FLOOR WORK ORDER # 0201266				х				NFPA 70 – 110.12
35		NO EMERGENCY EVACUATION SHEET		X						FBC 423.14:2:4
31		LENS & BULB COVER MISSING		Х						NFPA 708 401.3
30		COOKING EQUIPMENT IN FRONT OF THE ELECTRICAL PANEL		X						NFPA 70 110.26
30		NO FENCE AROUND PUMP STATION IN FRONT OF BUILDING			Х					
35		NO EMERGENCY EVACUATION SHEET.		X						FBC 423.14.2.4



DISTRICT: CLAY FACILITY#:	0013
FACILITY: CLAY HIGH SCHOOL 2025 HIGHWAY 16 WEST	
GREEN COVE SPRINGS, FLOR	RIDA 32043
INSPECTION DATE: OCTOBER 10, 2006	
That Sweatland	Oct 10.2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	7	ок								
92	8	REPLACE LOOSE BOARDS ON RAMP AND ON HANDRAIL	Х							
92	33	ок								
				inger op blikken Sigler beskriver						
								Trigitional (or 2 artis) over the first	sagsaction confit proglishmin	

Fleming Island High School





FISCAL YEAR 2006-2007

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

	Skei		3.241,713.551,14	ja julyttajaki		44,444,646	in this is		and the stand	e legación de la company d		3
	716	OTO	IOT.	\sim \sim \sim	V			ITV #	• • • • • • • • • • • • • • • • • • •)44		31
	ノバ	חוכ		ULM	Transfer seems.		MUIL	. 1 1 1 77		J-1-1	An logger of the section of the colors	94
35 6	unia)	and talk	Child Selection	indebegebles	ale a nia mari bina			49/15/04/05/05	Paratic State and	Mindrig call eggs	January and American Services	Æ.
1.30	1000			Committee and		manager out alternational	14.1.		Property of the second		11 Part 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY
ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 12, 2006

INSPECTOR'S SIGNATURE

Uct 12,2006

DAT

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac. "C"	lnfo. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	11	CEILING TILE MISSING		Х						FBC 804.2.3
1	12	LIGHT OUT		X						FBC 1205.3
1	28	STORAGE TOO CLOSE TO CEILING – MINIMUM 18"		Х						NFPA 1 12.1
1	109	AC LEAK	X							
1	122	FIRE ALARM NOT CERTIFIED	Х							69A-58.008
1.1	116	CEILING TILES MISSING		X						FBC 804.2.3
1	119	CEILING TILES STAINED	Х							FBC 804.2.3
1	140	WATER FOUNTAIN DAMAGED - CONTROLS	×							
1	142	OPEN ELECTRIC BOX		Х						NFPA 70-110.26
1	143	AC DRAINED CLOGGED WATER COMING OUT FROM UNDER UNIT	X							
1	149	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	151	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	171	STORAGE TO CLOSE TO CEILING –MINIMUM 18"		Х						NFPA 1 12-1
1	178	GFCI BOX COVER MISSING	×							NFPA 70 410.112



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY#: 0044
2233 VI	NG ISLAND HIGH SCHOOL LLAGE SQUARE PARKWAY SE PARK, FLORIDA 32003
INSPECTION DATE	: OCTOBER 12, 2006
Tod Sweath	Det 12,2006

DATE

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	182	GFCI COVER MISSING	Х							NFPA 70 410.12
1	255	I.S. CABLE UP DOOR FRAME				×				
1	270	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
1	272	ELECTRICAL PANEL MISSING	X							NFPA 70 410-12
1	298	I.S. CABLE CONNECTION NEEDS TO BE MOVED				X				
1	314	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
10	1022	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
1	332	FIRE ALARM BOX OPEN		X						NFPA 70 110-12
1	332	ELECTRICAL BOX OPEN AT AH13		Х						NFPA 70 110-12
1.	334	FIRE ALARM BOX OPEN – BARE WIRES	X							NFPA 70 110-12
1	334	RESEAL INSULATION AT AH	Х							
2	203	TWO OPEN ELECTRICAL BOXES – LOWER RIGHT HAND SIDE		X						NFPA 70 110-12
2	205	LIGHTS HANGING FROM WIRES	Х							NFPA 70 110-12



FISCAL YEAR 2006-2007

DISTRICT: CLAY	FACILITY#: 0044
FACILITY: FLEMING ISLAND	
2233 VILLAGE SO ORANGE PARK, I	QUARE PARKWAY FLORIDA 32003
INSPECTION DATE: OCTOR	
Inspector's Signature	<u>Oct [2,2006</u>

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv.: "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	207	LIGHTS HANGING FROM WIRES	Х							NFPA 70 110-12
2	268	REMOVE PAINT FROM GENERATOR ROOM		X						NFPA 1
10	1015	CEILING TILE MISSING		Х						FBC 804.2.3
10	1019B	TRASH, WOOD IN HALLWAY		X						FBC 1004



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN **COMPLIANCE WITH** F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FAC	ILITY#: 0044
FACILITY: <u>FLEMING ISLAND HIG</u> 2233 VILLAGE SQUAI ORANGE PARK, FLO	RE PARKWAY
INSPECTION DATE: OCTOBER	12, 2006
Tod Sweathans	Oet 12,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info, Serv, "I,S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	10	CLOSET DOOR HITS FLOOR	Х							
92	12	MISSING PANEL KNOCK-OUT	X							NFPA 70 110.12
92	12	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	20	EMERGENCY LIGHT NOT WORKING		Х						FBC 423,17.1
92	22	SIDING LOOSE BY RAMP – REATTACH TRIM @DOOR	х							FBC 423.17.1
92	30	EXTERIOR LIGHT GLOBE MISSING		X						NFPA 70: 401.3
92	31	RAMP BOUNCES		Х						FBC 1005.3
92	32	WEEDS GROWN UP BY RAMP		Χ						
92	42	WEEDS GROWN UP BY RAMP		Х						
92	63	MISSING DOOR GUARD		X						FBC 423.17.1
92	34	MISSING DOOR GUARD		Х						FBC 423.17.1
92	35	MISSING DOOR GUARD		×						FBC 423.17.1
92	44	MISSING DOOR GUARD		X						FBC 423.17.1



DISTRICT: CLAY FACILITY	′# :0044
FACILITY: FLEMING ISLAND HIGH S	CHOOL
2233 VILLAGE SQUARE P ORANGE PARK, FLORIDA	ARKWAY
INSPECTION DATE: OCTOBER 12, 2	
INSPECTOR'S SIGNATURE	Oct 12,200C

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	10	CLOSET DOOR HITS FLOOR	Х							
92	12	MISSING PANEL KNOCK-OUT	X							NFPA 70 110.12
92	12	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	20	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
92	22	SIDING LOOSE BY RAMP – REATTACH TRIM @DOOR	х							FBC 423.17.1
92	30	EXTERIOR LIGHT GLOBE MISSING		X						NFPA 70 401.3
92	31	RAMP BOUNCES		Х						FBC 1005.3
92	32	WEEDS GROWN UP BY RAMP		X						
92	42	WEEDS GROWN UP BY RAMP		Х						
ii 92	63	MISSING DOOR GUARD		X						FBC 423.17.1
92	34	MISSING DOOR GUARD		Х						FBC 423.17.1
92	35	MISSING DOOR GUARD		X						FBC 423.17.1
92	44	MISSING DOOR GUARD		Х						FBC 423.17.1



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN **COMPLIANCE WITH** F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILIT	TY#: 0044
FACILITY: FLEMING ISLAND HIGH	SCHOOL
2233 VILLAGE SQUARE	PARKWAY
ORANGE PARK, FLORID	A 32003
INSPECTION DATE: OCTOBER 12,	2006
Toll Sweathan	Oct 12,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	40	MISSING HALF EMERGENCY LIGHT		Х						FBC 423.17.1
92	43	TRIM @ DOOR NEEDS TO BE REATTACHED		Χ						
92	46	HANDRAIL WELDS BROKEN (ALUM)	Х							FBC 1005
92	47	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
92	48	MISSING LENS COVER		Х						NFPA 70 401.3
92	48	NO EMERENCY EVACUATION SHEET		Х						FBC 423.14.2.4
92	48	RAMP BOUNCES		Х						FBC 1005
92	· 82	EMERGENCY LIGHT NOT WORKING	X							FBC 423:17.1
92		AC FILTERS DIRTY IN ALL PORTABLES		Х						
Mazzurean			and the state of t							

Restone Heights

Imor/Senor High School





COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN **COMPLIANCE WITH** F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILIT	Y#: 0011
FACILITY: KEYSTONE HEIGHTS HIGHTS HIGHTS HIGHTS AVENU	
KEYSTONE HEIGHTS, FL	
INSPECTION DATE: OCTOBER 17, 2	2006
Jad Sweatland	Oct 17, 2006
MSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	112	OUTLET PLATE MISSING		Х						NFPA 70 410.1.2
1	160	FIRE ALARM TROUBLE LIGHT @ DUCT DETECTOR	X							NFPA 70 110.12
1	163	AV CABLES RUN THROUGH CEILING				X				
1	173	REMOVE STORAGE IN ELECTRICAL ROOM		X						NFPA 70 110.26
1	187	NEED NEW EXIT LIGHT NORTH END OF CORRIDOR	х							FBC 423.20.1
1	188	TV TOO LOW NEED TO MOVE DESK OR CABINET		X						FBC 423.20.1
4	403	ELECTRICAL SURGE PROTECTOR PLUGGED INTO SURGE PROTECTOR		х						NFPA 70 400.8
4	401	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
5	510	SWITCH COVER BROKEN BY PEPSI MACHINE		Х						NFPA 70 410.12
5	548	STORAGE IN ELECTRICAL CLOSET		X						NFPA 70 110.12
5	505	REMOVE WOOD BACKDROP FROM STAGE BLOCKS EXIT		х						FBC 423.20.1
- 5	550	REMOVE STORAGE & REPLACE CEILING TILES		X						FBC 423.20.1



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

TY#: 0011
IIGH SCHOOL NUE FLORIDA 32056
, 2006
Oct 17,2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
5	536	CEILING TILES MISSING		Х						FBC 804.2.3
6	609 E	STORAGE IN ELECTRICAL CLOSET		Х						NFPA 70 110.12
9	912	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
9	921	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
9	928	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
9	917	CEILING TILES MISSING		X						FBC 804.2.3
9		2 ND FLOOR MEZZANINE ELECTRICAL BOX COVER MISSING	х							NFPA 70 410.12
. 9	927	ROOF/AC LEAKS	X							
9	933	STORAGE IN ELECTRICAL CLOSET		Х						NFPA 70 110.12
20	17	EXIT BLOCKED BY WEIGHT BENCH		X						FBC 423.20.1



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN **COMPLIANCE WITH** F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY	/# :0011
FACILITY: KEYSTONE HEIGHTS HIG 900 S. W. ORCHID AVENU	
KEYSTONE HEIGHTS, FLO	
INSPECTION DATE: OCTOBER 17, 2	006
Tod Sive cottany	Oct 17,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	ок .								
92	2	OK								
92	3	ок								
92	4	ОК								
92	5	ок								
92	6	ОК			0					
92	7	ок								
92	11	ОК								
92	12	ОК								
92	13	ОК								
92	14	ок								
92	15	ок								
92	16	ок								

|--|

COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACIL	JTY#: 0011
FACILITY: <u>KEYSTONE HEIGHTS I</u> 900 S. W. ORCHID AVE KEYSTONE HEIGHTS, I	NUE
INSPECTION DATE: OCTOBER 17	7, 2006
INSPECTOR'S SIGNATURE	<u>Det 17, 2006</u>

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	17	ок								
92	18	ОК								
92	19	ок								
92	20	ок								
92	21	ОК								
92	22	OK								
92	23	ОК								
92	24	ОК								
92	25	ОК								
92	26	OK								
92	27	ок								
92	28	OK								
92	29	ок								



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILIT	Y#: 0011
FACILITY: KEYSTONE HEIGHTS HIGHTS HIG	
KEYSTONE HEIGHTS, FL	ORIDA 32056
INSPECTION DATE: OCTOBER 17, 2	2006
INSPECTOR'S SIGNATURE	<u>Oct 17,200c</u> DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	30	ок								
92	49	ОК								
92	51	ОК								
92	52	OK :								
92	53	ОК								
92	54	ОК								
92	55	ок								
92	56	ОК								
92	57	ок								
92	58	ОК								
92	59	ок								
92	60	ОК								
92	61	ОК								



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY	Y#: <u>0011</u>
FACILITY: KEYSTONE HEIGHTS HIG	GH SCHOOL
900 S. W. ORCHID AVENU	JE
<u>KEYSTONE HEIGHTS, FL</u>	ORIDA 32056
INSPECTION DATE: OCTOBER 17, 2	2006
Tod Sweatland	Oct 17,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	62	ок								
92	63	OK								
92	64	ОК								
92	65	ОК								
92	90	ок								
92	91	OK				A. S.				
										en e

Willed Eburg High School





COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

FACILITY:	MIDDLEBURG F	<u>IIGH SCHOO</u>	DL
	3750 C.R. 220		
	MIDDLEBURG, F	LORIDA 32	068
		<u> </u>	
NICDECTIC	NDATE: OCTO	DED 25 200	AC .

DATE

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	76	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
1 .	76	EMERGENCY LIGHT NEEDS COVER		Х						
1	89	NO EMERGENCY EVACUATION WSHEET		Х						FBC 423.14.2.4
1	249	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
1	203	STORAGE TOO HIGH WITHIN 18" OF SPRINKLER		Х						NFPA 1 12.1
1	-285	EXIT LIGHT COVER MISSING		X						
1	285	OCCUPANCY LOAD SIGN MISSING (1,770)		Х						FBC 1004.3
1	335	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
1	327	EXIT BLOCKED		Х						FBC 423.20.1
1	361	ROOF LEAK CEILING REPLACED		X						
1	284A	EXIT LIGHT OUT		Х						FBC 1016.3.1
35		EMERGENCY LIGHT OUT		X						FBC 423.17.1
35		2 LP TANKS STORED IN BUILDING – REMOVE		Х						NFPA 1.21-3.3.5



DISTRICT: CLAY FACILITY#: 0019
FACILITY: MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG, FLORIDA 32068
INSPECTION DATE: OCTOBER 25, 2006
Tod Sweathand Oct 25, 2006
INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac- "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9		LP TANKS STORED IN BUILDING - REMOVE		Х				<u> </u>		NFPA 1-21-3.3.5
10		LP TANKS STORED IN BUILDING - REMOVE		×						NFPA 1-21-3,3,5



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN **COMPLIANCE WITH** F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACI	LITY#: 0019
FACILITY: MIDDLEBURG HIGH S	CHOOL
3750 C.R. 220	
MIDDLEBURG, FLORI	DA 32068
INSPECTION DATE: OCTOBER 2	25, 2006
Tod Sweathand	Oct 25, 2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	7	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	9	NO EMERGENCY EVACUATION SHEET		X						FBC 423.17.1
92	33	BUILDING MILDEWED BY AC UNIT		Х						
92	5	OK								
92	31	ок								
92	32	OK								
92	34	ок								
92	35	OK								
92	36	ок								
92	41	ok								
92	42A	ок								
92	42B	ok								
92	43	ок				!				
92	44	OK			fer in the first					



FISCAL YEAR 2006-2007

DISTRICT: CLAY FACILITY #: 0019
FACILITY: MIDDLEBURG HIGH SCHOOL
3750 C.R. 220
MIDDLEBURG, FLORIDA 32068
INSPECTION DATE: OCTOBER 25, 2006
Tol Sweather Oct 25,2006
INSPECTOR'S SIGNATURE DATE


Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	45	ок								
92	46	OK								
92	47	ок								
92	51	OK								
92	52	ок								
92	53	OK								
92	54A	ок								
92	54B	OK								
92	55	ок								
92	70	OK								
92	71	ок								
92	72	OK								
92	73	ок								
92	74	OK								



DISTRICT: CLAY FACILITY#: 0019
FACILITY: MIDDLEBURG HIGH SCHOOL
3750 C.R. 220 MIDDLEBURG, FLORIDA 32068
WIDDLEBUNG, FLORIDA 32008
INSPECTION DATE: OCTOBER 25, 2006
Ted xweathan Oct 25,200C
ÍNSPECTOR'S SIGNATURE DATE

Bullding	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	75	ОК	Control of the Control of the Control							
92	76	OK								
92	77	ок								
92	78	jok								
92	79	ок								
				Appeller (hope 1/2) - Appeller (hope 1/2) - Appeller (hope 1/2) - Appeller (hope 1/2) - Appeller (hope 1/2)						

Orange Park High School





COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY#: 0007
	FACILITY: ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	INSPECTION DATE: OCTOBER 24, 2006
/	Tarrel hours 10/24/06
/ ,	INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Operi "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED OFF THROUGHOUT THE BUILDING SINCE THEY WERE INSTALLED IN JUNE 2006		×						
1	159A	EXIT LIGHT OUT	X							FBC 1016.3.1
1	151A	EXIT LIGHT OUT	Х							FBC 1016.3.1
1.	167A	EXIT LIGHT OUT	Х							FBC 1016.3.1
1	100	EXIT LIGHT OUT	Х							FBC 1016.3.1
1	181J	EXIT LIGHT OUT	. X							FBC 1016.3.1
1	220	EXIT LIGHT OUT	Х							FBC 1016.3.1
1	164	PROPANE FLOOR MACHINE STORED IN HALL DURING SCHOOL HOURS		X					71, col/do-100	
1	110	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
1	118	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
1	123	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED OFF THROUGHOUT THE BUILDING SINCE THEY WERE INSTALLED IN JUNE 2006		×						



	DISTRICT: CLAY FACILITY#: 0007
	FACILITY: ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	INSPECTION DATE: OCTOBER 24, 2006
۱ /	Lunel Suram 10/2 6/06
/	INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	159A	EXIT LIGHT OUT	Х							FBC 1016.3.1
1.	- 122	EVACUATION SHEET MISSING		×						FBC 423.14.2.4
1	226	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	224	EVACUATION SHEET MISSING		×						FBC 423.14.2.4
1	215	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	201	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
1	205	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	118	CEILING AT ENTRY TO ROOM 118 FALLING	X							FBC 804:23
1	220	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
12.4	101	COVER MISSING ON J-BOX (OUTLET)	X							NFPA 70.314.1
1	207	CEILING MOUNTED PROJECTOR NOT PROPERLY INSTALLED	х							
1.	204	CEILING MOUNTED PROJECTOR NOT PROPERLY INSTALLED	X							



FISCAL YEAR 2006-2007

DISTRICT: CLAY FACILITY	*#:0007
FACILITY: ORANGE PARK HIGH SCH	100L
2300 KINGSLEY AVENUE	
ORANGE PARK, FLORIDA	32073
INSPECTION DATE: OCTOBER 24,	2006
Larry & Swan	10/24/06
INCRECTOR'S SIGNATURE	DATÉ

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
2		NONE OF THE FIRE EXTINGUISHERS IN THE BULDING HAVE BEEN SIGNED OFF SINCE THEY WERE INSTALLED IN JUNE 2006								
2	14	LIGHT FIXTURE DANGLING FROM CEILING	X							
4		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED OFF SINCE THEY WERE INSTALLED IN JUNE 2006		X						
4	19B	LENSES MISSING ON CEILING LIGHT FIXTURES	×							
4	19A	LENSES MISSING ON CEILING LIGHT FIXTURES	Х							
4	17	LENSES MISSING ON CEILING LIGHT FIXTURE	X							
4	5	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
4	1	EMERGENCY LIGHT OUT	×							FBC 423.17.1
4	17C	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
4	1.1	EMERGENCY LIGHT OUT	X							FBC 423.17.1
4	17A	LIGHT SWITCH NOT WORKING	Х							FBC 423.17.1



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	CLAY FACILITY #: 0007
FACILITY:	ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE ORANGE PARK, FLORIDA 32073
INSPECTIO	ON DATE; OCTOBER 24, 2006
Zarrel	4. Sware 15/54/06 DATE DATE

Building .	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
4	21A	CEILING TILES MISSING		Х					·	FBC 804.2.3
4	17B	LIGHT SWITCH NOT WORKING	×							423.17.1
4	1	EXIT LIGHT MISSING S.E. EXIT	Х							FBC 1016.3.1
4	1	EXIT LIGHT MISSING S.E. EXIT	X							FBC 1016.3.1
4	5H	EXIT LIGHT	Х							FBC 1016.3.1
4	5	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
4	21A	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
4	1	EXTERIOR COVER MISSING ON WATER COOLER	X							
4	17H	CEILING BROKEN LARGE HOLES	Х							
10	112	VANITY BROKEN	×							
10		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED OFF SINCE THEY WERE INSTALLED JUNE 2006	х							



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

	,		
ACILITY:	ORANGE PARK H	IGH SCHOO)L
	2300 KINGSLEY A	VENUE	
	ORANGE PARK, F	LORIDA 320	073
Ω			
NSPECTIC	NATE: OCTO	BER 24, 2006	6
Xamill	1. Juan		10/24/06
NSPEC/TO	R'S SIGNATURE		DATE /

FACILITY#:

0007

DISTRICT: CLAY

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
10	102	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
10	104	EMERGENCY LIGHT OUT	X							FBC 423.17.1
10	112	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
10	124	LP TANK STORED IN ROOM 124		×						
10	116	EXTENSION CORD TO LAVA LAMP		X						
10	116	BACK DROP CURTAIN NOT FIRE RETARDANT		X						
10	110	NO DIFFUSER RESTING ON FIRE SPRINKLER UNIT		Х						
10	102	EMERGENCY LIGHT OUT	X							FBC 423,17.1
10		NO ROOM NUMBERS ON ROOMS 103, 104, 105, 106, 107								
12	141	DAMAGED WALL BY ENTRANCE	X							
12	141	PANELING REMOVED FROM WALL	X							
. 12	164	ENTRANCE TO 152 CLOSURES AND LOCKSET NOT OPERATING PROPERLY								
12	164	ELECTRICAL PANELS NOT SECURED	х							



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: ORANGE PARK HIGH SCHOOL
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 24, 2006

DISTRICT: CLAY FACILITY #: 0007

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
12		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED OFF SINCE INSTALLATION JUNE 2006		х						
12	105	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
12	116	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
12	161A	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
12	135	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
12	161B	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
12	140	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
12	135	COVER PLATE MISSING ON SWITCH		X						FBC 423.14.2.4
12	161A	LENSE MISSING ON CEILING LIGHT FIXTURE	Х							
12	164	SIDE EXIT LIGHTS OUT	X							FBC 1016.3.1
24	23	SOUND PANEL FALLING FROM WALL	Х							
24	34	CEILING TILES MISSING		×						FBC 804.2.3
24	33	CEILING TILES MISSING		×						FBC 804.2.3



	DISTRICT: CLAY FACILITY#: 0007
	FACILITY: ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	INSPECTION DATE: OCTOBER 24, 2006
! /	Tary 1 Sw 18/54/06
U	NŚPECTOR'S SIGNATURE DATÉ

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
24	32	CEILING TILES MISSING		Х						FBC 804.2.3
24	18	CEILING TILES MISSING		×						FBC 804.2.3
24	14	CEILING TILES MISSING		X						FBC 804.2.3
24		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X						
18C		NONE OF THE FIRE EXTINGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		x						
18C	1	EVACUATION SHEET MISSING		×						FBC 423:14:2:4
18C	3	EVACUATION SHEET MISSING		×						FBC 423.14.2.4
18C	6	EVACUATION SHEET MISSING		x						FBC 423.14.2.4
18C	2	HOLE IN WALL WHERE WATER COOLER WAS	Х							
19D		NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		×						
19D	9	EXIT LIGHT OUT	Х							FBC 1016.3.1
19D	8 :	EXIT LIGHT OUT	X							FBC 1016.3.1



	DISTRICT: CLAY FACILITY# 0007
	FACILITY: ORANGE PARK HIGH SCHOOL 2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	INSPECTION PATE: OCTOBER 24, 2006
	Langle he 10 124/06
/	LXNSPECTOR'S SIGNATURE DATE ′

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
20	10	NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		Х						
20	18A	EXIT LIGHT OUT	X							
20	18A	EXIT BLOCKED		X						
20	10	EVACUATION SHEETS MISSING		X						
20	1	EXTENSION CORD TO POWER STRIP TO SPLITTER		Х						
20	14	FIRE ALARM CERTIFIEC 10/2005 (EXPIRED)	X							
20	14	TROUBLE LIGHT ON FIRE ALARM	Χ.							
21		NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X						
21	2	NO EMERGENCY LIGHT								FBC 423.17.1



	DISTRICT: CLAY FACILITY#: 0007
	FACILITY: ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	INSPECTION DATE: OCTOBER 24, 2006
/	Xurull+ hu 10/5-4/06
,	INCRECTORISCIONATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
21	2	CEILING TILES MISSING		Х						FBC 804.2.3
22		NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X						
22	9	EXIT LIGHT OUT	Х							FBC 1016.3.1
.22	4 4	EXIT LIGHT OUT.	X							FBC 1016.3.1
22	7	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
22	6	EVACUATION SHEET MISSING		X						FBC:423.14.2.4
27		NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		х						
27	2	NO EVACUATION SHEET		X						FBC 423.14.2.4
27	3	EXIT LIGHT OUT	Х							FBC 1016.3.1
27	3	NO EMERGENCY LIGHT	X							FBC 423.17.1
27	4	COVERS MISSING ON LIGHT FIXTURE	Х							
27	6	COVERS MISSING ON LIGHT FIXTURE	X							
27	10	CEILING TILES MISSING		Х						FBC 804.2.3



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

ACILITY:	ORANGE PARK	HIGH SCHO	OL
	2300 KINGSLEY	AVENUE	
	ORANGE PARK	, FLORIDA 32	2073
Λ			
NSPĘĆTIC	NDATE: OCT	OBER 24, 200	06
Kary	4		18/24/06
NSPECTO	R'Ś SIGNATURE		DATE

DISTRICT: CLAY FACILITY #: 0007

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. 'O'	Facı "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
27	11	CEILING TILES MISSING		х						804.2.3
48		NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X						
48	1	PROPANE TANKS INSIDE	:	Х						
47	1	NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X						
47	1	PROPANE TANKS STORED INSIDE		Х						
43	1	NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X						
43	1	PROPANE TANKS STORED INSIDE		X						
51	⊕ 2	EMERGENCY LIGHT OUT	X							FBC 423.17.1
51	14	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
51	7	SWITCH COVER MISSING		×						FBC 423.14.2.4
51	12	SWITCH COVER BROKEN		Х						FBC 423.14.2.4



	DISTRICT: CLAY FACILITY#: 0007
	FACILITY: ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE ORANGE PARK, FLORIDA 32073
	INSPECTION DATE: OCTOBER 24, 2006
1	The first of the second of the

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info: Serv. "I.S."	Cost	No. of times Def.	Scheduled for Correction	Rule
GENE	RAL	NONE OF THE FIRE EXTIGUISHERS HAVE BEEN SIGNED SINCE INSTALLATION JUNE 2006		X				Cited		
92	24	EMERGENCY LIGHT NOT WORKING	X							FBC 423.17.1
92	24	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	25	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	26	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	27	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	27	COVER MISSING ON CLOSET LIGHT	х							FBC 423.14.2.4
92	28	EVACUATION SHEET MISSING		×						FBC 423.14.2.4
92	29	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	31	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	31	EMERGENCY LIGHT NOT WORKING	Х						-	FBC 423.17.1
92	32	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	41	EVACUATION SHEET MISSING		×						FBC 423.14.2.4



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101


	DISTRICT: CLAY FACILITY#: 0007
	FACILITY: ORANGE PARK HIGH SCHOOL
	2300 KINGSLEY AVENUE
	ORANGE PARK, FLORIDA 32073
	INSPECTION DATE: OCTOBER 24, 2006
/	Karrelt - 18/24/06
/	INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	41	OUTLET COVER MISSING BY PANEL		X						FBC 423.14.2.4
92	42	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	43	ELECTRICAL PANEL BLOCKED		X						
92	44	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	44	EMERGENCY LIGHT NOT WORKING	X							FBC 423.17.1
92	45	INTERCOM NOT WORKING	Х							
92	46	FIRE EXTINGUISHER MISSING		X						
92	48	ок								
92	49	OK								
92	52	ок								
92	53	HEAT DETECTOR MISSSING	X							
92	54	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	54	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	55	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	56	EVACUATION SHEET MISSING		×						FBC 423.14.2.4

OPHS 2006-07 SREF INSPECTION REPORT.doc

Ridgenten

High School





COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY	TY#: <u>0022</u>
Type 1997 1998 1998 1998 1998 1998 1998 1998	een oo dhaadaa ah oo ah ahaay ka moo baadaa hay bakaa dhaada bayaan
FACILITY: RIDGEVIEW HIGH SCHO	OOL
466 MADISON AVENUE	
ORANGE PARK, FLORID	OA 32065
INSPECTION DATE: OCTOBER 26	, 2006
Tod Sweethand)	Oct 26,2006
INSPECTOR'S SIGNATURE	DATE

Bullding	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	108A	TWO OPEN ELECTRICAL BOXES OVER EXTINGUISHER		х						NFPA 70 110.26
1	110	ELECTRICAL JUNCTION BOX COVER MISSING		X						NFPA 70 110.26
1		EMERGENCY SHEETS MISSING		Х						FBC 423.14.2.4
1	137	ELECTRICAL BOX COVER MISSING		X						NFPA 70 110.26
1	143	CLASSROOM NOT BY DESIGN – CHANGE DOOR SWING			х					FBC 423.13.1
1	149	NO OCCUPANCY LOAD SIGN		X						FBC 1004.3
2	212	CHAIR LIFT CERT NOT CURRENT		Х						
2	221	LIGHT DAMAGED NEEDS REPAIR	×							
2	223	FIRE EXTINGUISHER NOT SIGNED	·	Х						69A-58
2	227	EXIT LIGHT OUT		X						FBC 1006.3
2	236	EXIT LIGHT OUT		Х						FBC 1006.3
2	238	EMERGENCY LIGHT OUT		X						FBC 423.17.1
4	401	OPEN AC CONTROL BOX		Х						NFPA 70 110-26
4	401	SINK HOLE OUTSIDE BUILDING 4			×					

RHS 2006-07 SREF INSPECTION REPORT.doc



DISTRICT: CLAY FACILITY:	# : 0022
FACILITY: RIDGEVIEW HIGH SCHOOL	
466 MADISON AVENUE ORANGE PARK, FLORIDA 3	32065
INSPECTION DATE: OCTOBER 26, 20	
Tell Westland	Det 26,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	302	EMERGENCY EVACUATION SHEET MISSING		Х		30 - 13 to 40 - 10 to 40 - 10 to 40 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	Haladas Insulation Services	Sacking for a 16-time California (sel. 18-a)		FBC 423.14.2.4
3	315	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
3	320	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
3	333	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
3	340	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
5		ОК								
6	688	EXIT LIGHT OUT		Х						FBC 1006.3
6 '	689	EXIT LIGHT OUT		Х						FBC 1006.3
6	690	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
6	689	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
. 7	701	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
7	705	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
7	720	MISSING FIRE EXTINGUISHER		Х						69A-58
7:1	720	DOOR CLOSURE BROKEN	X							



DISTRICT: CLAY FACILI	TY# <u>0022</u>
FACILITY: RIDGEVIEW HIGH SCHO 466 MADISON AVENUE ORANGE PARK, FLORID	
INSPECTION DATE: OCTOBER 26	5, 2006
INSPECTOR'S SIGNATURE	<u>Oct 26,2006</u> DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9	911	NO OCCUPANCY LOAD SIGN		Х						FBC 1004.3
9	911	EMERGENCY LIGHT BROKEN		X		2 (* 15 de 1				FBC 423.17.1
9	911	EXTERIOR DOOR HANDLE BROKEN		Х						
9	910	EMERGENCY LIGHT HANGING		X						FBC 423:17.1
9	904	BATHROOM DOOR HANDLE BROKEN		Х						
9	904	BATHROOM SIGN MISSING		X						
9	914	NO EVACUATION SHEET		Х						FBC 423.14.2.4
9	914	EXIT DOOR HANDLE BROKEN		X		126, 12				
9	915	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
9	915	EXIT DOOR HANDLE BROKEN		X						
9	916	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
9	924	FIRE EXTINGUISHER MISSING		X						69A-58
9	919	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
9	941	TWO EMERGENCY LIGHT OUT		X		Territoria La Capacita				FBC 423.17.1



DISTRICT: CLAY FACIL	ITY#:0022
FACILITY: RIDGEVIEW HIGH SCHOOL 466 MADISON AVENUE	
ORANGE PARK, FLOR	
INSPECTION DATE: OCTOBER 2	6, 2006
Tod In eather	Oct 26,2006
INSDECTOD'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac: "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9	916	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
9	924	FIRE EXTINGUISHER MISSING		X						69A-58
9	919	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
9	1941	TWO EMERGENCY LIGHTS OUT		X						FBC 423.17.1
9	941	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
9	924	WATER COOLER RUSTY SHARP EDGES	X							



DISTRICT: CLAY FACILITY	#: <u>0022</u>
FACILITY: RIDGEVIEW HIGH SCHOOL	L
466 MADISON AVENUE ORANGE PARK, FLORIDA	32065
INSPECTION DATE: OCTOBER 26, 2	006
Toll (Weaffang)	Oct 26,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	3	NO FIRE EXTINGUISHER BY STOVE		X						69A-58
92	4	EXTINGUISHER NOT SIGNED		Х						69A-58
92	5	EMERGENCY LIGHT OUT		X.						FBC 423.17.1
92	6	EXTINGUISHER MISSING		Х						69A-58
92	7	ок								
92	8	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	9	OK								
92	10	ОК								
92	11	ОК								
92	12	ок								
92	21	OK								
92	25	ОК								
92	28	OK								



DISTRICT CLAY FACI	LITY#: 0022
FACILITY: RIDGEVIEW HIGH SC	
466 MADISON AVENU	
ORANGE PARK, FLOI	RIDA 32065
INSPECTION DATE: OCTOBER	26, 2006
Tod Sweatton	Oct 26,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	30	ок								
92	31	ok.								
. 92	41	ок								
92	42	OK								
92	43	ок								
92	44	OK								
92	46	ок								
92	. 48	OK								
92	50	ок								
92	61	OK			0.5					
92	63	ОК								
92	-64	ОК								
92	65	ОК								
92	67	OK								



DISTRICT: CLAY FACILIT	「 Y # : 0022
FACILITY: RIDGEVIEW HIGH SCHO	OL
466 MADISON AVENUE ORANGE PARK, FLORID	N 22065
ORANGE PARK, I LONID	A 32003
INSPECTION DATE: OCTOBER 26,	2006
Tod Xv Eatland	Oct 26,7006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	68	ок								
92	69	OK								
92	71	ок								
92	72	ок								
92	73	ок								
92	74	ок								
92	83	ок								
92	84	OK								
92	85	ок								
92	86	ок								
92	87	ОК								
92	88	OK								
92	89	ок								
92	90	OK								



COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN
COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY	#: 0022
FACILITY: RIDGEVIEW HIGH SCHOO	L
466 MADISON AVENUE	
ORANGE PARK, FLORIDA	32065
INSPECTION DATE: OCTOBER 26, 2	006
Ind No Catton	Oct 26,2006
INSPECTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	91	ок								
92	13	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	23	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	29	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	32	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	62	EMERGENCY LIGHT OUT		Χ						FBC 423.17.1
92	66	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	81	EMERGENCY LIGHT OUT		X						FBC 423.17.1
02	82	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	24	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
92	26	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
92	27	NO EMERGENCY EVACUATION SHEET		X						FBC 423.14.2.4
92	45	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
92	45	RAIL MISSING	X							FBC 1004:3



DISTRICT	<u>CLAY</u> F AC I	LITY#: <u>0022</u>
FACILITY:	RIDGEVIEW HIGH SC 466 MADISON AVENU ORANGE PARK, FLOR	E
Tods	ON DATE: OCTOBER WCaffau R'S SIGNATURE	26, 2006 Oct 26,2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	45	NAIL STICKING UP IN RAMP		Х						
92	69	SPINDLES MISSING @ RAMP		Х						FBC 1004.3
		Agricum, increase you, and reference or galacter and a proper section of the control of the cont	SCALURISTANIA SANDONI STANDA	econocompensor popul	springsparanosauprepadija	.conseptentatory prima	FORSE SECTION OF THE	andeschuser, euclasin	enelskerotonesterriorenseiti	
	i olisaantoonen			Programment Samuel		Sautovosaussessuss	Tilisassangia sultani			