



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

		o o
		오
0002		SC
000	7.50	RY
V.	5N 15.	TA
#		MEI
≽		Щ
믕		E
Ā		NE
		3EN
	24.4	ш
		ES
ΓĄ	Ę	ARL
ပ	计位数	공
ᄓ		<u>∵</u>
K		≒
DISTRICT: CLAY		FACILITY: CHARLES E. BENNETT ELEMENTARY SCHOOL
Mr.		

CHARLES E. BENNETT ELEMENTARY SC 1 SOUTH OAKRIDGE AVENUE GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE:

- DATE

OCTOBER 4, 2005

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "W"	Oper. "O"	Fac. "C"	Info. Serv. "[.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
-	5	Emergency Evacuation Sheet Missing		×						FBC 423.14.2.4
	9	Fire Alarm Panel Missing	X							NFPA 70.312.5
2	5	"K" Type Extinguisher Missing (within 15 ft)		×						
3	10	Emergency Light Not Working		X						FBC 423.17.1
3	9a	Emergency Evacuation Sheet Missing		×						FBC 423.14.2.4
ç	q6	Emergency Evacuation Sheet Missing		X						FBC 423.14.2.4
	13	Bulb Emergency Light Out		×						FBC 423.17.1
2	21	LB Conduit Cover Missing	X							NFPA-70 314.1
9	25	Missing Boys Restroom Sign		×						FBC 423.20.1
	26	Missing Girls Restroom Sign		Χ						FBC 423.20.1
8	29	Emergency Evacuation Sheet Missing		×						FBC 423.14.2.4
10	1b	Emergency Light Out		X						FBC 423.14.2.4
	~	Occupancy Load Sign Missing		×						FBC 1004.3

(000)

ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH COMPREHENSIVE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

FACILITY #: 000;

SCHOOL

GREEN COVE SPRINGS, FLORIDA 32043

OCTOBER 4, 2005 NSPECITOR'S SIGNATURE INSPECTION DATE:

Ruio	7.1		3	42.4	4.2.4	4.2.4	8			
	FBC 423.17.1		FBC 1004.3	FBC 423.14.2.4	FBC 423.14.2.4	FBC 423.14.2.4	FBC 804.2.3			
Scheduled for Correction										
No. of times										
Fac. Info. "C" Serv. "LS."										
Oper.	×	X	×	X	×	X	×		1	
Maint. "M"								X		
Deficiency Description and Corrective Action Required:	Bulb Emergency Light Out	"K" Extinguisher Missing	Occupancy Sign Missing	Emergency Evacuation Sheet Missing	Emergency Evacuation Sheet Missing	Emergency Evacuation Sheet Missing	Ceiling Tile Missing	Boys Restroom Missing Handicapped Lavatory		
Room	-	2	101	101	102	110	116		20 00 (A)	
Building	10	10	11		11	1	11	20		




COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: CHARLES E. BENNETT ELEMENTARY SCHOOL
1 SOUTH OAKRIDGE AVENUE
GREEN COVE SPRINGS, FLORIDA 32043
INSPECTION DATE: OCTOBER 4, 2005
INSPECTION DATE: OCTOBER 4, 2005
INSPECTION SIGNATURE DATE

Building	Room	Building. Room Deficiency Description and Corrective Action Required:	Maint "'N"	Oper. "O"	Fac. "C"	Info. Serv. "LS."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule	
82	46	Roof Leak over TV	×								
	47	Bookcase in front of Electric Panel		×						NFPA-70 110-26	
	43	OK									
	48	OK									
	49	OK									
	-20	ОК									
	51	OK									
	52	ОК									
	53	OK									
	54	Ж									
	55	OK									
	- 26	OK									
	25	OK									

Š



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY # 0002


FACILITY: CHARLES E. BENNETT ELEMENTARY SCHOOL
1 SOUTH OAKRIDGE AVENUE
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE:

10.4.0 DATE

OCTOBER 4, 2005

					1					
Building	Коош	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	ZG.	info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Ruie
92	501	OK								
	502	OK								
	601	OK								
	602	OK								
	603	OK								
	604	0K								
	909	R-38c Lens cover missing in storage room	×							NFPA 70 410.3
	701	Жо								
	702	OK								
	703)OK								
	801	Light cover missing		×						NFPA 70 410.3
	****	REPLACE WOOD RAMPS TO MEET ADA REQ	×							FBC 11-4.9.4



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

•		1.
_	41	п,
		110
	· .	
	_	150
	. 1	
-	-	. 10
_	=	
-	_	
•	٠.	1
_	,	- 2
_	_	
•	•	٠.;
•		
٠.		٠.
ш	ь.	. 7
-		
		٠,
		1.:
-		П.
	3	
		Ι.
		Ι.
1.	4.8	
v .	2	
		17
	3:	Ι.
		١.
- 4	351	
4		١.
		13
٠.		10.0
		١.
`	P	
,	-	13
	-	100
_	1	и.
_	•	
	- 1	
•	-	
	•	17
	1	10
٠,	•	
٠.,		.5
	1. 5	ALTO COLUMN
23	55	
•	7	12
-	_	6
17	7	
•	•	
Ŀ	J	1.
•	_	
•	-	
•	•	٠.
ш		
	٠,	
_	_	. 1
•	-	
-	_	. 4
7		1.5
•	•	3
-	-	17
ë		
Г	1	١,
	-	٠,
ź.,	4-	١,
Į,	11	
Į,	1	۲,

0021

FACILITY: CLAY HILL ELEMENTARY SCHOOL 6345 STATE ROAD 218

JACKSONVILLE, FLORIDA 32234

INSPECTION DATE: NOVEMBER 12, 2005

INSPECTOR'S SIGNATURE

DATE

			4	age of	_		10 gar	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
	NFPA 70 314.1	NFPA 70 314.1	FBC 423.25.6.4	NFPA 70 314.1	NFPA 70 314.1				
Rule	02	70.	23.2	70:	70				
	FPA	FPA	3C 4	FPA	FPA				
	z	Z	芷	Z	Z				
<u> </u>									
Scheduled for Correction									
တိ ဝိ									
Jef.									
No. of times Def. Cited									
									100
Cost									
Ö									
								8119150 8375155 2485165	
Info. Serv. "I.S."	,×								(4) (1) (1) (4) (1) (1) (4) (1) (1) (4) (1) (1)
		974.7 274.8							774794 2003
C									
Oper.									
o .									34761 3754
									//thes
waimt. "W"		×	×	×	×				
							10.5		
j j									
Jim De		98	Ħ	S					
on R		lade	n't 1	lace					
Acti		es/b) wc	0 0					
ctive		W	toc	g tv	X				
orre	<u> </u>	ing	ose	ssin	n bo		[
D D	l é	niss	t c	E.	atio			14.75 30.87	1500
	l gn	er	u II	ove	nic				
ad .	issi	So	r wi) X	mu				
Desc	E	ust	utte	n bc	00				0.37 ~ 5-63
D	t bo	xhe	ı sh	larr	r off		144		
Deficiency Description and Corrective Action Required:	Outlet box missing phone	Fan/exhaust cover missing; wires/blades	Storm shutter will not close; tool won't fit	Fire alarm box cover missing two places	Cover off communication box		120次 元指表式	44.55 shi 30.43 shi 30.37 shi	18.30
300000000000000000000000000000000000000	-		<i>(</i>)				2000 2000 2000 2000	76/10) 186.00	
Коош	222	400	504	506	909				
172-712-1-12-1	.,							100 mg/m	5.600 54.60
Building				5					
B	2	4	5	2	9				
SELECTION	<u> </u>	1146.75		最高等		Physica		(M.A).	

(CHE 2005-06 SREF INSPECTION REPORT.KPG.wpd)

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT CLAY FACILITY#

0021

FACILITY: CLAY HILL ELEMENTARY SCHOOL 6345 STATE ROAD 218

JACKSONVILLE, FLORIDA 32234

INSPECTION DATE: NOVEMBER 12, 2005

Nov!

INSPECTOR'S SIGNATURE

Rule Scheduled for Correction No. of times Def. Cited Cost Info. Serv. "I.S." rg. Car Oper. "O" Maint. "M" Deficiency Description and Corrective Action Required: ð 쏫 S Š Š Š Š Š Ş 충 S ş 엉 엉 Room 989 706 682 684 702 703 704 705 708 710 681 701 707 709 Building 92 92 92 92 92 92 92 92 92 92 92 92 92 92

COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

*	
0021	110
\sim	3.
~	1.1
$\underline{}$	5 .
0	1
-	1,3
. /1.	100
1.32.0	111
	1.
11.1	1.
1.7	7
1111	3.0
	·
-11-	re-
	- 21
	1.
~	5. 3
	, F) ,
	28°,
	4.7
_	
FACILITY #:	٠,
U	- 0
~	27
•	j.
11	
_	ж.
4.77	
	٠.
1.4	154
25 15	
3.00	- 74
3:10	
97.4	š.,
	11
6.7	
110	
371	1
1175	1
CLAY	: -
\sim	
~	1,12
-	. 3
الن	10.5
10	1.1
· •	
1	35
10 e	
4.5	1.
. ei e	J.
	vid
	1
6	
ပ	
င္ည	
<u> </u>	
RIC	
TRIC	
STRIC	
STRIC	
ISTRIC	
DISTRIC	
DISTRIC	
DISTRIC	
DISTRICT	にいいいのではない
DISTRIC	にいいいのではない
DISTRIC	The contract of the contract o

FACILITY: CLAY HILL ELEMENTARY SCHOOL 6345 STATE ROAD 218


JACKSONVILLE, FLORIDA 32234

INSPECTION DATE: NOVEMBER 12, 2005

INSPECTOR'S SIGNATURE D

DATE

Building	Room	E	Make a Wood Ast	Deficiency Description and Corrective Action Required:		5	Sesci	1	5		5	15	Ne /	ğ	E	g Gedi	<u>a</u>			Hillian.					25	Maint. "M"	THAT!		Oper. "O"				fac.	Zekow.		0. S. "I.S.	Info. Serv. "LS."	RAZENIATO	Cost		1.0	No. of times Def. Cited	g ,	Ø O	ched fo orre	Scheduled for Correction	Francisco Sassellaria		Rule	O		
92	711	¥ -	N.	ş	55 64	합 19			j.	iĝ.	3	74 (*)	5 c c c c c c c c c c c c c c c c c c c		er Er	id M	ij.		1) 1)		11. 10.	i. V			S.		4	W.	Q.	44		(i) (i)	ä				A D	<u>孫</u>	Ä		12) 14) 11	() /// 14.	41) 54) 61)	3							(). ().	
92	712	7	Ale S	Š				7. 616. 538.9		100			25 B					17.4			議議		Thurs !					40 15 CE			TEN.			1,455		10451		THE R		The s					19.700	Children (1.788704 1.1885370	300	10000			
92	760	٥		ş															l																	l																
92	762			OK																			17.98								The Art			242				MAN	159-159- 1400-01								\$4,640 B					
92	764	4		ş																																																
92	766	ဖ	-	Š																			5311L				W.W.	SA PAR		Aviole Avolyn 178	10440	製化		355				AMARIA.									1700E					
		(1) (1) (1)	176.74 176.74	121 1535 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1						n. 1 km s		7 3 1 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						\$100 (100 ft) \$100 (100 ft) \$100 (100 ft) \$100 (100 ft)				G G T						24,55 24,45			190 grands			The real		1.645 54.545		191736 191736									\$2555 \$6054		1 74.4 1 74.4 1 84.4		15 The Say	
		77/48 10/45	Ve/Ap		100			in but				715 161 #76	Think!	25, 5 25, 48	4844			A PARTY			3/3, 3/4 3/4/3/6		12 12 12 12 12 12 12 12 12 12 12 12 12 1	1. (4.17) 2. (4.17)			MARCHA DAY				- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			20 A A				W. C.		AMA			Mas (5445 S445		250%	4:35 405	49.44			
		3/3/	29.1%		1000				11.7 (1) (1) (11.7 (1) (1) (13.6 (1) (2)	17.00			0,8000 0,8000								0.5		327474 dente				100 mm / 100	18 VIII. 18 GUG			14000			VAR.	118 979 1924 Sa		16 16 16 16 16 16 16 16 16 16 16 16 16 1	A Property Statement									(1995) A 1995			4.1		
		100	777				15.9		616.31 - 1/2.51 - 14.54					1000		at a		77210	. The		1		12.5				24				A43			100	11/1/2	100	14.0	200					3.67	196	V.		3// Aug			1.4		



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

PISTRICT. CLAY FACILITY# 00008

FACILITY: DOCTORS INLET ELEMENTARY SCHOOL
2634 STATE ROAD 220
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 11, 2005

AMELIA - HWAMAN
INSPECTOR'S SIGNATURE DAT

/0 - // DATE

Building	Коош	Deficiency Description and Corrective Action Required:	Waint.	Oper "O"	Fac.	Info. Serv. "I.S."	Cost	No. of times Def. cited	Scheduled for Correction	Rule
4	110	TV not secured in bracket		×						
4	108	Covers missing on electrical boxes	X							NFPA 314.1
4	122	Emergency light out		×						FBC 423.17.1
2		OK								
9		OK								
L		Building numbers not on exterior		×						FBC 423:14.2.3
8		Building numbers not on exterior		×						FBC 423.14.2.3
8		Gutter on East and West sides plugged		×						
8	815	J-box on air handler open	×							NFPA 314.1
8	815	Door sticking		×						NFPA 1 14.5.2
6		Building numbers not on exterior			×					FBC 423.14.2.3



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: CLAY FACILITY # 0008

FACILITY: DOCTORS INLET ELEMENTARY SCHOOL
2634 STATE ROAD 220
MIDDLEBURG, FLORIDA 32068

MIDDLEBURG, FLORIDA 32068

ON INSPECTION DATE: OCTOBER 11, 2005

MANATA TOTALITY # 00008

Building	Room	Deficiency Description and Corrective Action Required:	Maint	Oper	Fac.	Cost	No. of	Scheduled	Rule	西极
					C" Serv. "I.S."		times Def. Cited	Correction		California (
92	836	OK								
92	837	OK								1880
92	838	OK								
92	839	OK								
92	840	OK								
-92	841 A&B	OK								415/5
92	842 A&B	OK								
92	843	OK								(1 Cr.,
95	844	OK								
92	845	ОК								(AC 81)
95	846	OK								
92	848	OK								(della
92	850	OK								
92	698	OK								49450

(DIS 2005-06 SREF INSPECTION REPORT.wpd)



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY #: 0008

FACILITY: DOCTORS INLET ELEMENTARY SCHOOL
2634 STATE ROAD 220
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 11, 2005

ANSPECTOR'S SIGNATURE

DATE

				,				
Building	Room	Deficiency Description and Corrective Action Required: "Mai	Maint: Oper. "M" "O"	Fac S	Info. Cost Serv. "I.S."	No. of times Def. Cited	Scheduled for Correction	Rule
92	870	OK						
92	871	OK						
92	872	ОК						
92	873	OK						
92	874	OK						
92	875	Emergency light inoperable	X					FBC:423:17.1
92	875	Fire exiting not checked monthly	×				2	NFPA 10, 4-2.1
92	876	ОК						
92	888	OK						
92	890	OK						
92	891	OK						
92	892	ЭК						
92	893	OK						
- 35	894	ЖО						



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: DOCTORS INLET ELEMENTARY SCHOOL
2634 STATE ROAD 220
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 11, 2005

MANNY 10 -1/-05

DATE

MSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint: Oper. "M" "O."	C S	Info. Cost Serv. "I.S."	t No. of times Def. Cited	Scheduled for Correction	Rule
92	895	Lens covers missing	×					
92	968	OK						
92	897	OK						
- 92	868	OK						
92	899	OK						
92	006	Two lights out	X					
92	901	УО						
92	902	OK						
92	904	OK						

(DIS 2005-06 SREF INSPECTION REPORT.wpd)



"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH COMPREHENSIVE SAFETY INSPECTION REPORT ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 F.S. 1013.12, 1013.20 & NFPA 101 STATE BOARD OF EDUCATION

CLAY FACILITY# 0038	FACILITY: FLEMING ISLAND ELEMENTARY SCHOOL	4425 LAKE SHUKE DKIVE ORANGE PARK, FLORIDA 32003
DISTRICT: CLAY	FACILITY:	

OCTOBER 13, 2005 NSPECTOR'S SIGNATURE INSPECTION DATE:

13.05 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper.	.c.	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
Υ-	114	NO FIRE EXTINGUISHER BY RANGE		×						69A-36
	120	EXCESSIVE STORAGE IN ELECTRICAL ROOM		X						NFPA-70-110.26
2		EMERGENCY EVACUATION SHEETS MISSING BLD		×						FBC 423.14.2.4
4		NO EXTERIOR NUMBER ON BUILDING		X						NEPA-1 10 13
7		NO EXTERIOR NUMBER ON BUILDING		×						NFPA-1 10.13
	712	NO FIRE EXTINGUISHER BY RANGE		×						69A-36
	721	NO FIRE EXTINGUISHER BY RANGE		×						69A-36
	721	WET SPOT ON CEILING (ROOF LEAK)	X							
98 93 93 93 93 93 93 93 93 93 93 94 94 95 95 95 95 95 95 95 95 95 95 95 95 95	70 m		5.4 217 217 217 217 217						A Company of the Comp	
						440 171 183 183				
92	601	ОК								
	602	OK								
	603	OK								
	604	EXHAUST FAN NOT WORKING	X							FBC 423



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

PISTRICT CLAY FACILITY# 0038 FACILITY: FLEMING ISLAND ELEMENTARY SCHOOL 4425 LAKE SHORE DRIVE	ORANGE PARK, FLORIDA 32003
--	----------------------------

INSPECTION DATE:

DATE

13.05

OCTOBER 13, 2005

Building	Room	Deficiency Description and Corrective Action Required:	Waint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times.Def. Cited	Scheduled for Correction	Rule
95	605	REPLACE NON-SKID ON RAMP		×						FBC 1013.9
	909	OK								
	209	OK								
	- 809	FIRE EXTINGUISHER NOT SIGNED		X						NFPA-1 7.6.4.1
	262	OK								NFPA-1 10.13
	798	OK								69A-36
	662	OK								69A-36
	800	Э								
	801	OK								
	802	OK								
	803	OK								
	804	NO.								
	805	REPLACE NON-SKID ON RAMP		×						FBC 1013.9
	805	EMERGENCY LIGHT OUT		×						FBC 423.17.1



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY # 0038

FACILITY: FLEMING ISLAND ELEMENTARY SCHOOL

4425 LAKE SHORE DRIVE
ORANGE PARK, FLORIDA 32003

N INSPECTION DATE: OCTOBER 13. 2005
IMSPECTION'S SIGNATURE DATE

DATE

Building	Коош	Deficiency Description and Corrective Action Required:	Maint "W"	0per "0"	Fac	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	908	REPLACE NON-SKID ON RAMP		×						FBC 1013.9
	807	ОК								NFPA-70 110:26
	808	BATHROOM LIGHT OUT		×						
	809	FIRE EXTINGUISHER MISSING.		X						
	810	EMERGENCY LIGHT OUT		×						FBC 423.17.1
	811	OK								
	812	OK	-							
	824	REPLACE NON-SKID ON RAMP		X						FBC 1013:9
	826	REPLACE NON-SKID ON RAMP		×						FBC 1013.9
	828	Уо								
	830	REPLACE NON-SKID ON RAMP		×						FBC 1013.9
	832	OK								
	841	FIRE EXTINGUISHER NOT SIGNED		×						69A-36
	842	EMERGENCY LIGHT OUT		X						FBC 423.17.1
		NO EXTINGUISHER BY STOVE		×						69A-36



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

 DISTRICT
 CLAY
 FACILITY #:
 0038

 FACILITY:
 ELEMING ISLAND ELEMENTARY SCHOOL
 4425 LAKE SHORE DRIVE

 ORANGE PARK, FLORIDA 32003

INSPECTION DATE:

OCTOBER 13, 2005

. 0 X

W

DATE

MSPEGTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	MainC "M"	Oper. "O"	Fac.	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Ruie
92	843	OK		1. 62.5 A 1. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.	S Charles	The first statement of the statement of				受けていた。 ないがい さいじょ はれた はなければは はいずい
	844	EXTINGUISHER NOT SIGNED		×						69A-36
	845	DOOR CLOSURE @ STAIR BROKEN		×						FBC 423.27.8.1
	846	CEILING-TILE MISSING IN BATHROOM		×						FBC 804.2.3
	847	ΟK								
	848)OK								
	849	NO.								
	850	REPLACE NON-SKID ON RAMP		X						FBC 1013.9
	851	EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
	852	REPLACE NON-SKID ON RAMP		X						FBC 1013;9
		LIGHT OUT IN BATHROOM		×						
	860	REPLACE NON-SKID ON RAMP		X						FBC 1013.9
		EMERGENCY EVACUATION SHEET MISSING		×						FBC 423.14.2.4
		EMERGENCY LIGHT OUT		X						FBC 423
	A 10	the designation of the second	C tanda amonto	the second second			200 00 00 00 00	the second second second		*



COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY # 0038

FACILITY: ELEMING ISLAND ELEMENTARY SCHOOL

4425 LAKE SHORE DRIVE

ORANGE PARK, FLORIDA 32003

INSPECTION DATE:

DATÉ

13.05

OCTOBER 13, 2005

海湖湖水湖			が発						
Supplied in the state of the st		Description and Corrective Action required:	"M"	O.,	 Serv. "[.S."	COST	no. or times Def. Cited	Scneduled for Correction	Kule
82	861	OK							
	862	OK							
	901	DRINKING FOUNTAIN OUT OF SERVICE	×						
	902	FIRE EXTINGUISHER NOT SIGNED		X					NFPA-1.7-6.4.1
	803	LENSE COVER MISSING @ ENTRY	×						
		BATHROOM EXHAUST FANS NOT WORKING BOTH	X						
		ROOM SIGNS MISSING		×					NFPA-1-10.13
	904	FIRE EXTINGUISHER NOT SIGNED		X					NFPA-1 7-6:4-1
		EMERGENCY LIGHT OUT		×					FBC 423.17.1
	905	FIRE EXTINGUISHER NOT SIGNED		X					NFPA-1 7-6.4.1
		DOOR @ STAIRS STICKS	×						
	906	уо							
	206	FIRE EXTINGUISHER NOT SIGNED		×					
	806	LENSE COVER MISSING STORAGE CLOSET LIGHT		X					NFPA-70 410.3
							,		



FISCAL YEAR 2005-2006 COMPREHENSIVE SAFETY INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "FIRE SAFETY, CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

Las conclusion		19.00	W. S. S.	F.	908	48×40F	Secretaria.	Sets	.,94.1.7
				1					
	Ξ:	NFPA-1 7-6 4.1		4					
	6.4	9		တ် 📗	646) 1474				160
<u>a</u>	7	1	THE STATE OF THE S	4					
Rule	NFPA-1 7-6.4.1	5		FBC 11-4.9.4				195 X 257 33	
	14	2		8					
	불	눌	731.7744 C135745	T [27.		1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	0.00
		No.	#124 P					1346	14.00
		1914		913 145	784 -	tant.		##.	
		是生物		db	199	24 55 C	15.74/44	1441	1.35
Scheduled for Correction				(1) (1)			Agriffy his		
월 우 필		200	Participal to	411 188		146.151	742.7		1855
% රි				133			- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	\$0.74 \$0.74	
VIEW TENET FREE		599	# # # # # # # # # # # # # # # # # # #	[24] 449	1966) 1966 (1	oriens)	\$54.52 Free 34	2% EQ.	\$1.55 \$1.55
							- 12314	2.	
g 0 g		71234 27-444		2.5		537994 2017 York			
No. of times Def. Cited									- 254
			74.5					12.4	
96401954 45906 5	<u> </u>	1,610¢	3,3454	191	(245)	\$ 5 6 9 W	469,5	1552	2540
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			进入数		
Cost			14454				3899		
8									45
									162
A PETONENCE I.		451.51	\$3.565		200	1992.31	Letters .	94.59	180 CH
Info. Serv. "1.S."				3	dia.				
≣ % : '			1234	7					
Tribling Art San		等 数定	V4578	- 3		(870)A	75969	35050	Approx.
				\$4 \$4	10 A		14,756		18910
Fac. "C"			4574	1					
128.W.4.19		Wille.	都将	12	MAC 1572	19/1/9/6			
		15,57	200	11,3		MON	W. 182	建	15.64
Oper. "O"	×	×				399			
0							100 Anna 1		
175 (340) (450)	-	1991.6	252,583	/2 /2	dia	75,47a.14	10((4))	97894F	7853
Maint "M"			17.03 (19.	×		a-bal W			
Ma				^					
である。 ないは、ことでは、ままた		8,5943 38,593	35354	100	600 3400	GUPAV Reviews	5335	RARA TA	193430
					ASAY Nin		15/44		
		300		兴 🗟					
				۶	545 100 51				
				4					
				₫				3670	
<u>ı</u>			4.78	6 l	56. 18.50.			1990	
 				0				6504	17.00
4			7.5	A	91A 940				1892
<u>.</u>	□		10444	A		7.77.74			445
Ą	NS.	[중]		8	1.90 1.50	Talkan (4/477		Charles A SASS
(ive	Sic	ਲ		T				4.7	
Ge	7		957	PS I					
ු දු	ž	¥		≱		###### ###############################			DATE
2	K.	껕		≥		7524	1.46		
	出	出出	344				58/6		
1	≌	<u>S</u>		8					# 10/94 # 10/0
Deficiency Description and Corrective Action Required:	FIRE EXTINGUISHER NOT SIGNED	FIRE EXTINGUISHER NOT SIGNED	46.14E.9 44.1E.3	**REPLACE WOOD RAMPS FOR ADA COMPLIANCE		V diam		1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	
Sec	Z	Z	14/14	8	GiC.	11/17/4 a		16.44 d. 5.65 d.	
ক	🔀	X		Ğ	erika Yaya		1000	11.75	
.5	Ш		100	료				h#b/4 2915/11	1.76 (1. -55%)
e e	<u> </u>	区	1.22%	流			71, 1, 1, 1, 1		
0	ഥ	E. 1133	4995	¥ 2		475	77.7		1000
ethis harmon's que		910	PASE	325 19				13 - 13 m	9983
Room	606	2		325			F 1/47/4		15,1401
Ä	တ	0			104. 104.	显然的		507 si 64940	
		315 P	17775-0	4,0	5.01	2.3845	3375C	674.734	5.4000 3.500
Building		1966 1796	ALC:	4.14		1,000		新花	100 A
₩.	92	51/4	3/2/8	1.0	444) 444)				41.04
•				17		444	4775		
		1	E 97.00	18.45	2 ST 1	200,000	29 25	33,997.9	125 1 16 1