


# RIDDGEVIEW SENIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 9-9-05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	108a	COVER PLATE ON J-BOX MISSING	X							NFPA-70 314.1
1	107a	EXIT LIGHT OUT		X						FBC 423.17.1
	135a	EXIT SIGN DIRECTION ARROW MISSING		X						FBC 423.17.1
	135a	EXIT SIGN OUT		X						FBC 423.17.1
	140	EXPOSED WIRES WHERE CLOCK WAS REMOVED	X							NFPA-70 312.5
	140	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	146	CEILING TILES BROKEN/MISSING/STAINED		X						FBC 804.2.3
	144	CEILING TILES BROKEN/MISSING/STAINED		X						FBC 804.2.3
	151	CEILING TILES BROKEN/MISSING/STAINED		X						FBC 804.2.3
	149	CEILING TILES BROKEN/MISSING/STAINED		X						FBC 804.2.3
	149	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2
	201	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2
	207	EXPOSED WIRES BY FIRE ALARM HORN	X							NFPA-70 312.5
2		ROOM NUMBERS MISSING		X						FBC 423.14.2.3

FISCAL YEAR 2005-2006



COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

9-9-05

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	223	EXTENSION CORD TO APPLIANCE BEHIND SINK		X						NFPA-1 11.1.5
	224	LENS COVER MISSING	X							NFPA-70 410.3
	233	FIRE EXTINGUISHER HEADS NOT OVER FRIERS	X							NFPA-1 50.4.4.6
	233	DOOR MISSING	X							
	233	LENS COVER MISSING	X							NFPA-70 410.3
	233	SWITCH PLATE MISSING	X							NFPA-70 314.1
	234	LENS COVER MISSING	X							NFPA-70 410.3
	221	LIGHT MISSING WIRES EXPOSED	X							NFPA-70 312.5
	216	LENS COVER MISSING	X							NFPA-70 410.3
	208	EXTENSION CORDS DRAPED FROM SUPPORT RODS		X						NFPA-1 11.1.5
	201	STAIR NOSING ON WEST SIDE BROKEN	X							FBC 1007.3.3
	211	EXIT SIGN MISSING		X						NFPA-1 7.10.6
	211	DOOR KNOB MISSING	X							NFPA-1 14.5.2
8	826	EXTENSION CORD TO MICROWAVE		X						NFPA-1 11.1.5

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0022

FACILITY : RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 9.9.05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
8	801	EXTINGUISHER COVER BROKEN		X						
	808	EXTINGUISHER COVER BROKEN		X						
	829	EMERGENCY LIGHT OUT		X						NFPA-101 7.9
	829	WIRES EXPOSED	X							NFPA-70 314.1
9	901	COVER PLATE MISSING BETWEEN AIR HANDLERS	X							NFPA-70 314.1
	901	MATERIALS STORED FRONT OF ELECTRICAL PANEL		X						NFPA-70 160.26
	902	LIGHT OUT		X						FBC 423.17.1
	911	EMERGENCY LIGHT OUT N WEST		X						FBC 423.17.1
	911	EMERGENCY LIGHT OUT N WEST		X						FBC 423.17.1
	911	EMERGENCY LIGHT OUT NORTH BLEACHER		X						FBC 423.17.1
	911	FIRE EXTINGUISHER AT NW CORNER MISSING		X						NFPA-10 7-6 15
	911	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2
	903	ROOM NUMBER MISSING		X						FBC 423.14.2.3
	903	COVER PLATE MISSING	X							NFPA-10 314.1

FISCAL YEAR 2005-2006



**COMPREHENSIVE SAFETY INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
"FIRE SAFETY, CASUALTY SAFETY & SANITATION  
INSPECTION" IN COMPLIANCE WITH  
F.S. 1013.12, 1013.20 & NFPA 101**

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
466 MADISON AVENUE  
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

9.9.05

INSPECTOR'S SIGNATURE \_\_\_\_\_ DATE \_\_\_\_\_

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
9	904	ROOM NUMBER MISSING		X						FBC 423.14.2.3
	904	EMERGENCY LIGHT OUT		X						FBC 423.17.1
	911	SW WALL COVER PLATE MISSING	X							NFPA-70 314.1
	924	EMERGENCY LIGHTS IN HALL BROKEN (3)		X						FBC 423.17.1
	919	EMERGENCY LIGHT OUT		X						FBC 423.17.1
	940	EMERGENCY LIGHT OUT		X						FBC 423.17.1
	941	EMERGENCY LIGHT OUT		X						FBC 423.17.1
	924	EXIT LIGHT OUT		X						FBC 423.17.1
	929	LIGHT OUT		X						
	916	EMERGENCY LIGHT OUT		X						NFPA-101 7.9
	914	EMERGENCY LIGHT OUT		X						NFPA-101 7.9
	930	EXIT LIGHT OUT WEST WALL		X						NFPA-101 7.9
	950	LOCK WILL NOT OPEN	X							NFPA-1 14.5.2
9		EMERGENCY EVACUATION SHEETS MISSING		X						FBC 423.14.2.4

FISCAL YEAR 2005-2006



COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0022

FACILITY : RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

9.9.05

DATE

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	301	FIRE EXTINGUISHER MISSING IN HALL		X						NFPA-10 7.6.15
	320	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	315	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	302	EXIT LIGHT MISSING IN FRONT OF RM 302		X						FBC 423.17.1
	301	LENS COVER MISSING WEST END	X							NFPA-70 312.5
	348	CEILING TILE MISSING		X						FBC 804.2.3
6	632	WIRES EXPOSED COVER MISSING	X							NFPA-70 314.1
	635	EXIT LIGHT OUT EAST END		X						FBC 423.17.1
	635	SWITCH PLATE COVER MISSING	X							NFPA-70 314.1
	602	FIRE EXTINGUISHER NOT WITHIN 15ft STOVE TOP		X						NFPA-13
	602	TRAP UNDER SINK LEAKING	X							
	666	TELEPHONE WIRES THROUGH DOORWAY				X				
	638	EXIT LIGHT BROKEN NORTH END		X						FBC 423.17.1
	689	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4

FISCAL YEAR 2005-2006



COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 9.9.05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
6	690	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	688	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	688	EXIT LIGHT OUT		X						FBC 423.17.1
7		ROOM NUMBERS MISSING		X						FBC 423.14.2.3
	705	EXIT LIGHT OUT		X						FBC 423.17.1
	705	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.3
10	1006	FIRE EXTINGUISHER MISSING		X						NFPA-13 10.7.6.15
		HANDRAILS MISSING AT STADIUM			X					NFPA-1
92	1	OK								
	2	OK								
	3	EMERGENCY LIGHT OUT		X						FBC 423.17.1
	4	OK								
	5	EMERGENCY LIGHT OUT		X						FBC 423.17.1

FISCAL YEAR 2005-2006



COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 9.9.05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	6	OK								
	7	OK								
	8	OK								
	9	OK								
	10	OK								
	11	OK								
	12	OK								
	21	REPLACE NON SKID		X						FBC 1013.9
	21	STROBE LIGHT MISSING	X							FBC
	22	RAMP HANDRAIL DAMAGED	X							FBC 423.23
	23	OK								FBC 423.14.2
	24	EMERGENCY LIGHT OUT		X						NFPA-101 7.9
	25	RAMP HANDRAIL DAMAGED	X							
	26	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4



FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

9.9.05

DATE

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	27	EMERGENCY LIGHT OUT		X						NFPA-101 7.9
	27	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	28	OK								
	29	REPLACE BUTTON SWITCH TIMEOUT ROOM	X							69A-58
	30	OK								
	31	OK								
	32	OK								
	41	OK								
	42	OK								
	43	OK								
	44	OK								
	45	OK								
	46	OK								
	48	OK								

FISCAL YEAR 2005-2006

COMPREHENSIVE SAFETY INSPECTION REPORT  
 STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
 "FIRE SAFETY, CASUALTY SAFETY & SANITATION  
 INSPECTION" IN COMPLIANCE WITH  
 F.S. 1013.12, 1013.20 & NFPA 101



DISTRICT: CLAY FACILITY #: 0022

FACILITY: RIDGEVIEW HIGH SCHOOL  
 466 MADISON AVENUE  
 ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 9.9.05

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	50	OK								
	61	OK								
	62	OK								
	63	LENSE COVER MISSING	X							NFPA-70
	64	OK								
	65	OK								
	66	OK								
	67	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	68	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	69	BATHROOM DOOR STICKS	X							
	70	RAMP MISSING SPINDLES	X							
	71	EXHAUST FAN LOOSE	X							NFPA-70 312.5
	71	SMOKE DETECTOR HANGING FROM CEILING	X							
	72	OK								

FISCAL YEAR 2005-2006

DISTRICT: CLAY FACILITY #: 0022



**COMPREHENSIVE SAFETY INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5  
"FIRE SAFETY, CASUALTY SAFETY & SANITATION  
INSPECTION" IN COMPLIANCE WITH  
F.S. 1013.12, 1013.20 & NFPA 101**

FACILITY: RIDGEVIEW HIGH SCHOOL  
466 MADISON AVENUE  
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: SEPTEMBER 9, 2005

9-9-05

INSPECTOR'S SIGNATURE: *[Signature]* DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	74	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	81	OK								
	82	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	83	OK								
	84	OK								
	85	OK								
	86	OK								
	87	INTERCOM NOT WORKING	X							
	88	OK								
	89	OK								
	90	EMERGENCY EVACUATION SHEET MISSING		X						FBC 423.14.2.4
	91	OK								
	***	REPLACE WOOD RAMPS FOR ADA REQUIREMENTS								