



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT:	CLAY	FACILITY #	0013	
l			- 141777777	The state of the state of the state of	

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FLORIDA 32043

٨	ISF	PECT	ION	DATE:	OCTOBER	2 2008
			1014	Unil.	OOIODEN	£. £000

NSPECTOR'S SIGNATURE

10.2-08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	117	BROKEN BASE TILE	. X							FBC 804.2.3
1	130	LIGHTS NOT WORKING	Х							FBC 1006.3
1	134	EQUIPMENT BLOCKING EXIT		Х						FBC 423.20.1
4	138	WALL CRACKING BY DOOR	X							
1	138B	CEILING TILE MISSING / STAINED		X						FBC 804.2.3
	143	LENS COVER ON LIGHT MISSING		X						NFPA 70
1	144A	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
1	144A	CEILING TILE MISSING		Х						FBC 804.2.3
2	202	FIRE SUPRESSION INSPECTION ON HOOD OUT OF DATE	х							
2	209	EXIT LIGHT OUT	Х							FBC 1006.3.1
2	224A	MOLD ON CEILING TILE		Х						FBC 804.2.3

CLAY HIGH SCHOOL 2008-09 SREF INSPECTION





COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY:	CLAY HIGH SCHOOL	
	2025 HIGHWAY 16 WEST	

GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: OCTOBER 2, 2008

MSPECTOR'S SIGNATURE

10.2.08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	325	WIRE EXPOSED IN CEILING	Х							NFPA 70 110.12
3	325	HEAT/SMOKE DETECTOR MISSING	Х							
3	328	CEILING TILES MISSING		Х						FBC 804.2.3
3	328	LENS COVER MISSING ON LIGHT								NFPA 70
3	333	DOOR WILL NOT CLOSE	Х							
3	342B	NO EVACUATION SHEET		Х						FBC 423.14.2.4
3	366A	CEILING TILES MISSING		Х						FBC 804.2.3
3	389A	NO EMERGENCY LIGHT	Х							FBC 423.17.1
3	389B	NO EMERGENCY LIGHT	Х							FBC 423.17.1
3	383	EMERGENCY LIGHT OUT	Х				2 %			FBC 423.17.1
3	383	CEILING TILES MISSING		Х						FBC 804.2.3
3	383	SMOKE DETECTOR ON CEILING LOOSE	Х							NFPA 70 110.12
3	393	CEILING TILES MISSING		Х						FBC 804.2.3



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY		FACILITY #:	0013	14		
April 7		- A					

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FLORIDA 32043

NSPECTION	DATE:	OCTOBER 2, 2008	
-----------	-------	-----------------	--

INSPECTOR'S SIGNATURE

ATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
4	<u> </u>	ОК								
5		OK								
6		ок								
7	730	LIGHT IN FRONT OF DOOR LOOSE	Х							NFPA 70 110.12
8	807	PAINT PEELING ON WALLS	X							
8	808	PAINT PEELING ON WALLS	Х							
8	809	MOLD ON CEILING TILES		Х						
8	828	SMOKE DETECTOR HANGING FROM CEILING	X							NFPA 70 110.12
8	830	MOLD ON CEILING TILE		Х						
8	830	TEAR IN STAGE CURTAIN		X						
8	830	RETURN AIR REFILL NEEDS CLEANING		Х						
8	831	PAINT PEELING ON WALLS	Х							19 151.17 19 15 15 15 15 15 15 15 15 15 15 15 15 15
8	831	ELECTRICAL OUTLET STRIP ON WALL BROKEN	Х							



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILIT	Y #:	0013	
_					

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE:	OCTOBER 2, 2008
------------------	-----------------

INSPECTOR'S SIGNATURE

ATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
8	831	EMERGENCY LIGHT HANGING	Х							NFPA 70 110.12
8	835	WIRES HANGING FROM CEILING	X							NFPA 70 110.12
8	835	EMERGENCY LIGHT LOOSE ON CEILING	Х							NFPA 70 11012
11	1129	PANEL COVERS NO ON PANEL								NFPA 70
29		ок								
30		OK	Mariana Mariana Mariana							
31		ок								
35		OK				14.3				
					e de cas la					



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY # : 0013	

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FLORIDA 32043

INSF	ÆC	TION	DATE:	OCTOBER 2, 2008

INSPECTOR'S SIGNATURE

10-7-08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rute
92	5A & B	ок								
92	7	WOOD RAMP – NON SKID		Х						FBC 1006
92	8	ок								
92	-17	oK								
92	18	ок								
92	19	OK.								
92	20	ROTTED WOOD FLOOR BY STAIR DOOR	Х							
92	31	OK.								
92	32	ок								
92	33	WOOD RAMP	Х							
92	41	ОК								
92	42	oK								
92	43	RANGE HOOD NOT DUCTED TO OUTSIDE	Х							



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY #:	0013
73 H			

FACILITY: CLAY HIGH SCHOOL

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FLORIDA 32043

INSF	PECTION	DATF:	OCTOBER	2	2008	
11401		₩/~\ I I III.		4-7	A	

INSPECTOR'S SIGNATURE

| 1-7-0\forall | DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	44	ок								
92	45	DOOR STICKS ON RAMP SIDE	X							
92	46	POOR ALLIGNMENT WHEN SET WALL & CEILING			Х					
92	47	OK				MANY				
92	49	ок								
92	58	OK								
			3.45							
							, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,			
								-		





COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY	#: (044
an esta como esta que a que en esta esta en esta en esta en en esta en entre en entre en entre en entre en en	A A CONTRACTOR AND A STREET	The state of the s	The American Control	

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

INSPECTOR'S SIGNATURE

100 100 5475

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	66	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	81	CEILING RUSTING		x		A SEA				FBC 804.2.3
1	119	CEILING TILE MISSING/STAINED		Х						FBC 804.2.3
1	134	CEILING TILE MISSING		Х						FBC 804.2.3
1	173	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
1	162	COVER PLATE MISSING/BROKEN		X						NFPA 70-110.12
1	141	CLEAN AC GRILLS & DUCTS		Х						
1	141	OCCUPANCY LOAD SIGNS MISSING		Х						FBC 423.14.2.2
10	1020	LOCK CYLINDERS MISSING		Х						
10	1024	LOCK CYLINDERS MISSING		X						
10	1027	LOCK CYLINDERS MISSING		Х						
10	1026	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
10	1025	DOOR STICKS		Х						



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FAC	LITY#:	0044	
		_{Sent} apertual and a	and the said		Talls of this of

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

Meatten/ INSPECTOR'S SIGNATURE

10-1-08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	1029	DOOR STICKS		Х						
1	220	STAIN ON CEILING		X						FBC 804.2.3
1	243	DOOR STICKS		Х						
1	264	FLOOR TILE PEELING @ EXPANSION JOINT		Χ						
1	280	FLOOR WET / PLUMBING LEAK	Х							
2	202	FIRE EXTINGUISHER NOT SIGNED		Х						69A-58.008
2	205	CEILING TILE STAINED		Х						FBC 804.2.3
2	207	CEILING TILE STAINED		Х						FBC 804.2.3
2	227	CEILING TILE MISSING		Х						FBC 804.2.3
2	230	GRILLS/RETURNS NEED TO BE CLEANED		Х						
2	240	GRILLS/RETURNS NEED TO BE CLEANED		Х						
2	228	CEILING TILES MISSING		Х		+ 1,4347 + 4 - 4 -				FBC 804.2.3
2	258	FIRE EXTINGUISHER NOT SIGNED		Х						69A-58.008

FLEMING ISLAND HIGH 2008-09 SREF REPORT



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DIS	TRIC	T:	CL	ΑY		FA	CILIT	Y #:	- 1	0044		
		-			Type and Self Type and Self							

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY

ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

NSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	240	DIRT ON SOUND PANELS		Х				2.00		
31	001	FIRE EXTINGUISHER NOT SIGNED		X						69A-58.008
31	06	CLEAN BATHROOMS		Х						
31	05	ENTRY DOOR STICKS		X						
31	04	REMOVE GAS BOTTLES		X						NFPA 1.21.1.3.3.5
31	04	FIRE EXTINGUISHER NOT SIGNED		X						69A-58.008
40	01	FIRE EXTINGUISHER NOT SIGNED		Х						69A-58.008
										Carlos Ca



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY #:	0044	
The second secon	the same transfer of the same of the same	The second section of the second	and the first of the first of the control of	age of the second section

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

Manueattane INSPECTOR'S SIGNATURE

10-7-08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	10	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	11	OK								
92	12	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	13	OK								
92	14	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	15	OK								
92	20	ОК								
92	21	OK								
92	22	EMERGENCY LIGHT NOT WORKING								FBC 423.17.1
92	23	OK								
92	24	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.2
92	25	RAMP EXCEEDS SLOPE	X					2		FBC 11.4.2
92	26	RESTROOM OK								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY #:	0044
	*. *.	The state of the s	

FACILITY: FLEMING ISLAND HIGH SCHOOL

2233 VILLAGE SQUARE PARKWAY ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

SPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	27	ок								
92	30	OK								
92	31	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	32	RAMP EXCEEDS SLOPE	X					2		FBC 11.4.8
92	33	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	34	RAMP EXCEEDS SLOPE	Х				l le	2		FBC 11.4.8
92	35	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	40	OK								
92	41	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	42	OK								
92	43	ок								
92	44	OK							To Manyang	
92	45	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY FACILITY # :	·	0044	1	
	The state of the s				

FACILITY: FLEMING ISLAND HIGH SCHOOL
2233 VILLAGE SQUARE PARKWAY

ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

Meatlan INSPECTOR'S SIGNATURE

10-7-08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	46	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	47	RAMP EXCEEDS SLOPE	Χ					2		FBC 11.4.8
92	48	LENSE COVER MISSING		Х						NFPA 70
92	49	OK								
92	50	ок								
92	51	EXTENSION CORD USED FOR OVERHEAD PROJECTOR, REMOVE ALL WIRES/CABLES NOT ALLOWED/. CLOSE CEILING TILES		X						
92	52	RAMP LANDING MISSING SPINDLES		Х						
92	52	RAMP DOOR STICKS, MAY NEED SHORING @ FLOOR	Х							
92	53	ок								
92	60	BATHROOM LIGHT MISSING COVER		Х						NFPA 70
92	61	ок								

FLEMING ISLAND HIGH 2008-09 SREF REPORT



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY #:	0044

FACILITY: FLEMING ISLAND HIGH SCHOOL 2233 VILLAGE SQUARE PARKWAY

ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

UNICATION WESTER TOR'S SIGNATURE

<u>10-7-08</u>

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	62	ок								
92	62	OK								
92	70	RAMP BOUNCY		Х						
92	71	OK								
92	72	ОК								
92	73	RAMP DOOR STICKS		Х						
92	80	ок								
92	81	OK								
92	82	RAMP SLOPE EXCEEDS 1/12	Х					2		FBC 11.4.8
92	83	LENS COVER MISSING BATHROOM/STORAGE	ye tiliği Majarı batısı	Х						NFPA 70
92	84	STAIR DOOR STICKS		Х						
92	85	EMERGENCY LIGHT MISSING LENS COVER @ RAMP DOOR		X						NFPA 70



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY #:	0044
The state of the s	the contract of the contract o	and the second of the second o

FACILITY: FLEMING ISLAND HIGH SCHOOL 2233 VILLAGE SQUARE PARKWAY

ORANGE PARK, FLORIDA 32003

INSPECTION DATE: OCTOBER 7, 2008

MSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	86	ок								
92	87	OK								
92	90	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	91	RAMP EXCEEDS SLOPE	Х					2		FBC 11.4.8
92	91	GUTTER HAS NO DOWNSPOUT		Х						
92	91	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	92	RAMP EXCEES SLOPE	Х					2		FBC 11.4.8
92	93	ОК								
92	94	ок			,					
92	95	ОК								
92	96	ок								
92	97	oK			i sa Hajir da ji sa					
1	1	1	1	1	1		1	l		



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY	r #: 0019)
	er til gjelde fram i dram halletter, eller er er ble	erani i Trefini a Propinsion	PROPERTY OF THE CONTRACTOR

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		SPRINKLER HEADS NEED TO BE ADJUSTED TO BELOW CEILING TILES – TOO HIGH	Х							NFPA 13
1	14	DOOR SHOWN ON FISH NOT THERE			X					
1	1	REMOVE ALL HOMECOMING DECORATIONS		Х						NFPA 101
1	1	REMOVE EXTENSION CORD TO DISPLAY LIGHTS		X						NFPA 70 – 400.8
1	67	SPRINKLER HEADS ABOVE CEILING	Х							NFPA 13
1C	129	EXTENSION CORD TO POWER STRIP		Х						NFPA 70 400.8
1C	126	EXTENSION CORD TO COMPUTER		Х						NFPA 70 400.8
1C	127	PANDUIT OPEN TO WIRING	X							NFPA 70
1C	122	EXTENSION CORD TO COMPUTER		X						NFPA 70 400.8
1D	144	EXCESSIVE DECORATIONS FOR HOMECOMING		X						NFPA 101
1D	159	STORAGE TO HIGH		Х						NFPA 13



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

는 사람들이 사용하는 생각 수 있다. 그는 사람들이 되었다. 그는 그는 사람들은 사람들이 사용하는 것이 되었다. 그는 사람들이 되었다. 그는 사람들이 사용하는 것이 모든 것이다. 그는 사람들이 사용하는 사람들은 사용하는 사람들이 되었다. 그는 사람들이 사용하는 것이 되었다. 그는 사용하는 사용하는 것이 되었다. 그는 사용하는 것이 되었다.	DISTRICT: CLAY	/ FA	CILITY #:	0019	

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

ATE /

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1D	164	EXTENSION CORD FROM HALL INTO CLASSROOM		х						NFPA 70 400.8
1F	241	POWER STRIP TO STRIP – REPLACE WITH LONG POWER STRIP		X						NFPA 70 400.8
1F	227	REMOVE FLAMABLE STORAGE AND FERTILIZERS OR CHANGE LIGHT TO EXPLOSION LIGHT		x						
.1F	230	ADD EXTINGUISHER BY STOVE		X						FAC 69A-58
1G	196	HALF OF EMERGENCY LIGHT BULBS OUT		Х						FBC 423.17.1
1H	285	OCCUPANCY LOAD SIGN MISSING (1800 MAX. CAP.)		Х						FBC 1004.3
1H	284A	DOORS CHAINED AFTER SCHOOL - REMOVE		Х						FBC 1006
11	339	SPRINKLERS TO HIGH - MISSING ESCUTCHEON	Χ							NFPA 13
1J	358	FIRE EXTINGUISHER NOT SIGNED		Х						FAC 69A-58
35		EMERGENCY LIGHT OUT		X						FBC 423.17.1
35		GAS BOTTLE STORED IN BUILDING		Х						NFPA 1.21-3.3.5



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY	# : 0019	Park Park Street Street

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE DAT

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
10		REMOVE ALL GAS BOTTLES		Х						NFPA 1.21-3.3.5
10		ELECTRICAL PANEL NEEDS KNOCKOUT	Х							NFPA 70 110.26
10		ELECTRICAL JUNCTION BOX - NO COVER		Х						NFPA 70 110.26
9		ELECTRICAL PANEL BLOCKED BY SHELF		X						NFPA 70 220.26



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACIL	.ITY#:	0019	

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

NSPECTION DATE: OCTOBER 14, 2008	NSPECTION DATE:	OCTOBER 14, 2008	
----------------------------------	------------------------	------------------	--

INSPECTOR'S SIGNATURE

OATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	RAMP EXCEEDS SLOPE 1-12	Х					2		FBC 11-4.8
92	5	OK								
92	7	ок								
92	9	ОК								
92	31	ок								
92	32	OK								
92	33	ок								
92	34	OK	malify est Taken y				Fact 1970			
92	35	ок								
92	36	OK								
92	41	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	1941	FACIL	ITY#:	0019	
		1 7	T	- 1850 / 186 <u>0 185</u>	Approximation of the control of the	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
And the second of the second				The Contract of the Contract o		

FACILITY: MIDDLEBURG HIGH SCHOOL


3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 200

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	42	ок								
92	43	OK								
92	44	ок								
92	45	OK								
92	46	ок								
92	47	OK								
92	51	ок								
92	52	OK								
92	53	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	54A	OK								
92	54B	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0019	

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

ATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	55	ок								
92	60	OK								
92	61	ок								
- 92	62	OK								
92	63	ок								
92	64	OK								
92	65	ок								
92	66	OK								
92	70	ок								
92	71	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	72									



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DIST	RICT	: CL	AY	FAC	CILITY	#:	0019	
						Andrews Entry History		

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		SPRINKLER HEADS NEED TO BE ADJUSTED TO BELOW CEILING TILES – TOO HIGH	Х							NFPA 13
1	14	DOOR SHOWN ON FISH NOT THERE			X					
1	1	REMOVE ALL HOMECOMING DECORATIONS		Х						NFPA 101
1	1	REMOVE EXTENSION CORD TO DISPLAY LIGHTS		Χ						NFPA 70 – 400.8
1	67	SPRINKLER HEADS ABOVE CEILING	X							NFPA 13
1C	129	EXTENSION CORD TO POWER STRIP		Х						NFPA 70 400.8
1C	126	EXTENSION CORD TO COMPUTER		X						NFPA 70 400.8
1C	127	PANDUIT OPEN TO WIRING	X							NFPA 70
1C	122	EXTENSION CORD TO COMPUTER		X						NFPA 70 400.8
1D	144	EXCESSIVE DECORATIONS FOR HOMECOMING		Х						NFPA 101
1D	159	STORAGE TO HIGH		Х						NFPA 13



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: C	CLAY	FACILITY#	: 0019	
그 있다니 어떤 속 강설하고 있다.		중요한 경험하는 그리가 말라.	THE 25 LOSS 1981 A	

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

ATÉ

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1D	164	EXTENSION CORD FROM HALL INTO CLASSROOM		Х						NFPA 70 400.8
1F	241	POWER STRIP TO STRIP - REPLACE WITH LONG POWER STRIP		×						NFPA 70 400.8
1F	227	REMOVE FLAMABLE STORAGE AND FERTILIZERS OR CHANGE LIGHT TO EXPLOSION LIGHT		Х						
1F	230	ADD EXTINGUISHER BY STOVE		X						FAC 69A-58
1G	196	HALF OF EMERGENCY LIGHT BULBS OUT		Х						FBC 423.17.1
1H	285	OCCUPANCY LOAD SIGN MISSING (1800 MAX. CAP.)		Х						FBC 1004.3
1H	284A	DOORS CHAINED AFTER SCHOOL – REMOVE		Х						FBC 1006
11	339	SPRINKLERS TO HIGH - MISSING ESCUTCHEON	Х							NFPA 13
1J	358	FIRE EXTINGUISHER NOT SIGNED		Х						FAC 69A-58
35		EMERGENCY LIGHT OUT		Х						FBC 423.17.1
35		GAS BOTTLE STORED IN BUILDING		Х						NFPA 1.21-3.3.5



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY	7# : 0019) B (
# : 보면 : : : : : : : : : : : : : : : : :			Service Service	. 5.7

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

)ATF

Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
	REMOVE ALL GAS BOTTLES		х				Acade Gold Control		NFPA 1.21-3.3.5
	ELECTRICAL PANEL NEEDS KNOCKOUT	Х							NFPA 70 110.26
	ELECTRICAL JUNCTION BOX - NO COVER		Х						NFPA 70 110.26
	ELECTRICAL PANEL BLOCKED BY SHELF		Χ						NFPA 70 220.26
	Room	Required: REMOVE ALL GAS BOTTLES ELECTRICAL PANEL NEEDS KNOCKOUT ELECTRICAL JUNCTION BOX – NO COVER ELECTRICAL PANEL BLOCKED BY SHELF	REMOVE ALL GAS BOTTLES ELECTRICAL PANEL NEEDS KNOCKOUT X ELECTRICAL JUNCTION BOX – NO COVER ELECTRICAL PANEL BLOCKED BY SHELF	REMOVE ALL GAS BOTTLES X ELECTRICAL PANEL NEEDS KNOCKOUT X ELECTRICAL JUNCTION BOX – NO COVER X ELECTRICAL PANEL BLOCKED BY SHELF X	REMOVE ALL GAS BOTTLES REMOVE ALL GAS BOTTLES X ELECTRICAL PANEL NEEDS KNOCKOUT ELECTRICAL JUNCTION BOX – NO COVER X ELECTRICAL PANEL BLOCKED BY SHELF X	Required: "M" Oper. "C" Serv. "I.S." REMOVE ALL GAS BOTTLES X ELECTRICAL PANEL NEEDS KNOCKOUT X ELECTRICAL JUNCTION BOX – NO COVER X ELECTRICAL PANEL BLOCKED BY SHELF X	Room Required: "M" "O" "C" Serv. "I.S." Cost "I.S." REMOVE ALL GAS BOTTLES X ELECTRICAL PANEL NEEDS KNOCKOUT X ELECTRICAL JUNCTION BOX – NO COVER X ELECTRICAL PANEL BLOCKED BY SHELF X	Room Deficiency Description and Corrective Action Required: "M" Oper. "C" Fac. Serv. "I.S." Cost Def. Cited REMOVE ALL GAS BOTTLES X X ELECTRICAL PANEL NEEDS KNOCKOUT X ELECTRICAL JUNCTION BOX – NO COVER X ELECTRICAL PANEL BLOCKED BY SHELF X ELECTRICAL PANEL BLOCKED BY SHELF	Room Deficiency Description and Corrective Action Required: "M" Oper. "C" Serv. "I.S." Cost Def. Cited for Correction REMOVE ALL GAS BOTTLES X X SELECTRICAL PANEL NEEDS KNOCKOUT X SELECTRICAL JUNCTION BOX – NO COVER X SELECTRICAL PANEL BLOCKED BY SHELF X X SELECTRICAL PANEL BLOCKED BY SHELF X SELECTRICAL PANEL BLOCKED BY SHELF SELECTRICAL BY SHELF BY SHEL

FISCAL YEAR <u>2008-2009</u>



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

<u> </u>	
FACILITY:	MIDDLEBURG HIGH SCHOOL
	2750 C D 220
	3750 C.R. 220
	MIDDLEBURG, FLORIDA 32068
	WIIDDLEDUKG, FLORIDA 32000

INSPECTION DATE: OCTOBER 14, 2008

DISTRICT: CLAY FACILITY #:

INSPECTOR'S SIGNATURE

ATE

0019

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	RAMP EXCEEDS SLOPE 1-12	Х					2		FBC 11-4.8
92	5	OK								
92	7	ок								
92	9	OK								
92	31	ок								
92	32	ok								
92	33	ОК								
92	34	OK								
92	35	ОК								
92	36	OK								
92	41	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY		FA	CILITY#	0019	÷
	10.3.44				• •

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	42	ок								
92	43	OK								
92	44	ок								
92	45	OK								
92	46	ОК								
92	47	OK								
92	51	ок								
92	52	OK								
92	53	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	54A	OK								
92	54B	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY		FACILITY	Y #: 00	19	
	W. S. C.			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
		and the second		· 李明·李宗帝等于1		1,11

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSI	PECTION	DATE:	OCTOBER 14, 2008

OR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	55	ОК								
92	60	OK								
92	61	ОК								
92	62	OK								
92	63	ок								
92	64	OK								
92	65	ОК								
92	66	OK								
92	70	ок								
92	71	RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	72									



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY		FACILITY # : 0019
	The state of the s	-	

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

NSP	€ C TI	Q-AO	ATE:	OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	71	ОК								
92	72	OK								
92	73	ОК								
92	74	OK								
92	75	ок								
92	76	OK								
92	77	ок								
92	78	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	79	ОК								
92	80	OK								
92	81	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT:	CLAY	FACILITY	#: 00)19
1					

FACILITY: MIDDLEBURG HIGH SCHOOL

3750 C.R. 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: OCTOBER 14, 2008

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	79	ОК								<u> </u>
. 92	80	OK								
92	81	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	82	RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	83	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	84	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	85	ок								
92	86	RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	87	RAMP EXCEEDS 1-12 SLOPE	х					2		FBC 11-4.8
92	88	RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	88	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
92	89	RAMP EXCEEDS 1–12 SLOPE	X					2		FBC 11-4.8



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY	/ #: 00	07
			the same of the sa	
1 (1.5 ftm) - 5 (4.5 gm), 2 (5.5 ftm)	· 医内侧皮皮 " " " " " " " " " " " " " " " " " " "	化氯化甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲		

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	100	EXTINGUISHER OVER CHARGED – REPLACED		Х						NFPA 14
1	118	NO EMERGENCY EVACUATION SHEET		Х						FBC 423.14.2.4
1	122	LENS COVER MISSING		Х						NFPA 70
1	104	GATES LOCKED WHILE OCCUPIED		X						NFPA 101, FBC 100.3
1	115	DOOR DRAGS ON FLOOR - HARD TO OPEN		Х						
1	117	EXTENSION CORD TO DECORATIONS IN HALL		Х						NFPA 70
1	165	TWO LENS COVERS MISSING		Х						NFPA 70
1	126	EMERGENCY LIGHT OUT - ELEC. ROOM		Х						FBC 423.17.1
1	126	FIRE ALARM BOX OPEN		Х						NFPA 70
1	214	OVERHEAD PROJECTOR STAND C-CLAMP TO FRAMING, NEEDS PROPER INSTALLATION				Х				
1	2	OVERHEAD PROJECTOR STAND C-CLAMP TO FRAMING, NEEDS PROPER INSTALLATION				X				



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FA	CILITY #:	0007	

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073


INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

10-30-08

No. of Info. Scheduled Fac. times Rule **Deficiency Description and Corrective Action** Maint. Oper. Serv. Cost Building Room for "C" "M" "O" Def. Required: "I.S." Correction Cited Х FAC 69A-58 REPLACE OLD EXTINGUISHER 1 226 Х FBC 423.17.1 1 **EMERGENCY LIGHT OUT** 252 Х NFPA 70 252 LENS COVER MISSING ON LIGHT 1 Χ FAC 69A-58 REPLACE OLD EXTINGUISHER 216 **EMERGENCY LIGHT NOT WORKING - BULBS** FBC 423.17.1 Χ 1 204 REMOVED Х 1 C - CLAMP TO OVERHEAD PROJECTOR 204 Х FBC 423.14.2.4 NO EMERGENCY EVACUATION SHEETS 1 231 1 NEAR ROOM 218 - DOOR CLOSURE NOT CLOSING Χ 800 SWITCH COVER BROKEN Х 3 1 X FBC 423.17.1 3 3 EMERGENCY LIGHT BROKEN/NOT WORKING MAX OCCUPANCY SIGN MISSING: 1350 MAX OCC. Χ 4 Χ FBC 1016.3.1 TWO EXIT LIGHTS BROKEN - REPLACE 4

ORANGE PARK HIGH SCHOOL 2008-09 SREF INSPECTION



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY FACILITY #:_	0007	
i de la companya de La companya de la co			

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073


INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

<u>10-30-08</u>

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
4	9	EXTINGUISHER MISSING		х						FAC-69A-58
4	9	LIGHT NOT WORKING		Х						
4	5	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
4	6	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
4	7	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
4	18	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
4	19	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
4	19A	REPLACE OLD EXTINGUISHER		Х						FAC 69A-58
10	100	OCCUPANCY LOAD SIGN MISSING		Х						FBC 423.14.2.2
10	122	WRENCH MISSING SPRINKLER BOX		Х						
10	111	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
10	114	EMERGENCY LIGHT OUT		Х						FBC 423.17.1

ORANGE PARK HIGH SCHOOL 2008-09 SREF INSPECTION



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FA	CILITY#	: 00	07	
			s renger kliger i i hit Jenst Lighter i i i			
			., .			

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073


INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

ATE

No. of Info. Scheduled **Deficiency Description and Corrective Action** Fac. times Rule Maint. Oper. Serv. Cost Building Room for "C" "O" Required: "M" Def. "I.S." Correction Cited Χ EXCRESSIVE PAPER ON WALLS 20% MAX 19 9 Χ FMC 804.2.3 19 8 **CEILING TILE MISSING** FBC 423.17.1 Х **EMERGENCY LIGHT OUT** 20 16 Χ 20 FIRE ALARM INSPECTION NOT CURRENT 14 20 Χ 14 **COVER MISSING** 20 CLEAR ISLE TO EXIT Χ 18A IT CONDUIT BOX OPEN - CLOSE Χ 21 X FBC 1016.3.1 22 12 FAN GRILL LOOSE LIGHT COVER MISSING Χ 25 13 FMC 804.2.3 **CEILING TILES MISSING** Χ 25 14 Х FMC 804.2.3 CEILING TILES MISSING 25 Х FBC 423.14.2.4 25 22 NO EVACUTATION SHEET Х 25 ATV PARKED IN BUILDING - MOVE OUT

ORANGE PARK HIGH SCHOOL 2008-09 SREF INSPECTION



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION **ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5** "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FAC	ILITY #:	0007	

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
27	2	EVACUATION SHEET MISSING		х						FBC 423.14.2.4
27	3	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
27	7	PAINT SOTRED IN BUILDING		Х						NFPA 101
27	11	CEILING TILES MISSING		Х						FMC - 804.2.3
47	1	REMOVE LP GAS BOTTLES - STORE OUTSIDE		Х						NFPA 1
51	2	FIRE ALARM PANEL NOT UP TO DATE CERT	Х							NFPA 101
51	8	EMERGENCY LIGHT NOT WORKING		Х						FBC 423.17.1
12	132	LP TANKS STORED IN BUILDING – REMOVE		X						NFPA 1
12	116	CEILING TILES MISSING		Х						FMC 804.2.3
12	161A	ROOF LEAKS	Х							
12	161A	SEVERAL ROOF LEAKS	Х							
12	141	CEILING TILES MISSING		Х						FMC 804.2.3



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY#: 0007
FACILITY: ORANGE PARK HIGH SCHOOL 2300 KINGSLEY AVENUE ORANGE PARK, FLORIDA 32073
INSPECTION DATE: OCTOBER 30, 2008

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "W"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	13	ок								
92	24	OK								
92	25	ОК					:			
92	26	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	27	ОК								
92	28	OK								
92	29	ок								
92	30	EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	31	ок								
92	32	OK								
92	35	ок								
92	36	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8

ORANGE PARK HIGH SCHOOL 2008-09 SREF INSPECTION



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY #:	0007		
			24.	

FACILITY: ORANGE PARK HIGH SCHOOL

2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	38	ОК								
92	39	OK								
92	40	ОК								•
92	41	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8
92	42	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8
92	43	OK								
92	44	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	45	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	46	EMERGENCY LIGHT OUT		Х	-					FBC 423.17.1
92	47	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	48	ОК								
92	49	OK				:				



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY #	‡ :	0007	
and group of the control groups that a material			Visite in the second		

FACILITY: ORANGE PARK HIGH SCHOOL


2300 KINGSLEY AVENUE

ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	50	ок								· · · · · · · · · · · · · · · · · · ·
92	51	EMERGENCY LIGHT NOT ATTACHED TO WALL		Х						FBC 423.17.1
92	52	EXCESSIVE COMBUSTIBLES ON WALL REMOVE		Х						NFPA 101
92	53	OK								
92	54	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8
92	55	EMERGENCY EVACUATION SHEET MISSING		Χ						FBC 423:14.2.4
92	56	EMERGENCY EVACUATION SHEET MISSING		Х						FBC 423.14.2.4
92	56	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8
92	59	VINYL TRANSITION SRIP AT DOOR LOOSE		Х						FBC 1003
92	59	VIDEO SCREEN BRACKET LOOSE		Х						
92	60	ок								
92	61	OK							er .	



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0007
grapher performance in the control of the control was been as the second of the control of the control of the second of the control of the control of the second of the control of the con
FACILITY: ORANGE PARK HIGH SCHOOL
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073
INSPECTION DATE: OCTOBER 30, 2008

INSPECTOR'S SIGNATURE

No. of Saladad

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	62	ОК								
92	63	OK								
92	64	ОК								
92	65	OK								
92	66	TRIP HAZARD @ RAMP		Х						FBC 1006
92	67	OK								
92	72	FOUNDATION BLOCKS MISSING		X						
92	72	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8
92	73	RAMP EXCEEDS 1/12 SLOPE	Х					2		FBC 11-4.8
92	74	FOUNDATION BLOCKS MISSING			X					
92										
92		La company of the second secon								

FISCAL YEAR <u>2008-2009</u>



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DI	S	ΓF	श	C7	Γ:	CL	Α١	1			= #	C	ILI	IT۱	/ #	Ŀ	0	02	2		
																Ī					5.0

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

IMSPECTOR'S SIGNATURE

WITE STE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	107	ADD FIRE EXTINGUISHER WITHIN 15' OF STOVE		Х						
1	1111	NORTH ENTRANCE EXTERIOR ROOF LEAK	×							
11	135	ROOF LEAK	Х							
1	149	OCCUPANCY LOAD SIGN MISSING		X						FBC 423.14.2.3
2	218	MATERIALS STORED IN ELECTRICAL ROOM		Х						NFPA 70
2	227	EXIT LIGHT COVER BROKEN	X							FBC 1016.3.1
2	224	LIGHT COVER MISSING	Х							NFPA 70 401.3
3	333	NO EMERGENCY EVACUATION SHEET		Χ,						FBC 14.2.4
3	301	EAST ENTRANCE - LINTEL	X							
5	520	LOCKSET MISSING	Х							
6		GENERAL – SEVERAL ROOF LEAKS	Х							
6	688	EXIT LIGHT OUT	X							FBC 423.17.1
6	657	EXTENSION CORD THRU ATTIC		Х						NFPA 70



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY:	RIDGEVIEW HIGH SCHOOL
	466 MADISON AVENUE
	ORANGE PARK, FLORIDA 32065


DISTRICT: CLAY **FACILITY** #: 0022

INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
6	658	EXTENSION CORD THRU ATTIC		Х						NFPA 70
6	632	FIRE ALARM PANEL OPEN	X							NFPA 70 110.26
7	705	ENTRANCE – CEILING TILE OUT		Х						FBC 804.2.3
8		EXTERIOR COVER MISING ON DRAIN	X							
9	914	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	915	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	913	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	930	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	933	EMERGENCY LIGHTS OUT	х							FBC 423.17.1
9	941	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	941	OUTLET COVER BROKEN		х						NFPA 70 410.1.2
10		EXTERIOR BUILDING # MISSING %"	X	\$ 000 PV						
.10	1021	FIRE EXTINGUISHER MISSING	Х							



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY FACILITY#: 0022
FACILITY:	RIDGEVIEW HIGH SCHOOL
	466 MADISON AVENUE
	ORANGE PARK, FLORIDA 32065

Harry Movember 4, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
11	1101	DOOR HANDLE BROKEN	Х							
11	1103	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
12	1201	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
-12	1202	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
12	1203	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
13		OK		14.						
							3,755			



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	Γ: CLAY	FACILITY	/ #: 0	022	:

FACILITY: RIDGEVIEW HIGH SCHOOL


466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065

INSPE	CTION	DATE:	NOVEMBER 4	, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	EMERGENCY LIGHTS OUT	х							FBC 423.17.1
92	2	DOOR GRILL ON BOYS ROOM RUSTED - SHARP EDGES	X							
92	3	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	4	OK								
92	5	ок								
92	6	OK								
92	7	ок								
92	- 8	EMERGENCY LIGHTS OUT	Х	7.50 SILT						FBC 423.17.1
92	9	ок								
.92	10	OK								
92	11	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	12	ОК								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	: CLAY	FACIL	I TY #: 00)22
		· · · · · · · · · · · · · · · · · · ·		

FACILITY: RIDGEVIEW HIGH SCHOOL


466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

NSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	13	EMERGENCY LIGHTS OUT	х							FBC 423.17.1
. 92	14A/B	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	21	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	22	WOOD RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 1:1-4.8
92	23	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	24	WOOD RAMP EXCEEDS 1-12 SLOPE	Х	· Carlotte				2		FBC 11-4.8
92	25	WOOD RAMP EXCEEDS 1-12 SLOPE	x					2		FBC 11-4.8
92	26	WOOD RAMP EXCEEDS 1-12 SLOPE	×					2		FBC 11-4.8
92	27	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	28	EMERGENCY LIGHTS OUT	X							FBC 423.17.1
92	29	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	30	OK								
92	31	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065

DISTRICT: CLAY **FACILITY** #: 0022

INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	32	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	33	WOOD RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	34	ОК			=					
92	41	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	42	EXPOSED WIRES ON THERMOSTAT IN MENS ROOM	Х							
92	43	WOOD RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	44	ОК								
92	45	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	46	ок								
92	47	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	48	ОК								
92	49	LENS COVER MISSING ON LIGHTS	×							NFPA 70 401.3
92	50	EXCESSIVE COMBUSTIBLES ON WALLS/CEILING		Х						NFPA 70 110.28



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	C)	S	TI	R	IC	Τ		С	L	A	Y								F	A	C	:	LI	T	Y	#	ŀ			0	02	22)				
	Ų.		26			20		 200	tret.	40.00	- 45	20	. 10.7	20.	1.67	- 1	2.00	40.00	- 1			360					i (1)	10	100	 		5.77	12.7		 7,12	 40.0	V	
1								Šě.								w			4																			d

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065


INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

WTE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	107	ADD FIRE EXTINGUISHER WITHIN 15' OF STOVE		Х						
1	111	NORTH ENTRANCE EXTERIOR ROOF LEAK	1 X							
1	135	ROOF LEAK	Х							
1	149	OCCUPANCY LOAD SIGN MISSING		\ X ::						FBC 423.14.2.3
2	218	MATERIALS STORED IN ELECTRICAL ROOM		Х						NFPA 70
2	227	EXIT LIGHT COVER BROKEN	X							FBC 1016.3.1
2	224	LIGHT COVER MISSING	Х							NFPA 70 401.3
÷ 3	333	NO EMERGENCY EVACUATION SHEET		X		1477				FBC 14.2.4
3	301	EAST ENTRANCE - LINTEL	Х							
5	520	LOCKSET MISSING	X							
6		GENERAL – SEVERAL ROOF LEAKS	Х							
6	688	EXIT LIGHT OUT	X				1 12.09			FBC 423.17.1
6	657	EXTENSION CORD THRU ATTIC		Х						NFPA 70

FISCAL YEAR <u>2008-2009</u>



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

C	l	S	Т	R	1	C	T		i	(٦i	ر	Α	Υ						I	F,	A	(3	IL	1	1	1	1	1	ŧ:	0.000	4	Ü	C	C	2	2					
								3	9	T.									Ž,			į																			ij		1000

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

DÁTE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
6	658	EXTENSION CORD THRU ATTIC		х						NFPA 70
6	632	FIRE ALARM PANEL OPEN	_ X							NFPA 70 110.26
7	705	ENTRANCE - CEILING TILE OUT		Х						FBC 804.2.3
8		EXTERIOR COVER MISING ON DRAIN	Х							
9	914	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	915	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	913	EMERGENCY LIGHTS OUT	х							FBC 423.17.1
9	930	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	933	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9. 19	941	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
9	941	OUTLET COVER BROKEN		Х						NFPA 70 410.1.2
10		EXTERIOR BUILDING # MISSING "po"	Х	1.000 (1) 2.15 (2)						
10	1021	FIRE EXTINGUISHER MISSING	Х							



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	CLAY FACILIT#_ 0022
FACILITY:	RIDGEVIEW HIGH SCHOOL
	466 MADISON AVENUE
	ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

ANSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
11	1101	DOOR HANDLE BROKEN	х							
.11	1103	EMERGENCY LIGHT OUT	X							FBC 423.17.1
12	1201	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
12	1202	EMERGENCY LIGHTS OUT	X							FBC 423.17.1
12	1203	EMERGENCY LIGHTS OUT	х							FBC 423.17.1
13		OK								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	١	FACILITY:	RIDGEV	/IEW HIG	н ѕсно	OL.		
DISTRICT: CLAY FACILITY #: 0022			U_A			\	0022	

ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

//-4-68

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	2	DOOR GRILL ON BOYS ROOM RUSTED - SHARP EDGES	×							
92	3	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	4	OK								
92	5	ок								
92	6	OK		74.200						
92	7	ок								
92	- 8	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	9	ок								
.92	-10	OK								
92	11	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	12	OK		West.			A STATE OF THE STA			



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	<u>CLAY</u> FACILITY #: 0022
FACILITY	RIDGEVIEW HIGH SCHOOL
1	466 MADISON AVENUE
	ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

11-4-08

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	13	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	14A/B	WOOD RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	21	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	- 22	WOOD RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	23	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	24	WOOD RAMP EXCEEDS 1-12 SLOPE	x					2		FBC 11-4.8
92	25	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	26	WOOD RAMP EXCEEDS 1-12 SLOPE	×					2		FBC 11-4.8
92	27	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	28	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	29	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	30	OK	turit id							
92	31	ок								

FISCAL YEAR <u>2008-2009</u>



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRIC	I: CLAY	kalia abay abay a	ACILITY#	: 0022	
					Jacobski sebeka
2 3 (0.00) (0.00)	E 4 10 4 10 10 10 10 14 14 14	nibeli li perceptatione			

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065

INSPECTION	DATE:	NOVEMBER 4	, 2008

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	32	EMERGENCY LIGHTS OUT	Х							FBC 423.17.1
92	33	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	34	ОК								
92	41	EMERGENCY LIGHTS OUT	X							FBC 423.17.1
92	42	EXPOSED WIRES ON THERMOSTAT IN MENS ROOM	Х							
- 92	43	WOOD RAMP EXCEEDS 1-12 SLOPE	X					2		FBC 11-4.8
92	44	ок						:		
92	45	WOOD RAMP EXCEEDS 1-12 SLOPE	Х					2		FBC 11-4.8
92	46	ок								
92	47	EMERGENCY LIGHT OUT	Χ							FBC 423.17.1
92	48	ок								
92	49	LENS COVER MISSING ON LIGHTS	Х							NFPA 70 401.3
92	50	EXCESSIVE COMBUSTIBLES ON WALLS/CEILING		Х						NFPA 70 110.28



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

RIDGEVIEW HIGH SCHOOL
466 MADISON AVENUE
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

DISTRICT: CLAY **FACILITY #**: 0022

INSPECTOR'S SIGNATURE

// NATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	51	EMERGENCY LIGHT OUT		х						FBC 423.17.1
92	52	OK								
92	53	ОК								
92	54	OK								
92	61	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
92	62	OK								
92	63	ок								
92	64	FLOOR TILE MISSING ON ENTRIES	X							
92	65	ОК								
- 92	66	EMERGENCY LIGHT OUT		X						FBC 423:17.1
92	67	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	- 68	OK		12 1 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						
92	69	EMERGENCY LIGHT OUT		Х						FBC 423.17.1



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

		100			124		March.	100	4	100					1. 110			100	177					100	2.10-19.2			Belle and	518 Turk	40.00	
	_	-	-	~ 1	~		1111	CI		10		200	1-7-5	200		A	\sim		-		ш.	30.0			\sim	^			100,000	170.00	
	1			~ 1			2	. 1	Δ	·Y	. 12171. 1	1915a e 1		1200		4	6 .			Y	ш.		14 P. 1		11/	/	1776		1.0		
	_				v		11.5	\cdot		۱ I »	7879.2	12.75			a Bar	~	•	_			и.	1297	120	~~	ᇨ	_	10000	7.5	1 6. 7		
40.0			1.120	200	100	10.11			-							41.5					21, 11,				2.1 y 2.5 mg 2		1.22			11.1	
1711		1		- 16季 食り		1.14				14.00	2 15 15 17 1	1966	431.6	3 . 12 . 71	S. 15. 1	200		fare to a	100	100		* No. 3	13.2			建二层化		Charles			

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065

INSPECTION DATE: NOVEMBER 4, 2008

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	70	ОК								
92	71	OK								
92	72	ок								
92	73	OK				101 A				
92	74	ок		-						
92	81	EMERGENCY LIGHT OUT		Х			7541773 . 112.415			FBC 423.17.1
92	82	ок								
92	83	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	84	ок								
92	- 85	ok								
92	86	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92	87	OK						in his property of the second		
92	88	ОК								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

ַ	DIS	TR	IC	T:	CL	A١	'			M.	F	A	C	IL	IT	Y	#:		(00	22			17
									7 (18) 2 (2)														dan.	

FACILITY: RIDGEVIEW HIGH SCHOOL

466 MADISON AVENUE

ORANGE PARK, FLORIDA 32065

INSPECTIO	N_DATE:	NOVEMBER -	4, 2008

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	89	EMERGENCY LIGHT OUT		х						FBC 423.17.1
92	90	OK								
92	91	ок								
92	92	EMERGENCY LIGHT OUT		×						FBC 423.17.1
92	101A	ок								
92	101B	OK				- 7				10.
92	103	ок								