2005-2006

LOCAL FIRE CONTROL ANNUAL INSPECTION CLAY DISTRICT FACILITIES

PER F.S. 1013.12(2)
RULE 69A-58

CONDUCTED BY THE CLAY COUNTY FIRE DEPARTMENT



District Clay

School CHARLES E BENNETT ELEMENTARY

Address 1 S OAKRIDGE AVENUE

Inspection date 2006-01-18

Notes -

Inspectors present

State No

District No

Local Yes

Co	de Viol	ation	Bldg	Room	Comp date	Cited	Notes
026	D2 EXIT	r LIGHTS INOPERABLE NORMAL DE	9- PERMANENT	901	2006- 02-25	. 0	Room 920.
049	99 FIRE		1- PERMANENT		2006- 02-18	0	Expose wiring at pull station
02	D2 EXIT	FUTCUTC INCDEDABLE NORMAL			2006- 02-18	1	two exit signs need bulbs
02	D2 EXIT	FLIGHTS INOPERABLE NORMAL		_	2006- 02-18	0	N/A
02	04 EME	RG LIGHTS NOT OPERATIONAL	10- PERMANENT		2006- 02-18	0	N/A
08	99 UTII	LITIES OTHER	92- PORTABLE	502	2006- 02-18	0	place blank in panel box
08	99 UTII	LITIES OTHER	92- PORTABLE	701	2006- 02-18	0	place blank in panel box
02	04 EME	RG LIGHTS NOT OPERATIONAL	92- PORTABLE	801	2006- 02-18	0	N/A
08	99 UTII	LITIES OTHER	92- PORTABLE	47	2006- 02-18	0	tripped breaker needs tobe researched for cause
	y that t	the district has complied with sec the local authority having jurisdic				No Yes	
ereby certi pection dat		the required fire drills have been	completed a	s of thi	s	Yes	
knowledger	nent N/	(Or) A.				No	

Primary inspector

Kevin, Mobiey

Additional inspector

District Clay

School CLAY HILL ELEMENTARY

Address 6345 STATE ROAD 218

Inspection date 2006-02-07

Notes -

Inspectors present

State No District No Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0204	EMERG LIGHTS NOT OPERATIONAL	1- PERMANENT	125	2006- 03-09	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	705	2006- 03-09	0	N/A
		knowledged					······································
		knowledged that the district has complied with se	ction 1013.12	2(1)(b),	, F.S.	No	
I hereby I hereby	certify to					No Yes	
I hereby I hereby section 1	certify to certify the certify to certify the certify to certify the certification.	hat the district has complied with se hat the local authority having jurisdi	ction has con	nplied w	vith		
I hereby I hereby section I	certify to certify the certify to certify the certify to certify the certification.	that the district has complied with se that the local authority having jurisdi (2)(b), F.S.	ction has con	nplied w	vith	Yes	

Primary inspector Karen, Golish **Additional inspector**

Page 1 of 3

State Fire Marshal - Inspection Report

District Clay

School DOCTORS INLET ELEMENTARY

Address 2634 STATE ROAD 220

Inspection date 2006-02-15

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bidg	Room	Comp date	Cited	Notes
	0805	GFCI'S NOT INSTALLED IN WET LOCATIONS	4- PERMANENT	109	2006- 03-15	0	By sink in front office
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4- PERMANENT	106	2006- 03-15	0	Clear Asile from storage
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	4- PERMANENT	106	2006- 03-15	0	Fire Extinguisher to high near room 108 in hallway
	0304	PENETRATION PROTECT MISSING/INADEQUATE	4- PERMANENT		2006- 03-15	0	Missing outlet cover in ceiling and ceiling tile clamage.
	0803	EXTENSION CORD NOT RATED FOR USE	4- PERMANENT		2006- 03-15	0	N/A
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	4- PERMANENT		2006- 03-15	0	Water Heater
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4- PERMANENT		2006- 03-15	0	Remove paint and Flammable liquids and place in flammabe locker.
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	4- PERMANENT		2006- 03-15	0	Missing outlet cover in ceiling
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4- PERMANENT		2006- 03-15	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	4-		2006- 03-15	0	N/A
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	9- PERMANENT		2006- 03-15	0	Storage to high or clear the floor area 903B,907B,908B,904B,902B
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	9- PERMANENT		2006- 03-15	0	Remove all storage and Paint
	0299	MEANS OF EGRESS OTHER	9- PERMANENT		2006- 03-15	0	Front door hard to open from inside
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	9- PERMANENT		2006- 03 - 15	0	Remove storage and Bike
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	8- PERMANEN		2006- 03-15	0	Remove storage, computers, and no number on door
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	8- PERMANEN		2006- 03-15	0	Clear floor area 805B,801B,802B
	0808	IMPROPED STORAGE IN	8- PERMANEN		2006- 03-15	0	N/A
·	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	8- PERMANEN		2006- 03-15	0	Plate cover missing F A relay
			7-		2006-		

http://app.bebr.ufl.edu/egroupware/Fire_Inspection/main.php?menuaction=Fire_Inspection.bo_inspsele... 3/6/2006

State Fire Marshal - Public School Reporting System [Fire_Inspection]

0211	BLOCKED/LOCKED EXITS	PERMANENT	708	03-15	0	Blocked
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	7- PERMANENT	706B	2006- 03-15	0	Clear floor area 707
8080	THE PARTY OF THE	7- PERMANENT		2006- 03-15	0	716
0809	ARTH ELECTRICAL BUNCTION DOV	7-	716	2006- 03-15	0	Cover for exposed wire box
0211	BLOCKED/LOCKED EXITS	92- PORTABLE	836	2006- 02-15	0	Corrected 838,891,897
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	838	2006- 03-15	0	To high
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	848	2006- 03-15	0	N/A
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	92- PORTABLE	848	2006- 03-15	0	To much wall cover with paper 839
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	878	2006- 03-15	0	872,
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	873	2006- 03-15	0	921
0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	874	2006- 03-15	0	Outside electric not secure
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	899	2006- 02-15	0	Exit door sticks Being corrected today
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	92- PORTABLE	869	2006- 03-15	0	Store room
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	839	2006- 03-15	0	Waiting for replacement
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	870	2006- 03-15	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	890	2006- 03-15	0	Tripping hazard, CATV cable wire on floor in front of rear exit.
0211	BLOCKED/LOCKED EXITS	92- PORTABLE	896	2006- 03-15	0	Rear exit with paper and items hanging from ceiling
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	5- PERMANENT	. 103	2006- 03-15	0	Remove storage and props from stage
0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	5- PERMANENT		2006- 03-15	0	N/A
0304	PENETRATION PROTECT MISSING/INADEQUATE	5- PERMANENT	R110	2006- 03-15	3	Missing and damaged ceiling tile
0199	GENERAL REQUIREMENTS	5- PERMANENT		2006- 03-15	3	No number for room posted
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	4- PERMANENT	4	2006- 03-15	3	No Number on all Permanent buildings 5,7,8,9

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Acknowledgement N/A.

Yes

No

Mar 06 06 09:30a Clay Fire Prevention State Fire Marshal - Public School Reporting System [Fire_Inspection]

(904)284-2647

Page 3 of 3

Primary inspector Additional inspector

Philip, Crider

Silver, Ware

District Clay

School FLEMING ISLAND ELEMENTARY

Address 4425 LAKESHORE DRIVE

Inspection date 2006-01-23

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	1- PERMANENT	120	2006- 02-23	0	N/A
	0209	RATED OPENINGS NOT MAINTAINED	1- PERMANENT		2006- 02-23	1	N/A
	0299	MEANS OF EGRESS OTHER	3- PERMANENT	304	2006- 02-23	0	window in door covered
	0301	UNPROTECTED VERTICAL OPENING	3- PERMANENT	305	2006- 01-23	0	missing ceiling tile corrected on site
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	3- PERMANENT	305	2006- 01-23	0	corrected on site
	0899	UTILITIES OTHER	4- PERMANENT	400	2006- 01-23	0	missing outlet inserts for all rooms
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	4- PERMANENT	400	2006- 02-23	0	broken cover
	0899	UTILITIES OTHER	7- PERMANENT	700	2006- 02-23	0	missing outlet insert
	0803	EXTENSION CORD NOT RATED FOR USE	2- PERMANENT	208	2006- 02-23	0	N/A
	0301	UNPROTECTED VERTICAL OPENING	2- PERMANENT		2006- 02-23	0	missing ceiling tile, also room 227
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	797	2006- 01-23	0	corrected
	0499	FIRE ALARM OTHER	92- PORTABLE	800	2006- 01-23	0	pull station blocked corrected on site
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	811	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	810	2006- 02-23	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	807	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	805	2006- 01-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	802	2006- 02-23	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	843	2006- 02-23	0	N/A
		INADEQUATE ACCESS TO	92-		2006-		

http://app.bebr.ufl.edu/egroupware/Fire_Inspection/main.php?menuaction=Fire_Inspection.bo_inspselect.g... 2/9/2006

(0801	ELECTRICAL PANEL	PORTABLE	845	02-23	0	N/A
(0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	845	2006- 02-23	0	N/A
(0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	849	2006- 01-23	0	corrected
(0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	847	2006- 01-23	0	corrected
(0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	902	2006- 01-23	0	corrected
١	0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	904	2006- 02-23	0	N/A
1	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	908	2006- 02-23	0	N/A
(0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	858	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	848	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	846	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	842	2006- 02-23	.0	N/A
	0899	UTILITIES OTHER	92- PORTABLE	842	2006- 02-23	0	outlet inserts required
	0201	INADEQUATE EGRESS WIDTH	92- PORTABLE	871	2006- 01-23	0	fixed on site
	0201	INADEQUATE EGRESS WIDTH	92- PORTABLE	826	2006- 02-23	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	824	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	601	2006- 02-23	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

No

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector Scott, Baltes

Additional inspector

District Clay

School FLEMING ISLAND ELEMENTARY

Address 4425 LAKESHORE DRIVE

Inspection date 2006-01-23

Notes

Inspectors present

State No

District No

Local Yes

lef	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	1- PERMANENT	120	2006- 02-23	0	N/A
	0209	RATED OPENINGS NOT MAINTAINED	1- PERMANENT		2006- 02-23	1	N/A
	0299	MEANS OF EGRESS OTHER	3- PERMANENT	304	2006- 02-23	0	window in door covered
	0301	UNPROTECTED VERTICAL OPENING	3- PERMANENT		2006- 01-23	0	missing ceiling tile corrected on site
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	3- PERMANENT	305	2006- 01-23	0	corrected on site
	0899	UTILITIES OTHER	4- PERMANENT	400	2006- 01-23	0	missing outlet inserts for all rooms
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	4- PERMANENT	400	2006- 02-23	0	broken cover
	0899	UTILITIES OTHER	7- PERMANENT	700	2006- 02-23	0	missing outlet insert
	0803	EXTENSION CORD NOT RATED FOR USE	2- PERMANENT	208	2006- 02-23	0	N/A
	0301	UNPROTECTED VERTICAL OPENING	2- PERMANENT	202	2006- 02-23	0	missing ceiling tile, also room 227
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	797	2006- 01-23	0	corrected
	0499	FIRE ALARM OTHER	92- PORTABLE	800	2006- 01-23	0	pull station blocked corrected on site
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	811	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	810	2006- 02-23	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	807	2006- 02-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	805	2006- 01-23	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	802	2006- 02-23	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	843	2006- 02-23	0	N/A
		INADEQUATE ACCESS TO	92-		2006-		

0801	ELECTRICAL PANEL	PORTABLE	845	02-23	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	845	2006- 02-23	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	849	2006- 01-23	0	corrected
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	847	2006- 01-23	0	corrected
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	902	2006- 01-23	0	corrected
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	904	2006- 02-23	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	908	2006- 02-23	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	858	2006- 02-23	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	848	2006- 02-23	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	846	2006- 02-23	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	842	2006- 02-23	0	N/A
0899	UTILITIES OTHER	92- PORTABLE	842	2006- 02-23	0	outlet inserts required
0201	INADEQUATE EGRESS WIDTH	92- PORTABLE	871	2006- 01-23	0	fixed on site
0201	INADEQUATE EGRESS WIDTH	92- PORTABLE	826	2006- 02-23	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	824	2006- 02-23	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	601	2006- 02-23	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

No Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector Scott, Baltes

Additional inspector

Baltes

District Clay

ռ Aph 10 06 09:31a

School GROVE PARK ELEMENTARY

Address 1643 MILLER STREET

Inspection date 2006-01-10

Notes

Inspectors present

State No

District No

Local Yes

Code	Violation	Bldg	Room	Comp date	Cited	Notes
0399	PROTECTION OTHER	8- PERMANENT	144a	2006- 03-26	0	holes in the drywall
0899	UTILITIES OTHER	6- PERMANENT	600	2006- 03-26	0	outlet inserts
0899	UTILITIES OTHER	7- PERMANENT	700	2006- 03-26	0	outlet inserts
0299	MEANS OF EGRESS OTHER	2- PERMANENT	129a	2006- 03 -2 6	0	hand rails too low
0299	MEANS OF EGRESS OTHER	92- PORTABLE	504	2006- 02-26	0	no exit plan
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	528	2006- 02-26	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	91- PORTABLE	525	2006- 02-26	0	N/A
0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	521	2006- 02-26	0	missing blank in elect panel
0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	28	2006- 02-26	0	blank in electric panel
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	6	2006- 02-26	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	10	2006- 02-26	0	N/A

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

http://app.bebr.ufl.edu/egroupware/Fire_Inspection/main.php?menuaction=Fire_Inspection.bo_inspsel... 4/10/2006

Apr 10 06 09:31a Clay Fire Prevention
State Fire Marshal - Public School Reporting System [Fire_Inspection]

(904)284-2647

р.

Page 2 of 2

Primary inspector Scott, Baltes **Additional inspector**

District Clay

School KEYSTONE HEIGHTS ELEMENTARY

Address 335 S PECAN STREET

Inspection date 2005-10-27

Notes

Inspectors present

State No Dis

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
		INADEQUATE ACCESS TO ELECTRICAL PANEL	3- PERMANENT	1	2005- 11-15	0	Stove blocking
	(1)2(1)2	EXTENSION CORD NOT RATED FOR USE	4- PERMANENT		2005- 11-15	0	N/A
	0405	SMOKE DETECTORS INOPERABLE/MISSING	6- PERMANENT	20	2005- 11-27	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	7- PERMANENT	1011	2005- 11-15	0	secondary means of egress obscuredby paper
	0210	EXIT ACCESS NOT MAINTAINED	8- PERMANENT		2005- 11-15	0	secondary means of egress obscuredby paper
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	8- PERMANENT		2005- 11-27	0	N/A
	0499	FIRE ALARM OTHER	10- PERMANENT	20M	2005- 11-15	1	repair broken magneric fire door opener
	0210	EXIT ACCESS NOT MAINTAINED	10- PERMANENT	₋ 26	2005- 11-15	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	702	2005- 11-27	0	N/A
	0408	MANUAL PULL STATION MISSING/INOPERABLE	92- PORTABLE	721	2005- 11-15	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	704	2005- 11-27	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	91- PORTABLE	724	2005- 11-27	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	706	2005- 11-27	0	N/A
	1301	FIRE LANES NOT POSTED/MAINTAINED	0-Building N/A See notes	1	2006- 01-15	0	mark fire access roadway Orchid St. and establish \"No Parking Zone\" to fire access roadway

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. Yes

I hereby certify that the required fire drills have been completed as of this

http://app.bebr.ufl.edu/egroupware/Fire_Inspection/main.php?menuaction=Fire_Inspection.bo_inspsel... 5/22/2006

May 22 06 03:39p Clay Fire Prevention the Fire Marshal - Public School Reporting System [Fire_Inspection]

(904)284-2647

p.:

Page 2 of 2

rimary inspector lichael, Swartz **Additional inspector**

District Clay

School LAKE ASBURY ELEMENTARY

Address 2901 SANDRIDGE ROAD

Inspection date 2006-03-22

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	115	2006- 04-22	0	Room 127
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT		2006- 04-22	0	N/A
	0899	UTILITIES OTHER	1- PERMANENT	107	2006- 04-22	0	need 30" clearance around Hot water heater
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 04-22	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	1- PERMANENT		2006- 04-22	0	N/A
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	2- PERMANENT		2006- 04-22	0	N/A
	0506	EXTINGUSHER MISSING FROM LOCATION	2- PERMANENT		2006- 04-22	0	N/A
	0899	UTILITIES OTHER	2- PERMANENT		2006- 04 - 22	0	Room 217 Exposed wiring
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4- PERMANENT		2006- 04-22	0	N/A
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	4- PERMANENT		2006- 04-22	0	N/A
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	5- PERMANENT		2006- 04-22	0	N/A
	0301	UNPROTECTED VERTICAL OPENING	6- PERMANENT		2006- 04-22	0	celling tiles missing
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	6- PERMANENT		2006- 04-22	0	N/A
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	6- PERMANENT	777	2006- 04-22	0	N/A
	0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	79B	2006- 04-22	0	N/A
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	81	2006- 04-22	0	N/A
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	39A	2006- 04-22	0	N/A
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	R41	2006- 04-22	0	N/A
		INADEQUATE ACCESS TO	92-		2006-		

Clay Fire Prevention , Ar 10 06 09:55a (904)284-2647 p.2 State Fire Marshal - Public School Reporting System [Fire_Inspection] Page 2 of 2 PORTABLE R41 04-22 0801 ELECTRICAL PANEL 0 N/A **EMERG LIGHTS NOT** 92-2006-48 0 N/A **OPERATIONAL PORTABLE** 04-22 **EMERG LIGHTS NOT** 2006-92-0204 0 11 N/A **OPERATIONAL PORTABLE** 04-22 NFPA101- 0211 BLOCKED/LOCKED EXITS 92-2006-0 11 **Emergency Exit Blocked PORTABLE** 04-10 NFPA101- 0211 BLOCKED/LOCKED EXITS 92-2006-0 Emergency exit blocked PORTABLE 04-10 Statements acknowledged I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with Yes section 1013.12(2)(b), F.S. I hereby certify that the required fire drills have been completed as of this Yes inspection date. (Or) Acknowledgement N/A. No

Primary inspector Karen, Golish Additional inspector

District Clay

School LAKESIDE ELEMENTARY

Address 2752 MOODY ROAD

Inspection date 2006-03-14

Inspectors present

State No

District No

Local Yes

ef 	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0204	EMERG LIGHTS NOT OPERATIONAL	2- PERMANENT	136A	2006- 03-14	0	136B,136C and 143 Need Emergency lights
	0304	PENETRATION PROTECT MISSING/INADEQUATE	2- PERMANENT		2006- 03-14	0	120, 139 Damaged or missing ceiling tile
	0899	UTILITIES OTHER	2- PERMANENT	. 121	2006- 03-14	0	large cable or wire hanging from ceiling with open end
	0204	EMERG LIGHTS NOT OPERATIONAL	2- PERMANENT		2006- 03-14	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT		2006- 03-14	0	Stage entrance blocked by storage
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT		2006- 03-14	0	No storage in or around wheel chair lift to stage. It is there exit
	0204	EMERG LIGHTS NOT OPERATIONAL	1- PERMANENT		2006- 03-14	0	Needs Emergency lights
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2006- 03-14	0	N/A.
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	6- PERMANENT		2006- 03-14	0	N/A.
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	6- PERMANENT		2006- 03-14	0	612:
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	6- PERMANENT		2006- 03-14	0	602B Clear floor area
	0704	COMPRESSED GAS CYLINDERS NOT SECURED	6- P ERMANEN T		2006- 03-14	0	N/A
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	6- PERMANEN		2006- 03-14	0	N/A
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	7- PERMANEN		2006- 03-14	0	Wall has a large percentage covered wit paper and other material with a large paper tree in middle of room
	0211	BLOCKED/LOCKED EXITS	7- PERMANEN	T ⁷⁰¹	2006- 03-14	0	Door covered with material and covering door handle
	0304	PENETRATION PROTECT MISSING/INADEQUATE	7- PERMANEN		2006- 03-14	0	and room number sign missing
	0106	ACCUMULATION OF	8- PERMANEN		2006- 03-14	0	Clear floor area
	0204	EMERG LIGHTS NOT	92- PORTABLE	23	2006- 03-14	0	24

Mar 24 06 01:45p Clay Fire Prevention (904)284-2647 p.2 Page 2 of 2 State Fire Marshal - Public School Reporting System [Fire_Inspection] 2006-92-**INADEQUATE ACCESS TO** 0 N/A PORTABLE 03-14 **ELECTRICAL PANEL** 92-2006-PORTABLE EXTINGUISHER 0 N/A 0502 **PORTABLE** 03-14 IMPROPERLY MOUNTED SMOKE DETECTORS 92-2006-0 Harging from ceiling 0405 51 **PORTABLE** INOPERABLE/MISSING 03-14 Statements acknowledged I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No. I hereby certify that the local authority having jurisdiction has complied with Yes section 1013.12(2)(b), F.S. I hereby certify that the required fire drills have been completed as of this Yes inspection date. (0r)No Acknowledgement N/A. **Additional inspector Primary Inspector** Philip, Crider N/, A

District Clay

School MCRAE ELEMENTARY

Address 6770 COUNTY ROAD 315

Inspection date 2006-01-05

Notes

Inspectors present

State No

District No

Local Yes

Réf	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	1- PERMANENT	100	2006- 02-27	1	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	1- PERMANENT	101	2006- 02-27	1	Room 123
1	0202	EXIT LIGHTS INOPERABLE NORMAL MODE		204	2006- 01-23	1	N/A
	0299	MEANS OF EGRESS OTHER	2- PERMANENT	201	2006- 02-27	1	Exit Doors Panic Hardware hard to operate when Doors are locked
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE			2006- 02-27	1	Rooms 313 314 320
	0299	MEANS OF EGRESS OTHER	6- PERMANENT		2006- 02-27	1	Rear Exit hard to open
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	707	2006- 02-27	1	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	705	2006- 02-27	1	N/A
	0499	FIRE ALARM OTHER	92- PORTABLE	708	2006- 02-27	1	Install Heat Detector in Bathroom if used for storage
	0499	FIRE ALARM OTHER	92- PORTABLE	403	2006- 02-27	0	Reinstall Heat Detector
	0499	FIRE ALARM OTHER	92- PORTABLE	801	2006- 02-27	0	Heat Detector shall be place in Bathroom if used for storage
	0499	FIRE ALARM OTHER	92- PORTABLE	803	2006- 02-27	0	Heat Detector shall be installed in Bathrooms if used for storage Romm 804
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	824	2006- 02-27	0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	92- PORTABLE	320	2006- 02-27	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

No Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

Primary inspector		Additional inspector	
Acknowledgement N/A.	(Or)	No	
State Fire Marshal - Public S	School Reporting S	System [Fire_Inspection]	

N/, A

Silver, Ware

Page 2 of 2

ate Fire Marshal - Public School Reporting System [Fire_Inspection]

State Fire Marshal - Inspection Report

District Clay

School MIDDLEBURG ELEMENTARY

Address 3958 MAIN STREET

Inspection date 2006-05-19

Notes -

Inspectors present

State No

District Yes

Local No

ef	Code	Violation 	Bldg	Room	Comp date	Cited	Notes
		EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	5	2006- 05-19	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT	13	2006- 05-19	0	N/A
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT	. 9	2006- 05-19	0	N/A
	0408	MANUAL PULL STATION MISSING/INOPERABLE	2- PERMANENT		2006- 05-19	0	Pulled at rear door
	0210	EXIT ACCESS NOT MAINTAINED	2- PERMANENT	_	2006- 05-19	0	Blocked with table
	0408	MANUAL PULL STATION MISSING/INOPERABLE	3- PERMANENT		2006- 05-19	0	Pull station blocked
	0803	EXTENSION CORD NOT RATED FOR USE	3- PERMANENT		2006- 05-19	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	4- PERMANENT		2006- 05-19	0	N/A
	0304	PENETRATION PROTECT MISSING/INADEQUATE	4- PERMANENT		2006- 05-19	0	Missing ceiling tile in hall over list door.
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION			2006- 05-19	0	Pin pulled
	0803	EXTENSION CORD NOT RATED FOR USE	7- PERMANENT		2006- 05-19		N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	7- PERMANENT		2006- 05-19		N/A
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	7- PERMANEN		2006- 05-19	3	Fire extinguisher out of date at stagdoor.
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	7- PERMANEN	_	2006- 05-19		N/A
	0299	MEANS OF EGRESS OTHER	7- PERMANEN		2006- 05-19		Remove Flammable Storage sign.
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	-	r outsideexitsings	2006- 05-19		N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	9- PERMANEN		2006- 05-19		N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	9- PERMANEN		2006- 05-19		N/A
		EXTINGUSHER MISSING FROM	9-		2006-		

Clay Fire Prevention

on (904)284-2647

P.2 Page 2 of 2

State Fire Marshal - Public School Reporting System [Fire_Inspection]

0506	LOCATION	PERMANENT	107	05-19	0	IV/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	9- PERMANENT	104	2006- 05-19	0	'V/A
0204	EMERG LIGHTS NOT OPERATIONAL	90- PORTABLE	35	2006- 05-19	0	N/A
1303	EXIT DISCHARGE NOT MAINTAINED	90- PORTABLE	29A	2006- 05-19	0	Nail heads pushing up with trip hazard
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	90- PORTABLE	38	2006- 05-19	0	N/A
1205	FIRE EVACUATION PLAN(S) NOT POSTED	90- PORTABLE	23	2006- 05-19	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	90- PORTABLE	23	2006- 05-19	0	Emergengy exit sign covered.
0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	90- PORTABLE	42	2006- 05-19	0	Box has no marking to breakers
1399	OUTSIDE STRUCTURE OTHER	90- PORTABLE	41	2006- 05-19	0	No door closer
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	90- PORTABLE	69	2006- 05-19	0	Pin pulled.
0899	UTILITIES OTHER	0-Building N/A See notes	nonlisted	2006- 05-19		The water treatment tank area unlocked X 2. Chlorine marked room unlocked.

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. Yes

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector Stephen, Arzie

Additional inspector

District Clay

School MONTCLAIR ELEMENTARY

Address 2398 MOODY ROAD

Inspection date 2006-04-18

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0210	EXIT ACCESS NOT MAINTAINED	4- PERMANENT	407	2006- 05-18	0	N/A.
	0408	MANUAL PULL STATION MISSING/INOPERABLE	5- PERMANENT	514	2006- 04-18	0	blocked
	0899	UTILITIES OTHER	0-Building N/A See notes	1000	2006- 05-18	0	fire hydrant needs to be turned.
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	21	2006- 04-18	0	A/N
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	22	2006- 04-18	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	53	2006- 04-18	0	, A/N
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	52	2006- 04-18	0	A\N
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	51	2006- 04-18	0	А/И

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

(Or)

Yes

Yes

I hereby certify that the required fire drills have been completed as of this

inspection date.

Acknowledgement N/A.

No

Primary inspector

Scott, Baltes

Additional inspector

N/, A

http://app.bebr.ufl.edu/egroupware/Fire Inspection/main.php?menuaction=Fire_Inspection.bo_inspsel... 5/18/2006

District Clay

School ORANGE PARK ELEMENTARY

Address 1401 PLAINFIELD AVENUE

Inspection date 2006-03-20

Notes

spectors present

:ate No

District No

Local Yes

ef	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0201	INADEQUATE EGRESS WIDTH	1- PERMANENT	01	2006- 06-05	0	window 6 foot drop to the floor. as the exit
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT		2006- 06-05	0	missing celling tile
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 06 - 05	0	remove ext. cord
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2006- 06 - 05	0	N/A
	0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	0-Building N/A See notes		2006- 06-05	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	0-Building N/A See notes	7	2006- 06-05	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	0-Building N/A See notes	6	2006- 06-05	0	N/A
	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	5	2006- 06-05	0	N/A
	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	15	2006- 06-05	0	N/A
	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	14	2006- 06-05	0	N/A
	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	13	2006- 06-05	0	N/A
	0211	BLOCKED/LOCKED EXITS	0-Building N/A See notes	12	2006- 06 - 05	0	N/A
	021	BLOCKED/LOCKED EXITS	0-Building N/A See notes	11	2006- 06-05	0	N,/A
	021:	BLOCKED/LOCKED EXITS	0-Building N/A See notes	10	2006- 06-05	0	only one egress from these rooms

tate Fire Marshal - Public School Reporting System [Fire_Inspection]

Statements acknowledged

section 1013.12(2)(b), F.S.

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. ${f No}$ I hereby certify that the local authority having jurisdiction has complied with

I hereby certify that the required fire drills have been completed as of this Inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector

Scott, Baltes

Additional inspector

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 1 of 2

State Fire Marshal - Inspection Report

District Clay

School ROBERT M PATERSON ELEMENTARY

Address 5400 PINE AVENUE

Inspection date 2006-04-06

Notes

Inspectors present

State No District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	. 100	2006- 05-06	0	remove door stops
		INADEQUATE ACCESS TO ELECTRICAL PANEL	2- PERMANENT		2006- 05-06	0	N,'A
	0399	PROTECTION OTHER	2- PERMANENT		2006- 04-06	0	fire curtains are original and need to be retreated
	0010	IMMINENT HAZARD	2- PERMANENT		2006- 04-06	0	the refrig has a lock that will not permit exit
	0010	IMMINENT HAZARD	2- PERMANENT		2006- 04-06	0	freezer can be locked not leting person to exit.
	0699	SPECIAL PROVISIONS OTHER	4- PERMANENT		2006- 04-06	1	1st grade needs outlet inserts
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	5- PERMANENT		2006 - 05-06	0	N/A
	0211	BLOCKED/LOCKED EXITS	5- PERMANENT	522	2006- 05-06	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	5- PERMANENT	500	2006 - 05-06	0	desk in hallway
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	4	2006- 05-06	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	18	2006- 05-06	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	24	2006- 05-06	0	N/A
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	26	2006- 05-06	0	too high
	0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	27	2006- 04-06	0	fire ext. empty
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	54	2006 - 04-06	0	missing tag
	0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	41	2006- 04-06	0	fire ext. empty
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	47	2006- 04-06	0	N/A

Statements acknowledged

Apr 13 06 09:33a

Clay Fire Prevention

(904)284-2647

p. 10

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 2 of 2

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. ${f No}$

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector Scott, Baltes **Additional inspector**

State Fire Marshal - Public School Reporting System [Fire_Inspection]

State Fire Marshal - Inspection Report

District Clay

School RIDEOUT ELEMENTARY

Address 3065 APALACHICOLA BOULEVARD

Inspection date 2006-03-15

Notes -

Inspectors present

District No.

State No		District No	Local Yes					
Ref	Code	Violation		Bidg	Room	Comp date	Cited	Notes
	0803	EXTENSION CORD FOR USE	NOT RATED	1- PERMANENT	311	2006- 03-15	0	307,
	0502	PORTABLE EXTING IMPROPERLY MOUN	UISHER NTED	1- PERMANENT		2006- 03-15	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTER		1- PERMANENT	345	2006- 03-15	0	223,125
	0304	PENETRATION PROMISSING/INADEQU		1- PERMANENT	. 344	2006- 03-15	0	438, Damaged or missing Ceiling tile
	0204	EMERG LIGHTS NO OPERATIONAL	T	1- PERMANENT		2006- 03-15	0	Needs Emergency lights in room now a class room
	0106	ACCUMULATION O COMBUSTIBLE MA		1- PERMANENT		2006- 03-15	0	427,464,447,449,412,228, No access into rooms because floors are covered with paper and other products
	0802	CIRCUITS NOT LEGIBLE/PERMANE	NTLY LABELED	1- PERMANENT	430	2006- 03-15	0	Panel PB3 not labeled properly
	1101	COMBUSTIBLE MA		1- PERMANENT		2006 - 03-15	0	Paints need to be removed and stored in combusible lockers
	8080	IMPROPER STORAGELECT/MECH ROOM		1- PERMANENT	200	2006- 03-15	0	N/A
	0106	ACCUMULATION O		1- PERMANENT	216	2006- 03-15	0	Remove storage on the Stage
	0106	ACCUMULATION OF		25- PERMANENT	co2	2006- 03-15	0	floor covered thruout and tripping hazards
	1308	BLDG ADDRESS/I. PRESENT/VISIBLE		92- PORTABLE	43	2006- 03-15	0	No number outside on building
	0408	MANUAL PULL STA MISSING/INOPERA		92- PORTABLE	23	2006- 03-15	0	Pull arm in down position
	0502	DODTARI E EVITNO	GUISHER	92- PORTABLE	23	2006- 03-15	0	N,/A
	0801	INADEQUATE ACC	ESS TO	92- PORTABLE	26	2006- 03-15	0	25
	0299	MEANS OF EGRES	S OTHER	92- PORTABLE	28	2006- 03-15	0	Door covered with paper hard to see door
	0211	BLOCKED/LOCKE	EXITS	92- PORTABLE	30	2006- 03-15	0	Door blocked with rugs
	0106	ACCUMULATION O		92- PORTABLE	30	2006- 03-15	0	Through out the class room and store mom, Tripping hazards on the floor

Mar 24 06 01:45p Clay Fire Prevention State Fire Marshal - Public School Reporting System [Fire Inspection]

(904)284-2647

p. 4

Page 2 of 2

0210 EXIT ACCESS NOT MAINTAINED

92-PORTABLE 2006-03-15

0 Top of door scraping and sticking

Statements acknowledged

 $_{ ilde{1}}$ I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

fes

I hereby certify that the required fire drills have been completed as of this

inspection date.

Yes

(Or) Acknowledgement N/A.

No

Primary inspector

Additional inspector

Philip, Crider

District Clay

School RIDGEVIEW ELEMENTARY

Address 421 JEFFERSON AVENUE

Inspection date 2006-04-11

Notes -

Inspectors present

State No District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	1- PERMANENT	101	2006- 05-11	0	Exit sign out
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	1- PERMANENT	103	2006- 05-11	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	108	2006 - 05-11	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	1- PERMANENT	107	2006- 05-11	0	Panel will not open
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	1- PERMANENT		2006- 05-11	0	To High
	0200	MEANS OF EGRESS	1- PERMANENT		2006- 05-11	0	Lighted Exit sign missing
	0207	INADEQUATE EXIT WIDTHS	1- PERMANENT		2006- 05-11	0	N/A
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT		2006- 05-11	0	Ceiling Tile damaged
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	2- PERMANENT		2006- 05-11	0	N/A
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	2- PERMANENT		2006- 05-11	0	Wheel chair lift for stage filled with shirts and jackets
	0304	PENETRATION PROTECT MISSING/INADEQUATE	2- PERMANEN		2006- 05-11	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	2-		2006- 04-11	0	Panel LK face is falling off
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	2- PERMANEN		2006- 05-11	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	2		2006- 05-11	0	Cover exposed wires
	0799	BUILDING SERVICES OTHER	4- PERMANEN		2006- 05-11	0	Boller Certificate expired by 1 yr. No service records found last was 2000
	0408	MANUAL PULL STATION MISSING/INOPERABLE	3- PERMANEN		2006- 04-11	0	Blocked and corrected
	1205	FIRE EVACUATION DIAMIS) NOT	3- PERMANEN		2006- 04-11	0	N/A
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	3- PERMANEN		2006- 05-11	0	N/A
			6-		2006-		

0901	IMPROPER STORAGE	PERMANENT	616	05-11	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	6- PERMANENT	610	2006- 05-11	0	N/A
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	6- PERMANENT		2006- 05-11	0	612A&C, 611C, 611D, 609A Clear floor area of storage
	IMPROPER STORAGE IN ELECT/MECH ROOMS	6- PERMANENT		2006- 05-11	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	6- PERMANENT	605	2006- 04-11	0	601
0210	EXIT ACCESS NOT MAINTAINED	7- PERMANENT	705	2006- 05-11	0	706, 702
0408	MANUAL PULL STATION MISSING/INOPERABLE	7- PERMANENT		2006- 05-11	0	Blocked
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	7- PERMANENT		2006- 05-11	0	Clear floor area
8080	IMPROPER STORAGE IN ELECT/MECH ROOMS	7- PERMANENT		2006- 05-11	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	7- PERMANENT		2006- 05-11	0	Door sticking
0799	BUILDING SERVICES OTHER	31- PERMANENT	1	2006- 05-11	0	Need flammable Lockers for all the paint
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	30- PERMANENT	1	2006- 05-11	0	N/A
	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	742	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	744	2006- 05-11	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	745	2006- 05-11	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	746	2006- 05-11	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	774	2006- 05-11	0	No Exit signs
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	774	2006- 05-11	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	747B	2006- 05-11	0	Girls Bathroom
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	750	2006- 05-11	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	755	2006- 05-11	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	758	2006- 05-11	0	Too High
0899	UTILITIES OTHER	92- PORTABLE	738B	2006- 05-11	0	Open box falling off the wall
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	735	2006- 05-11	0	Exit door scrapping on the bottom
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- Portable	732	2006- 05-11	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	729	2006- 05-11	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	716	2006- 05-11	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	715	2006- 05-11	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	718	2006- 05-11	0	N/A
	BLDG ADDRESS/I.D. NOT	1-		2006-		All Permanent buildings have no numbers

May 18 06 03:10p Clay Fire Prevention State Fire Marshal - Public School Reporting System [Fire Inspection] (904) 284-2647

p.:

Page 3 of 3

1308 PRESENT/VISIBLE

PERMANENT 1

05-12

on outside

1399 OUTSIDE STRUCTURE OTHER

PERMANENT 401

2006-05-12 Fuel tank outside of building 4 has no

Placard

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

10

0

I hereby certify that the required fire drills have been completed as of this

inspection date.

(Or)

Acknowledgement N/A.

No

No

Primary inspector

Philip, Crider

Additional inspector

[404] 284-264 [

State Fire Marshal - Inspection Report

District Clay

School S BRYAN JENNINGS ELEMENTARY

Address 215 CORONA DRIVE

Inspection date 2006-05-23

Notes

Inspectors present

State No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT	r35c	2006- 06-23	0	chairs in pathway
		HOOD SYSTEM NEEDS INSPECTION/MAINTENANCE	1- PERMANENT	31A	2006- 06-23	0	Fire suppression system required over hot plate.
	0211		1- PERMANENT		2006- 05-24	0	remove chain from second set of exit doors.
		FIRE EXTINGUISHER REQUIRES INSPECTION	2- PERMANENT		2006- 06-23	0	tag not in cuurent date reads expire in 2008
	0204	EMERG LIGHTS NOT OPERATIONAL	3- PERMANENT		2006- 06-23	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	9- PERMANENT		2006- 06-23	0	remove from acroos doorway
	0506	EXTINGUSHER MISSING FROM LOCATION	1- PERMANENT		2006- 06-23	0	N/A
	0299	MEANS OF EGRESS OTHER	5- PERMANENT		2006- 06-23	0	exit door hard to open
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	4- PERMANENT		2006- 06-23	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	30	2006- 06-23	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	38	2006- 06-23	0	remove bookshelf
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	35	2006- 06-23	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	35	2006- 06-23	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	44	2006- 06-23	0	secure power box outside
	0506	EXTINGUSHER MISSING FROM LOCATION	10- PERMANEN	т ¹	2006- 06-23	0	N/A
	0199	GENERAL REQUIREMENTS	92- PORTABLE	77 A	2006- 06-23	0	remove padlock from storage door
٠.	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE	76	2006- 06-23	0	N/A

Statements acknowledged

(904)284-2647

p.2

Page 2 of 2

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

Primary inspector

Additional inspector

, Horace, Earls

Silver, Ware

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 1 of 2

State Fire Marshal - Inspection Report

District Clay

School SWIMMING PEN CREEK ELEMENTARY

Address 1630 WOODPECKER LANE

Inspection date 2006-03-17

Notes -

Inspectors present

State No

District No Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
10 THE REST OF THE BODY TO A	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	1- PERMANENT	128	2006- 03-17	0	Storage to high
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT		2006- 03-17	0	N/A
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	2- PERMANENT	. 203	2006- 03-17	0	Storage to high
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	2- PERMANENT	. 201	2006- 03-17	0	Remove storage from stage
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	3- PERMANENT		2006- 03 - 17	0	31.6 Storage to high
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	3- PERMANENT	306	2006- 03-17	0	301
	0803	EXTENSION CORD NOT RATED FOR USE	3- PERMANENT	308	2006- 03-17	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	3- PERMANENT		2006- 03-17	0	Exit door sticking near room 302
	0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	4- PERMANENT		2006- 03-17	0	41.N Not labeled completely
	0299	MEANS OF EGRESS OTHER	4- PERMANENT		2006- 03-17	0	Need 2nd exit out of room, was teacher planning room now a class room, Not right type of window for exit Same in rooms 5:33, 627
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	4- PERMANENT	424	2006- 03-17	0	N,'A
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4- PERMANENT		2006- 03-17	0	405 Clear floor area
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	5- PERMANEN	T ⁵⁰⁴	2006- 03-17	0	520 Storage to high
	0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	6- PERMANEN	г ⁶³²	2006- 03-17	0	6HS,6LN,6HN Not labeled correctly or completely
	0304	PENETRATION PROTECT MISSING/INADEQUATE	6- PERMANEN		2006- 03-17	0	Ceiling tile missing
	0210	EXIT ACCESS NOT MAINTAINED	6- PERMANEN		2006- 03-17	0	Exit door sticking
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	6- PERMANEN		2006- 03-17	0	622, Storage to high
		ACCUMULATION OF	6-		2006-		606,605,"614" Clear floor area unable to

(904) 284-2647

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 2 of 2

0106	COMBUSTIBLE MATERIALS	PERMANENT	613	03-17	0	enter
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	6- PERMANENT	617	2006- 03-17	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	801	2006- 03-17	0	N/A
0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	801	2006- 03-17	0	On all portables the outside Electric and other boxes are not locked
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	807	2006- 03-17	0	703,705
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	807	2006- 03-17	0	N/A
0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	705	2006- 03-17	0	N/A
0211	BLOCKED/LOCKED EXITS	92- PORTABLE	707	2006- 03-17	0	Corrected
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	708	2006- 03-17	0	708 Exit door will not open all the way in 707 Exit door sticking and scrapping on the bottom in 708
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	92- PORTABLE	801	2006- 03-17	0	All portables do not have numbers on the door and some havve two different numbers on them
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	1- PERMANENT	. 1	2006- 03-17	0	No Number is posted on the outside to let you know what building it is. All Permanent buildings

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with Yes section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

Primary inspector

Additional inspector

Philip, Crider

State Fire Marshal - Inspection Report

District Clay

School THUNDERBOLT ELEMENTARY

Address 2020 THUNDERBOLT ROAD

Inspection date 2006-02-13

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	1- PERMANENT	304a	2006- 03-26	0	N/A
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT	all	2006- 02-26	1	all fire doors have door stops the magnetic opens never installed
	0211	BLOCKED/LOCKED EXITS	1- PERMANENT		2006- 02-26	0	desk in the hallway
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	310	2006- 02-26	0	N/A
	0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	1- PERMANENT	. 324a	2006- 02-26	0	N/A
	0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	1- PERMANENT	. 324	2006- 02-26	0	N/A
	0599	SPRINKLER OTHER	1- PERMANENT	. 261a	2006- 02-26	0	missing hanger for the sprinler pipe
	0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	1- PERMANENT	. 265	2006- 02-26	0	blocked by hanging light
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	171	2006- 02-26	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	. 118	2006- 02-26	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2006- 02-26	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	1-	126	2006- 02-26	0	blank in electric panel

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

No

No

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Acknowledgement N/A.

Νо

Mar 06 06 09:29a

Clay Fire Prevention

(904)284-2647

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 2 of 2

Primary inspector

Scott, Baltes

Additional inspector

Page 1 of 2

State Fire Marshal - Inspection Report

District Clay

School TYNES ELEMENTARY

Address 1550 TYNES BOULEVARD

Inspection date 2006-04-25

Notes "

Inspectors present

State No

District Yes

Local No

Code	Violation	Bldg	Room	Comp date	Cited	Nates
(181)4	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	101	2006- 05-10	1	N/A
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2006- 05 - 10	0	Mulit plug adapter
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 05-10	2	surge protector to surge protector
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 05-10	0	N/A
0504	EXTINGUSIHER ACCESS OBSTRUCTED	1- PERMANENT		2006- 05-10	0	N/A
0504	EXTINGUSIHER ACCESS OBSTRUCTED	2- PERMANENT		2006- 05-10	0	N/A
0506	EXTINGUSHER MISSING FROM LOCATION	2- PERMANENT		2006- 05-10	0	N/A
NVO	No violations noted this date	3- PERMANENT	_	2006- 05-10	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	4- PERMANENT		2006- 05-10	0	N/A.
0504	EXTINGUSIHER ACCESS OBSTRUCTED	5- PERMANENT		2006- 05-10	0	N/A.
0304	PENETRATION PROTECT MISSING/INADEQUATE	6- PERMANENT	612	2006- 05-10	0	Missing ceiling tiles
0304	PENETRATION PROTECT MISSING/INADEQUATE	6- PERMANENT		2006- 05-10	0	Missing ceiling tile
0504	EXTINGUSIHER ACCESS OBSTRUCTED	6- PERMANENT		2006- 05-10	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6- PERMANEN		2006- 05-10	0	N/A
1205	FIRE EVACUATION PLAN(S) NOT POSTED	6- PERMANEN		2006- 05-10	0	N/A
0299	MEANS OF EGRESS OTHER	91- PORTABLE	5	2006- 05 - 10	0	Door closer broken.
0408	MANUAL PULL STATION MISSING/INOPERABLE	91- PORTABLE	8	2006- 05-10	0	Missing glass bar
1205	FIRE EVACUATION PLAN(S) NOT POSTED	91- PORTABLE	10	2006- 05-10	0	N/A
	BLDG ADDRESS/I.D. NOT	91-		2006-		

May 12 06 03:10p

Clay Fire Prevention

(904) 284-2647

p.6

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 2 of 2

1308	PRESENT/VISIBLE	PORTABLE	10	05-10	0	No fish number posted
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	91- PORTABLE	22	2006- 05-10	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	91- PORTABLE	22A	2006- 05-10	0	Mulit plug adapter in closet.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	91- PORTABLE	23	2006- 05-10	0	surge to surge
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	91- PORTABLE	25	2006- 05-10	0	N/A
0410	SYSTEM NOT PROERLY INSPECTED/MAINTAINED	91- PORTABLE	26	2006- 05 - 10	2	Puli station missing glass bar
0899	UTILITIES OTHER	91- PORTABLE	26	2006- 05 - 10	0	Electric cord running under door into supply room.
0499	FIRE ALARM OTHER	91- PORTABLE	28	2006- 05-10	0	Pull station blocked.
0410	SYSTEM NOT PROERLY INSPECTED/MAINTAINED	91- PORTABLE	66	2006- 05 - 10	0	Pull station missing glass bar.
0499	FIRE ALARM OTHER	91- PORTABLE	66	2006 - 05-10	0	Pull station blocked.
0210	EXIT ACCESS NOT MAINTAINED	91- PORTABLE	67	2006- 05-10	0	Discharge blocked by stacked boxs.

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **Yes**I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. **Yes**

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

inspection dute.

Acknowledgement N/A.

No

, **Primary inspector** Stephen, Arzie Additional inspector

District Clay

School J L WILKINSON ELEMENTARY

Address 4965 COUNTY ROAD 218

Inspection date 2006-02-07

Notes

Inspectors present

State No District No Local Yes

Ref	Code	Violation	Bidg	Room	Comp date	Cited	Notes
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	140	2006- 03-09	0	Room 142
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	140	2006- 03-09	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	68	2006- 02-09	0	N/A
	0299	MEANS OF EGRESS OTHER	92- PORTABLE	38	2006- 03-09	0	Emergency exit sign missing
	0299	MEANS OF EGRESS OTHER	92- PORTABLE	34	2006- 03-09	0	Emergency exit sign missing
	0299	MEANS OF EGRESS OTHER	92- PORTABLE	18	2006- 03-09	0	Emergency exit sign missing
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	7	2006- 03-09	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	42	2006- 03-09	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	5	2006- 03-09	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	48	2006- 03-09	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	19	2006- 03-09	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	50	2006- 03-09	0	N/A
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	51 .	2006- 03-09	0	N/A
	0399	PROTECTION OTHER	92- PORTABLE	11	2006- 03-09	0	Ceiling missing. open trusses.

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

No

Yes

I hereby certify that the required fire drills have been completed as of this

inspection date.	Yes Or)
Acknowledgement N/A.	No
Primary inspector	Additional inspector
Karen, Golish	N/, A

State Fire Marshal - Inspection Report

District Clay

School WE CHERRY ELEMENTARY

Address 420 EDSON DRIVE

Inspection date 2006-04-05

Notes

Inspectors present

State No

District No

State No		District No Local Yes					
Ref	Code	Violation	Bidg	Room	Comp date	Cited	Notes
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT	4	2006- 04-12	0	wrong wall bracket for extinguisher
	0506	EXTINGUSHER MISSING FROM LOCATION	2- PERMANENT	810	2006- 04-10	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	2- PERMANENT	. 75	2006- 04-10	0	in process of being repaired
	0204	EMERG LIGHTS NOT OPERATIONAL	2- PERMANENT	. 77	2006- 04-14	. 0	has been removed needs to be replaced
	0211	BLOCKED/LOCKED EXITS	2- PERMANENT		2006- 04-10	0	chairs stacked between stairs and door
	0304	PENETRATION PROTECT MISSING/INADEQUATE	3- PERMANENT	. 55	2006- 04-10	0	replace missing ceiling tile
	0304	PENETRATION PROTECT MISSING/INADEQUATE	3- PERMANENT		2006- 04-10	0	replace celling tile
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	3- PERMANENT		2006- 04-10	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3- PERMANENT	FF0	2006- 04-10	0	multistrip into multistrip
	0299	MEANS OF EGRESS OTHER	3- PERMANEN	r ¹⁶	2006- 04-10	0	missing emergency exit signs on door
	UNK	UNKNOWN CODE VIOLATION	3- PERMANEN		2006- 04-10	0	greater than 25% of wall area covered with paperwork and pictures, doesn't include bullentin boards
	UNK	UNKNOWN CODE VIOLATION	4- PERMANEN	T 15	2006- 04-10	0	greater than 25% of wall area covered with paperwork and pictures, doesn't include bullentin boards
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	4- PERMANEN	T 11	2006- 04-10	0	N/A
	0299	MEANS OF EGRESS OTHER	4- PERMANEN		2006- 04-10	0	missing emergency exit signs on door
	UNK	UNKNOWN CODE VIOLATION	4- PERMANEN		2006- 04-10	0	greater than 25% of wall area covered with paperwork and pictures, doesn't include bullentin boards
	120	FIRE EVACUATION PLAN(S) NOT POSTED	7 4- PERMANEN	T 12	2006- 04-10	0	not visibily mounted near door
	029	MEANS OF EGRESS OTHER	4- PERMANEN		2006- 04-10	0	clear area around roof access ladder

0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4- PERMANENT	. 23	2006- 04-10	0	multistrip into multistrip
0299	MEANS OF EGRESS OTHER	4- PERMANENT	. 21	2006- 04-10	0	missing emergency exit sign on door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	26	2006- 04-10	0	emergency exit sign on door
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	27	2006- 04-10	0	need to post visibily by door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	37	2006- 04-10	0	ernergency exit signs needed on doors
UNK	UNKNOWN CODE VIOLATION	92- Portable	38	2006- 04-10	0	remove paper from closet dor, door totally covered
0299	MEANS OF EGRESS OTHER	92- PORTABLE	38	2006- 04-10	0	missing emergency exit sign on door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	39	2006- 04-10	0	missing emergency exit sign on door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	43	2006- 04-10	0	missing emergency exit sign on door
UNK	UNKNOWN CODE VIOLATION	92- PORTABLE	42	2006- 04-10	0	greater than 25% of wall area covered with paperwork and pictures, doesn't include bullentin boards
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	42	2006- 04-10	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	42	2006- 04-10	0	discontinue use of extension cords
0299	MEANS OF EGRESS OTHER	92- PORTABLE	41	2006- 04-10	0	missing emergency exit sign on door
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	41	2006- 04-10	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	40	2006- 04-10	0	N/A
UNK	UNKNOWN CODE VIOLATION	92- PORTABLE	40	2006- 04-10	0	greater than 25% of wall area covered with paperwork and pictures, doesn't include bullentin boards
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	29	2006- 04-10	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	31	2006- 04-10	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	30	2006- 04-10	0	missing emergency exit sign on door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	32	2006- 04-10	0	missing emergency exit sign on door
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	32	2006- 04-10	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	33	2006- 04-14	0	height of first step goin up last coming down greater then eight inches could be trip or fall hazard in emergency, school advises they have requested slab be poured
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	34	2006- 04-10	0	N/A
0213	AREA OF REFUGE NOT PROVIDED	92- PORTABLE	52	2006- 04-10	0	locked out of this building, maintenance does not have key only PE teacher does. recommended maintenace be given a key
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	49	2006- 04-10	0	bookcase in front of panel
0299	MEANS OF EGRESS OTHER	92- Portable	49	2006- 04-10	0	emergency exit sign blocked by pictures
		92-		2006-		

0299	MEANS OF EGRESS OTHER	PORTABLE	48	04-10	0	missing emergency exit sign on door
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	54	2006- 04-10	0	mult-strip plugged into multistrip
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	54	2006- 04-10	0	N/A
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	1	2006- 04-10	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	11- PERMANENT	67	2006- 04-10	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	46	2006- 04-10	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	20- PERMANENT	1	2006- 04-10	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complled with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

Primary inspector Michael, Swartz

Additional inspector

District Clay

School R C BANNERMAN LEARNING RESOURCE CENTER

Address 608 MILL STREET

Inspection date 2006-02-08

Notes -

Inspectors present

State No District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0515	HOOD SYSTEM NEEDS INSPECTION/MAINTENANCE	2- PERMANENT	214	2006- 04-08	0	Room. 217 stoves in nurseys shall be protected with fire suppression system.
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	3- PERMANENT	320	2006- 03-08	1	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	38	2006- 03-08	0	N/A
			92-		2006-		Remove Christmas lights from the room
		UTILITIES OTHER	PORTABLE	8	03-08	0	theycan not be attached to the building walls.
I hereby I hereby section I hereby	nents acl y certify t y certify t 1013.12	chat the local authority having jurisdictly, F.S.	pORTABLE ction 1013.12 ction has con	2(1)(b), nplied v	03-08 , F.S. vith	No Yes	
I hereby I hereby section I hereby	y certify to 1013.12(cnowledged that the district has complied with se that the local authority having jurisdi (2)(b), F.S.	pORTABLE ction 1013.12 ction has con	2(1)(b), nplied v	03-08 , F.S. vith	No Yes	

Primary inspector

Kevin, Mobley

Additional inspector

District Clay

School GREEN COVE SPRINGS JUNIOR HIGH

Address 1220 BONAVENTURE AVENUE

Inspection date 2006-01-27

Notes

Inspectors present

State No District No

Ref	Code	Violation	Bidg	Room	Comp date	Cited	Notes
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	14A	2006- 02-27	0	Damage ceiling tiles
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	15	2006- 02-27	0	Replace ceiling tiles above Television
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	0-Building N/A See notes	800	2006- 02-27	0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	2- PERMANENT	. 800	2006- 02-27	0	N/A
	0301	UNPROTECTED VERTICAL OPENING	2- PERMANENT	. 800	2006- 02-27	0	replace damage ceiling tiles
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	2- PERMANENT		2006- 02-27	0	N/A
	0301	UNPROTECTED VERTICAL OPENING	4- PERMANENT		2006- 02-27	0	Room 425 replace damage ceiling tiles
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4- PERMANENT		2006- 02-27	1	N/A
	0210	EXIT ACCESS NOT MAINTAINED	4- PERMANENT		2006- 02-27	0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE		C4E	2006- 02-27	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6- PERMANENT	. 105G	2006- 02-27	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	6- PERMANENT		2006- 02-27	0	N/A
Nfpa101- 7.2.1.6	0211	BLOCKED/LOCKED EXITS	8- PERMANENT		2006- 02-27	0	Remove Chains and lock form exit doors by Restroom
	0210	EXIT ACCESS NOT MAINTAINED	8- PERMANENT	021	2006- 02-27	0	Room 803 remove table
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	112	2006- 02-27	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	107	2006- 02-27	0	N/A
	0506	EYTINGUICHED MISSING EDOM	92- PORTABLE	106	2006- 02-27	0 .	N/A

0204	EMERG LIGHTS NOT OPERATIONAL	PORTABLE	516	02-28	0	N/A
112111	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	515	2006- 02-28	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	515	2006- 02-28	0	please mount
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	514	2006- 02-28	0	N/A
0301	UNPROTECTED VERTICAL OPENING	92- PORTABLE	505	2006- 02-28	0	ceiling is falling in
0300	PROTECTION	92- PORTABLE	505	2006- 01-30	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	507	2006- 02-28	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	711	2006- 02-28	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	711	2006- 02-28	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	712	2006- 02-28	0	N/A
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	707	2006- 02-28	0	fire. ext. used empty
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	702	2006- 02-28	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	717	2006- 02-28	0	steps are not equal heights
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	717	2006- 02-28	0	N/A
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	718	2006- 02-28	0	ext. has been used. needs service
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	719	2006- 02-28	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S.

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

No

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector Scott, Baltes Additional inspector

State Fire Marshal - Inspection Report

District Clay

School LAKESIDE JUNIOR HIGH

Address 2750 MOODY ROAD

Inspection date 2006-03-20

Notes -

Inspectors present

State No District No Local Yes

state NO		District NO Local 1es					
Ref	Code	Violation	Bidg	Room	Comp date	Cited	Motes
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	2	2006- 03-20	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	. 30	2006- 03-20	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	1- PERMANENT		2006- 03-20	0	%/ A
	0299	MEANS OF EGRESS OTHER	2- PERMANENT		2006- 03-20	0	No Exit sign by door
	0204	EMERG LIGHTS NOT OPERATIONAL	2- PERMANENT		2006- 03-20	0	Hallway
	0304	PENETRATION PROTECT MISSING/INADEQUATE	2- PERMANENT		2006- 03-20	0	Damaged or missing Ceiling tile
	0803	EXTENSION CORD NOT RATED FOR USE	2- PERMANENT		2006- 03-20	0	N/A
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	3- PERMANENT		2006- 03-20	0	N/A
	0304	PENETRATION PROTECT MISSING/INADEQUATE	3- PERMANENT		2006- 03-20	0	66 Damaged or missing ceiling tile
	0299	MEANS OF EGRESS OTHER	3- PERMANENT		2006- 03-20	0	Needs Exit sign
	0211	BLOCKED/LOCKED EXITS	8- PERMANENT		2006- 03-20	0	Corrected
	0304	PENETRATION PROTECT MISSING/INADEQUATE	8- PERMANENT	. 822	2006- 03-20	0	Missing or damaged ceiling tile
	0702	LP GAS CYL IMPROPERLY LOCATED/STORED	6- PERMANENT		2006- 03-20	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	9- PERMANENT		2006- 03-20	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	9- PERMANENT	.1	2006- 03-20	0	Corrected
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	9- PERMANENT		2006- 03 <i>-</i> 20	0	951
	0803	EXTENSION CORD NOT RATED FOR USE	9- PERMANENT		2006- 03-20	0	Corrected
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	9- PERMANENT		2005- 03-20	0	N/A
		PORTABLE EXTINGUISHER	9-		2006-		

3:24PM

	IMPROPERLY MOUNTED	PERMANENT 901A	03-20 2006-	0	N/A.
	EMERG LIGHTS NOT OPERATIONAL	7- PERMANENT 2	03-22	O	N/A.
	ACCUMULATION OF COMBUSTIBLE MATERIALS	20- PERMANENT ¹	2006- 03-22	0	Need Flammable locker
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	5- PERMANENT 116	2006- 03-22	0	Toc High
0211	BLOCKED/LOCKED EXITS	5- PERMANENT 112	2006- 03-22	0	N/A
0399	PROTECTION OTHER	0-Building N/A See 110 notes	2006- 03-22	0	Remove door stops on fire doors
0899	UTILITIES OTHER	5- PERMANENT 116	2006- 03-22	0	Frayed electric cords on food line
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	5- PERMANENT 116	2006- 03-22	0	Remove storage from stage
0210	EXIT ACCESS NOT MAINTAINED	5- PERMANENT 124	2006- 03-22	0	Wheel chair lift for stage blocked
0102	OCCUPANCY LOAD EXCEEDED/NOT POSTED	5- PERMANENT 116	2006- 03-22	0	Noi: posted
0506	EXTINGUSHER MISSING FROM LOCATION	5- PERMANENT 133	2006- 03-22	0	N/A
0304	PENETRATION PROTECT MISSING/INADEQUATE	5- PERMANENT ²⁰⁷	2006- 03 - 22	0	Celling tile
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	5- PERMANENT 247	2006- 03-22	0	Overloaded storage
0408	MANUAL PULL STATION MISSING/INOPERABLE	5- PERMANENT 217	2006- 03-22	0	Blocked
0210	EXIT ACCESS NOT MAINTAINED	91- PORTABLE 745A	B 2006- 03-22	0	73'9 Missing non skid on stairs and ramps
080	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE 743	2006- 03-22	0	725, 703, 791
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	92- PORTABLE 737	2006- 03-22	0	Storage all over
0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE 737	2006- 03-22	0	N/A
040	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE 724	2006- 03 -2 2	0	Hanging
029	MEANS OF EGRESS OTHER	92- PORTABLE 723	2006- 03-22	0	Tripping hazards all the internet lines on the ground
040	MISSING/INOPERABLE	92- PORTABLE 725	2006- 03-22	0	Blacked
050	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE 721	2006- 03-22	U	708,794
030	PENETRATION PROTECT MISSING/INADEQUATE	92- PORTABLE 710	c 2006- 03-22		Ceiling hanging down
021	0 EXIT ACCESS NOT MAINTAINED	92- PORTABLE 705	2006- 03-22		Exit door sticking
101- 15.3.4.2 040	7 FACP INDICTAES TROUBLE CONDITION	5- PERMANENT ¹²¹	2006- 03-20		System malfunction
101- 15.2.2 021	0 EXIT ACCESS NOT MAINTAINED	5- PERMANENT 111	2006- 03-20		Walk in freezers locked with bar

Statements acknowledged

Mar 24 06 01:47p

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

(904)284-2647

P.9 Page 3 of 3

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

Primary inspector

Philip, Crider

Additional Inspector

Scott, Baltes

District Clay

School ORANGE PARK JUNIOR HIGH

Address 1500 GANO AVENUE

Inspection date 2006-01-25

Notes

Inspectors present

State No District No

Local Yes

lef	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	101	2006- 02-28	0	doors need thumb turn lock only
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	120	2006- 02-28	0	N/A
	0299	MEANS OF EGRESS OTHER	1- PERMANENT		2006- 02-28	0	remove door hasp from door.
	0299	MEANS OF EGRESS OTHER	1- PERMANENT		2006- 02-28	0	remove hasp
	0299	MEANS OF EGRESS OTHER	1- PERMANENT		2006- 02-28	0	remove eyelet from foor so it may not be chained.
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT		2006- 02-28	0	caulk holes in wall
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 02-28	0	remove multiplug outlet
	0212	AREA OF REFUGE NOT MAINTAINED	3- PERMANENT		2006- 02-28	0	remove combustible in stairwell
	0299	MEANS OF EGRESS OTHER	3- PERMANENT		2006- 02-28	0	2nd exit not marked
	0210	EXIT ACCESS NOT MAINTAINED	2- PERMANENT		2006- 01-30	0	door knob fell off
	0303	INADEQUATE FIRE RESISTANCE	2- PERMANENT		2006- 02-28	0	curtins over exit not rated
	0212	AREA OF REFUGE NOT MAINTAINED	2- PERMANENT		2006- 01-30	0	exit door knob not working
	0299	MEANS OF EGRESS OTHER	2- PERMANENT		2006- 01-30	0	removed hasp on door corrected on site
	0211	BLOCKED/LOCKED EXITS	2- PERMANENT		2006- 01-30	0	second exit blocked. fixed on site
	0803	EXTENSION CORD NOT RATED FOR USE			2006- 02-28	0	remove ext. cord
	0803	EXTENSION CORD NOT RATED FOR USE			2006- 02-28	0	remove ext. cord
	0210	EXIT ACCESS NOT MAINTAINED	6- PERMANEN		2006- 02-28	0	remove all door stops on door with autoclosing
	0301	UNPROTECTED VERTICAL OPENING	5-		2006- 02-28	0	replassing missing ceiling tile
			92-		2006-		

http://app.bebr.ufl.edu/egroupware/Fire_Inspection/main.php?menuaction=Fire_Inspection.bo_inspselect.g... 2/9/2006

Statements acknowledged

section 1013.12(2)(b), F.S.

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. I hereby certify that the local authority having jurisdiction has complied with

No Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

Primary inspector

Additional inspector

Kevin, Mobley

District Clay

School JACK L WILKINSON JUNIOR HIGH

Address 5025 STATE ROAD 218

Inspection date 2006-03-15

Notes

Inspectors present

State No

District No

f Code	Violation	Bldg	Room	Comp date	Cited	Notes
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT	A104	2006- 03-28	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	1- PERMANENT		2006- 04-15	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT		2006- 04-15	0	N/A
0202	EXIT LIGHTS INOPERABLE NORMAL MODE	2- PERMANENT		2006- 04-28	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	2- PERMANENT		2006- 04-28	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	2- PERMANENT		2006- 04-28	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3- PERMANENT		2006- 04-28	0	N/A
0899	UTILITIES OTHER	2- PERMANENT		2006- 04-28	0	Eletrical panel box door falling off
0301	UNPROTECTED VERTICAL OPENING	3- PERMANENT		2006- 04-28	0	ceiling tiles missing
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4- PERMANENT		2006- 04-28	0	N/A
0299	MEANS OF EGRESS OTHER	4- PERMANENT		2006- 04-28	0	Roof access obstructed
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	5- PERMANENT		2006- 04-28	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	5- PERMANEN		2006- 04-28	0	N/A
080	OPEN ELECTRICAL JUNCTION BOX	5-		2006- 04-28	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	6- PERMANEN		2006- 04-28	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	6- PERMANEN		2006- 04-28	0	N/A
080	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	7- PERMANEN		2006- 04-28	0	N/A
030:	LINPROTECTED VERTICAL	7- PERMANEN		2006- 04-28	0	ceiling tiles missing
		7-		2006-		

Clay Fire Prevention

p.2

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page	2	of	2
------	---	----	---

N211	BLOCKED/LOCKED EXITS	PERMANENT	722	03-28	0	Blocked emergency exit
0502	PORTABLE EXTINGUISHER	7-	730	2006-	0	Rooms: 749.757,767
0302	IMPROPERLY MOUNTED	PERMANENT	730	04-28	U	ROGITIS. 743.737,707
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	7- PERMANENT	739	2006- 04-28	0	Room 760
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	4	2006- 04-28	0	N/A
1399	OUTSIDE STRUCTURE OTHER	92- PORTABLE	6	2006- 04-28	0	front outside wall rotten wood with large holes, wet insulation
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	9	2006- 04-28	0	A/N
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	2	2006- 04-28	0	A/N
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE	2	2006- 04-28	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	12	2006- 04-28	0	needs to be mounted
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	17	2006- 04-28	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	17	2006- 04-28	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	91- PORTABLE	18	2006- 03-28	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	27	2006- 04-28	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	21	2006- 04-28	0	N/A
0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	24	2006- 04-28	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92- PORTABLE	96	2006- 04-28	0	mount fire extinguisher

Statements acknowledged

I hereby certify that the district has complled with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with Yes section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

Primary inspector

Additional inspector

Karen, Golish

District Clay

School CLAY HIGH SCHOOL

Address 2025 HIGHWAY 16 W

Inspection date 2006-02-22

Notes

Inspectors present

State No District No

Ref	Code	Violation	Bidg	Room	Comp date	Cited	Notes
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	1- PERMANENT	128	2006- 02-22	0	N/A
	0809	OPEN ELECTRICAL JUNCTION BOX	1- PERMANENT		2006- 02-22	0	N/A
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	1- PERMANENT		2006 - 02-22	0	REMOVE ALL STORAGE FROM ELECTRICAL ROOM.
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT		2006- 02-22	0	REPLACE ALL DAMAGED OR MISSING CEILING TILES.
	0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	1- PERMANENT		2006- 02-22	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	2- PERMANENT	200	2006- 02-22	0	CAN NOT STACK SURGE PROTECTORS
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	2- PERMANENT	. 208	2006- 02-22	0	N/A:
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3- PERMANENT	367	2006- 02-22	0	CAN NOT STACK SURGE PROTECTORS
	0809	OPEN ELECTRICAL JUNCTION BOX	3- PERMANENT	389	2006- 02-22	0	PUT COVER PLATE ON OUTLET.
	0211	BLOCKED/LOCKED EXITS	3- PERMANENT	315	2006- 02-22	0	REMOVE FURNITURE BLOCKING EXIT
	0899	UTILITIES OTHER	3- PERMANENT	215	2006- 02-22	0	REMOVE CHRISTMAS LIGHTS FROM CEILING AND WALL.
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	3- PERMANENT	r 325	2006- 02-22	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3- PERMANEN	г ³³⁸	2006- 02-22	0	CAN NOT STACK SURGE PROTECTOR
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	3- PERMANEN	T ³⁴⁰	2006- 02-22	0	N/A
	1202	DANGEROUS CONDITION EXISTS	₹-		2006- 02-22	0	NO BURNING OF CANDLES IN BUILDING.
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3- PERMANEN	251	2006- 02-22	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3- PERMANEN	T 362	2006- 02 - 22	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4- PERMANEN	405	2006- 02-22	0	REMOVE CORD THAT COPIER IS PLUGGED INTO MOVE COPIER TO PROVIDE ACCESS TO PANEL BOXES.

THE ENTIRE BUILDING NEEDS CEILING

TILES REPLACED THAT ARE DAMAGED

OR MISSING. THIS WAS CITED LAST

State Fire Marshal - Public School Reporting System [Fire Inspection]

Page 2 of 2

p.6

EXIT LIGHTS INOPERABLE 2006-PERMANENT 401 0 N/A **NORMAL MODE** 02-22 0202 EXIT LIGHTS INOPERABLE 2006-PERMANENT 510A 0 N/A **NORMAL MODE** 02-22 **EXIT LIGHTS INOPERABLE** 2006-PERMANENT 510B 0 0202 N/A **NORMAL MODE** 02-22 **EXTENSION CORD NOT RATED** 2006-0803 0 PERMANENT 510B N/A FOR USE 02-22 **EXIT LIGHTS INOPERABLE** 2006-PERMANENT 517B 0 N/A **NORMAL MODE** 02-22 2006-0211 BLOCKED/LOCKED EXITS 0 PERMANENT 788 N/A 02-22 **IMPROPER USE OF** 2006-0 N/A PERMANENT 789 02-22 MULTISTRIP/EXTEN CORDS **ACCUMULATION OF** 9-2006-CAN NOT STORE CAP AND GOWN BOXES PERMANENT 919 0 0106 COMBUSTIBLE MATERIALS 02-22 IN ELECTRICAL ROOM. **EXIT LIGHTS INOPERABLE** 9-2006-0202 0 PERMANENT 903 N/A NORMAL MODE 02-22 2006-**EXTENSION CORD NOT RATED** 0803 0 PERMANENT 1115 N/A FOR USE 02-22 2006-PENETRATION PROTECT REPLACE MISSING OR DAMAGED 0304 PERMANENT 1122 0 MISSING/INADEQUATE 02-22 CEILING TILES. REMOVE FURNITURE THAT BLOCKS THE 2006-**INADEQUATE ACCESS TO** 90-FIRE EXTINGUISHER, PANEL BOX AND 0801 CI899 0 **PORTABLE ELECTRICAL PANEL** 02-22 PROPERLY USE STACKED SURGE STRIPS. PORTABLE EXTINGUISHER 90-2006-0502 0 35 ALSO ALARM BOX NEEDS REPAIR. IMPROPERLY MOUNTED **PORTABLE** 02-22

Statements acknowledged

0304

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **No**I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

PENETRATION PROTECT

MISSING/INADEQUATE

Yes

2006-

02-22

1

YEAR.

(Or)

Acknowledgement N/A.

No

Primary inspector Kevin, Mobley Additional inspector

PERMANENT ALLROOMS

District Clay

School FLEMING ISLAND SENIOR HIGH

Address 2233 VILLAGE SQUARE PARKWAY

Inspection date 2006-05-12

Notes -

Inspectors present

State No

District No

lef	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	013	2006- 04-25	0	N∕A
	0704	COMPRESSED GAS CYLINDERS NOT SECURED	0-Building N/A See notes	017	2006- 04-25	0	N/A
	0515	HOOD SYSTEM NEEDS INSPECTION/MAINTENANCE	0-Building N/A See notes	042	2006- 04-25	0	N/A.
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0-Building N/A See notes	052	2006- 04 - 25	0	N/A
	0899	UTILITIES OTHER	0-Building N/A See notes	048	2006- 04-25	0	blank in electric panel
	0404	TEST/MAINT NOT PERFORMED AND/OR RECORDED	0-Building N/A See notes	1005	2006- 04-25	0	out of date and not monitored
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	0-Building N/A See notes	1018	2006- 04-25	0	N/A
	0408	MANUAL PULL STATION MISSING/INOPERABLE	0-Building N/A See notes	1018	2006- 04-25	0	blocked
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	1008	2006- 04-25	0	ការ lti plug with ice maker in room. not o gfi
	1101	COMBUSTIBLE MATERIAL IMPROPERLY STORED	0-Building N/A See notes	263	2006- 04-25	0	N/.4
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	0-Building N/A See notes	281	2006- 04-25	0	N/A
	0899	UTILITIES OTHER	0-Building N/A See notes	302	2006- 04-25	0	outlet need cover
	0899	UTILITIES OTHER	0-Building	g 176	2006- 04-25	0	exposed wires

		See notes			
0899	UTILITIES OTHER	0-Building N/A 142 See notes	2006- 04-25	0	exposed wires
114117	UNPROTECTED VERTICAL OPENING	0-Building N/A 142 See notes	2006 - 04-25	0	caulk ceiling
0010	IMMINENT HAZARD	0-Building N/A 180 See notes	2006- 04-25	0	no key to elevator on site.
0210	EXIT ACCESS NOT MAINTAINED	0-Building N/A 105 See notes	2006- 04-25	0	only one exit from room
0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	0-Building N/A 230 See notes	2006- 04-25	0	N/A .
0505	IMPROPER RATING OF EXTINGUISHER	0-Building N/A 001 See notes	2006- 04-25	0	class k fire ext. needed
0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE ⁸⁰	2006- 05-22	0	in store room
0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE 81	2006- 05-22	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE ⁸¹	2006- 05-22	0	remove hasp/lock
0899	UTILITIES OTHER	92- PORTABLE ⁹²	2006- 05-22	0	missing blank in electrical panel
0299	MEANS OF EGRESS OTHER	92- PORTABLE ⁶⁰	2006- 05-22	0	loose door closer on rear exit
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE 30	2006- 05-22	0	rear exit will not open fully
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE ³⁰	2006- 05-22	0	N/A
1399	OUTSIDE STRUCTURE OTHER	92- PORTABLE 30	2006- 05-22	0	broken welds on reamp mid support
0299	MEANS OF EGRESS OTHER	92- PORTABLE ⁴⁷	2006- 05-22	0	remove locl hasp to store room
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE ²⁴	2006- 05-22	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE ¹³	2006- 05-22	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE ¹²	2006- 05-22	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE ¹²	2006- 05-22	0	reinstall brackert on wall
0807	, MISSING/BROKEN RECEPTACLE/FACEPLATE	91- PORTABLE ¹²	2006- 05-22	0	N/A
0405	SMOKE DETECTORS INOPERABLE/MISSING	91- PORTABLE 20	2006- 05-22	0	in storeroom
0204	EMERG LIGHTS NOT OPERATIONAL	91- PORTABLE ²⁰	2006- 05-22	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE ¹⁰	2006- 05-22	0	rear door handle hard to open, remove haspe on storeroom door

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

May 22 06 08:32			(904)284-2647	p.3
State Fire Marshal - Publi	ic School Reporting System [Fire_Insp	pection		Page 3 of 3
I hereby certify that the req inspection date.	uired fire drills have been completed as of t	this Yes		
·	(Or)			
Acknowledgement N/A.		No		
	·			

Primary inspector Scott, Baltes

Additional inspector

Silver, Ware

May 22 06 03:40p tate Fire Marshal - Public School Reporting System [Fire_Inspection]

State Fire Marshal - Inspection Report

District Clay

School KEYSTONE HEIGHTS JUNIOR/SENIOR HIGH

Address 900 SW ORCHID AVENUE

Inspection date 2005-11-23

Notes -

Inspectors present

State No

District No

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	170	2006- 01-15		change swing of exit door to swing in the direction of travel
		IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	182	2006- 01-15	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT	62	2005- 12-15	0	REMOVE BOOKCASE FROM BLOCKING PATH OF TRAVEL TO EXIT
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT	. 192	2005- 12-15	0	REMOVE BOOKCASE FROM BLOCKING PATH OF TRAVEL TO EXIT
	0405	SMOKE DETECTORS INOPERABLE/MISSING	1- PERMANENT		2006- 01-15	0	PLACE HEAT DETECTOR IN STORE ROOM
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4- PERMANENT		2006- 01-15	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	4- PERMANENT		2006- 01-15	0	N/A
	0599	SPRINKLER OTHER	5- PERMANENT		2005- 12-15	0	REMOVE STORAGE BLOCKING RISER
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	6- PERMANEN		2005- 12-15	0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	7- PERMANEN		2006- 01-15	0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	9- PERMANEN		2006- 01-15	0	N/A
	0199	GENERAL REQUIREMENTS	18- PERMANEN	_	2005- 12-15	0	Store all flammable liquids in approved location
	0299	MEANS OF EGRESS OTHER	34- PERMANEN		2006- 05-22	2	install hand rails per NFPA 101
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	78	2006- 01-15	0	N/A
	0804	IMPROPER LISE OF	92- PORTABLE	80	2006- 01-15	0	N/A
	0202	EXIT LIGHTS INOPERABLE	92- PORTABLE	18	2006- 01-15	0	N/A
	0202	EXIT LIGHTS INOPERABLE	92- PORTABLE	1	2006- 01-15	0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	92- PORTABLE	92	2006- 01-15	0	N/A

May 22 06 03:39p Clay Fire Prevention ate Fire Marshal - Public School Reporting System [Fire_Inspection]

(Or)

(904)284-2647

Page 2 of 2

rspection date.

Yes

icknowledgement N/A.

No

Primary inspectorSilver, Ware

Additional inspector

District Clay

School MIDDLEBURG SENIOR HIGH

Address 3750 STATE ROAD 220

Inspection date 2006-05-10

Notes

Inspectors present

State No District Yes

Local No

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	. 378	2006- 05-10	0	Times 2 extinguishers
	0704	COMPRESSED GAS CYLINDERS NOT SECURED	1- PERMANENT	. 360	2006- 05-10	2	N,'A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	. 351	2006- 05-10	0	N/A
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	. 351	2006- 05-10	0	No fish number posted.
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	. 358	2006- 05-10	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	358	2006- 05-10	0	N/A
	0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	1- PERMANENT	00000	2006- 05-10	4	Most electrical panel boxs threw out do not have circuts marked.
NFPA- 101sec.7.	9 0299	MEANS OF EGRESS OTHER	1- PÉRMANEN	00000	2006- 05-10	4	Permanent exit signs missing threw ou the building.
	0405	SMOKE DETECTORS INOPERABLE/MISSING	1- PERMANEN		2006- 05-10	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE			2006- 05-10	0	Orange cord
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANEN	T 350	2006- 05-10	0	Orange cord.
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANEN	340	2006 <i>-</i> 05-10	0	1. extinguisher with broken guage. 2. extinguisher at rear door pin pulled.
	0899	UTILITIES OTHER	1- PERMANEN	т ³⁴⁰	2006- 05-10	0	Emergency shut off blocked.
	0803	EXTENSION CORD NOT RATED FOR USE			2006- 05-10	0	N/A
	0299	MEANS OF EGRESS OTHER	1- PERMANEN		2006- 05-10	3	Exit sign missing.
	0299	MEANS OF EGRESS OTHER	1- PERMANEN	130	2006- 05-10	0	Door closer broken
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANEN	т 122	2006- 05-10	0	N/A
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANEN	01	2006- 05-10	0	N/A

	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	91	2006- 05-10	0	Orange cords.
	0803	EXTENSION CORD NOT RATED FOR USE			2006- 05-10	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2006- 05-10	0	Yellow cord.
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 05-10	0	surge to surge
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 05-10	3	surge to surge.
	0504	EXTINGUSIHER ACCESS OBSTRUCTED	1- PERMANENT	148	2006- 05-10	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	148	2006- 05-10	0	Surge to surge.
	0506	EXTINGUSHER MISSING FROM LOCATION	1- PERMANENT	151	2006- 05-10	3	N/A
	0899	UTILITIES OTHER	1- PERMANENT	163	2006- 05-10	4	Electric cord running as permanent wiring under door.
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	161	2006- 05-10	0	Crange cord.
101sec.7	0211	BLOCKED/LOCKED EXITS	1- PERMANENT	GymHallway	2006- 04-25	3	Found the exit doors with chain and locked two consecutive days.
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	335	2006- 05-10	2	N/A
	0499	FIRE ALARM OTHER	1- PERMANENT	335	2006- 05-10	0	Pull station blocked.
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE		GymHallway	2006- 05-10	0	Broken and pulling away from wall at Tropicana drinks.
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	291	2006- 05-10	4	The exit sign outside 291 missing.
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT	294	2006- 05-10	0	Tiles missing.
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	206	2006- 05-10	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	206	2006- 05-10	2	Extension cord running Cappaccino.
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT	212	2006- 05-10	0	Door is missing.
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	274	2006- 05-10	2	There is a lockable hasp on the door that is occupied.
	0204	EMERG LIGHTS NOT OPERATIONAL	90- PORTABLE	7	2006- 05-11	0	N/A
	1200	FIRE EVACUATION PLAN(S) NOT POSTED	90- PORTABLE	7	2006- 05-11	0	N/A
		FIRE EVACUATION PLAN(S) NOT POSTED	90- PORTABLE	9	2006- 05-11	0	N/A
	0004	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	90- PORTABLE	9	2006- 05-11	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	90- PORTABLE	52	2006- 05-11	0	N/A
	0004	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	90- PORTABLE	52	2006- 05-11	0	N/A
	0506	EXTINGUSHER MISSING FROM LOCATION	90- PORTABLE	42A	2006- 05-11	0	N/A
		UTILITIES OTHER	90- PORTABLE	42A	2006- 05-11	0	There is a TV cable running across wall under door then across ceiling in next room.
	0499	FIRE ALARM OTHER	90-	53	2006-	0	Pull station missing glass bar.

		PORTABLE		05-11		
0501	FIRE EXTINGUISHER	90- PORTABLE	43	2006- 05-11	0	Pin pulled.
0299	MEANS OF EGRESS OTHER	90- PORTABLE	54B	2006- 05-11	0	Door closer broken.
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	90- PORTABLE	46	2006- 05-11	0	Covered with display.
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	90- Portable	47	2006- 05-11	0	No fish number.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	90- PORTABLE	47	2006- 05-11	0	Surge to surge.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	90- PORTABLE	47	2006- 05-11	0	N/A
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	90- PORTABLE	72	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	90- PORTABLE	72	2006- 05-11	0	N/A
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	90- PORTABLE	75	2006- 05-11	0	N/A
0504	EXTINGUSIHER ACCESS OBSTRUCTED	90- PORTABLE	75	2006- 05-11	0	N/A
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	90- PORTABLE	79	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	90- PORTABLE	79	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	90- PORTABLE	34	2006- 05-11	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	90- PORTABLE	26	2006- 05-11	0	Surge to surge and an orange cord.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	90- PORTABLE	8	2006- 05-11	0	Surge to surge
0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	9- PERMANENT	9	2006- 05-11	0	At football field.
0299	MEANS OF EGRESS OTHER	1- PERMANENT	217	2006- 05-11	0	No exit sign.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	242	2006- 05-11	0	Surge to surge.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT	231	2006- 05-11	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-	244	2006- 05-11	2	Surge to surge on computers.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	240	2006- 05 - 11	2	Surge to surge at computers.
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	239	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT		2006- 05-11	0	N/A
0899		1- PERMANENT	253	2006- 05-11	0	Exposed wiring on surge strip.
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	253	2006- 05-11	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	263	2006- 05-11	0	1. Orange cord 2. Black cord at sewing area. 3. Surge to surge.
0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT	263	2006- 05-11	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	178	2006- 05-11	0	Surge to surge and an orange cord.

(904) 284-2647

Clay Fire Prevention May 12 06 03:10p State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 4 of 4

0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT ²⁵⁹	2006- 05-11	0	Pin pulled and be mounted.
0899	UTILITIES OTHER	1- PERMANENT ¹⁵⁴	2006- 05-11	0	Multi plug adapter.
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT 166	2006- 05-11	0	N/A
0699	SPECIAL PROVISIONS OTHER	1- PERMANENT ¹⁸¹	2006- 05-11	0	Ther a wire running around ceiling unknown reason.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT ¹³⁶	2006 <i>-</i> 05-11	0	Surge to surge.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT ¹³⁶	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT 107	2006- 05-11	0	1998
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT 133	2006- 05-11	0	N/A
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	2- PERMANENT Boilerroom	2006- 05-11	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. Yes

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

Primary inspector Stephen, Arzie

Additional inspector

Page 1 of 6

State Fire Marshal - Inspection Report

District Clay

School ORANGE PARK SENIOR HIGH

Address 2300 KINGSLEY AVENUE

Inspection date 2006-04-17

Notes -

Inspectors present

State No

District No

f	Code	Violation	Bldg R	oom	Comp date	Cited	Notes
	0199	GENERAL REQUIREMENTS	1- PERMANENT ¹⁸	85	2006- 04-28	0	unable to open door, painted shut will have to be forced
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT 1		2006- 04-28	0	replace missing ceiling tile
	0199	GENERAL REQUIREMENTS	1- PERMANENT ¹	13	2006- 04-21	0	reduce wall covering to less than 25%
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	1- PERMANENT 1		2006- 04 - 21	0	CPIX dummies and materials stored under stairway
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT ¹		2006- 04-28	0	replace missing/broken ceiling tile
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT ¹		2006- 04-28	0	need emergency exit sign on door
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT ¹		2006- 04-28	0	need emergency exit sign on door
	0299	MEANS OF EGRESS OTHER	1- PERMANENT ¹		2006- 04-28	0	Door locked, maintenance does not have key. ROTC storage.
	0299	MEANS OF EGRESS OTHER	1- PERMANENT ¹		2006- 04-28	0	uncover window on door
	0299	MEANS OF EGRESS OTHER	1- PERMANENT ¹	16C	2006- 04-28	0	uncover window on door
	0199	GENERAL REQUIREMENTS	1- PERMANENT ¹	118	2006- 04-28	0	reduce wall coverage to less than 25%
	0211	BLOCKED/LOCKED EXITS	1- PERMANENT ¹		2006- 04-21	0	clear area around emergency exit
	0199	GENERAL REQUIREMENTS	1- PERMANENT ²		2006- 04 - 28	0	reduce wall coverage to less than 25%
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT ²		2006- 04-28	0	discontinue use of extension cord chang out for powerstrip
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 2		2006- 04-28	0	discontinue multistrip into multistrip
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 04-28	0	discontinue use of extension cord
	0199	GENERAL REQUIREMENTS	1- PERMANENT		2006- 04-28	0	reduce wall covering to less than 25%
	0199	GENERAL REQUIREMENTS	1- PERMANENT		2006- 04-28	0	reduce wall covering to less than 25%
		IMPROPER USE OF	1-		2006-		discontinue use of extension cord

Page 2 of 6

0804	MULTISTRIP/EXTEN CORDS	PERMANENT	215	04-28	0	multistrip plugged into cord
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	203	2006- 04-28	0	discontinue use of extension cord
0199	GENERAL REQUIREMENTS	1- PERMANENT		2006- 04-28	0	reduce wall coverage to less than 25%
0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	750	2006- 04 - 28	0	replace missing/broken ceiling tile
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	205	2006- 04-28	0	discontinue use of extension cord
0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT		2006- 04-18	0	replace missing ceiling tile around LCD projector and missing tile in front corner of room
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	207	2006- 04-28	0	discontinue use of extension cord goin to LCD projector, have outlet installed in ceiling by projector
0100	GENERAL REQUIREMENTS	1- PERMANENT	208	2006- 04-28	0	reduce wall covering to less than 25%
0504	EXTINGUSIHER ACCESS OBSTRUCTED	1- PERMANENT		2006- 04-28	0	move couch from in front of extinguisher, by room 210
0199	GENERAL REQUIREMENTS	1- PERMANENT	211	2006- 04-28	0	reduce wall covering to less than 25%
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2006- 04-28	0	discontinue use of extension cord
0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT		2006- 04-28	0	replace missing/broken ceiling tile
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	10- PERMANENT	109	2006- 04-28	0	discontinue use of extension cord
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	10- PERMANENT		2006- 04-28	0	discontinue use of extension cord
0204	EMERG LIGHTS NOT OPERATIONAL	10- PERMANENT		2006- 04-28	0	replace broken lense
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT		2006- 04-28	0	discontinue use of extension cord
0210	EXIT ACCESS NOT MAINTAINED	12- PERMANENT	110	2006- 04-28	0	need emergency exit sign on door
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT	116	2006- 04-28	0	discontinue use of extension cord multistrip plugged into extension cord
0199	GENERAL REQUIREMENTS	12- PERMANENT	116	2006- 04-28	0	reduce wall covering to less than 25%
0199	GENERAL REQUIREMENTS	12- PERMANENT		2006- 04 - 28	0	reduce wall covering to less than 25%
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT	135	2006- 04-28	0	discontinue multistrip into multistrip
0210	EXIT ACCESS NOT MAINTAINED	12- PERMANENT		2006- 04-28	0	need emergency exit sign on door
0202	EXIT LIGHTS INOPERABLE NORMAL MODE	12- PERMANENT		2006- 04-28	0	repair emergency light near room 141
0211	BLOCKED/LOCKED EXITS	12- PERMANENT		2006- 04-28	0	unblock emergency exit
0199	GENERAL REQUIREMENTS	12- PERMANENT		2006- 04-28	0	replace missing/broken celling tile
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	12- PERMANENT		2006- 04-28	0	exsposed wiring on floor outlets, receptable broken
0299	MEANS OF EGRESS OTHER	0-Building N/A See notes		2006- 04-18	0	Elg 16 (A Wing) door locked CCSO Officer room No Access
0405	SMOKE DETECTORS INOPERABLE/MISSING	0-Building N/A See	14	2006- 05-26	0	Ellg 16 (A Wing) detector has been removed

Page 3 of 6

			notes				
	0405	SMOKE DETECTORS INOPERABLE/MISSING	0-Bullding N/A See notes	13	2006- 05-26	0	Bldg 16 (A Wing) detector has been removed
	0299	MEANS OF EGRESS OTHER	0-Building N/A See notes	5	2006- 04-18	0	Bldg 16 (A Wing) locked CCSO Officer room no access
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	3	2006- 04-28	0	Big 16 (A Wing) discontinue use of extension cord
.	0299	MEANS OF EGRESS OTHER	0-Building N/A See notes	18	2006- 04 - 18	0	Bldg: 16 (A Wing) locked CCSO Officer room no access
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	19	2006- 04-28	0	Bldg 16 (A Wing) discontinue use of extension cord
	0299	MEANS OF EGRESS OTHER	0-Building N/A See notes	16	2006- 04-18	0	Bldg 16 (A Wing) locked CCSO Officer room no access
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	2	2006- 04-28	0	discontinue use of extension cord
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	0-Building N/A See notes	5	2006- 04-28	0	Bldg 17 (B Wlng) clear area in front of electric panel
	0299	MEANS OF EGRESS OTHER	0-Building N/A See notes	7	2006- 04-28	0	Bldg 17 (B Wing) locked no access
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A See notes	8	2006- 04-28	0	Bldg 17 (B Wing) discontinue use of extension cord
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Bullding N/A See notes	4	2006- 04-28	0	Bldg 17 (B Wing) discontinue use of extension cord
	0211	BLOCKED/LOCKED EXITS	20- PERMANENT	10	2006- 04-28	0	move desks from in front of emergency exit and keep clear
	0199	GENERAL REQUIREMENTS	18- PERMANENT	6	2006- 04-28	0	reduce wall coverage to less than 25%
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	19- PERMANENT	6	2006- 04-28	0	discontinue use of extension cord
	0199	GENERAL REQUIREMENTS	19- PERMANENT	3	2006- 04-28	0	clean room up general housekeeping
	0301	UNPROTECTED VERTICAL OPENING	21- PERMANENT	2	2006- 04-28	0	replace missing/broken ceiling tile
	0301	UNPROTECTED VERTICAL OPENING	21- PERMANENT	4	2006- 04-28	0	replace missing/broken ceiling tile
	0301	UNPROTECTED VERTICAL OPENING	21- PERMANENT		2006- 04 - 28	0	replace missing/broken ceiling tile
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	21- PERMANENT	_	2006- 04-28	0	discontinue use of extension cord
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	22- PERMANENT	1	2006- 04-28	0	discontinue use of extension cords discontinue multistrip into multistrip
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	22- PERMANENT		2006- 04 - 28	0	discontinue use of expension cord
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	22- PERMANENT	_	2006- 04-28	0	discontinue multistrip into multistrip
	0199	GENERAL REQUIREMENTS	22- PERMANENT	6	2006- 04-28	0	reduce wall covering to less than 25%
	0204	EMERG LIGHTS NOT	22-	4	2006-	0	repair exit light

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 4 of 6

	OPERATIONAL	PERMANENT		04-28		
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	22- PERMANENT	2	2006- 04-28	0	discontinue use of extension cord
0210	EXIT ACCESS NOT MAINTAINED	22- PERMANENT	2	2006- 04-28	0	need emergency exit sign on door
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT	11	2006- 04-28	0	replace missing/broken ceiling tile
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT	1	2006- 04-28	0	replace missing/broken ceiling tile
0899	UTILITIES OTHER	27- PERMANENT	1	2006- 04-28	0	exsposed wiring broken light fixture
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT	4	2006- 04-28	0	replace missing/broker ceiling tile
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT	10	2006- 04-28	0	replace missing/broken ceiling tile
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	2- PERMANENT	1	2006- 04-28	0	mount extinguisher
0299	MEANS OF EGRESS OTHER	4- PERMANENT	5B	2006- 04-28	0	locked no access maintenance needs key
0299	MEANS OF EGRESS OTHER	4- PERMANENT	1	2006- 04-28	0	Exil: light needs to be resecured to ceiling mount hanging by wires
0299	MEANS OF EGRESS OTHER	4- PERMANENT	8A	2006- 04 - 28	0	locked no access maintenance needs key
0301	UNPROTECTED VERTICAL OPENING	4- PERMANENT	10	2006- 04-28	0	replace missing/broken ceiling tile
0301	UNPROTECTED VERTICAL OPENING	4- PERMANENT	22B	2006- 04-28	0	replace missing/broken ceiling tile
0901	IMPROPER STORAGE	4- PERMANENT	22C	2006- 04-28	0	remove uniforms and other Items out of HVAC closet
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	24- PERMANENT	1	2006- 04-28	0	discontinue use of extension cord
0301	UNPROTECTED VERTICAL OPENING	51- PERMANENT	6	2006- 04-28	0	replace missing/broken celling tile
0211	BLOCKED/LOCKED EXITS	51- PERMANENT	11	2006- 04-28	0	do not block door acces to electrical panel room
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	51- PERMANENT	11	2006- 04-28	0	N/.4
0702	LP GAS CYL IMPROPERLY LOCATED/STORED	41- PERMANENT	1	2006- 05-05	1	need to secure propane tanks
0702	LP GAS CYL IMPROPERLY LOCATED/STORED	48- PERMANENT	1	2006- 05 - 05	1	secure propane tanks
0010	IMMINENT HAZARD	47- PERMANENT	1	2006- 05 - 05	1	secure propane tanks
0702	LP GAS CYL IMPROPERLY LOCATED/STORED	43- PERMANENT	1	2006- 05-05	1	secure propane tanks
0804	MULTISTRIP/EXTEN CORDS	43- PERMANENT	1	2006- 05-05	1	discontinue use of extension cord
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	26	2006- 05 - 05	0	discontinue use of extension cord
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	26	2006- 05-05	0	keep area around emergency exit clear
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	26	2006- 05-05	0	clear area around electrical panel
0199	GENERAL REQUIREMENTS	92- PORTABLE	25	2006- 05-05	0	reduce wall coverage to less than 25%
0199	GENERAL REQUIREMENTS	92- PORTABLE	24	2006- 05 - 05	0	reduce wall coverage to less than 25%
		92-		2006-		

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 5 of 6

0299	MEANS OF EGRESS OTHER	PORTABLE	24	05-05	0	need emergenxy exit sign on door
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	24	2006- 05-05	0	discontinue powerstrip Into powerstrip
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	27	2006- 05-05	0	discontinue use of extension cord
0199	GENERAL REQUIREMENTS	92- PORTABLE	27	2006- 05-05	0	reduce wall coverage to less than 25%
0200	MEANS OF EGRESS	92- PORTABLE	27	2006- 05-05	0	need emergency exit sign on door
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	32	2006- 05-05	0	clear area around electrical panel
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	32	2006- 05-05	0	discontinue powerstrip into extension cord, discontinue use of extension cords, discontinue use of multiplug adapter in wall,
0899	UTILITIES OTHER	92- PORTABLE	32	2006 - 05-05	0	don't tape electrical wires to floor
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	28	2006- 05-05	0	discontinue powerstrip into powerstrip
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	28	2006- 05-05	0	clear areaaround electrical panel
0299	MEANS OF EGRESS OTHER	92- PORTABLE	28	2006- 05-05	0	no emergency evacuation plan posted by door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	31	2006- 05-05	0	no emergency evacuation plan posted by door
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	31	2006- 05-05	0	clear area around electrical panel
0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	31	2006- 05-05	0	clear area around fire extinguisher
0299	MEANS OF EGRESS OTHER	92- PORTABLE	46	2006- 05-05	0	no emergency evacuation plan posted by
0299	MEANS OF EGRESS OTHER	92- PORTABLE	45	2006- 05-05	0	no emergency evacuation plan posted by
0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	45	2006- 05-05	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	45	2006- 05-05	0	N/A
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	44	2006- 05-05	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	44	2006- 05-05	0	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	44	2006 - 05-05	0	no evacuation plan posted by door
0299	MEANS OF EGRESS OTHER	92- PORTABLE	42	2006- 05-05	0	no evacuation plan posted
0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	42	2006- 05-05	0	N/A
0199	GENERAL REQUIREMENTS	92- PORTABLE	42	2006- 05-05	0	reduce wall coverage to less than 25%
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	42	2006- 05-05	0	discontinue use of extension cord ie going to TV and DVD
0299	MEANS OF EGRESS OTHER	92- PORTABLE	41	2006- 05-05	0	no evacuation plan posted by door
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE	41	2006- 05-05	0	need cover on outlet by electrical panel
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	43	2006- 05 - 05	0	N/A
0299	MEANS OF EGRESS OTHER	92-	43	2006-	0	no evacuation plan posted by door

р.13

(904) 284-2647

Clay Fire Prevention

May 12 06 03:12p

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 6 of 6

PORTABLE

05-05

0199 GENERAL REQUIREMENTS

92-PORTABLE 43 2006-05-05

0

reduce wall coverage to less than 25%

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. ${f No}$

I hereby certify that the local authority having jurisdiction has complied with

section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this

(Or)

inspection date.

Yes

Acknowledgement N/A.

No

Primary inspector

Additional inspector

Michael, Swartz

Apr 25 06 02:27p Clay Fire Prevention

State Fire Marshal - Public School Reporting System [Fire_Inspection]

State Fire Marshal - Inspection Report

District Clay

School RIDGEVIEW SENIOR HIGH

Address 466 MADISON AVENUE

Inspection date 2006-04-11

Notes -

Inspectors present

State No

Local No

ef	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0303	INADEQUATE FIRE RESISTANCE	1- PERMANENT	136	2006- 05-24	0	Restore Fire restive rating of Fire Wall by Rechauk Fire wall pentrations
	8080	IMPROPER STORAGE IN ELECT/MECH ROOMS	2- PERMANENT		2006- 05-25	0	N/A
	1299	OPERATING FEATURES OTHER	2- PERMANENT		2006- 05 - 25	0	remove flammable liquids or store in approve flammable locker
	0506	EXTINGUSHER MISSING FROM LOCATION	3- PERMANENT		2006- 05-25	0	N/A
	0102	OCCUPANCY LOAD EXCEEDED/NOT POSTED	3- PERMANENT		2006- 05 - 25	0	N/A
	0304	PENETRATION PROTECT MISSING/INADEQUATE	3- PERMANENT		2006- 04-25	0	Restore Fire Protective rating of Ceiling by re chauking holes in Fire Wall/Ceiling
	0499	FIRE ALARM OTHER	6- PERMANENT		2006- 05-25	0	Repair broken Magnetic door closure of Fire Door
	0299	MEANS OF EGRESS OTHER	6- PERMANENT		2006- 05-25	0	Install Emergency Lights and Exit Lights
	0304	PENETRATION PROTECT MISSING/INADEQUATE	6- PERMANENT		2006- 05 - 25	0	Restore Fire Rated Ceilings in Electrical Room
	0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	6- PERMANENT		2006- 05-25	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	8- PERMANENT		2006- 05-25	0	A/N
	0405	SMOKE DETECTORS INOPERABLE/MISSING	8- PERMANENT		2006- 05-25	0	Place smoke Detector in store room
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	9- PERMANENT		2006- 05-25	0	N/A
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	93- PORTABLE	1	2006 - 05-25	0	South Wall
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	93- PORTABLE	3	2006- 05-25	0	Sink area
	0899	UTILITIES OTHER	93- PORTABLE	3	2006- 05 - 25	0	Cirect (Microwave area) over loaded. Statstes unable to use one appilance at a time
	0204	EMERG LIGHTS NOT OPERATIONAL	93- PORTABLE	3	2006- 05-25	0	N/A.
	0299	MEANS OF EGRESS OTHER	93- PORTABLE	3	2006- 05 - 25	0	Provide Emergency light in all student occupied spaces Bathroom

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 2 of 3

C	17114	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	5	2006- 05 - 25	0	N/A
(211	BLOCKED/LOCKED EXITS	92- PORTABLE	12	2006- 05-25	0	Remove lock and haspe store room door
(204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	8	2006- 05 - 25	0	N/A
(0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE	4	2006- 05-25	0	90" elbow at front ramp
(0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	21	2006- 05-25	0	resecure floor to ramp
(0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	24	2006- 05-25	0	N/A
(0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	43	2006- 04-25	0	restore wooden ramp per LSC101
1	0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	44	2006- 05-25	0	restore wooden ramp per LSC101
	1202	DANGEROUS CONDITION EXISTS	92- PORTABLE	61	2006- 05-25	0	repair hole in floor in front of store room door
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	61	2006- 05 - 25	0	N/A
	1205	FIRE EVACUATION PLAN(S) NOT POSTED .	92- PORTABLE	67	2006- 05-25	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	67	2006- 05-25	.0	N/A
	0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	69	2006- 05-25	0	replace missing smoke/heat detector in store room
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	69	2006- 05 - 25	0	N/A
	0209	RATED OPENINGS NOT MAINTAINED	92- PORTABLE	71	2006- 05-25	0	re weld broken welds on metal picketts on ramp
	0899	UTILITIES OTHER	92- PORTABLE	71	2006- 05-25	0	replace missing screws securing panle cover to 200 Amp panle
	0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	71	2006- 05-25	0	install smoke/heat detectors in store room (bathroom)
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	74	2006- 05-25	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	68	2006- 05-25	0	N/A
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	68	2006- 05 - 25	0	N/A
	0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	62	2006- 05-25	0	restore wooden ramp per LSC101
	0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	87	2006- 05-25	0	restore wooden ramp per LSC101
	0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	89	2006- 05-25	0	restore wooden ramp per LSC101
	0211	BLOCKED/LOCKED EXITS	92- PORTABLE	82	2006- 05 - 25	0	remove lock/haspe on store room door
		the state of the s	,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, 				

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

Yes

(Or)

I hereby certify that the required fire drills have been completed as of this inspection date.

Apr 25 06 02:28p

Clay Fire Prevention

(904)284-2647

p.3

State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 3 of 3

Acknowledgement N/A.

No

Primary inspector Silver, Ware Additional inspector

ate Fire Marshal - Public School Reporting System [Fire_Inspection]

State Fire Marshal - Inspection Report

District Clay

School ADMINISTRATIVE OFFICES ORANGE PARK ANNEX

Address 2300 KINGSLEY AVENUE

Inspection date 2006-04-17

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0211	BLOCKED/LOCKED EXITS	16- PERMANENT	9	2006- 05-22	0	door locked CCSO office room. No Access
		SMOKE DETECTORS INOPERABLE/MISSING	16- PERMANENT	. 14	2006- 05-22	0	N/A
		SMOKE DETECTORS INOPERABLE/MISSING	16- PERMANENT		2006- 05-22	0	N/A
	0211	BLOCKED/LOCKED EXITS	16- PERMANENT		2006- 05-22	0	doo: locked CCSO office room. No Access
	1112117	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	16- PERMANENT		2006- 05-22	0	N/A
	0211	BLOCKED/LOCKED EXITS	16- PERMANENT		2006- 05-22	0	door locked CCSO office room. No Access
		IMPROPER USE OF MULTISTRIP/EXTEN CORDS	16- PERMANENT		2006- 05-22	0	N/A
	0211	BLOCKED/LOCKED EXITS	16- PERMANENT		2006- 05-22	0	door locked CCSO office room. No Access
		IMPROPER USE OF MULTISTRIP/EXTEN CORDS	16- PERMANENT		2006- 05-22	.0	N/A.
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	17- PERMANENT		2006- 05-22	0	N/A
	0211	BLOCKED/LOCKED EXITS	17- PERMANENT	_	2006- 05-22	0	A/N
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	17- PERMANEN		2006- 05-22	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	17- PERMANEN		2006- 05-22	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Acknowledgement N/A.

No

Yes

http://app.bebr.ufl.edu/egroupware/Fire_Inspection/main.php?menuaction=Fire_Inspection.bo_inspsel... 5/22/2006

tate Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 1 of 1

State Fire Marshal - Inspection Report

District Clay

School CLAY SUPERINTENDENT'S OFFICE

Address 900 WALNUT STREET

Inspection date 2006-05-11

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code Violation	Bldg	Room	Comp date	Cite	d Notes
	0299 MEANS OF EGRESS OTHER	3- PERMANENT	21	2006- 05-22	0	Storage under stairs
	0299 MEANS OF EGRESS OTHER	2- PERMANENT	15	2006- 05-22	0	reinstall door closure on fire rated door

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Acknowledgement N/A.

No

Yes

Primary inspector

Horace, Earls

Additional inspector

Silver, Ware

Page 1 of 1

State Fire Marshal - Inspection Report

District Clay

School FOOD SERVICES STORAGE

Address 720 CENTER STREET

Inspection date 2006-05-23

Notes

Inspectors present

State No

Horace, Earls

District No

Local Yes

Ref	Code Violation	Bldg	Room	Comp date	Cite	d Notes	
	NVO No violations noted this date	95- PORTABLE	1 1	2006- 05-23	0	N/A	
Statem	nents acknowledged						
	y certify that the district has complied wil	th section 1013	3.12(1)	(b), F.S.	No		
	y certify that the local authority having ju 1013.12(2)(b), F.S.	risdiction has o	complie	d with	Yes		
I hereb	y certify that the required fire drills have ion date.	been complete	d as of	this	No		
	(Or)						
Acknow	vledgement N/A.				Yes	•	
Prima	ry inspector	Additi	onal in	spector			

4:57PM

State Fire Marshal - Inspection Report

District Clay

School HARRIS C LONG ADMINISTRATION

Address 23 S GREEN STREET

Inspection date 2006-05-11

Notes

Inspectors present

State No District No Local Yes

Ref	Code Violation	Bldg	Room	Comp date	Cited	Notes
	NVO No violations noted this date	1- PERMANENT	. 100	2006- 05-11	0	N/A
Stateme	ents acknowledged					
I hereby	y certify that the district has complled to	with section 1013.	12(1)(t), F.S. I	No	
I hereby	y certify that the local authority having 1013.12(2)(b), F.S.			with	Yes	
	y certify that the required fire drills have on date.	ve been completed	as of t	his ,	Yes	
	(Or)					
Acknowl	ledgement N/A.			1	No	
ACKNOWI	reagement IV/A.			,	NO	

Primary inspector

Horace, Earls

Additional inspector

Silver, Ware

(904) 284-2647

p.10 Page 1 of 1

State Fire Marshal - Inspection Report

District Clay

School KEYSTONE TRANSPORTATION

tate Fire Marshal - Public School Reporting System [Fire_Inspection]

Address 6800 COUNTY ROAD 315

Inspection date 2005-11-23

Notes -

Inspectors present

State No District No

Ref	Code	Violation		Bldg	Room	Comp date	Cited	Notes
	NVO	No violations note	ed this date	0- Building N/A See notes	1	2005-11- 23	0	N/A
		nowledged						
•	-		complied with				No	
I hereby	certify t	that the district has that the local author (2)(b), F.S.	•				No Yes	
I hereby section 1	certify t 013.12(certify t	hat the local autho	ority having juris	diction has	compli	ied with		
I hereby section 1 I hereby	certify t 013.12(certify t	that the local author(2)(b), F.S.	ority having juris	diction has	compli	ied with	Yes	
I hereby section 1 I hereby inspectio	certify to 013.12(certify to date.	that the local authorized (2)(b), F.S.	rity having juris	diction has	compli	ied with	Yes	
I hereby section 1 I hereby	certify to 013.12(certify to date.	that the local authorized (2)(b), F.S.	rity having juris	diction has	compli	ied with	Yes	
I hereby section 1 I hereby inspectio	certify to 013.12(certify to date.	that the local authorized (2)(b), F.S.	rity having juris	diction has	compli	ied with	Yes	
I hereby section 1 I hereby inspectio	certify to 013.12(certify to date.	that the local authorized (2)(b), F.S.	rity having juris	diction has	compli	ied with	Yes	

Primary inspector

Silver, Ware

Additional inspector

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No
I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Acknowledgement N/A.

(904)284-2647

Primary inspector Silver, Ware

May 22 06 03:40p

Additional inspector

N/, A

Clay Fire Prevention

Page 1 of 1

State Fire Marshal - Inspection Report

District Clay

School MIDDLEBURG TRANSPORTATION

Address 3674 COUNTY ROAD 2

Inspection date 2006-04-25

Notes -

Inspectors present

State No District Yes

Local No

Ref	Code	Violation	Bidg	Room	Comp date	Cite	d Notes
	0204	EMERG LIGHTS NOT OPERATIONAL	0-Building N/A See notes	5	2006- 05-10	1	One in stairwell second on upper floor.
	0600	SPECIAL PROVISIONS	90- PORTABLE	101	2006- 05-10	2	Portable is run down and unmaintained Used as a tire storage.
	NVO	No violations noted this date	2- PERMANENT	. 2	2006- 05-10	1	N/A

inspection date. (Or)

I hereby certify that the required fire drills have been completed as of this

Yes

Acknowledgement N/A.

No

rimary inspector

Additional inspector

Stephen, Arzie

Page 1 of 1

State Fire Marshal - Inspection Report

District Clay

School SCHOOL BUS GARAGE

Address 800 CENTER STREET

Inspection date 2006-05-23

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT	1	2006- 06-23	1	in garage area fire extinguishers mounte to high for size of extinguisher
	0506	EXTINGUSHER MISSING FROM LOCATION	91- PORTABLE	1	2006- 06-23	0	N/A
		knowledged		47414		••-	
		that the district has complied with that the local authority having jur			with		
		(2)(b), F.S.	isdiction has co	mpneu	WILII	Yes	
	y certify ion date.	that the required fire drills have t	een completed	as of t	his	No	
		(Or)					
Acknov	vledgeme	nt N/A.				Yes	

Silver, Ware

State Fire Marshal - Inspection Report

District Clay

School SUPPORT SERVICES CENTER

Address 925 W CENTER STREET

Inspection date 2006-05-23

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg f	Room	Comp date	Cited	l Notes
	0805	GFCT'S NOT INSTALLED IN WET LOCATIONS	5- PERMANENT	4	2006- 06-23	0	N/A
	0805	GFCI'S NOT INSTALLED IN WET LOCATIONS	5- PERMANENT	25	2006- 06-23	0	N/A
	0299	MEANS OF EGRESS OTHER	11- PERMANENT	102A	2006- 06-23	0	Storage under stairs
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	9-	903	2006- 06-23	0	mounted to high
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT	210	2006- 06-23	0	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. ${f No}$

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

(Or)

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

No

Acknowledgement N/A.

Yes

Primary inspector

Horace, Earls

Additional inspector

Silver, Ware

May 23 06 03:17p Clay Fire Prevention

«State Fire Marshal - Public School Reporting System [Fire_Inspection]

Page 1 of 1

State Fire Marshal - Inspection Report

District Clay

School SUPPORT SERVICES AG LOT

Address ROBERTS STREET

Inspection date 2006-05-23

Notes

Inspectors present

State No

District No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	NVO	No violations noted this date	90- PORTABLE	1	2006- 05 - 23	0	N/A
		knowledged					
-	-	that the district has complied with s				No	
I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.							
I hereby	•	that the required fire drills have bee	en complete	d as of	this	No	
		(Or)					
Acknowle	edgeme	nt N/A.				Yes	
Primary	y inspec	ctor	Additio	onal in	spector	•	The state of the s
Horace,	Earls		N/, A				