

Junior High Schools

State Fire Marshal - Inspection Report

District - Clay

School - R C BANNERMAN LEARNING RESOURCE CENTER

Address - 608 MILL STREET

Inspection date - 2007-01-17

Notes -

Inspectors present

State No **District No** **Local Yes**

Ref	Code Violation	Bldg	Room	Comp date	Cited	Notes
0301	UNPROTECTED VERTICAL OPENING	1-PERMANENT	318	2007-01-18	1	Replace ceiling tiles that get blown out by air.
0210	EXIT ACCESS NOT MAINTAINED	1-PERMANENT	207	2007-01-18	0	Remove storage of carts, pressure washer and other various items from blocking the exit into room 208.

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **Yes**

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. **Yes**

I hereby certify that the required fire drills have been completed as of this inspection date. **Yes**

(Or)

Acknowledgement N/A. **No**

Primary inspector

Kevin, Mobley

Additional inspector

N/, A

State Fire Marshal - Inspection Report**District** - Clay**School** - GREEN COVE SPRINGS JUNIOR HIGH**Address** - 1220 BONAVENTURE AVENUE**Inspection date** - 2007-01-22**Notes****Inspectors present****State No** **District No** **Local Yes**

Ref	Code Violation	Bldg	Room	Comp date	Cited Notes
0803	EXTENSION CORD NOT RATED FOR USE	1-PERMANENT	8	2007-01-22 0	Remove extension cord and Christmas lights from use. Use an approved surge protector.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	19	2007-01-22 0	Do not stack surge strips one into another.
0803	EXTENSION CORD NOT RATED FOR USE	1-PERMANENT	21	2007-01-22 0	Remove extension cord and Christmas lights from use.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	21	2007-01-22 0	Do not stack surge protectors one into another.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	101G	2007-01-22 0	Remove extension cord from use and do not stack surge protected strips one into another.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	3-PERMANENT	34	2007-01-22 0	Mount fire extinguisher in proper mounting bracket.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3-PERMANENT	15B	2007-01-22 0	Remove extension cord and multiplug adapter from use.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	3-PERMANENT	10	2007-01-22 0	Mount fire extinguisher in proper mounting bracket.
0210	EXIT ACCESS NOT MAINTAINED	8-PERMANENT	831	2007-01-22 1	Remove all storage of props from both ends of stage to allow egress from stage to exits.
0211	BLOCKED/LOCKED EXITS	8-PERMANENT	831	2007-01-22 1	Can not use chain and locks on outside exit doors. Remove them immediately.
0301	UNPROTECTED VERTICAL OPENING	4-PERMANENT	422	2007-01-22 1	Replace all ceiling tiles that are damaged or missing.
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	4-PERMANENT	422	2007-01-22 1	Remove all combustible storage from electrical room.
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	0-Building N/A -- See notes	footballfieldconcessionst	2007-01-22 0	Fire extinguisher is discharged. Needs recharging and inspection.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92-PORTABLE	112	2007-01-22 1	Mount fire extinguisher in proper bracket.

Statements acknowledgedI hereby certify that the district has complied with section 1013.12(1)(b), F.S. **Yes**

I hereby certify that the local authority having jurisdiction has complied with

section 1013.12(2)(b), F.S.

Yes

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.


No

Primary inspector

Kevin, Mobley

Additional inspector

N/, A



State Fire Marshal - Inspection Report - JACK L WILKINSON JUNIOR HIGH

District: Clay
 School: JACK L WILKINSON JUNIOR HIGH
 Address: 5025 STATE ROAD 218
 Inspection Date: October 26, 2006
 Note: N/A

Inspectors present

State: No District: No Local: Yes

Reference	Code	Violation	Building	Room	Anticipated Compliance Date	Cited	Notes
N/A	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1-PERMANENT	A104	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	A113	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	A135	November 27, 2006	1	N/A
N/A	1205	FIRE EVACUATION PLAN(S) NOT POSTED	1-PERMANENT	407	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	407	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4-PERMANENT	D103D	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4-PERMANENT	43A	November 27, 2006	1	N/A
N/A	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	4-PERMANENT	418	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4-PERMANENT	418	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3-PERMANENT	301	November 27, 2006	1	N/A

State Fire Marshal - Inspection Report - JACK L WILKINSON JUNIOR HIGH

N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	3-PERMANENT	324	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	5-PERMANENT	503	November 27, 2006	1	N/A
N/A	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	6-PERMANENT	600	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6-PERMANENT	600	November 27, 2006	1	N/A
N/A	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	6-PERMANENT	603	November 27, 2006	1	N/A
N/A	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	6-PERMANENT	607	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6-PERMANENT	608	November 27, 2006	1	N/A
N/A	0299	MEANS OF EGRESS OTHER	7-PERMANENT	Hall	November 27, 2006	2	Missing Panic Hardware
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	7-PERMANENT	716	November 27, 2006	1	N/A
N/A	0304	PENETRATION PROTECT MISSING/INADEQUATE	8-PERMANENT	816	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	8-PERMANENT	816	November 27, 2006	1	N/A
N/A	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	9-PERMANENT	913	November 27, 2006	1	N/A
N/A	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92-PORTABLE	3	November 27, 2006	1	N/A
N/A	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92-PORTABLE	5	November 27, 2006	1	N/A
N/A	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92-PORTABLE	6	November 27, 2006	1	N/A
N/A	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92-PORTABLE	8	November 27, 2006	1	N/A
N/A	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	92-PORTABLE	12	November 27, 2006	1	N/A
N/A	0204	EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	22	November 27, 2006	1	N/A
N/A	0204	EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	24	November 27, 2006	1	N/A
N/A	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92-PORTABLE	27	November 27, 2006	1	N/A
N/A	1205	FIRE EVACUATION PLAN(S) NOT POSTED	92-PORTABLE	27	November 27, 2006	1	N/A

State Fire Marshal - Inspection Report - JACK L WILKINSON JUNIOR HIGH

Reference	Code	Violation	Building	Room	Anticipated Compliance Date	Cited	Notes
N/A	0204	EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	40	November 27, 2006	1	N/A
N/A	0304	PENETRATION PROTECT MISSING/INADEQUATE	92-PORTABLE	40	November 27, 2006	1	N/A
N/A	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	92-PORTABLE	40	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92-PORTABLE	40	November 27, 2006	1	N/A
N/A	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92-PORTABLE	41	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92-PORTABLE	42	November 27, 2006	1	N/A
N/A	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92-PORTABLE	46	November 27, 2006	1	N/A

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. No

I hereby certify that the required fire drills have been completed as of this inspection date. Yes

Or:

Acknowledgement N/A. No

Primary Inspector: Karen Golish

Additional inspector: N/A

State Fire Marshal - Inspection Report**District** - Clay**School** - LAKE ASBURY JUNIOR HIGH**Address** - 2851 SANDRIDGE ROAD**Inspection date** - 2006-12-12**Notes** - Portable**Inspectors present****State No** **District No** **Local Yes**

Ref	Code Violation	Bldg	Room	Comp date	Cited	Notes
0209	RATED OPENINGS NOT MAINTAINED	1-PERMANENT	119	2007-01-05	0	N/A
0506	EXTINGUISHER MISSING FROM LOCATION	1-PERMANENT	119	2007-01-05	0	N/A
0515	HOOD SYSTEM NEEDS INSPECTION/MAINTENANCE	1-PERMANENT	119	2007-01-05	0	N/A
0301	UNPROTECTED VERTICAL OPENING	1-PERMANENT	133	2007-01-05	0	Tile missing
0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	2-PERMANENT	205	2007-01-05	0	N/A
0301	UNPROTECTED VERTICAL OPENING	2-PERMANENT	215	2007-01-05	0	N/A
0209	RATED OPENINGS NOT MAINTAINED	2-PERMANENT	215	2007-01-05	0	Door will not close. Dragging on floor.
0803	EXTENSION CORD NOT RATED FOR USE	3-PERMANENT	324	2006-12-13	0	N/A
0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	3-PERMANENT	322	2007-01-05	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	3-PERMANENT	315	2007-01-05	0	Brown
0809	OPEN ELECTRICAL JUNCTION BOX	5-PERMANENT	519	2007-01-05	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	5-PERMANENT	519	2007-01-05	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	5-PERMANENT	501	2007-01-05	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	5-PERMANENT	501	2007-01-05	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6-PERMANENT	601	2007-01-05	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	6-PERMANENT	606	2006-12-12	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6-PERMANENT	611	2007-01-05	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6-PERMANENT	613	2007-01-05	0	N/A
	EXTENSION CORD NOT RATED	6-		2007-		

0803	FOR USE	PERMANENT	614	01-05	0	N/A
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	6- PERMANENT	614	2007- 01-05	0	No Fish #
0510	SPARE HEADS MISSING OR WRONG TYPE	6- PERMANENT	615	2007- 01-05	0	N/A
0511	SPRINK HEAD WRENCH MISSING OR WRONG TYPE	0-Building N/A -- See notes	1	2007- 01-05	0	There is not a head wrench at any of the sprinkler head boxes.
0301	UNPROTECTED VERTICAL OPENING	6- PERMANENT	615	2007- 01-05	0	Over head inside of door.
0301	UNPROTECTED VERTICAL OPENING	6- PERMANENT	616	2007- 01-05	0	The hole is over head.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	7- PERMANENT	702	2007- 01-05	0	N/A
0504	EXTINGUISHER ACCESS OBSTRUCTED	7- PERMANENT	706	2007- 01-12	0	N/A
0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	7- PERMANENT	713	2007- 01-05	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	7- PERMANENT	719	2007- 01-05	0	Orange
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	7- PERMANENT	726	2007- 01-05	0	N/A
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	8- PERMANENT	8044	2007- 01-05	0	Excessive class A material on ceiling and walls.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	8- PERMANENT	8056	2007- 01-05	0	Extension cord running under door.
0803	EXTENSION CORD NOT RATED FOR USE	8- PERMANENT	8071	2007- 01-05	0	White
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	8- PERMANENT	8131	2007- 01-05	0	Two of four fire extinguishers are poorly mounted behind HVAC.
0803	EXTENSION CORD NOT RATED FOR USE	8- PERMANENT	8115	2007- 01-05	0	White
0199	GENERAL REQUIREMENTS	8- PERMANENT	8123	2007- 01-05	0	CAT 5 wire running under door
0101	CHANGE OF OCCUPANCY OR SUB-CLASS	8- PERMANENT	8121	2007- 01-05	0	Storage area is now used as a class room.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	8- PERMANENT	8125	2007- 01-05	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	8- PERMANENT	8096	2007- 01-05	0	Wheeled card cord used as permanent wiring. Wire ties in place on cord.
0803	EXTENSION CORD NOT RATED FOR USE	8- PERMANENT	8034	2007- 01-05	0	White
0301	UNPROTECTED VERTICAL OPENING	8- PERMANENT	8012	2007- 01-05	0	Hole in ceiling
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	8- PERMANENT	8031	2007- 01-05	0	Ceiling covered with combustible material.
1400	CONSTRUCTION/RENOVATION	0-Building N/A -- See notes	P422	2006- 12-13	0	Portable
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0-Building N/A -- See notes	P421	2007- 01-05	0	Portable
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	0-Building N/A -- See notes	P404	2007- 01-05	0	Portable
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	0-Building N/A -- See notes	P406	2007- 01-05	0	Need to be mounted also.

0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A -- See notes	P406	2007-01-05	0	Portable
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0-Building N/A -- See notes	P408	2007-01-05	0	Portable
0210	EXIT ACCESS NOT MAINTAINED	0-Building N/A -- See notes	P403	2006-12-12	0	Portable
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	0-Building N/A -- See notes	P424	2007-01-05	0	Portable has no Fish number.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	0-Building N/A -- See notes	P424	2007-01-05	0	Portable
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	0-Building N/A -- See notes	P426	2007-01-05	0	Wrong fish number posted. Portable
0301	UNPROTECTED VERTICAL OPENING	0-Building N/A -- See notes	P426	2007-01-05	0	Portable has ceiling tile pushed up in closet.
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	0-Building N/A -- See notes	P427	2007-01-05	0	Portable has wrong fish number posted.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	0-Building N/A -- See notes	P425	2007-01-05	0	PORTABLE
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	0-Building N/A -- See notes	P425	2007-01-05	0	Portable has wrong fish number posted.
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	0-Building N/A -- See notes	P423	2007-01-05	0	Portable - pin pulled.
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	0-Building N/A -- See notes	P423	2007-01-05	0	Portable has no fish number posted.
0405	SMOKE DETECTORS INOPERABLE/MISSING	0-Building N/A -- See notes	Portables	2007-01-05	0	The new portables are missing smoke detectors in supply rooms.
0199	GENERAL REQUIREMENTS	0-Building N/A -- See notes	Portables	2007-01-05	0	The new portables do not have room numbers assigned to the storage rooms.
1399	OUTSIDE STRUCTURE OTHER	0-Building N/A -- See notes	Portables	2007-01-05	0	The new portables are anchored on two of the four sides.
0499	FIRE ALARM OTHER	1- PERMANENT	119	2007-01-05	0	This alarm system is not monitored.

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **Yes**

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. **Yes**

I hereby certify that the required fire drills have been completed as of this inspection date. **Yes**

(Or)

Acknowledgement N/A. **No**

Primary inspector

Stephen, Arzie

Additional inspector

N/, A

State Fire Marshal - Inspection Report**District** - Clay**School** - LAKESIDE JUNIOR HIGH**Address** - 2750 MOODY ROAD**Inspection date** - 2007-02-08**Notes** -**Inspectors present****State No** **District No** **Local Yes**

Ref	Code Violation	Bldg	Room	Comp date	Cited	Notes
0809	OPEN ELECTRICAL JUNCTION BOX	5-PERMANENT	129	2007-02-08	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	5-PERMANENT	142	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	5-PERMANENT	141	2007-02-08	0	N/A
1002	ELEVATOR SERVICE RECORD NOT MAINTAINED	5-PERMANENT	133	2007-02-08	0	Inspection tag in elevator room last dated 6-04
0210	EXIT ACCESS NOT MAINTAINED	5-PERMANENT	124	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	5-PERMANENT	124	2007-02-08	0	N/A
0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	5-PERMANENT	125	2007-02-08	0	N/A
0399	PROTECTION OTHER	5-PERMANENT	112	2007-02-08	0	Fire extinguishers mounted to high top less than 5 foot
1202	DANGEROUS CONDITION EXISTS	5-PERMANENT	111	2007-02-08	0	Walk in freezer bolts stuck unable to push out if locked in
0399	PROTECTION OTHER	5-PERMANENT	116	2007-02-08	0	N/A
0899	UTILITIES OTHER	5-PERMANENT	116	2007-02-08	0	Cover and all missing to thermostat
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	5-PERMANENT	227	2007-02-08	0	N/A
0200	MEANS OF EGRESS	5-PERMANENT	229	2007-02-08	0	Needs emergency lights
0211	BLOCKED/LOCKED EXITS	1-PERMANENT	1	2007-02-08	0	by desks
0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	1-PERMANENT	7	2007-02-08	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	1-PERMANENT	29	2007-02-08	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	1-PERMANENT	28	2007-02-08	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	1-PERMANENT	19	2007-02-08	0	N/A
	EMERG LIGHTS NOT	2-		2007-		

0204	OPERATIONAL	PERMANENT	38	02-08	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	2- PERMANENT	51	2007-02-08	0	N/A
NVO	No violations noted this date	3- PERMANENT	1	2007-02-08	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	8- PERMANENT	810	2007-02-08	0	N/A
0304	PENETRATION PROTECT MISSING/INADEQUATE	9- PERMANENT	903	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	9- PERMANENT	906	2007-02-08	0	N/A
0299	MEANS OF EGRESS OTHER	9- PERMANENT	905A	2007-02-08	0	Push bar on exit door comming apart and parts missing
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	9- PERMANENT	90	2007-02-08	0	N/A
0504	EXTINGUSIHER ACCESS OBSTRUCTED	9- PERMANENT	90	2007-02-08	0	N/A
0211	BLOCKED/LOCKED EXITS	9- PERMANENT	90	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	7- PERMANENT	2	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	7- PERMANENT	3	2007-02-08	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	743	2007-02-08	0	N/A
0304	PENETRATION PROTECT MISSING/INADEQUATE	92- PORTABLE	743	2007-02-08	0	Holes in walls
0809	OPEN ELECTRICAL JUNCTION BOX	92- PORTABLE	703	2007-02-08	0	Most portables have access to electrical boxes outside not locked
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	706	2007-02-08	0	N/A
0100	GENERAL REQUIREMENTS	92- PORTABLE	708	2007-02-08	0	Light out in lock down room
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	708	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	723	2007-02-08	0	N/A
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	722	2007-02-08	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	735	2007-02-08	0	N/A
0803	EXTENSION CORD NOT RATED FOR USE	92- PORTABLE	735	2007-02-08	0	N/A
0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	92- PORTABLE	794	2007-02-08	0	N/A
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92- PORTABLE	794	2007-02-08	0	N/A
1308	BLDG ADDRESS/I.D. NOT PRESENT/VISIBLE	92- PORTABLE	793	2007-02-08	0	Building has wrong number on it
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	791	2007-02-08	0	N/A
1201	FIRE DRILLS NOT BEING CONDUCTED	5- PERMANENT	228	2007-02-08	0	Mixing in lock downs and tornado drills to count as fire drills do not count.

Statements acknowledgedI hereby certify that the district has complied with section 1013.12(1)(b), F.S. **No**I hereby certify that the local authority having jurisdiction has complied with **Yes**

section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

No

(Or)

Acknowledgement N/A.

Yes

Primary inspector

Philip, Crider

Additional inspector

N/, A

State Fire Marshal - Inspection Report**District** - Clay**School** - ORANGE PARK JUNIOR HIGH**Address** - 1500 GANO AVENUE**Inspection date** - 2006-01-24**Notes** -**Inspectors present****State No** **District No** **Local Yes**

Ref	Code Violation	Bldg	Room	Comp date	Cited	Notes
FBC423.14.2.2	0102 OCCUPANCY LOAD EXCEEDED/NOT POSTED	1-PERMANENT	122	2006-02-24	0	OCCUPANCY LOAD SIGN MISSING
	0202 EXIT LIGHTS INOPERABLE NORMAL MODE	2-PERMANENT	215	2006-02-24	0	EXIT LIGHTS LOOSE
FBC1016.3.1	0204 EMERG LIGHTS NOT OPERATIONAL	5-PERMANENT	501	2006-02-24	0	EMERGENCY LIGHT OUT/HANGING
FBC1016.3.1	0204 EMERG LIGHTS NOT OPERATIONAL	5-PERMANENT	522	2006-02-24	0	EMERGENCY LIGHT OUT/HANGING
FBC1016.3.1	0205 EMERG LIGHTING NOT TESTED/RECS MAINT'D	5-PERMANENT	517A	2006-02-24	0	EMERGENCY LIGHT OUT/HANGING
NFPA70400-8	0804 IMPROPER USE OF MULTISTRIP/EXTEN CORDS	6-PERMANENT	610	2006-02-24	0	EXTENSION CORDS RUN THROUGH DOORWAY
NFPA70	0211 BLOCKED/LOCKED EXITS	92-PORTABLE	503	2006-02-24	0	CABINET IN FRONT OF ELECTICAL PANEL
FBC11-8.4	0299 MEANS OF EGRESS OTHER	92-PORTABLE	504	2006-02-24	0	RAMP AHS SOME LOOSE BOARDS
69A-36	0506 EXTINGUISHER MISSING FROM LOCATION	92-PORTABLE	507	2006-02-24	0	FIRE EXTINGUISHER NOT BY EXIT
	0299 MEANS OF EGRESS OTHER	92-PORTABLE	509AB	2006-02-24	0	STAIRS IN BAD SHAPE
69A-36	0506 EXTINGUISHER MISSING FROM LOCATION	92-PORTABLE	511	2006-02-24	0	FIRE EXTINGUISHER NOT BY THE EXIT
FBC423.17.1	0204 EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	514	2006-02-24	0	EMERGENCY LIGHT NOT WORKING
	0299 MEANS OF EGRESS OTHER	92-PORTABLE	514	2006-02-24	0	DOOR HANDLE BROKEN
69A-36	0503 MONTHLY INSPECTION NOT DONE/RECORDED	92-PORTABLE	515	2006-02-24	0	FIRE EXTINGUISHER NOT SIGNED
FBC423.17.1	0200 MEANS OF EGRESS	92-PORTABLE	516	2006-02-24	0	EMERGENCY LIGHT NOT WORKING
FBC423.17.1	0204 EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	702	2006-02-24	0	EMERGENCY LIGHT NOT WORKING
69A-36	0506 EXTINGUISHER MISSING FROM LOCATION	92-PORTABLE	706	2006-02-24	0	FIRE EXTINGUISHER NOT BY COOK TOP
69A-36	0506 EXTINGUISHER MISSING FROM LOCATION	92-PORTABLE	707AB	2006-02-24	0	NO FIRE EXTINGUISHER BY COOKTOP
	EXTINGUISHER MISSING FROM	92-		2006-		

69A-36	0506	LOCATION	PORTABLE	708	02-24	0	NO FIRE EXTINGUISHER BY COOKTOP
	0299	MEANS OF EGRESS OTHER	92-PORTABLE	709	2006-02-24	0	RAMP STEELING - MISSING SPINDLE
69A-36	0506	EXTINGUISHER MISSING FROM LOCATION	92-PORTABLE	710	2006-02-24	0	NO FIRE EXTINGUISHER BY COOKTOP
FBC423.17.1	0204	EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	711	2006-02-24	0	EMERGENCY LIGHT NOT WORKING
FBC423.17.1	0204	EMERG LIGHTS NOT OPERATIONAL	92-PORTABLE	719	2006-02-24	0	EMERGENCY LIGHT NOT WORKING

Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **Yes**

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. **No**

I hereby certify that the required fire drills have been completed as of this inspection date. **Yes**

(Or)

Acknowledgement N/A. **No**

Primary inspector

larry, swanson

Additional inspector

N/, A