# Senior High Schools

District Clay

School CLAY HIGH SCHOOL

Address 2025 HIGHWAY 16 W

Inspection date 2007-01-25

**Notes** 

**Inspectors** present

Local Yes State No **District** No

Ref	Code	Violation	Bldg	Room	Comp date	Cited	l Notes
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	. 141	2007- 01-25	0	Replace damaged or missing ceiling tiles.
,	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	147	2007 01-25	1	Replace missing or damaged ceiling tiles.
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	. 138B	2007- 01-25	0	Replace damaged or missing ceiling tiles.
	0809	OPEN ELECTRICAL JUNCTION BOX	1- PERMANENT	. 138B	2007- 01-25	0	Cover exposed wiring.
	0301	UNPROTECTED VERTICAL OPENING	3- PERMANENT	. 319356325A	2007- 01-25	2	Replace damaged or missing ceiling tiles throughout building 3. The rooms mentioned are the worst.
1	0809	OPEN ELECTRICAL JUNCTION BOX	3- PERMANENT	. 366	2007- 01 <b>-</b> 25	0	Replace cover on exposed outlet.
	0803	EXTENSION CORD NOT RATED FOR USE	3- PERMANENT	. 366	2007- 01-25	0	Remove all extension cords and replace with surge protection strips.
	0803	EXTENSION CORD NOT RATED FOR USE	3- PERMANENT	. 355	2007- 01-25	0	Replace extension cord to fish tank with a surge protection strip.
	0304	PENETRATION PROTECT MISSING/INADEQUATE	3- PERMANENT	. 325A	2007- 01-25	0	Ceiling tiles should be sealed areound the sprinkler heads.
	0204	EMERG LIGHTS NOT OPERATIONAL	5- PERMANENT	E4.0B	2007- 01-25	1	Replace bulbs in exit lights.
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	7- PERMANENT	. 757A	2007- 01-25	0	Remove storage of all combustible materials.
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	8- PERMANENT		2007- 01-25	0	Replace bulbs in exit signs.
	0210	EXIT ACCESS NOT MAINTAINED	8- PERMANENT		2007- 01-25	0	Remove all storage from exit access. The exit must be free of obstructions.
	0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	711	2007- 01-25	0	Repair or replace emergency lighting.

### Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. Yes

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this

Primary inspector	Additional inspector	r
Acknowledgement N/A.	(Or)	No
inspection date.	(0-)	Yes

**Additional inspector** 

District - Clay

School - FLEMING ISLAND SENIOR HIGH

Address - 2233 VILLAGE SQUARE PARKWAY

Inspection date - 2004-11-18

Notes - 2000

### **Inspectors present**

State No

**District** No

Local Yes

Ref	Code	Violation	Bldg	Room	Comp date Cited	Notes
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92-PORTABLE	40	2006-12-18 0	N/A
	11711/	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	92-PORTABLE	30	2006-12-18 0	N/A
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	91-PORTABLE	43	2006-12-18 0	the hydro inspection ring was cut
	0299	MEANS OF EGRESS OTHER	92-PORTABLE	38	2006-12-18 0	hand rails broken
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92-PORTABLE	45	2006-12-18 0	remove multi outlet
	0408	MANUAL PULL STATION MISSING/INOPERABLE	92-PORTABLE	49	2006-12-18 0	N/A
	0899	UTILITIES OTHER	92-PORTABLE	24	2006-12-18 0	missing outlet cover
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1-PERMANENT	11	2006-12-18 0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1-PERMANENT	21	2006-12-18 0	N/A
	0212	AREA OF REFUGE NOT MAINTAINED	1-PERMANENT	61	2006-12-18 0	remove door hasp.
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	1-PERMANENT	72	2006-12-18 0	N/A
	0202	EXIT LIGHTS INOPERABLE NORMAL MODE	1-PERMANENT	92	2006-12-18 0	N/A
	0212	AREA OF REFUGE NOT MAINTAINED	1-PERMANENT	81	2006-12-18 0	remove door hasp
,		FIRE ALARM OTHER	1-PERMANENT	100	2006-12-18 3	alarm not monitored

### Statements acknowledged

I hereby certify that the district has complied with section 1013.12(1)(b), No

I hereby certify that the local authority having jurisdiction has complied No with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date. (Or)

Acknowledgement N/A.

No

No

**Primary inspector** 

**Additional inspector** 

Scott, Baltes

District Clay

School KEYSTONE HEIGHTS JUNIOR/SENIOR HIGH

Address 900 SW ORCHID AVENUE

Inspection date 2006-10-17

Notes

**Inspectors present** 

State No District Yes Local No

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0809	OPEN ELECTRICAL JUNCTION BOX	1- PERMANENT	112	2006- 10-25	1	N/A
	0499	FIRE ALARM OTHER	1- PERMANENT	160	2006- 10-25	1	Duck dection Malfuction center of room
	0405	SMOKE DETECTORS INOPERABLE/MISSING	1- PERMANENT		2006- 10-25	1 .	N/A
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	1- PERMANENT		2006- 10-25	1	N/A
	0299	MEANS OF EGRESS OTHER	1- PERMANENT		2006- 10-25	1	Install Exit light
	0211	BLOCKED/LOCKED EXITS	1- PERMANENT		2006- 10-25	. 1	Pathway blocked by low hanging TV
	0210	EXIT ACCESS NOT MAINTAINED	2- PERMANENT		2006- 10-25	1	Closures will not close Fire rated doors
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	2- PERMANENT		2006- 10-25	1	secure power towers to floor
	1205	FIRE EVACUATION PLAN(S) NOT POSTED	5- PERMANENT		2006- 10-25	1	N/A
	0303	INADEQUATE FIRE RESISTANCE	5- PERMANENT		2006- 10-25	1	remove wall constructed on rear of stage and all storage
	0399	PROTECTION OTHER	5- PERMANENT		2006- 10-25	1	replace missing "D" ring to smoke doors
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	5- PERMANENT		2006- 10-25	1	N/A
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	6- PERMANENT	. 609E	2006- 10-25	1	N/A
	0399	PROTECTION OTHER	9- PERMANENT		2006- 10-25	1	repair broken door closure
	0399	PROTECTION OTHER	9- PERMANENT		2006- 10-25	1	repair door closure
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	9- PERMANENT		2006- 10-25	1	N/A
	0211	BLOCKED/LOCKED EXITS	20- PERMANENT		2006- 10-25	1	N/A
	0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	62	2006- 10-25	1	N/A
		SMOKE DETECTORS	92-		2006-		

0405	INOPERABLE/MISSING	PORTABLE	55	10-25	1	N/A
0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	53	2006- 10-25	1	N/A
0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	50	2006- 10-25	1	N/A
0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	92- PORTABLE	90	2006- 10-25	1	N/A
	· ·					

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No I hereby certify that the local authority having jurisdiction has complied with Yes section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

**Primary inspector** 

**Additional inspector** 

N/, A

Silver, Ware

District Clay

School MIDDLEBURG SENIOR HIGH

Address 3750 STATE ROAD 220

Inspection date 2007-03-14

Notes

**Inspectors present** 

State No District Yes

Local No

Ref	Code	Violation	Bldg	Room	Comp date	Cited	l Notes
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT	. 11	2007- 03-17	0	Brown extension cord
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	Brown cord
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	Brown
	0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT	05	2007- 03-17	0	Ceiling tile missing
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	. 129	2007- 03-17	0	N/A
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2007- 03-17	1	Surge to surge
	0304	PENETRATION PROTECT MISSING/INADEQUATE	0-Building	136	2007- 03-17	0	Ceiling tile broken at TV
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT	. 136	2007- 03-17	0	N/A
	0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT		2007- 03-17	0	N/A
	0801	INADEQUATE ACCESS TO ELECTRICAL PANEL	1- PERMANENT		2007- 03-17	0	N/A
	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	1	One orange and one brown cord.
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2007- 03-17	2	Surge to surge.
	0803	EXTENSION CORD NOT RATED	1- PERMANENT		2007- 03-17	0	Orange cord.
-	0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT		2007- 03-17	0	Brown cord.

0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>189</sup>	2007- 03-17	1	Orange cord.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>189</sup>	2007- 03-17	1	Surge to surge.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>188</sup>	2007- 03-17	1	Orange cord.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>191</sup>	2007- 03-17	0	Brown cord.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>192</sup>	2007- 03-17	1	Orange cord.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>192</sup>	2007- 03-17	1	Surge to surge.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>185</sup>	2007- 03-17	1	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 168	2007- 03-17	1	surge to surge.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 166	2007- 03-17	2	Surge to surge.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>217</sup>	2007- 03-17	0	Brown cord.
0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT <sup>151</sup>	2007- 03-17	0	Ceiling tile missing.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>204</sup>	2007- 03-17	1	N/A
0508	INADEQUATE CLEARANCE BELOW SPRINK HEAD	1- PERMANENT 50	2007- 03-17	0	Over sprinkler head.
0599	SPRINKLER OTHER	1- PERMANENT <sup>260</sup>	2007- 03-17	1	Unable to gain access due to storage.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>259</sup>	2007- 03-17	1 .	Surge to surge.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>263</sup>	2007- 03-17	0	Surge to extension cord.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>253</sup>	2007- 03-17	0	Surge to surge.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>239</sup>	2007- 03-17	0 .	Surge to surge.
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT <sup>240</sup>	2007- 03-17	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>240</sup>	2007- 03-17	1	Surge to surge.
0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT 240	2007- 03-17	0	Trash bags stacked.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT 312	2007- 03-17	0	Extension cord running through ceiling.
0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT 355	2007- 03-17	0	Ceiling tile damaged.
0899	UTILITIES OTHER	1- PERMANENT 358	2007- 03-17	0	Open blanks in panel.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>241</sup>	2007- 03-17	1	Surge to surge.
0803	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT <sup>242</sup>	2007- 03-17	0	Orange cord.
0899	UTILITIES OTHER	1- PERMANENT <sup>229A</sup>	2007- 03-17	1	There a a wire running under one door and across hall floor to another room.
0704	COMPRESSED GAS CYLINDERS NOT SECURED	1- PERMANENT <sup>228</sup>	2007- 03-17	0	N/A
0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT 336	2007- 03-17	0	Ceiling tile missing.

115011	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT 231A	2007- 04-04	0	Extinguisher needs recharge.
0599	SPRINKLER OTHER	1- PERMANENT <sup>51</sup>	2007- 04-04	1	FDC cap missing.
1399 (	OUTSIDE STRUCTURE OTHER	1- PERMANENT 229C	2007- 04-04	0	Door closer broken on door to outside.
0299 1	MEANS OF EGRESS OTHER	1- PERMANENT 274	2007- 04-04	2	Hasp on class room door.
0510.	SPARE HEADS MISSING OR WRONG TYPE	1- PERMANENT 196	2007- 04-04	1	N/A
HIXH 3	EXTENSION CORD NOT RATED FOR USE	1- PERMANENT 38	2007- 04-04	3	N/A
0399	PROTECTION OTHER	1- PERMANENT <sup>227</sup>	2007- 04-04	0	The room listed as flammable now has regular light bulbs. The protective cover is missing also.
0599	SPRINKLER OTHER	1- PERMANENT <sup>337B</sup>	2007- 04-04	0	The sprinkler head is one foot or more from the ceiling. Appears that the ceiling has changed it height.
0299	MEANS OF EGRESS OTHER	0-Building N/A See 000 notes	2007- 04-04	0	The gate to the ponds a waste treatment are not open and not locked. This is on the bus side.
0200	MEANS OF EGRESS	1- PERMANENT 00	2007- 04-04	5	The hall exit signs are missing. It is hard to find any inside signs.

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **Yes** I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or) Acknowledgement N/A.

No

**Primary inspector** Stephen, Arzie

Additional inspector

**District** Clay

School ORANGE PARK SENIOR HIGH

Address 2300 KINGSLEY AVENUE

Inspection date 2006-12-08

Notes Inspection started on December 8 and completed on December 13, 2006

State No **District** No Local Yes

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT	180B	2007- 01-12	0	Discontinue powerstrip into powerstrip, each must be plugged directly into wall outlet.
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	180F	2007- 01-12	0	replace missing ceiling tile
	0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	1- PERMANENT		2007- 01-12	0	Paint needs to be stored in a flammable locker
	0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	1- PERMANENT		2007- 01-12	0	label electrical panel
	0,804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2007- 01-12	1	Discontinue powerstrip into extension cord, must be plugged directly into wall outlet. Extension cords not allowed.
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	1- PERMANENT	181I	2007- 01-12	1	N/A
	0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	1- PERMANENT		2007- 01-12	0	N/A
	0899	UTILITIES OTHER	1- PERMANENT		2007- 01-12	0	need blanks placed in open spaces of electrical panel
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	1- PERMANENT		2007- 01-12	0	by water cooler
	0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT	152	2007- 01-12	0	replace missing ceiling tile
	0299	MEANS OF EGRESS OTHER	1- PERMANENT	112	2007- 01-12	0	replace weather strip safety hazard sticks out into egress path
	0199	GENERAL REQUIREMENTS	1- PERMANEŅT	103B	2007- 01-12	0	housekeeping, clean area
٠	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2007- 01-12	0	Discontinue extension cord and plug adapter.
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT		2007- 01-12	0	Discontinue use of extension cord.
	0501	FIRE EXTINGUISHER REQUIRES INSPECTION	1- PERMANENT		2007- 01-12	0	extinguisher by door needs service and being resealed
	0799	BUILDING SERVICES OTHER	1- PERMANENT		2007- 01-12	0	replace broken window below emergency exit
	0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT		2007 01-12	0	keep area to emergency exit clear
			1-		2007-		

0210	EXIT ACCESS NOT MAINTAINED	PERMANENT 201	01-12	0	keep area to emergency exit clear
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	1- PERMANENT 203	2007- 01-12	0	repair or replace mount for extinguisher and mount same
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>204</sup>	2007- 01-12	1	Discontinue use of all extension cords through out the room. Replace with powerstrips.
0211	BLOCKED/LOCKED EXITS	1- PERMANENT 205	2007- 01-12	0	keep area to door clear
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>205</sup>	2007- 01-12	0	Discontinue use of all extension cords in room. May replace with powerstrips.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 206	2007- 01-12	0	Discontinue use of extension cord.
0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT <sup>207</sup>	2007- 01-12	0	replace ceiling tiles
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>207</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each must be plugged directly into wall outlet.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>215</sup>	2007- 01-12	0	Discontinue powerstrip into extension cord, must be plugged directly into wall outlet. Extension cords not allowed.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>222</sup>	2007- 01-12	0	Discontinue use of extension cords
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 228	2007- 01-12	0	Discontinue use of extension cords
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>229</sup>	2007- 01-12	0	Discontinue use of extension cords
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 230	2007- 01-12	0	Discontinue use of all extension cords
0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT 230	2007- 01-12	0	Keep area to second exit clear
0211	BLOCKED/LOCKED EXITS	1- PERMANENT <sup>219</sup>	2007- 01-12	0 ·	Unlock upstairs exit by this room whenever school is occupied
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 223	2007- 01-12	0	Discontinue use of extension cords
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	1- PERMANENT 223	2007- 01-12	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>224B</sup>	2007- 01-12	0	Discontinue use of extension cords
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>211</sup>	2007- 01-12	0	Discontinue use of all extension cords
0210	EXIT ACCESS NOT MAINTAINED	1- PERMANENT 210	2007- 01-12	0	keep area to second exit clear
0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT <sup>209</sup>	2007- 01-12	0	replace missing ceiling tile
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>209</sup>	2007- 01-12	0	Discontinue use if extension cords
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>208</sup>	2007- 01-12	0	Discontinue powerstrip into extension cord,must be plugged directly into wall outlet. Extension cords not allowed.
0802	CIRCUITS NOT LEGIBLE/PERMANENTLY LABELED	1- PERMANENT 236	2007- 01-12	0	label panel across from room 236
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>125</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each must be plugged directly into wall outlet.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>125</sup> C	2007- 01-12	0	Discontinue powerstrip into powerstrip, each must be plugged directly into wall outlet.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>125D</sup>	2007- 01-12	0	Discontinue use of all extension cords

1101	COMBUSTIBLE MATERIAL IMPROPERLY STORED	1- PERMANENT <sup>164</sup>	2007- 01-12	1	remove materials from under stairs, non-protected area
0301	UNPROTECTED VERTICAL OPENING	1- PERMANENT <sup>166</sup>	2007- 01-12	0	replace missing ceiling tile
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT 128	2007- 01-12	0	Discontinue use of extension cords
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	1- PERMANENT 118C	2007- 01-12	0	N/A
1205	FIRE EVACUATION PLAN(S) NOT POSTED	1- PERMANENT 125D	2007- 01-12	0	N/A
1299	OPERATING FEATURES OTHER	1- PERMANENT <sup>167</sup>	2007- 01-12	0	No access locked with special lock custodial personnel do not have key for. Key needs to be maded available.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>129</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each must be plugged directly into wall outlet.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>104</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each must be plugged directly into wall outlet.
0303	INADEQUATE FIRE RESISTANCE	1- PERMANENT 110	2007- 01-12	0	reduce wall coverage to less than 25%
0303	INADEQUATE FIRE RESISTANCE	1- PERMANENT <sup>118</sup>	2007- 01-12	0	reduce wall coverage to less than 25%
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>120</sup>	2007- 01-12	0	Discontinue powerstrip into extension cord,must be plugged directly into wall outlet. Extension cords not allowed.
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>106F</sup>	2007- 01-12	0	Discontinue powerstrip into extension cord, must be plugged directly into wall outlet.
0304	PENETRATION PROTECT MISSING/INADEQUATE	1- PERMANENT 106H	2007- 01-12	0	seal around conduit through ceiling
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	1- PERMANENT <sup>124</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each one must be plugged directly into wall outlet.
0211	BLOCKED/LOCKED EXITS	1- PERMANENT <sup>123</sup>	2007- 01-12	0	move plant from in front of emergency exit
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT <sup>122</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each one must be plugged directly into wall outlet.
1202	DANGEROUS CONDITION EXISTS	12- PERMANENT <sup>119</sup>	2007- 01-12	0	quit and emove coffee maker on top of stove
0299	MEANS OF EGRESS OTHER	12- PERMANENT <sup>121</sup>	2007- 01-12	0	locked no access with master keys
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT <sup>102</sup>	2007- 01-12	1	Discontinue powerstrip into powerstrip, each one must be plugged directly into wall outlet.
0301	UNPROTECTED VERTICAL OPENING	12- PERMANENT <sup>109</sup>	2007- 01-12	0	replace ceiling tile
0299	MEANS OF EGRESS OTHER	12- PERMANENT 110	2007- 01-12	0	need emergency exit sign on door
0803	EXTENSION CORD NOT RATED FOR USE	12- PERMANENT <sup>118</sup>	2007- 01-12	0	discontinue use of all extension cord
0303	INADEQUATE FIRE RESISTANCE	12- PERMANENT <sup>118</sup>	2007- 01-12	0	reduce wall coverage to less than 25%
0803	EXTENSION CORD NOT RATED FOR USE	12- PERMANENT 131	2007- 01-12	0	discontinue use of extension cord
1400	CONSTRUCTION/RENOVATION	12- PERMANENT <sup>129</sup>	2007- 01-12	0	N/A
					Discontinue powerstrip into powerstrip,

	•				r
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	12- PERMANENT <sup>134</sup>	2007- 01-12	0	each one must be plugged directly into wall outlet.
0503	MONTHLY INSPECTION NOT DONE/RECORDED	12- PERMANENT 139	2007- 01-12	0	N/A
0301	UNPROTECTED VERTICAL OPENING	12- PERMANENT <sup>149</sup>	2007- 01-12	0	replace ceiling tile in hall outside Room 149
0504	EXTINGUSIHER ACCESS OBSTRUCTED	12- PERMANENT <sup>153</sup>	2007- 01-12	0	clear area around extinguisher
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	12- PERMANENT <sup>158</sup>	2007- 01-12	0	need to mount extinguisher
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	12- PERMANENT 161B	2007- 01-12	0	N/A
0301	UNPROTECTED VERTICAL OPENING	12- PERMANENT 160	2007- 01-12	1	replace ceiling tile
0204	EMERG LIGHTS NOT OPERATIONAL	10- PERMANENT <sup>104</sup>	2007- 01-12	1	replace lense
0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT <sup>107</sup>	2007- 01-12	0	replace ceiling tile
0499	FIRE ALARM OTHER	10- PERMANENT <sup>109</sup>	2007- 01-12	<b>0</b> .	clear access to pull station
0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT <sup>129</sup>	2007- 01-12	0	replace ceiling tile
0301	UNPROTECTED VERTICAL OPENING	PERMANENT 130	2007- 01-12	1	replace ceiling tile
0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT <sup>132</sup>	2007- 01-12	0	replace ceiling tile
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	10- PERMANENT <sup>124</sup>	2007- 01-12	0	need plate over switch
0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT <sup>113</sup>	2007- 01-12	0	replace ceiling tile
0301	UNPROTECTED VERTICAL OPENING	10- PERMANENT <sup>114</sup>	2007- 01-12	0	repice ceiling tile
0999	HVAC OTHER	10- PERMANENT <sup>111</sup>	2007- 01-12	0	clean AC return/vents
0899	UTILITIES OTHER	2- PERMANENT <sup>4</sup>	2007- 01-12	0	cover wiring in conduit box
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	2- PERMANENT <sup>9</sup>	2007- 01-12	0	mount extinguisher
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	2- PERMANENT <sup>1</sup>	2007- 01-12	1	mount extinguisher
0299	MEANS OF EGRESS OTHER	4- PERMANENT <sup>17A</sup>	2007- 01-12	0	locked with padlock no access with master key
0504	EXTINGUSIHER ACCESS OBSTRUCTED	4- PERMANENT <sup>1</sup>	2007- 01-12	0	clear area around extinghuiser
0210	EXIT ACCESS NOT MAINTAINED	4- PERMANENT <sup>1</sup>	2007- 01-12	0	clear access to exit
0899	UTILITIES OTHER	4- PERMANENT <sup>19A</sup>	2007- 01-12	0	hot water heater needs to be hardwired
0199	GENERAL REQUIREMENTS	4- PERMANENT <sup>19B</sup>	2007- 01-12	0	general housekeeping
0502	PORTABLE EXTINGUISHER IMPROPERLY MOUNTED	4- PERMANENT <sup>4</sup>	2007- 01-12	0	mount extinguisher
0299	MEANS OF EGRESS OTHER	4- PERMANENT <sup>5B</sup>	2007- 01-12	0	locked no access with master keys
0299	MEANS OF EGRESS OTHER	4- PERMANENT <sup>8A</sup>	2007- 01-12	1	locked no access
0301	UNPROTECTED VERTICAL OPENING	4- PERMANENT <sup>10</sup>	2007- 01-12	1	replace ceiling tile

0304	PENETRATION PROTECT MISSING/INADEQUATE	4- PERMANENT <sup>13</sup>	2007- 01-12	1	fill opening in wall between rooms
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	4- PERMANENT <sup>15</sup>	2007- 01-12	0	discontinue use of multiadapter at outlet
0803	EXTENSION CORD NOT RATED FOR USE	25- PERMANENT <sup>1</sup>	2007- 01-12	0	discontinue use of extension cord
0301	UNPROTECTED VERTICAL OPENING	24- PERMANENT <sup>32</sup>	2007- 01-12	0	replace ceiling tile
0211	BLOCKED/LOCKED EXITS	23- PERMANENT <sup>23</sup>	2007- 01-12	0	clear access to emergency exit
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	24- PERMANENT <sup>22</sup>	2007- 01-12	0	replace outlet cover
0803	EXTENSION CORD NOT RATED FOR USE	24- PERMANENT <sup>24</sup>	2007- 01-12	0	discontinue use of extension cord
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	41- PERMANENT <sup>1</sup>	2007- 01-12	0	need plate without slot for second switch
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	41- PERMANENT <sup>1</sup>	2007- 01-12	0	paint needs to be stored in flammable locker
0899	UTILITIES OTHER	41- PERMANENT <sup>1</sup>	2007- 01-12	0	hardwire hot water heater
0199	GENERAL REQUIREMENTS	41- PERMANENT <sup>1</sup>	2007- 01-12	0	Safety issue, replace or remove shattered mirror from wall
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	43- PERMANENT <sup>1</sup>	2007- 01-12	3	discontinue use of all extension cords
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	51- PERMANENT <sup>7</sup>	2007- 01-12	0	N/A
0301	UNPROTECTED VERTICAL OPENING	51- PERMANENT <sup>6</sup>	2007- 01-12	2	replace ceiling tile
0211	BLOCKED/LOCKED EXITS	19- PERMANENT <sup>8</sup>	2007- 01-12	0	N/A
0211	BLOCKED/LOCKED EXITS	19- PERMANENT <sup>7</sup>	2007- 01-12	0	move desk away from emergency exit
0301	UNPROTECTED VERTICAL OPENING	19- PERMANENT <sup>6</sup>	2007- 01-12	0	replace ceiling tile
0211	BLOCKED/LOCKED EXITS	18- PERMANENT <sup>3</sup>	2007- 01-12	0	move desk away from emergency exit
0210	EXIT ACCESS NOT MAINTAINED	18- PERMANENT <sup>5</sup>	2007- 01-12	0	move chair and flip chart away from emergency exit
0210	EXIT ACCESS NOT MAINTAINED	18- PERMANENT <sup>4</sup>	2007- 01-12	0	clear area around doorway
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	20- PERMANENT <sup>1</sup>	2007- 01-12	0	Discontinue powerstrip into powerstrip, each one must be plugged directly into wall outlet.
0303	INADEQUATE FIRE RESISTANCE	20- PERMANENT <sup>11</sup>	2007- 01-12	0	need to treat curtans or remove them
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	20- PERMANENT <sup>11</sup>	2007- 01-12	0	Discontinue powerstrip into extension cord, must be plugged directly into wall outlet. Extension cords not allowed
0303	INADEQUATE FIRE RESISTANCE	21- PERMANENT <sup>1</sup>	2007- 01-12	.0	treat curtains or remove them
0301	UNPROTECTED VERTICAL OPENING	21- PERMANENT <sup>5B</sup>	2007- 01-12	0	replace ceiling tile
0211	BLOCKED/LOCKED EXITS	21- PERMANENT <sup>8</sup>	2007- 01-12	0	move desk away from emergency exit
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	21- PERMANENT 8	2007- 01-12	0	Discontinue powerstrip into extension cord, must be plugged directly into wall outlet.
	IMPROPER USE OF	22-	2007-		Discontinue powerstrip into extension

0804	MULTISTRIP/EXTEN CORDS	PERMANENT	1	01-12	1	cord, must be plugged directly into wall outlet. Extension cords not allowed
0211	BLOCKED/LOCKED EXITS	22- PERMANENT	2	2007- 01-12	0	clear access to exit
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	22- PERMANENT	4	2007- 01-12	0	discontinue use of extension cord
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	22- PERMANENT	8	2007- 01-12	1	discontinue use of extension cord
0210	EXIT ACCESS NOT MAINTAINED	22- PERMANENT		2007- 01-12	0 .	clear area around emergency exit
0211	BLOCKED/LOCKED EXITS	22- PERMANENT	5	2007- 01-12	0	clear area around exit
0501	FIRE EXTINGUISHER REQUIRES INSPECTION	22- PERMANENT		2007- 01-12	0	extinguisher outside room 1 needs to be serviced out of date
0303	INADEQUATE FIRE RESISTANCE	27- PERMANENT		2007- 01-12	0	treat curtains or remove them
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT		2007- 01-12	0	replace ceiling tile in storage room
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT	_	2007- 01-12	0	replace ceiling tile
0304	PENETRATION PROTECT MISSING/INADEQUATE	27- PERMANENT	6	2007- 01-12	0	fill in horizontal opening in wall
0899	UTILITIES OTHER	27- PERMANENT	6	2007- 01-12	1	repair or replce light, exposed wiring
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	27- PERMANENT	. 3	2007- 01-12	<b>o</b> .	paint needs to be in flammable locker
0303	INADEQUATE FIRE RESISTANCE	27- PERMANENT	. 3	2007- 01-12	0	curtains need to be treated or removed
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	27- PERMANENT		2007- 01-12	Ö	remove extension cord going through ceiling at back wall
0301	UNPROTECTED VERTICAL OPENING	27- PERMANENT		2007- 01-12	0	replace ceiling tile
0304	PENETRATION PROTECT MISSING/INADEQUATE	27- PERMANENT	. 9	2007- 01-12	0	fill in hole in wall
0303	INADEQUATE FIRE RESISTANCE	92- PORTABLE	9	2007- 01-12	0	need to treat or remove curtains
0106	ACCUMULATION OF COMBUSTIBLE MATERIALS	92- PORTABLE	11	2007- 01-12	0	paint needs to be a flammable locker
0211	BLOCKED/LOCKED EXITS	92- PORTABLE	26	2007- 01-12	1	clear access to emergency exit
0299	MEANS OF EGRESS OTHER	92- PORTABLE	26	2007- 01-12	0	need mergency exit sign on door
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	26	2007- 01-12	1	Discontinue powerstrip into overhead cart, must be plugged directly into wall outlet.
0199	GENERAL REQUIREMENTS	92- PORTABLE	7	2007- 01-12	0	general housekeeping
0303	INADEQUATE FIRE RESISTANCE	92- PORTABLE	25	2007- 01-12	0	need to reduce wall coverage to less than 25%
0299	MEANS OF EGRESS OTHER	92- PORTABLE	24	2006- 12-26	0	need emergency exit sign
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	24	2007- 01-12	0	Discontinue powerstrip into powerstrip, each one must be plugged directly into wall outlet.
0805	GFCI'S NOT INSTALLED IN WET LOCATIONS	92- PORTABLE	61	2007- 01-12	0	need GFCI installed at sink
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	63	2007- 01-12	0	need extinguisher in portable "came without one"
0303	INADEQUATE FIRE RESISTANCE	92-	64	2007-	0	reduce wall coverage to less than 25%

	•					
		PORTABLE		01-12		
0504	EXTINGUSIHER ACCESS OBSTRUCTED	92- PORTABLE	42	2007- 01-12	1	N/A
0299	MEANS OF EGRESS OTHER	92- PORTABLE	42	2007- 01-12	0	need emergency exit sign on door
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	43	2007- 01-12	1 .	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	43	2007- 01-12	0	discontinue use of extension cords
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	4.7	2007- 01-12	0	N/A
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	51	2007- 01-12	0	N/A
0303	INADEQUATE FIRE RESISTANCE	92- PORTABLE	52	2007- 01-12	0	reduce wall coverage to less than 25%
0299	MEANS OF EGRESS OTHER	92- PORTABLE	55	2007- 01-12	2	locked no access SEDNET building
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	56	2007- 01-12	0	discontinue use of extension cord
0506	EXTINGUSHER MISSING FROM LOCATION	92- PORTABLE	53	2007- 01-12	0	removed by teacher due to it being used in fight, move mount over by teacher's desck and remount
0299	MEANS OF EGRESS OTHER	92- PORTABLE	27	2007- 01-12	1	need emergency exit sign
0303	INADEQUATE FIRE RESISTANCE	92- PORTABLE	27	2007- 01-12	0	reduce wall coverage to less than 25% third time teacher advised different room
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	31	2007- 01-12	0	discontinue use of all extension cords
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	32	2007- 01-12	0	discontinue use of extension cord
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE	59	2007- 01-12	0	N/A

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. No

I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S.

I hereby certify that the required fire drills have been completed as of this inspection date.

(Or)

Yes

Acknowledgement N/A.

No

**Primary inspector** Michael, Swartz

**Additional inspector** 

District Clay

School RIDGEVIEW SENIOR HIGH

Address 466 MADISON AVENUE

Inspection date 2007-04-11

Notes

**Inspectors present** 

State No **District** Yes Local No

Ref	Code	Violation	Bldg	Room	Comp date	Cited	Notes
	0303	INADEQUATE FIRE RESISTANCE	1- PERMANENT	. 136	2006- 05-24	0	Restore Fire restive rating of Fire Wall by Rechauk Fire wall pentrations
	0808	IMPROPER STORAGE IN ELECT/MECH ROOMS	2- PERMANENT	. 218	2006- 05-25	0	N/A
	1299	OPERATING FEATURES OTHER	2- PERMANENT	. 210	2006- 05-25	0	remove flammable liquids or store in approve flammable locker
	0506	EXTINGUSHER MISSING FROM LOCATION	3- PERMANENT		2006- 05-25	0	N/A
	0102	OCCUPANCY LOAD EXCEEDED/NOT POSTED	3- PERMANENT		2006- 05-25	0	N/A
	0304	PENETRATION PROTECT MISSING/INADEQUATE	3- PERMANENT		2006- 04-25	0	Restore Fire Protective rating of Ceiling by re chauking holes in Fire Wall/Ceiling
	0499	FIRE ALARM OTHER	6- PERMANENT		2006- 05-25	0 ,	Repair broken Magnetic door closure of Fire Door
	0299	MEANS OF EGRESS OTHER	6- PERMANENT		2006- 05-25	0	Install Emergency Lights and Exit Lights
	0304	PENETRATION PROTECT MISSING/INADEQUATE	6- PERMANENT		2006- 05-25	0	Restore Fire Rated Ceilings in Electrical Room
	0203	EXIT LIGHTS INOPERABLE EMERGENCY MODE	6- PERMANENT		2006- 05-25	0	N/A
	0204	EMERG LIGHTS NOT OPERATIONAL	8- PERMANENT	829	2006- 05-25	0	N/A
	0405	SMOKE DETECTORS INOPERABLE/MISSING	8- PERMANENT		2006- 05-25	0	Place smoke Detector in store room
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	9- PERMANENT		2006- 05-25	0	N/A
	0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	93- PORTABLE	1	2006- 05-25	0	South Wall
	0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	93- PORTABLE	3	2006- 05-25	0	Sink area
	0899	UTILITIES OTHER	93- PORTABLE	3	2006- 05-25	0	Cirect (Microwave area) over loaded. Staff ststes unable to use one appilance at a time
	0204	EMERG LIGHTS NOT OPERATIONAL	93- PORTABLE	3	2006- 05-25	0	N/A
	0299	MEANS OF EGRESS OTHER	93- PORTABLE	3	2006- 05-25	0	Provide Emergency light in all student occupied spaces Bathroom

0204	EMERG LIGHTS NOT	92-	5	2006-	0	N/A
0204	OPERATIONAL	PORTABLE	5	05-25	U	NA
0211	BLOCKED/LOCKED EXITS	92- PORTABLE	12	2006- 05-25	0	Remove lock and haspe store room door .
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	8	2006- 05-25	0	N/A
0807	MISSING/BROKEN RECEPTACLE/FACEPLATE	92- PORTABLE	4	2006- 05-25	0	90* elbow at front ramp
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	21	2006- 05-25	0	resecure floor to ramp
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	24	2006- 05-25	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	43	2006- 04-25	0	restore wooden ramp per LSC101
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	44	2006- 05-25	0	restore wooden ramp per LSC101
1202	DANGEROUS CONDITION EXISTS	92- PORTABLE	61	2006- 05-25	0	repair hole in floor in front of store room door
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	61	2006- 05-25	Ó	N/A
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	67	2006- 05-25	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	67	2006- 05-25	0	N/A
0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	69	2006- 05-25	0	replace missing smoke/heat detector in store room
0204	EMERG LIGHTS NOT OPERATIONAL	92- PORTABLE	69	2006- 05-25	0	N/A
0209	RATED OPENINGS NOT MAINTAINED	92- PORTABLE	71	2006- 05-25	0	re weld broken welds on metal picketts on ramp
0899	UTILITIES OTHER	92- PORTABLE	71	2006- 05-25	0	replace missing screws securing panle cover to 200 Amp panle
0405	SMOKE DETECTORS INOPERABLE/MISSING	92- PORTABLE	71	2006- 05-25	0	install smoke/heat detectors in store room (bathroom)
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	74	2006- 05-25	0	N/A
0804	IMPROPER USE OF MULTISTRIP/EXTEN CORDS	92- PORTABLE	68	2006- 05-25	0	N/A
1205	FIRE EVACUATION PLAN(S) NOT POSTED	92- PORTABLE	68	2006- 05-25	0	N/A
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	62	2006- 05-25	0	restore wooden ramp per LSC101
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	87	2006- 05-25	0	restore wooden ramp per LSC101
0210	EXIT ACCESS NOT MAINTAINED	92- PORTABLE	89	2006- 05-25	0	restore wooden ramp per LSC101
0211	BLOCKED/LOCKED EXITS	92- PORTABLE	82	2006- 05-25	0	remove lock/haspe on store room door

I hereby certify that the district has complied with section 1013.12(1)(b), F.S. **No** I hereby certify that the local authority having jurisdiction has complied with section 1013.12(2)(b), F.S. **Yes** 

I hereby certify that the required fire drills have been completed as of this inspection date.

Yes

(Or)

Acknowledgement N/A.

No

**Primary inspector** Silver, Ware

**Additional inspector**