



BANKERBRIAN

LEARNING CENTER



GREEN COVE SPRINGS

JUNIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58**



ANNUAL PERMANENT BUILDING INSPECTION
 ANNUAL RELOCATABLE BUILDING INSPECTION
 FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 2

TYPE OF INSPECTION

DISTRICT: CLAY FACILITY #: 0001

FACILITY: GREEN COVE SPRINGS JUNIOR HIGH
1220 BONAVENTURE AVENUE
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: JANUARY 17, 2006


INSPECTOR'S SIGNATURE: *[Signature]*

DATE: 1-17-06

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
		FIRE EXTINGUISHERS NOT SIGNED	X							69A-36
		MANY EMERGENCY EVACUATIONS SHEETS MISSING		X						FBC 423.17.1
4	424	EMERGENCY LIGHT OUT		X						FBC 1006.2
4	422	GAS GRILL STORED INSIDE		X						NFPA 101-13
5	535	NO EMERGENCY LIGHTS		X						FBC 423.17.1
5	545	NO EMERGENCY LIGHTS		X						FBC 423.17.1
5	530	EXIT LIGHT OUT		X						FBC 423.17.1
7	701	MAXIMUM CAPACITY SIGN MISSING	X							FBC-423.14.2.2

LAKERS SIDE

JUNIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58



TYPE OF INSPECTION

ANNUAL PERMANENT BUILDING INSPECTION
 ANNUAL RELOCATABLE BUILDING INSPECTION
 FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 5

DISTRICT: CLAY FACILITY # 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
2750 MOODY ROAD
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: JANUARY 25, 2006

INSPECTOR'S SIGNATURE: [Signature] DATE: Jan 25, 2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	34	ALARM J-BOX NO COVER	X							NFPA 70
2	46	EMERGENCY LIGHT NOT WORKING ACROSS FROM ROOM 44		X						FBC 423.17.1
3	56	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	57	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	58	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	66	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	69	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	70	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	71	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	79	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	80	NO EMERGENCY LIGHT		X						FBC 423.17.1
3	81	NO EMERGENCY LIGHT		X						FBC 423.17.1

FISCAL YEAR 2005-2006

FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58



TYPE OF INSPECTION

ANNUAL PERMANENT BUILDING INSPECTION
 ANNUAL RELOCATABLE BUILDING INSPECTION
 FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 5

DISTRICT: CLAY FACILITY # 0014

FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
2750 MOODY ROAD
ORANGE PARK, FLORIDA 32073


INSPECTION DATE: JANUARY 25, 2006

Zed Sweetland
 INSPECTOR'S SIGNATURE Jan 25, 2006
 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
3	74	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
5	110	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
5	138	EMERGENCY LIGHT - BULB BROKEN		X						FBC 423.17.1
5	231	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
5	235	WIRE FROM PANEL NOT IN CONDUIT	X							NFPA 70
8	804	EXIT LIGHT OUT		X						FBC 1016.3.1

ORANGED PARK

JUNIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58



TYPE OF INSPECTION

ANNUAL PERMANENT BUILDING INSPECTION ANNUAL RELOCATABLE BUILDING INSPECTION
 FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 5

DISTRICT: CLAY FACILITY # 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1500 GANO AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: JANUARY 24, 2006

INSPECTOR'S SIGNATURE: [Signature] DATE: Jan 24, 2006

Building	Room	Deficiency Description and Corrective Action Required	Maint. "M"	Oper. "O"	Fac. "C"	Intro. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	503	CABINET IN FRONT OF ELECTRIC PANEL		X						NFPA 70
92	504	RAMP HAS SOME LOOSE BOARDS	X							FBC 11-8.4
92	507	FIRE EXTINGUISHER NOT BY THE EXIT		X						69A-36
92	509 A/B	STAIRS IN POOR SHAPE	X							
92	511	FIRE EXTINGUISHER NOT BY THE EXIT		X						69A-36
92	514	EMERGENCY LIGHT NOT WORKING		X						FBC 423-17.1
92	514	DOOR HANDLE BROKEN	X							
92	515	FIRE EXTINGUISHER NOT SIGNED		X						69A-36
92	516	EMERGENCY LIGHT NOT WORKING		X						FBC 423-17.1
92	702	EMERGENCY LIGHT NOT WORKING		X						FBC 423-17.1
92	706	NO FIRE EXTINGUISHER BY COOK TOP		X						69A-36
92	707 A/B	EMERGENCY LIGHT NOT IN "B" SIDE		X						FBC 423-17.1
92	708	NO FIRE EXTINGUISHER BY COOK TOP		X						69A-36
92	709	RAMP SETTLING/MISSING SPINDLE	X							



FISCAL YEAR 2005-2006

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58**

TYPE OF INSPECTION

ANNUAL PERMANENT BUILDING INSPECTION

ANNUAL RELOCATABLE BUILDING INSPECTION

FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 5

DISTRICT: CLAY FACILITY #: 0016

FACILITY: ORANGE PARK JUNIOR HIGH SCHOOL
1500 GANO AVENUE
ORANGE PARK, FLORIDA 32073


INSPECTION DATE: JANUARY 24, 2006

INSPECTOR'S SIGNATURE: DATE: Jan 24, 2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost.	No. of times Def. Cited	Scheduled for Correction	Rule
92	710	NO FIRE EXTINGUISHER BY COOK TOP		X						69A-36
92	711	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1
92	719	EMERGENCY LIGHT NOT WORKING		X						FBC 423.17.1

WILLKINSON

JUNIOR HIGH SCHOOL



FISCAL YEAR 2005-2006

FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58



TYPE OF INSPECTION

ANNUAL PERMANENT BUILDING INSPECTION
 ANNUAL RELOCATABLE BUILDING INSPECTION
 FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 4

DISTRICT: CLAY FACILITY #: 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
5025 C.R. 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 26, 2006

INSPECTOR'S SIGNATURE: *[Signature]* DATE: Jan 26, 2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2	211	COVER MISSING ON J BOX, NW DOOR	X							
2	220	EMERGENCY LIGHT OUT		X						FBC 423.17.1
2	211	EXIT LIGHT OUT		X						FBC 423.17.1
2	220	COVER MISSING ON ENTRY LIGHT	X							
3	301	OCCUPANCY CAPACITY SIGN MISSING		X						FBC 1004.3
3	311	DOOR SWING - CLASSROOM NOT BY DESIGN			X					
4	407	EMERGENCY EVACUATION SIGN MISSING		X						FBC 423.14.2.4
6	600	EXIT LIGHT OUT		X						FBC 423.17.1
9	901B	EMERGENCY LIGHT OUT		X						FBC 423.17.1
9	906B	EMERGENCY LIGHT OUT		X						FBC 423.17.1

FISCAL YEAR 2005-2006

**FIRE SAFETY INSPECTION REPORT
FOR EDUCATIONAL FACILITIES
FLORIDA STATUTES 1013.12 & RULE 69A-58**



TYPE OF INSPECTION

ANNUAL PERMANENT BUILDING INSPECTION ANNUAL RELOCATABLE BUILDING INSPECTION
 FIRE DRILL LOG: NUMBER OF DRILLS PERFORMED: 4

DISTRICT: CLAY FACILITY # 0017

FACILITY: WILKINSON JUNIOR HIGH SCHOOL
5025 C.R. 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: JANUARY 26, 2006

INSPECTOR'S SIGNATURE: [Signature] DATE: Jan 26, 2006

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	2	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	2	FIRE EXTINGUISHER MISSING		X						
92	7	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	11	GLOBE IN CLOSET MISSING	X							
92	21	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	21	EVACUATION SHEET MISSING		X						FBC 423.14.2.4
92	25	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	27	EMERGENCY LIGHT OUT		X						FBC 423.17.1
92	42	EMERGENCY LIGHT OUT		X						FBC 423.17.1