

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ARGYLE ELEMENTARY SCHOOL  
 2625 SPENCER PLANTATION BLVD.  
 ORANGE PARK, FL 32073

*Jay Baker*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	701A						
92	702	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide. Back door was locked by a non-conforming device. This device is only to be used during an emergency situation. This is a major violation. This will be reported to the Fire Marshall.					X
92	702A						
92	703						
92	704	Emergency lights are not working.					X
92	705	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	706	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	706A						
92	707						
92	707A						
92	708						
92	710	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36"). The fire extinguisher is pinned against the wall by bookcase and unable to remove from bracket.					X
92	710A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ARGYLE ELEMENTARY SCHOOL  
 2625 SPENCER PLANTATION BLVD.  
 ORANGE PARK, FL 32073

*[Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	710B						
92	711	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (1.10.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	711A						
92	713						
92	713A						
92	713B						
92	713C						
92	713D						
92	713E						
92	714						
92	714A						
92	801	Reset button on outlet in bathroom is broken. Heat detector is hanging down from ceiling and light fixture in bathroom missing cover.					X
92	801A						
92	802						
92	802A						
92	803						
92	803A						
92	804						
92	804A						
92	805	Back steps are coming off wall. Needs to be reattached.					X
92	805A						
92	806						
92	806A						
92	807						
92	807A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: ARGYLE ELEMENTARY SCHOOL  
 2625 SPENCER PLANTATION BLVD.  
 ORANGE PARK, FL 32073

*Jerry Patis*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

3/26/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	808						
92	808A						
92	901						
92	901A						
92	902	Emergency light is covered up by boxes on top of cabinet. Must remove all boxes.					X
92	902A						
92	903						
92	903A						
92	904	Call station and fire extinguisher is blocked by boxes and garbage cans must keep clear at all times. Both exits are blocked by bookshelf and garbage can must keep both clear.					X
92	904A						
92	905						
92	905A						
92	906	Back door was locked by a non-conforming device. This device is only to be used during an emergency situation. This is a major violation. This will be reported to the Fire Marshal.					X
92	906A						
92	907	Back door was locked by a non-conforming device. This device is only to be used during an emergency situation. This is a major violation. This will be reported to the Fire Marshal.					X
92	908	Data cables are on the floor in front of door creating a tripping hazard and must be relocated.					X
92	908A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: CHARLES E. BENNETT ELEM. - 0071  
 1 SOUTH OAKRIDGE AVENUE  
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE:   
 BUILDING INSPECTION DATE: 10/29/2022  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	040	Cabinet is blocking front door. must have a clear path through front door of 36 inches.					X
92	040A						
92	041	Electrical panel is blocked. Must have 3 feet clearance in front of panel egress. Door is blocked by desk. Must have a clear path to the exit door.					X
92	041A	Electrical panel is blocked. Must have 3 feet clearance in front of panel egress two door is blocked by desk. Must have a clear path to the exit door it's portable has a lot of extra storage.					X
92	042	This portable is being used for storage.					
92	042A						
92	043						
92	045						
92	045A						
92	046						
92	047						
92	047A						
92	048						
92	048A						
92	049	Electrical panel is blocked by row of filing cabinets. Must move cabinets over from in front of electrical panel.					X
92	049A						
92	050						
92	050A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: CHARLES E. BENNETT ELEM. - 0071  
 1 SOUTH OAKRIDGE AVENUE  
 GREEN COVE SPRINGS, FL 32043

*[Handwritten Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

10/29/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	051	Book storage.					
92	051A						
92	052						
92	052A						
92	053						
92	053A						
92	054						
92	055	Portable has treadmills but no weight room.					
92	055A						
92	055B						
92	056						
92	056A						
92	056B						
92	057						
92	057A						
92	057B						
92	501						
92	502	This is a custodial office.					
92	602A	This is a clothes closet portable.					
92	602B						
92	603A						
92	603B						
92	604	GFCI by sink does not trip - see picture. The test button will trip the receptacle but a tester will not Trip GFCI, is wired incorrectly.				X	X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: CHARLES E. BENNETT ELEM. - 0071  
 1 SOUTH OAKRIDGE AVENUE  
 GREEN COVE SPRINGS, FL 32043

*Gay Parks*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

10/29/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	604A						
92	604B						
92	605						
92	605A						
92	702						
92	702A						
92	703	Piano blocking second exit, must relocate piano.					X
92	703A						
92	703B						
92	803						
92	803A						
92	803B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Lake*

12/31/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	027	Electrical panel was blocked by tables leaning against the wall.					
92	029	Bathroom is being used for storage. No smoke detector and the shelf is blocking the fire alarm device.					
92	029A						
92	031	Bathroom being used for storage. There's no smoke detector and the shelf in storage is blocking the fire alarm device.					
92	031A						
92	032	Electrical panel is blocked. Electrical must be kept clear at all times. Relocate all items in front of electrical panel. Electrical panel is still blocked. This is the second year violation. A non-approved rug in front of door creates a tripping hazard and no evacuation map.					
92	032A						
92	033						
92	033A						
92	034A						
92	034B						
92	036	Large bushes on side of building needs to be removed.					
92	036A						
92	037						
92	037A						
92	038						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Park*

12/31/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	038A						
92	039	Emergency light does not work.					
92	039A						
92	040	Siding beside ramp needs to be repaired.					
92	040A						
92	041	Electrical panel is blocked. Electrical must be kept clear at all times.					
92	041A						
92	042A						
92	042B						
92	042C						
92	043						
92	043A						
92	044	Emergency light did not work.					
92	044A						
92	044B						
92	045	No evacuation map.					
92	045A						
92	045B						
92	048						
92	049						
92	050	Non approved rug by front door can be a tripping hazard.					
92	050A						
92	051						
92	051A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

*Yang Park*  
 INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE: 12/31/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	053						
92	053A						
92	054						
92	054A						
92	054B						
92	055						
92	055A						
92	056	Electrical panel was blocked by hanging poster and GFCI receptacle has no cover on the outside building.					
	056A						
	057	Fire alarm pull station by door is blocked. MUST REMOVE ALL ITEMS AROUND THE FIRE ALARM PULL STATION SO IT IS ACCESSIBLE AT ALL TIMES. Handi cap ramp railing is blocked by vines growing on parts of hand railing. Remove all vines from railing. This is the second year of this violation.					
	057A						
	058						
	058A						
	059	Electrical panel pad poster board covering. Must leave electrical panel exposed at all times.					
	059A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Beck*

12/31/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	060	Time out room is being used as storage without heat detector. This is the second year of this violation.					
	061						
	061A						
	062						
	062A						
	063	Receptacle by sink needs to be GFCI. This is a second year violation.					
	063A						
	064	Emergency light is blocked by items on top of the cabinet. Electrical panel is blocked by book shelf. Remove items from top of cabinet and keep clear at all times. THESE VIOLATIONS HAVE NOT BEEN CORRECTED FROM LAST YEAR.					
	064A						
	065	Electrical panel is blocked by book shelf. Needs to be removed.					
	065A						
	066	Emergency lights do not work and back exit is blocked by filing cabinet.					
	066A						
	067						
	067A						
	068	Desk is blocking the back exit.					
	068A						
	069						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

12/31/2022

<b>FISCAL YEAR:</b> 2022/2023
<b>DISTRICT:</b> CLAY
<b>FACILITY:</b> W. E. CHERRY ELEMENTARY - 0241 420 EDSON DRIVE ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	069A						
	070						
	070A						
	026A						
	026B						
	026C						
	030						
	030A						
	030B						
	030C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

3/4/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: CLAY HILL ELEMENTARY - 0411  
 6345 COUNTY ROAD 218  
 JACKSONVILLE, FL 32234

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	682						
92	682A						
92	682B						
92	701						
92	703						
92	704						
92	705	Back door is blocked by desk. Must keep clear access to exit door at all times.					X
92	705A						
92	706						
92	707	Electrical panel was blocked. Must keep clear access at all times. Emergency light does not work.					X
92	707A						
92	707B						
92	708						
92	708A						
92	709						
92	709A						
92	709B						
92	710						
92	710A						
92	712						
92	712A						
92	760						
92	760A						
92	762						
92	762A						




**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/202  
 DISTRICT: CLAY  
 FACILITY: COPPERGATE ELEMENTARY - 0601  
 2250 COUNTY ROAD 209 N.  
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE:  


BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE: 1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	511	Emergency lights do not work and front door is blocked by desk.					X
92	511A						
92	512						
92	512A						
92	514						
92	514A						
92	520						
92	520A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: DOCTORS INLET ELEMENTARY - 0261  
 2634 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

*Yany Pats*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

11/17/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	836	This Portable has swing hanging from ceiling.					X
92	836A						
92	837	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO BUILDING AND MAKE AN UNSAFE CAMPUS. They need to be trimmed so they are off the building or removed. Emergency light does not work.					X
92	838	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING AND MAKE AN UNSAFE CAMPUS. They need to be trimmed so they are off the building or removed. Toilet is either leaking or overflowing, paper towels are all around the outside of toilet.					X
92	838A						
92	839						
92	840	Emergency light did not work.					X
92	843						
92	844	BACK DOOR EXIT IS BLOCKED BY TREES AND SHRUBS. LIFE SAFETY ISSUE - MUST MOVE ASAP.					X
92	845	Emergency light does not work. Teacher storing umbrella pole in front of emergency light.					X
92	845A						
92	847						
92	847A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: DOCTORS INLET ELEMENTARY - 0261  
 2634 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *Yamir Pats*  
 BUILDING INSPECTION DATE: 11/17/2022  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	849	Portable has weight bench with stacks of heavy weights.					X
92	849A						
92	869						
92	869A						
92	869B						
92	870						
92	870A						
92	870B						
92	871	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. They need to be trimmed so they are off the building or removed.					X
92	871A						
92	871B						
92	872						
92	872A						
92	873						
92	874	No DCA sticker and no documentation.		X			
92	876	Emergency light does not work. Emergency light is wired through light switch. When the switch is off the light does not work. Must be directly wired to the electrical panel.					X
92	888	Plants need to be trimmed away from ramp walkway.					X
92	888A						
92	889						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Young Pato*

11/17/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: DOCTORS INLET ELEMENTARY - 0261  
 2634 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	889A						
92	890						
92	890A						
92	890B						
92	891	Teacher has bathroom exhaust fan covered up with plastic. Could cause a fire. Hazard needs to be removed.					X
92	891A						
92	893	Emergency light does not work.					X
92	893A						
92	894						
92	895						
92	895A						
92	895B						
92	896						
92	896A						
92	897						
92	897A						
92	899	emergency light does not work					
92	899A						
92	899B						
92	921	Teacher has gas can stored inside along with Rototiller and leaf blower that has gas. These items cannot be stored in a portable.					
92	921A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: DOCTORS INLET ELEMENTARY - 0261

2634 COUNTY ROAD 220

MIDDLEBURG, FL 32068



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 11/17/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	923	Outside receptacle cover is half on a half out needs to be secured					
92	923A						
92	842A	Emergency light on the portable side "A" does not work. Bushes are overgrown around portable and handicap ramp. They need to be trimmed so they are off the building or removed.					
92	842B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

*Jew Parks*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

7/24/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	601	2022 NEED TO REMOVE PALM TREE BY RAMP AS IT HAS LARGE THORNS AND COULD INJURE STUDENTS. THORNS ARE AT EYE LEVEL!!! THIS TREE NEEDS TO BE REMOVED IMMEDIATELY.				X	
92	601A						
92	601B						
92	602						
92	602A						
92	602B						
92	603						
92	603C						
92	603D						
92	604	EMERGENCY LIGHTS DO NOT WORK.					X
92	604A						
92	605	PORTABLE HAS SWING HANGING FROM THE CEILING.CEILING IS SHEETROCK.					X
92	605A						
92	605B						
92	606						
92	606A						
92	606B						
92	607	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. RECCOMENDED TO REMOVE SHRUBS.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: FLEMING ISLAND ELEMENTARY - 0521

4425 LAKESHORE DRIVE

FLEMING ISLAND, FL 32003

*Yong Pate*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 7/24/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	607A						
92	607B						
92	608	PORTABLE WALLS HAVE MORE THAN 20% COVERAGE.					X
92	608A						
92	608B						
92	801	BATHROOM FAN DOES NOT WORK.					X
92	801A						
92	801B						
92	802						
92	802A						
92	802B						
92	803						
92	803A						
92	803B						
92	804	EMERGENCY LIGHTS DO NOT WORK.					X
92	804A						
92	804B						
92	805	EMERGENCY LIGHTS DO NOT WORK.					X
92	805A						
92	806	BATHROOM LIGHT DOES NOT WORK.					X
92	806A						
92	807						
92	807A						
92	807B						
92	812	EMERGENCY LIGHTS DO NOT WORK.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

*Jerry Pate*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

7/24/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	812A						
92	812B						
92	821						
92	824	BACK DOOR EGRESS IS PARTIALLY BLOCKED BY FILING CABINET. MUST RELOCATE CABINET. SEE PICTURE THIS VIOLATION IS STILL IN PLACE FROM LAST YEAR!!!					X
92	824A						
92	824B						
92	826	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. RECOMMENDED TO REMOVE SHRUBS.					X
92	826A						
92	826B						
92	828						
92	828A						
92	830	MUST REMOVE LATCH OFF BATHROOM DOOR. LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. RECOMMENDED TO REMOVE SHRUBS.					X
92	830A						
92	830B						
92	832						
92	832A						
92	832B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE: 7/24/2022  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	843						
92	843A						
92	844	EMERGENCY LIGHTS DO NOT WORK AND GFCI BY MICROWAVE DOES NOT WORK.					X
92	844A						
92	846	PORTABLE BEING USED FOR STORAGE.					X
92	846A						
92	848	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. RECOMMENDED TO REMOVE SHRUBS.					X
92	848A						
92	848B						
92	850						
92	850A						
92	850B						
92	860	EMERGENCY LIGHT DOES NOT WORK AND ELECTRICAL PANEL IS BLOCKED BY BOOK SHELF. MUST KEEP 3" AREA CLEAR IN FRONT OF ELECTRICAL PANEL.					X
92	860A						
92	860B						
92	861						
92	861A						
92	861B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

*Jerry Lake*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

7/24/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	862	VINES GROWING UP THE SIDE OF BUILDING. THERE IS A BROKEN CEILING TILE THAT NEEDS TO BE REPLACED.					X
92	862A						
92	899	THIS PORTABLE HAS BEEN MOVED!!		X			
92	901						
92	901A						
92	904	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING SEE PICTURES EMERGENCY LIGHTS DO NOT WORK.					X
92	904A						
92	904B						
92	905						
92	905A						
92	906	EMERGENCY LIGHTS DO NOT WORK.					X
92	906A						
92	906B						
92	907						
92	907A						
92	907B						
92	908	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING EMERGENCY LIGHTS DO NOT WORK.					X
92	908A						
92	908B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

7/24/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	909	THIS PORTABLE HAS BEEN MOVED!!		X			
92	909A						
92	909B						
92	910	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. RECCOMENDED TO REMOVE SHRUBS.					X
92	910A						
92	910B						
92	842	LARGE SHRUBS ALONG BUILDING MAY CAUSE DAMAGE TO SIDING. RECCOMENDED TO REMOVE SHRUBS.					X
92	842A	EMERGENCY LIGHTS DO NOT WORK.					X
92	842B						
92	842C						
92	842D						
92	842E						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** GROVE PARK ELEMENTARY - 0232  
 1643 MILLER STREET  
 ORANGE PARK, FL 32073

*[Handwritten Signature]*

1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	009						
92	009A						
92	010	Receptacle by sink in classroom is not GFCI protected.					X
92	010A						
92	010B						
92	027						
92	029						
92	029A						
92	029B						
92	030						
92	030A						
92	030B						
92	031	Back door is blocked. Must keep a clear path at all times.					X
92	031A						
92	031B						
92	043						
92	043A						
92	043B						
92	044						
92	044A						
92	044B						
92	071						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: GROVE PARK ELEMENTARY - 0232

1643 MILLER STREET

ORANGE PARK, FL 32073

*[Inspector Signature]*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	071A						
92	500						
92	500A						
92	501						
92	501A						
92	501B						
92	504						
92	505						
92	506						
92	506A						
92	506B						
92	507	Emergency light does not work.					X
92	507A						
92	522						
92	523	The back door was blocked by desk and chairs. Exits must be kept clear at all times. Electrical panel was blocked by filing cabinets and boxes. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	524						
92	525						
92	525A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Signature]*  
 1/29/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: GROVE PARK ELEMENTARY - 0232  
 1643 MILLER STREET  
 ORANGE/PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	005						
92	005A						
92	005B						
92	005C						
92	006						
92	006A						
92	006B						
92	006C						
92	006D						
92	006E						
92	007						
92	007A						
92	007B						
92	007C						
92	007D						
92	520A						
92	520B						
92	521A	Emergency light in back room does not work.					X
92	521B						
92	008	Room eight - F receptacle by kitchen sink is not GFCI protected.					X
92	008A						
92	008B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: GROVE PARK ELEMENTARY - 0232  
 1643 MILLER STREET  
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE:   
 BUILDING INSPECTION DATE: \_\_\_\_\_  
 PORTABLE INSPECTION DATE: 1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	008C						
92	008D						
92	008E						
92	008F						
92	008G						
92	008H						
92	008J						
92	008K						
92	008L						
92	008M						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pater*

3/4/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: S. BRYAN JENNINGS ELEMENTARY - 0331  
 215 CORONA DRIVE  
 ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	026						
92	027	Electrical panel is blocked by materials. Area in front of electrical panel must be kept clear at all times. 2023 electrical panel now is blocked by cabinets. Complete access is blocked. Must be cleared. Will report this to the Fire Marshal.					X
92	028A	Electrical panel is blocked. Must have access to electrical panel at all times.					X
92	028B						
92	028C						
92	029			X			
92	029A	DCA sticker should be E - 002114.					
92	030						
92	032						
92	033						
92	033A						
92	035						
92	036	Emergency light does not work.					X
92	037	Emergency light did not work.					X
92	037A						
92	039	Emergency light has been removed from wall. Need to replace.					X
92	039A						
92	042						
92	042A						
92	042B						
92	043	Back doors blocked by easel. Must keep access to all exterior doors at all times.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**

*Young Pata*

**BUILDING INSPECTION DATE:**

3/4/2023

**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: S. BRYAN JENNINGS ELEMENTARY - 0331

215 CORONA DRIVE

ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	043A						
92	043B						
92	044						
92	044A						
92	044B						
92	075	GFCI by classroom sink needs to be replaced. When tripped and still has power.					X
92	075A						
92	075B						
92	077						X
92	077A	GFCI by classroom sink does not work.					
92	077B						
92	078						
92	078A						
92	078B						
92	080A						
92	080B						X
92	076	This portable is the clinic.					
92	076A						
92	076B						
92	076C						
92	076D						
92	076E						
92	076F						
92	076G						
92	076H						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: S. BRYAN JENNINGS ELEMENTARY - 0331

215 CORONA DRIVE

ORANGE PARK, FLORIDA 32073

*[Inspector Signature]*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

3/4/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	076J						
92	076K						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pats*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY -0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701	Emergency light did not work.					X
92	702	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object.					X
92	702A						
92	703	Emergency lights do not work. Electrical receptacle by classroom sink is not a GFCI and polarity is reversed.					X
92	703A						
92	704						
92	704A						
92	705A	Fire extinguisher is covered by material.					X
92	705B						
92	706						
92	706A						
92	707						
92	707A						
92	707B						
92	708	Emergency light does not work.					X
92	708A						
92	708B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pata*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY -0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	709	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	709A						
92	710	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	710A						
92	712	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object					X
92	712A						
92	713						
92	713A						
92	714						
92	714A						
92	714B						
92	715						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yours Pat*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY -0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	716A						
92	716B						
92	716C						
92	717						
92	717A						
92	718	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	718A						
92	719						
92	719A						
92	720						
92	720A						
92	721						
92	724						
92	724A						
92	750						
92	750A						
92	751						
92	751A						
92	751B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: KEYSTONE HEIGHTS ELEMENTARY -0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

*[Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

5/14/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	751C						
92	760						
92	760A						
92	770						
92	770A						
92	771						
92	771A						
92	772						
92	772A						
92	773	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object					X
92	773A						
92	774	Fire extinguisher needs to be hung on the wall.					X
92	774A						
92	722						
92	722A						
92	722B						
92	722C						
92	722D						
92	001A	This portable is a restroom. Did not inspect.					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY -0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

*Gene Pate*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

5/14/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pate*

2/26/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: LAKE ASBURY ELEMENTARY - 0451  
 2901 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	009						
92	009A						
92	010						
92	010A						
92	010B						
92	011	Bathroom fan does not work.					X
92	011A						
92	012	Emergency lights not working.					X
92	012A						
92	013						
92	013A						
92	013B						
92	014	Receptacle behind microwave needs to be GFCI protected.					X
92	014A						
92	015						
92	015A						
92	015B						
92	016	Back door is blocked by teachers desk and other tables. Must keep back door clear at all times.					X
92	016A						
92	018						
92	018A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

2/26/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY ELEMENTARY - 0451  
 2901 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	018B						
92	039A						
92	039B						
92	039C						
92	040	Fire extinguisher partially blocked. It needs to be kept clear at all times.					X
92	040A						
92	041	Need to repair electrical box beside microwave. It is pulled out of wall. Exhaust fan does not work in bathroom.					X
92	041A						
92	042						
92	042A						
92	043						
92	043A						
92	044	Electrical panel was blocked by baskets must be kept cleared. Paper was hanging over fire alarm pull station must be visible at all times.					X
92	044A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: LAKE ASBURY ELEMENTARY - 0451  
 2901 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE: 2/26/2023  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	045	Portable has no DCA sticker. Portable has been repainted but fire extinguisher has never been hung back up.		X			X
92	046	Back exit is blocked by desk and large ball.					X
92	046A						
92	046B						
92	048						
92	048A						
92	048B						
92	069						
92	069A						
92	071	Fan does not work in restroom.					X
92	071A						
92	071B						
92	072	Handrail and loop is loose. Needs to be tightened on ramp at the bottom.					X
92	072A						
92	073						
92	073A						
92	074						
92	075	No exhaust fan in restroom.					X
92	075A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKE ASBURY ELEMENTARY - 0451

2901 SANDRIDGE ROAD

GREEN COVE SPRINGS, FL 32043

*Jerry Pate*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

2/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	075B						
92	076	Need to remove bush going up ramp in between ramp and building. 2023 Bush still there between ramp - second-year violation.					X
92	076A						
92	077						
92	077A						
92	079						
92	079A						
92	079B						
92	079C						
92	080						
92	080A						
92	081						
92	081A						
92	082						
92	082A						
92	084	Has no DCA sticker and no documentation of missing sticker. Holes by electrical panel has not been repaired and teacher still blocking electrical panel. The GFCI by sink has been repaired.		X			X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT:

CLAY

FACILITY:

LAKE ASBURY ELEMENTARY - 0451

2901 SANDRIDGE ROAD

GREEN COVE SPRINGS, FL, 32043

*Young Patis*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

2/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	084A						
92	086	Electrical panel was blocked by storage box and back door drags back ramp.					X
92	086A						
92	087	DCA STICKER IS MISSING.		X			
92	087A						
92	088	DCA STICKER MISSING. HAS DOCUMENTATION FOR STICKER.					
92	088A						
92	089						
92	089A						
92	090	DCA STICKER MISSING. HAS DCA DOCUMENTATION. One ceiling tile needs replacing.					X
92	090A						
92	091						
92	091A						
92	093						
92	093A						
92	094	Electrical panel is blocked. Must keep clear area in front of electrical panel at all times. Relocate stand blocking electrical panel.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKE ASBURY ELEMENTARY - 0451

2901 SANDRIDGE ROAD

GREEN COVE SPRINGS, FL 32043



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

2/26/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	094A						
92	094B						
92	095						
92	095A						
92	096						
92	096A						
92	085	This portable is the clinic. All GFCI breakers or receptacles labeled as GFCI are not protected.					X
92	085A						
92	085B						
92	085C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKESIDE ELEMENTARY - 0352

2752 MOODY ROAD

ORANGE PARK, FL 32073

*Jerry Parks*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

4/8/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010	Fire extinguisher was not located within five feet of a door. -- 2nd year violation					X
92	011	2023 fire extinguisher is not located within 5 feet of a door This is a 2nd year violation.  An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical					X
92	012						
92	012A						
92	013						
92	014	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	015						
92	016	Emergency light did not work.					X
92	017						
92	018						
92	018A						
92	019						
92	019A						
92	020						
92	021						
92	021A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKESIDE ELEMENTARY - 0352

2752 MOODY ROAD

ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *Yous Pater*

BUILDING INSPECTION DATE: 4/8/2023

4/8/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	022	Fire extinguisher is not within 5 feet of the door. This is a 2nd year violation.					X
92	023						
92	024						
92	025						
92	026	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	027	Emergency light did not work.					X
92	042A	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	042B						
92	044	Corner support block of portable is being washed out, concrete block is tilted.					X
92	044A						
92	045						
92	045A						
92	046						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
 AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jane Parks*

4/8/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: LAKESIDE ELEMENTARY - 0352  
 2752 MOODY ROAD  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	046A	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide					X
		The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					
92	047	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) You must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
		The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					
92	047A	Exit ramp has a gate that blocks the required egress path. This gate needs to be removed.					
92	047B						
92	047C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: LAKESIDE ELEMENTARY - 0352  
 2752 MOODY ROAD  
 ORANGE PARK, FL 32073

*Jays Park*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

4/8/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	048	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	048A						
92	051A	One of the two emergency lights did not work.					X
92	051B						
92	051C						
92	052						
92	052A						
92	053						
92	053A						
92	054	Both emergency lights did not work.					X
92	054A						
92	055						
92	055A						
92	056						
92	056A						
92	060						
92	060A						
92	061						
92	061A						
92	062						
92	062A						
92	063	Emergency light did not work.					X
92	063A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

4/8/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE ELEMENTARY - 0352  
 2752 MOODY ROAD  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	043						
92	57	Restrooms					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MCRAE ELEMENTARY - 0511  
 6770 COUNTY ROAD 315 C  
 KEYSTONE HEIGHTS, FL 32656

*[Handwritten Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

5/14/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	401	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	401A						
92	401B						
92	402						
92	402A						
92	403						
92	403A						
92	403B						
92	404						
92	405						
92	406						
92	406A						
92	407						
92	407A						
92	408						
92	408A						
92	701	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pate*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** MCRAE ELEMENTARY - 0511  
 6770 COUNTY ROAD 315 C  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	702	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	702A						
92	703						
92	703A						
92	704						
92	704A						
92	705						
92	706						
92		An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	707						
92	708						
92	708A						
92	801						
92	801A						
92	802						
92	802A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND**

**FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yang Pato*

5/14/2023

FISCAL YEAR: 2022/2023  
DISTRICT: CLAY  
FACILITY: MCRAE ELEMENTARY - 0511  
6770 COUNTY ROAD 315 C  
KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	803	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	803A						
92	804						
92	804A						
92	806						
92	806A						
92	821						
92	821A						
92	821B						
92	823	Fire alarm pull station shield is blocked by cabinet and cannot open it. Must relocate cabinet so you have full access to pull station. This is a second year violation. This will be reported to the Fire Marshall.					X
92	823A						
92	823B						
92	824	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	825						
92	825A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MCRAE ELEMENTARY - 0511  
 6770 COUNTY ROAD 315 C  
 KEYSTONE HEIGHTS, FL 32656

*Jerry Pate*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

5/14/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	826	The fire extinguisher was blocked by balls hanging on the wall. Please relocate rubber balls so the fire extinguisher is assessable at all times.					X
92	827						
92	828A						
92	828B						
92	842						
92	842A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: MIDDLEBURG ELEMENTARY - 0271

3958 MAIN STREET

MIDDLEBURG, FL 32068

*Yang Peters*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

2/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	023						
92	023A						
92	024						
92	024A						X
92	025	Storage room.					
92	025A						
92	035						
92	037						
92	037A						
92	038						X
92	039	Emergency light did not work.					
92	040						
92	040A						
92	041						
92	041A						
92	043						
92	043A						
92	055						
92	055A						
92	057						
92	057A						
92	059						
92	059A						
92	064						
92	064A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG ELEMENTARY - 0271  
 3958 MAIN STREET  
 MIDDLEBURG, FL 32068

*Jerry Parks*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

2/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	065A						
92	065B						
92	068						
92	068A						
92	069	Back exit is blocked by desk must keep a clear path to the exit at all times.					X
92	069A						
92	026A						
92	026B						
92	029A						X
92	029B	Emergency light is blocked by storage on top of cabinet.					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** MONTCLAIR ELEMENTARY - 0381  
 2398 MOODY ROAD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:** 1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021						
92	022	Emergency light does not work.					X
92	023						
92	023A						
92	024	One of the exits is blocked by a desk. Must keep egress path clear at all times.					X
92	024A						
92	025A						
92	025B						
92	026	The wood ramp does not have the correct handrail. Install correct handrail to meet ADA.				X	X
92	027						
92	028						X
92	028A	GFCI in restroom is broken needs to be replaced.					
92	029						
92	029A	Back door is blocked by students desk must remove and have a clear path to the door					X
92	030						
92	030A	Front door was blocked by rolling cabinet.					X
92	031	Emergency light does not work and there is posterboard stapled to the ceiling and too much paper on the walls. This well exceeds the 20% rule.					X
92	032						
92	032A						
92	033						
92	033A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MONTCLAIR ELEMENTARY - 0381  
 2398 MOODY ROAD  
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *Jerry Baker*  
 BUILDING INSPECTION DATE: 1/29/2023  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	034	Door is blocked by chair from teachers desk. Need to have a clear path.					X
92	035						
92	036	Emergency light does not work.					X
92	036A						
92	036B						
92	037						
92	037A						
92	038						
92	039	Door is falling off hinges.					X
92	039A						
92	039B						
92	040						
92	041						
92	042	Back door was blocked by refrigerator and vacuum cleaner.					X
92	043	Shelf was leaning against fire extinguisher. Please find somewhere to store shelf.					X
92	044						
92	045	Electrical panel is blocked by printer.					X
92	046A						
92	046B	Emergency light does not work in back room.					X
92	047						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**


F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MONTCLAIR ELEMENTARY - 0381  
 2398 MOODY ROAD  
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: 

6/7/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
4		Water fountain on right is not working. Repair/replace as needed. (SREF 5.13(b) Plumbing 9.) Drinking fountains shall be maintained in an operational condition at all times.					X
4	Exterior	Picnic tables/benches need repairs/replacement. SREF 5.2(6) Wood. Structural wood, casework and cabinets shall meet the following minimum casualty safety and sanitation requirements for structural members, framing, benches, tables, etc. shall be maintained in a safe condition and free from hazards, including loose fastenings, wood rot, chips, splits, cracks and wood-destroying insects.					X
Playgrounds		The sand under the playground equipment needs to be refilled. (SREF 5.2(s)5.) The ground under any playground equipment provided shall be resilient material, either unitary or loose-laid, and maintained to prevent injury.					X
	104 Staff Restroom	Faucet on right side of sink does not work. Repair/replace as needed. (SREF 5.16(b) Plumbing.) Water closets, urinals, lavatories, faucet, flush valves, dispensers, partitions, lower half of walls and floors shall be maintained in a clean and sanitary condition at all times.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yany Palerm*

3/25/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF VILLAGE ELEMENTARY - 0621  
 410 OAKLEAF VILLAGE PARKWAY  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	901	Emergency lights do not work. Emergency light by front doors blocked by hanging posters from ceiling must be removed. Bathroom is still being used for storage with no heat detector. light fixture in bathroom hanging from ceiling is loose. Insignia sticker does not match paperwork.		X			X
92	901A						
92	903						
92	903A						
92	905	Bathroom being used for storage with no heat detector.					X
92	905A						
92	906	Emergency light does not work.					X
92	906A						
92	907						
92	907A						
92	908	DCA sticker should be MB E 010902. Missing certification sticker.		X			X
92	908A						
92	909	Water spot on ceiling tile near back door. Emergency lights are not working.					X
92	909A						
92	910	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	910A						
92	911	GFCI in bathroom and by classroom sink are not wired correctly. Tester says hot and ground reversed.					X
92	911A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF VILLAGE ELEMENTARY - 0621  
 410 OAKLEAF VILLAGE PARKWAY  
 ORANGE PARK, FL 32065

*[Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	912						
92	912A						
92	913						
92	913A						
92	914	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	914A						
92	916						
92	916A						
92	902						
92	904						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

*Greg Park*

1/2/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK ELEMENTARY - 0201  
 1401 PLAINFIELD AVENUE  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021						
92	021A						
92	022A						
92	022B						
92	023	Electrical panel is blocked. Must keep a clear opening to the electrical panel at all times.					X
92	023A						
92	024						
92	034	Back exit was blocked by boxes. Must keep a clear path to the door at all times.					X
92	034A						
92	035	Back exit was blocked by materials. Must keep a clear path to the door at all times.					X
92	035A						
92	036						
92	036A						
92	037						
92	038	Emergency light does not work.					X
92	038A						
92	041						
92	041A						
92	042						
92	042A						
92	043						
92	044						
92	044A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Rato*

1/2/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK ELEMENTARY - 0201  
 1401 PLAINFIELD AVENUE  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	045						
92	050						
92	050A						
92	051						
92	051A						
92	052						
92	052A						
92	053						
92	054						
92	039A						
92	039B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jos Lab*

9/25/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: PATERSON ELEMENTARY - 0471  
 5400 PINE AVENUE  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
91	001						
91	001A						
92	002						
92	002A						
91	003	NO HEAT DETECTORS IN BIG CLOSET. FAN DOES NOT WORK AND LIGHT ON FAN IS BROKEN.				X	X
92	003A						
92	003B						
92	004A						
92	004B						
92	005	NEED HEAT DETECTOR IN STORAGE ROOM. NO DCA STICKER IN PORTABLE AND DID NOT SEE ANY DCA STICKER DOCUMENTS POSTED.		X		X	X
92	006	OUTSIDE GFCI NOT WORKING, EMERGENCY LIGHTS NOT WORKING.				X	X
92	006A						
92	007						
92	007A						
92	008	EMERGENCY LIGHTS DO NOT WORK. THE BATHROOM FAN DOES NOT WORK. NO HEAT DETECTORS IN LARGE STORAGE ROOM.				X	X
92	011	NO DCA STICKER IN PORTABLE AND DID NOT SEE ANY DCA STICKER DOCUMENTS POSTED.		X			
92	011A						
92	013						
92	013A						
92	014						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

*George P. [Signature]*

9/25/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: PATERSON ELEMENTARY - 0471  
 5400 PINE AVENUE  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	014A						
92	014B						
92	015	NO HEAT DETECTORS IN BIG CLOSET.				X	X
92	015A						
92	015B						
92	016	NO HEAT DETECTORS IN BIG CLOSET. ROTTING SIDING AT RAMP.				X	X
92	016A						
92	016B						
92	017						
92	017A						
92	018	NO HEAT DETECTORS IN BIG CLOSET.				X	X
92	018A						
92	021						
92	021A						
92	022						
92	022A						
92	023						
92	023A						
92	024	ROTTING SIDING IN SEVERAL PLACES.				X	X
92	024A						
92	025						
92	025A						
92	026	NO HEAT DETECTORS IN BIG CLOSET. EMERGENCY LIGHT DOES NOT WORK.				X	X
92	026A						
92	026B						
92	027						
92	027A						
92	027B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: PATERSON ELEMENTARY - 0471  
 5400 PINE AVENUE  
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:



9/25/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	028	NEED HEAT DETECTOR IN STORAGE ROOM, BACK DOOR EXIT IS BLOCKED!! CLEAR EXIT PATH.				X	X
92	028A						
92	028B						
92	029	SIDDING IS ROTTING ALONG RAMP.				X	X
92	029A						
92	030						
92	030A						
92	041						
92	041A						
92	042						
92	042A						
92	043	BATHROOM FAN DOES NOT WORK. THERE IS WATER ON THE FLOOR BY FILING CABINET, COULD NOT SEE WHERE THE WATER IS COMING FROM. SEE PICTURES.				X	X
92	043A						
92	044	EMERGENCY LIGHT BATTERY IS VERY WEAK.					X
92	044A						
92	044B						
92	045						
92	045A						
92	045B						
92	046						
92	046A						
92	046B						
92	047						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: PATERSON ELEMENTARY - 0471  
 5400 PINE AVENUE  
 FLEMING ISLAND, FL 32003

*Jerry P. [Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

9/25/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	047A						
92	048						
92	048A						
92	048B						
92	049						
92	049A						
92	050						
92	050A						
92	050B						
92	051	NO HEAT DETECTOR IN STORAGE ROOM. SEE PICTURE.				X	X
92	051A						
92	051B						
92	052						
92	053						
92	053A						
92	054						




**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 CLAY  
 RIDEOUT ELEMENTARY - 0541  
 2065 APALACHICOLA BOULEVARD  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**



1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	10						
92	010A						
92	011	Emergency light does not work.					X
92	011A						
92	012	Emergency light does not work.					X
92	012A						
92	013						
92	013A						
92	014	Emergency light does not work.					X
92	014A						
92	020						
92	020A						
92	021						
92	021A						
92	022						
92		Back door needs a clear pathway, leading to the door, move one of the desk/tables.					X
92	022A						
92	022B						
92	022C						
92	025						
92	025A						
92	025B						
92	023A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 CLAY  
 RIDEOUT ELEMENTARY - 0541  
 2065 APALACHICOLA BOULEVARD  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*  
 1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	023B						
92	023C						
92	023D						
92	023E						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW ELEMENTARY - 0401  
 421 JEFFERSON AVENUE  
 ORANGE PARK, FL 32065

*Greg [Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

1/30/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	711A						
92	711B						
92	711C						
92	712						
92	712A						
92	714						
92	714A						
92	715	Emergency light did not work.					X
92	715A						
92	717	Back exit is blocked by cabinet. FIRE EXTINGUISHER is under sink cabinet must be mounted within 5 feet of door.					X
92	717A						
92	718						
92	718A						
92	728						
92	728A						
92	729	Emergency light did not work.					X
92	729A						
92	730						
92	730A						
92	731	Emergency light does not work. Bathroom light does not work. Several light fixtures are missing covers and bulbs.					X
92	731A						
92	732						
92	732A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**INSPECTOR SIGNATURE:**



**BUILDING INSPECTION DATE:**

1/30/2023

**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW ELEMENTARY - 0401  
 421 JEFFERSON AVENUE  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	733						
92	734						
92	734A						
92	735						
92	735A						
92	737						
92	737A						
92	741						
92	742	Electrical panel is blocked by items must keep clear access to panel at all times. Back doors blocked by teachers chair and boxes of storage supplies. Must keep clear access to exit at all times. Emergency light does not work.					X
92	742B						
92	743						
92	744	Emergency light does not work. Bathroom light does not work. Several light fixtures are missing covers and bulbs.					X
92	745						
92	746	Items hanging on fire alarm pull station must remove and keep clear at all times.					X
92	749						
92	751						
92	754						
92	754A						
92	755	Emergency light does not work. Bathroom light does not work. Several light fixtures are missing covers and bulbs.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**


F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**INSPECTOR SIGNATURE:**



**BUILDING INSPECTION DATE:**

1/30/2023

**PORTABLE INSPECTION DATE:**

1/30/2023

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: RIDGEVIEW ELEMENTARY - 0401

421 JEFFERSON AVENUE

ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	755A						
92	756						
92	756A						
92	758						
92	758A						
92	759	Electrical cabinet blocked by book cabinet.					X
92	759A						
92	760						
92	760A						
92	760B						
92	772						
92	772A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**INSPECTOR SIGNATURE:**



**BUILDING INSPECTION DATE:**

6/7/2023

**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: RIDGEVIEW ELEMENTARY - 0401

421 JEFFERSON AVENUE

ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	602		The faucet is dripping and the water fountain is not working. Repair/replace fixtures as needed. SREF 5.2(16)(b) Plumbing, drinking fountains shall be maintained in an operational condition at all times.				X
	702		The water fountain is not working. Repair/replace fixtures as needed. SREF 5.2(16)(b) Plumbing, drinking fountains shall be maintained in an operational condition at all times.				X
	747 Exterior Walkway		The water fountain (located outside near portable 747) unit on the right is not working. Repair/replace as needed. SREF 5.2(16)(b) Plumbing, drinking fountains shall be maintained in an operational condition at all times.				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**



6/7/2023

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: RIDGEVIEW ELEMENTARY - 0401  
 421 JEFFERSON AVENUE  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Garden Deck at Front of Administration		Repair or replace the deck/ pergola structure. SREF 6.2(6) Wood. Structural wood, casework and cabinets shall meet the following minimum casualty, safety, and sanitation requirements for structural members, framing, benches, tables, etc. Miscellaneous blocking; trim; handrails; guardrails; boardwalks; relocatable platform, ramps and steps; stage and gymnasium flooring; casework; cabinets and paneling, where provided, shall be maintained in a safe condition and free from hazards, including loose fastenings, wood rot, chops, splits, cracks and wood-destroying insects. Wood floors, where provided, shall be free of loose of broken boards, holes, uneven projections, protruding nails, splintered and other tripping hazards.				X
	737		The rear foundation pier blocks have been shifted and no longer supporting the rear side of the structure due to a waterline break that washed out the ground under the unit. This must be repaired prior to anyone occupying the classroom. The Director of Maintenance was notified at time of observance to shut off and repair the waterline and reinforce the foundation piers.				X

