

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: SWIMMING PEN CREEK ELEMENTARY - 0571

1630 WOODPECKER LANE

MIDDLEBURG, FL 32068

*Yous Park*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

3/4/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701						
92	703						
92	703A						
92	705	Electrical panel was blocked. Must keep clear at all times. Fire extinguisher is blocked behind a cabinet.					X
92	705A						
92	707						
92	707A						
92	801						
92	801A						
92	803	Back exit is blocked. Must keep a clear path at all times.					X
92	803A						
92	806	Back exit is blocked. Must keep a clear path to both exit at all times.					X
94	702						
94	704	Electrical panel is blocked by bookshelf, and both emergency lights do not work.					X
94	706A	Electrical panel was blocked. Must keep clear at all times.					X
94	706B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: SWIMMING PEN CREEK ELEMENTARY - 0571  
 1630 WOODPECKER LANE  
 MIDDLEBURG, FL 32068

*[Handwritten Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/4/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
94	706C						
94	706D						
94	706E						
94	706F						
94	708	Both exits are blocked by desk and tables. Must keep at least a 36 inch clear path to each door.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: THUNDERBOLT ELEMENTARY - 0531  
 2020 THUNDERBOLT ROAD  
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

*Yany Bates*

9/25/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701	ELECTRICAL PANEL BLOCKED.					X
92	701A						
92	702						
92	702A						
92	703						
92	703A						
92	704						
92	704A						
92	705						
92	705A						
92	706						
92	706A						
92	707	NO EVACUATION MAP BY DOOR.					X
92	707A						
92	710						
92							
92	711						
92	711A						
92	713						
92	721						
92	721A						
92	721B						
92	722						
92	722A						
92	722B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pate*

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: THUNDERBOLT ELEMENTARY - 0531  
 2020 THUNDERBOLT ROAD  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	723	CLASSROOM 723 HAS A HANGING ROPE APPARATUS HANGING FROM THE CEILING. CHECK WITH THE SCHOOLS BUILDING DEPARTMENT TO SEE IF THIS IS ALLOWED IN A PORTABLE. THE STORAGE ROOM HAS A LIGHT FIXTURE WITH THE COVER OPEN. NEED TO CLOSE LIGHT FIXTURE COVER.					X
92	723A						
92	723B						
92	724A						
92	724B						
92	724C						
92	725						
92	725A						
92	726						
92	726A	BUSH IS GROWING THROUGH RAMP RAILING. NEED TO REMOVE BUSH OUT OF THE RAMP.					X
92	727						
92	727A						
92	728	FAN DOES NOT WORK IN RESTROOM AND NO GLOBE ON LIGHT FIXTURE IN THE RESTROOM.					X
92	728A						
92	729						
92	730						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: THUNDERBOLT ELEMENTARY - 0531  
 2020 THUNDERBOLT ROAD  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	731	RESTROOM LIGHT DOES NOT WORK. GFI BY CLASSROOM SINK IN BROKEN. LINOLEUM IS COMING OFF THE WALL AT BASEBOARD IN RESTROOM.					X
92	731A						
92	732	BASEBOARD LAMINATE IN RESTROOM IS COMING OFF THE WALL. NEEDS REPAIR.					X
92	732A						
92	733						
92	733A						
92	734						
92	734A						
92	735	EMERGENCY LIGHT OVER MAIN DOOR NOT WORKING.					X
92	735A						
92	736						
92	737	OUTLET BY SINK IN CLASSROOM IS INCORRECT. NEEDS TO BE GFCI. SEE PICTURE.					X
92	737A						
92	738	REGULAR RECEPTACLE IN BATHROOM NEEDS TO BE GFCI.					X
92	738A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: THUNDERBOLT ELEMENTARY - 0531  
 2020 THUNDERBOLT ROAD  
 FLEMING ISLAND, FL 32003

*[Handwritten Signature]*

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	739	THERE IS A RUG IN FRONT OF CLASSROOM THAT IS A TRIPPING HAZARD. MUST REMOVE RUG. THE ELECTRICAL PANEL IS BLOCKED AND NOT VISIBLE. ELECTRICAL PANEL MUST BE ACCESSIBLE AND VISIBLE AT ALL TIMES. THE LIGHT FIXTURE IN THE RESTROOM IS MISSING COVER.					X
92	739A						
92	740						
92	740A						
92	741	THE ELECTRICAL PANEL IS BLOCKED AND NOT VISIBLE. ELECTRICAL PANEL MUST BE ACCESSIBLE AND VISIBLE AT ALL TIMES.					X
92	741A						
92	742	BATHROOM RECEPTACLE BY SINK IS NOT GFCI PROTECTED. RECEPTACLE MUST BE GFCI.					
92	742A						
92	744	THE ELECTRICAL PANEL IS BLOCKED AND NOT VISIBLE. ELECTRICAL PANEL MUST BE ACCESSIBLE AND VISIBLE AT ALL TIMES.					X
92	744A						
92	712A						
92	712B	THIS IS A STAND ALONE PORTABLE RESTROOM.					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Patis*

2/26/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: TYNES ELEMENTARY - 0501  
 1550 TYNES BOULEVARD  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001						
92	001A						
92	001B						
92	002						
92	002A						
92	002B						
92	003	2021 emergency light has been removed from the wall. Electrical panel is blocked. Need at least 3 feet clear space in front of electrical panel. 2023 violations still exist. This is a serious violation. Will report this to Fire Marshall.					X
92	004	Receptacle by classroom sink is not protected. Needs to be GFCI.					X
92	004A						
92	005						
92	005A						
92	006	Electrical panel is blocked by cabinet. Must keep panel clear at all times. This is a two-year violation.					X
92	006A						
92	007	Bathroom exhaust fan does not work. 2023 bathroom exhaust fan still does not work.					X
92	007A						
92	008						
92	008A						
92	009	Electrical panel is still blocked by cards and not visible. Electrical panel must be visible at all times					X
92	009A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: TYNES ELEMENTARY - 0501

1550 TYNES BOULEVARD

MIDDLEBURG, FL 32068

*Yany Roberts*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

2/26/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010	Electrical panel is blocked by posterboard. Electrical panel must be visible at all times.					X
92	022						
92	022A						
92	022B						
92	023						
92	023A						
92	023B						
92	024						
92	024A						
92	024B						
92	025	Emergency light does not work.					X
92	025A						
92	025B						
92	026						
92	026A						
92	026B						
92	027	Emergency light does not work.					
92	027A						
92	028						
92	028A						
92	029						
92	029A						
92	030	Keep back door clear it all times and keep electrical panel cleared all times.					X
92	030A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: TYNES ELEMENTARY - 0501  
 1550 TYNES BOULEVARD  
 MIDDLEBURG, FL 32068

*John Kato*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

2/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	041						
92	042	Two pieces of ceiling tile are sagging.					X
92	042A						
92	043	Emergency light did not work.					X
92	044						
92	044A						
92	045						
92	045A						
92	046						
92	046A						
92	046B						
92	047	Back door is blocked by boxes. Must keep a clear path to the back door.					X
92	048	Students desk are blocking the exit path to the back door. Must relocate desk to have a clear path to door.					X
92	048A						
92	049	Emergency light did not work.					X
92	049A						
92	061	Emergency light did not work.					X
92	061A						
92	063						
92	063A						
92	065						
92	065A						
92	066	Emergency light did not work.					X
92	066A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: TYNES ELEMENTARY - 0501

1550 TYNES BOULEVARD

MIDDLEBURG, FL 32068

*Greg Parks*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

2/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	067	Emergency light did not work.					X
92	067A						
92	068	Emergency light does not work.					X
92	068A						
92	062						
92	062A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Patis*

3/4/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001	Boxes and items stacked in front of electrical panel and blocking the fire alarm pull station. Area in front of electrical must be kept clear at all times. Fire alarm pull station must be visible and clear at all times. Relocate all boxes and items blocking area.					X
92	002						
92	003	Back door exit path is blocked by desk. Relocate desk.					X
92	003A						
92	004						
92	004A						
92	005						
92	005A						
92	006						
92	006A						
92	007	Electrical panel was blocked by boxes.					X
92	007A						
92	008	Emergency light does not work.					X
92	008A						
92	010						
92	010A						
92	011	Poster board over electrical panel. Must keep electrical panel visible at all times.					X
92	012						
92	013						
92	013A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Pate*

3/4/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	014	Need to remove small bush, growing up between transformer and building underneath portable eaves.					X
92	014A						
92	016						
92	016A						
92	017						
92	017A						
92	017B						
92	018	Back door was blocked. Must keep access to exit doors at all times. Also had the emergency bracket locking the door.					X
92	020						
92	020A						
92	022						
92	031						
92	031A						
92	033						
92	033A						
92	034						
92	034A						
92	035						
92	035A						
92	035B						
92	036						
92	036A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

*[Handwritten Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

3/4/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	037	Back doors blocked by items. Must keep a clear path to exit doors at all times.					X
92	037A						
92	038	Portable has eye hook in ceiling with set up for swing. Must remove the hook and apparatus.					X
92	038A						
92	039						
92	039A						
92	040	Teacher has created a non-monitored storage area with curtains from ceiling to floor. Must remove curtains.					X
92	040A						
92	041						
92	041A						
92	042						
92	042A						
92	043						
92	043A						
92	044	Back door was blocked. Make sure to have clear access at all times.					X
92	044A						
92	045	Rolling cart has been removed from last year, but the exit was blocked by emergency bracket. This item will be turned over to the fire marshal.					X
92	045A						
92	045B						
92	046	Portable being used for storage room.					X
92	046A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: WILKINSON ELEMENTARY - 0491

4965 COUNTY ROAD 218 W.

MIDDLEBURG, FL 32068

*Jens Peters*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

3/4/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	047	Back door is still blocked by rug and pillows. This is a second year violation will be turned over to the fire marshal.					X
92	047A						
92	047B						
92	048						
92	048A						
92	048B						
92	049						
92	049A						
92	049B						
92	050	Back door is blocked by a book cabinet. Must keep a clear access to exit doors at all times.					X
92	050A						
92	050B						
92	051	Poster board covering fire extinguisher pull station. Must keep pull station visible at all times.					X
92	051A						
92	052	This is the second year of the back door having the emergency bracket locking the door. This is a major violation will be contacted by the fire marshal.					X
92	052A						
92	052B						
92	061						
92	061A						
92	063	Electrical panel is blocked by green screen. Need to find a new place to store screen. Must keep electrical panel clear at all times.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

*Jean Pate*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/4/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	063A						
92	066						
92	066A						
92	066B						
92	068						
92	068A						
92	062						
92	062A						
92	062B						
92	062C						
92	064						
92	064A						
92	064B						
92	064C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: GREEN COVE JUNIOR HIGH - 0021  
 1220 BONAVENTURE AVENUE  
 GREEN COVE SPRINGS, FL 32043

Inspector Signature: *Yung Lata*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

10/30/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	070						
92	070A						
92	071						
92	071A						
92	074						
92	075						
92	075A						
92	076	Emergency light does not work.					
92	104	This protable is being used for storage. The electrical panel needs breaker space covers.					X
92	105	Emergency light does not work.					X
92	105A						
93	106						
92	106A						
92	106B						
92	106C						
93	107						
92	107A						
92	107B						
92	107C						
93	112	Has a non-approved rug in front of door. Creates a trip hazard.					X
93	113						
93	113A						
93	113B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

10/30/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: GREEN COVE JUNIOR HIGH - 0021  
 1220 BONAVENTURE AVENUE  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *Jay Peters*  
 BUILDING INSPECTION DATE: 7/24/2022  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	390						
92	390A						
92	391	BACK EXIT IS BLOCKED BY ROW OF DESK. MOVE ROW OF DESK OUT OF PATH OF EGRESS TO DOOR. MUST KEEP A 3 FOOT PATH TO DOOR.					X
92	391A						
92	392	BACK EXIT IS BLOCKED BY ROW OF DESK. MOVE ROW OF DESK OUT OF PATH OF EGRESS TO DOOR. MUST KEEP A 3 FOOT PATH TO DOOR.					X
92	392A						
92	393						
92	393A						
92	394						
92	394A						
92	401	EMERGENCY LIGHTS NOT WORKING.					X
92	401A						
92	402						
92	402A						
92	403	EMERGENCY LIGHTS NOT WORKING.					X
92	403A						
92	404	EMERGENCY LIGHTS NOT WORKING.					X
92	404A						
92	405	EMERGENCY LIGHTS NOT WORKING.					X
92	405A						
92	406						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Gary Patton*

7/24/2022

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	406A						
92	407						
92	407A						
92	408						
92	408A						
92	409						
92	409A						
92	410	EMERGENCY LIGHTS NOT WORKING.					X
92	410A						
92	421	BACK EXIT IS BLOCKED BY ROW OF DESK. MOVE ROW OF DESK OUT OF PATH OF EGRESS TO DOOR. MUST KEEP A 3 FOOT PATH TO DOOR.					X
92	421A						
92	422	BACK EXIT IS BLOCKED BY ROW OF DESK. MOVE ROW OF DESK OUT OF PATH OF EGRESS TO DOOR. MUST KEEP A 3 FOOT PATH TO DOOR.					X
92	423	EMERGENCY LIGHTS NOT WORKING NO EVACUATION MAP BY DOOR.					X
92	423A	NO EVACUATION MAP BY DOOR.					X
92	424						
92	425	EMERGENCY LIGH DOES NOT WORK. CEILING TILE NEEDS REPAIRING.					X
92	425A						
92	426	NEED COVER OVER LIGHT FIXTURE.					
92	426A						X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

*Jess Park*

BUILDING INSPECTION DATE:

7/24/2022

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKE ASBURY JUNIOR HIGH - 0481

2851 SANDRIDGE ROAD

GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	427	EMERGENCY LIGHTS NOT WORKING RR BEING USED FOR STORAGE WITH NO HEAT DETECTOR.					X
92	427A						
92	428						
92	428A						
92	427						
92	427						
92	430	GREEN HOUSE -DID NOT INSPECT.					
92	430A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073


INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE: 7/24/2022  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701	2022 - THERE WAS NO EVACUATION MAP PLACED BY DOOR.					X
92	701A						
92	701B						
92	702	2022 - EMERGENCY LIGHT DOES NOT WORK. NEED TO REPLACE.					X
92	702A						
92	703	NEED TO REMOVE BUSHES GROWING THROUGH THE FRONT DOOR RAMP.					X
92	703A						
92	703B						
92	704	2022 - THERE WAS NO EVACUATION MAP PLACED BY DOOR.					X
92	704A						
92	705						
92	705A						
92	705B						
92	705C						
92	706	2022- THERE IS A MISSING FLOOR TILE BY BACK DOOR. MUST REPLACE MISSING TILE. THERE WAS NO EVACUATION MAP PLACED BY DOOR.					X
92	706A						
92	707						
92	707A						
92	708						
92	708A						
92	708B						
92	721						
92	722						
92	723	2022 - THERE WAS NO EVACUATION MAP PLACED BY DOOR.					X
92	723A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**BUILDING INSPECTION DATE:** 7/24/2022  
**PORTABLE INSPECTION DATE:**

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	731						
92	731A						
92	732	OVERGROWN BUSHES AROUND AND NEXT TO PORTABLE NEEDS TO BE EITHER CUT BACK OFF THE BUILDING OR REMOVED. THE BUSHES ARE CAUSING THE SIDING TO ROT.					
92	732A						
92	733	NEED TO REMOVE BUSHES GROWING THROUGH THE FRONT DOOR RAMP. THIS IS A SECOND YEAR VIOLATION!!					X
92	733A						
92	734	2022 - THERE WAS NO EVACUATION MAP PLACED BY DOOR. THIS PORTABLE IS BEING USED FOR A WEIGHT ROOM.					X
92	735						
92	791	2022 RECEPTACLE BY WATER FOUNTAIN IS NOT GFCI PROTECTED. THIS IS A SECOND YEAR VIOLATION!!!					X
92	791A						
92	791B						
92	791C						
92	793	RECEPTACLE ON BOTH SIDES OF SINK ARE NOT GFCI PROTECTIVE. ALL RECEPTACLES SHO2W AN OPEN GROUND. THIS NEEDS TO BE FIXED ASAP AS IT IS A DANGEROUS VIOLATION!!!					X
92	793A						
92	794						
92	794A						
92	794B						
92	794C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:** 7/24/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	710						
92	710A						
92	710B						
92	737						
92	737A						
92	737B						
92	745	THIS PORTABLE IS BEING USED FOR A LOCKER ROOM.					X
92	745A						
92	745B						
92	745C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

*[Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	601	Bathroom being used for storage with no smoke detector. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	601A						
92	602	Bathroom being used for storage with no smoke detector. Emergency lights are not working.					X
92	602A						
92	603	Bathroom being used for storage with no smoke detector.					X
92	603A						
92	604						
92	604A						
92	605	Bathroom light fixture missing cover.					X
92	605A						
92	606	Emergency lights are not working. Bathroom being used for storage with no smoke detector.					X
92	606A						
92	607						
92	607A						
92	608	Bathroom is being used for storage with no smoke detector.					X
92	608A						
92	609						
92	609A						
92	610	Bathroom being used for storage with no smoke detector.					X
92	610A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

*James R. [Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	611	Bathroom being used for storage with no smoke detector. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	611A						
92	612						
92	612A						
92	613						
92	613A						
92	614	Light in bathroom does not work. Fan has bearing squealing.					X
92	614A						
92	615						
92	615A						
92	616	Bathroom being used for storage with no smoke detector.					X
92	616A						
92	617	Bathroom being used for storage with no smoke detector. 2023 violation has not been corrected. Bathroom is full of trash and boxes. This is a serious violation will be reported to the fire marshal.					X
92	617A						
92	618	Bathroom being used for storage with no smoke detector.					X
92	618A						
92	619	Bathroom being used for storage with no smoke detector.					X
92	619A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT:

FACILITY:

CLAY  
 OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	620	Bathroom light fixture does not have a cover. Bathroom being used for storage with no smoke detector.					X
92	620A						
92	702						
92	704						X
92	704A	Bathroom fan not working.					
92	708						
92	708A						
92	709						
92	709A						
92	710						
92	710A						
92	711						
92	711A						
92	712	Bathroom being used for storage closet with no smoke detector.					X
92	712A						
92	713						
92	713A						
92	714	back door is dragging steps. needs to be corrected					X
92	714A						
92	801						
92	807						
92	807A	Bathroom being used for storage has no smoke detector.					X
92	809						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *James Palmer*  
 BUILDING INSPECTION DATE: 3/25/2023  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	809A						
92	810						
92	810A	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	811						
92	811A						
92	821						
92	821A						
92	823						
92	823A	Emergency light does not work.					X
92	824						
92	824A	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	808A						
92	808B	RESTROOM					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jan Pats*

12/31/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK JUNIOR HIGH - 0361  
 1500 GANO AVENUE  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	501						
92	505	Emergency light did not work and electrical panel was blocked by cabinet.					
92	505A						
92	505B						
92	510						
92	511						
92	703						
92	503						
92	503A						
92	503B						
92	504	Found the fire extinguisher laying on the floor with a bracket pulled out of the wall and the pin out of the fire extinguisher. Needs to be replaced.					
92	504A						
92	507						
92	507A						
92	507B						
92	509A	Exits are blocked by desk, must rearrange desk to keep exit cleared at all times.					
92	509B						
92	516						
92	706						
92	706A						
92	706B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK JUNIOR HIGH - 0361  
 1500 GANO AVENUE  
 ORANGE PARK, FL 32073

*Jerry Pate*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

12/31/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	708	Outlet by kitchen sink is not a GFCI and both outlets by handwashing sinks in classroom are not GFCI.					
92	708A						
92	708B						
92	710						
92	710A						
92	710B						
92	702						
92	704						
92	704A						
92	704B						
92	704C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Patus*

3/4/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON JUNIOR HIGH - 0371  
 5025 COUNTY ROAD 218  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	002						
92	003	Back doors blocked by desk. Need to keep a clear path to exit doors at all times. Back stairs bottom step dirt needs to be filled in more than 7 1/4 inches.					X
92	004						
92	005						
92	005A						
92	006	Fire extinguisher on floor in the middle of the room needs to be within 5 feet of door and hung on the wall.					X
92	007	Back exit is blocked by chairs and not approved rug. Electrical panel was blocked by bookshelf. Paper trash everywhere creates a fire hazard.					X
92	007A						
92	008						
92	009						
92	009A						
92	010						
92	011						
92	011A						
92	011B						
92	021						
92	022						
92	022A						
92	023	Emergency light did not work.					X
92	024						
92	025	Emergency light did not work.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Patis*

3/4/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: WILKINSON JUNIOR HIGH - 0371  
 5025 COUNTY ROAD 218  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	026	Rug by the back door needs replacing starting to curl up, creating a tripping hazard.					
92	027	No DCA sticker or document stating DCA number. Need plate over data box.		X			X
92	040	Electrical panel is blocked by fake plant. Must have access to electrical panel times.					X
92	041	Electrical box outside the portable cover is old and has knock out missing with open wires and needs to be sealed up.					
92	041A						
92	043						X
92	043A	This portable is being used for a dental office.					
92	042	Two doors are blocked. One with a chair, the other one with the coat rack. Must keep a clear access to exit doors at all times. Dressing room light switch does not have a cover plate.					X
92	042A						
92	042B						
92	042C						
92	048						
92	048A						
92	048B						
92	096						
92	096A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*  
 10/29/2022

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30243


Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	007						
92	007A						
92	007B						
92	017						
92	018						
92	018A						
92	019						
92	020	Palm tree growing up next to building needs to be removed .This violation still exists also emergency light does not .					X
92	032						
92	032A						
92	033						X
92	033A						
92	033B						
92	040			X			
92	041	No DCA Sticker and no documentation.					
92	041A						
92	042						
92	042A						
92	043						
92	043A						
92	043B						
92	044	Back exit is blocked by desk. Need to keep a clear path to excellent at all times.					X



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 320243

INSPECTOR SIGNATURE:  


BUILDING INSPECTION DATE: 10/29/2022  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	044A						
92	045						
92	045A						
92	046	Outside receptacle has no cover. Inside office has turned in to be storage room. Does not have a smoke detector.					X
92	046A						
92	046B						
92	047						X
92	047A	Emergency light does not work.					
92	048						
92	048A						
92	049	Need to rearrange the desk. Exit is blocked. Need to keep a clear path to the exit door at all times.					X
92	049A						
92	054						X
92	054A	Emergency light does not work.					
92	058						
92	005A						
92	005B						
92	008						X
92	008A	Emergency light does not work.					
92	008B						
92	008C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30243

INSPECTOR SIGNATURE:   
 BUILDING INSPECTION DATE: \_\_\_\_\_  
 PORTABLE INSPECTION DATE: 10/29/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	031	Portable has three exits. One set of stairs leads to a gate that is locked. Second set of stairs in the middle, leads to a ramp which has a pallet over the end so it is blocked and bushes are overgrown on ramp. Third set of stairs are the main set to the entrance and they are clear. Must keep all exit/egress pathways clear at all times.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: *[Signature]*

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 9/5/2022

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551

2233 VILLAGE SQUARE PARKWAY

FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010						
92	010A						
92	011						
92	011A						
92	012						
92	012A						
92	013						
92	014						
92	015	Emergency light has one light burned out.					X
92	020	GFCI receptacle at sink not working. It is a regular rec could be tied into GFCI down run. 2022 Regular receptacle is not GFCI between sinks this is the second year.				X	X
92	021						
92	022	A Plant is hanging in front of the electrical panel and emergency light. This is a direct code violation. The plant must be removed. A book stand and desk are blocking the back door egress. The book stand must be relocated and the desk rearranged to allow 36 inches of egress to back door.					X
92	022A						
92	023	2020 ALL VIOLATIONS WERE CORRECTED.					
92	024						
92	025						
92	030	NO EVACUATION MAP BY DOOR.					X
92	031	Emergency light does not work					X
92	032						
92	033	Emergency light does not work.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yong Park*

9/5/2022

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	034						
92	035	Rear door is blocked by desk and rolling cart. The rolling cart must be relocated and the desk rearranged to allow 36 inches of egress to back door.					X
92	041	Water is undermining portable. Has cracked sidewalk. Something will have to be done soon.				X	X
92	042						
92	043						
92	044	Electrical panel was covered by hanging decoration. Electrical panel must be visible at all times.					X
92	045						
92	046						
92	046A						
92	046B						
92	046C						
92	047						
92	047A						
92	047B						
92	047C						
92	047D						
92	049	2022 one light is out on the emergency lights.					X
92	050						
92	050A						
92	051						
92	051A						
92	052						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Roberts*

9/5/2022

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	052A						
92	053	Emergency light does not work.					X
92	053A						
92	060						
92	060A						
92	061						
92	061A						
92	062	Rear door is blocked by desk. The desk rearranged to allow 36 inches of egress to back door.					X
92	062A						
92	063	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks.					X
92	063A						
92	070						
92	070A						
92	071						
92	071A						
92	072						
92	072A						
92	073						
92	073A						
92	080						
92	080A						
92	081	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks. <b>This violation has not been corrected.</b>					X
92	081A						
92	082	Emergency light does not work					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

*John Pate*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE: 9/5/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	082A						
92	083						
92	083A						
92	084						
92	084A						
92	085	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks. Emergency light does not work.					X
92	085A						
92	086						
92	086A						
92	087	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks. Emergency light does not.					X
92	087A						
92	090	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks. This violation has not been corrected.					X
92	090A						
92	091						
92	092	This portable is being used for storage		X			
92	093	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks.					X
92	093A						
92	094						
92	094A						
92	095						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

*Jerry Pate*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE: 9/5/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	095A						
92	096	Back exit is blocked by a row of desks. Path of egress must be kept clear at all times. Relocate row of desks.					X
92	096A						
92	097						
92	097A						
92	040						
92	048	Need covers over fluorescent light fixtures. 2022 light fixture still need covers on them					X
92	027A	RESTROOMS-DID NOT INSPECT					
92	027B						
92	064A	RESTROOMS- DID NOT INSPECT					
92	064B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*S. R. Young*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001	Emergency light does not work.					X
92	002						
92	004						
92	006						
92	006A						
92	006B						
92	011						
92	012	Emergency light does not work.					X
92	012A						
92	013						
92	014						
92	015						
92	016						
92	017						
92	017A						
92	017B						
92	018						
92	018A						
92	019						
92	019A						
92	019B						
92	020						
92	020A						
92	020B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yung Pato*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	021A						
92	022						
92	022A						
92	023						
92	023A						
92	024						
92	024A						
92	025						
92	025A						
92	026						
92	026A						
92	027						
92	027A						
92	028						
92	028A						
92	028B						
92	050						
92	050A						
92	051						
92	051A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Hans Pate*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	052						
92	052A						
92	053						
92	053A						
92	054						
92	054A						
92	055						
92	055A						
92	056						
92	056A						
92	057						
92	057A						
92	058						
92	058A						
92	058B						
92	059	Exterior siding is in bad shape, needs immediate attention.					X
92	060						
92	060A						
92	060B						
92	061						
92	062	Emergency light does not work. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	062A						
92	062B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yenny Pata*

5/14/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	063	Emergency light does not work.					X
92	063A						
92	064						
92	064A						
92	065						
92	072	Electrical panel door hinges are broken and needs to be repaired. Cannot open electrical panel.					X
92	072A						
92	074						
92	074A						
92	078						
92	078A						
92	080						
92	082	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	082A						
92	084						
92	084A						
92	090						
92	090A						
92	090B						
92	091						
92	091A						
92	091B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL - 0311

900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

*James Pate*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

5/14/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	029						
92	029A						
92	029B						
92	029C						
92	056A	Restrooms - did not inspect.					
92	056B						
92	076A	Restrooms - did not inspect.					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: MIDDLEBURG HIGH SCHOOL - 0391

3750 COUNTY ROAD 220

MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *Jerry Potts*

BUILDING INSPECTION DATE:

2/25/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001						
92	007						
92	009						
92	009A						
92	031						
92	031A						
92	031B						
92	032						
92	032A						
92	032B						
92	033						
92	033A						
92	034						
92	035						
92	036						
92	036A						
92	036B						
92	041						
92	041A						
92	041B						
92	042	Emergency light did not work.					X
92	042A						
92	042B						
92	043						
92	044						
92	044A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Parks*

2/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	044B						
92	045						
92	045A						
92	045B						
92	046	Emergency light did not work.					X
92	046A						
92	046B						
92	051						
92	051A						
92	051B						
92	052						
92	052A						
92	052B						
92	053						
92	053A						
92	053B						
92	055						
92	055A						
92	060	Back exit is blocked by desk. Must relocate desk out of the exit path. 2023 back exit is still blocked. This is the second year of this violation.					X
92	061	Electrical panel blocked by construction paper.					X
92	061A						
92	062						
92	062A						
92	063						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Peters*

2/25/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	063A						
92	064						
92	064A						
92	065						
92	065A						
92	066	Fire extinguisher is blocked by a cabinet and it will not come off the bracket.					X
92	066A						
92	067						
92	067A						
92	070						
92	071						
92	071A						
92	072						
92	073						X
92	073A						
92	073B						
92	074						
92	074A						
92	074B						
92	075						
92	075A						
92	076						
92	076A						
92	076B						
92	077	Emergency light did not work.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**INSPECTOR SIGNATURE:**

*Yang Pats*

**BUILDING INSPECTION DATE:**

2/25/2023

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: MIDDLEBURG HIGH SCHOOL - 0391

3750 COUNTY ROAD 220

MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	077A						
92	077B						
92	077C						
92	077D						
92	078						
92	078A						
92	079						
92	079A						
92	079B						
92	079C						
92	080						
92	080A						
92	081						
92	082	Emergency lights did not work.					X
92	084	Emergency light did not work.					X
92	084A						
92	086						
92	088						
92	005	Emergency light does not work.					X
92	005A						
92	005B						
92	005C						
92	054A	One of the two exit lights do not work.					X
92	054B						
92	054C						
92	054D						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

*Yang Pater*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010						
92	010A						
92	011	Emergency lights are not working.					X
92	011A						
92	015						
92	015A						
92	015B						
92	015C						
92	015D						
92	016	Cabinet blocking front door with ramp. Fire extinguisher electrical panel and pull station being blocked by cabinet by the back door. Floor tile is missing need repairs.					X
92	016A						
92	021	Emergency light did not work.					X
92	021A						
92	022	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36"). The heat detector in the bathroom is hanging from the ceiling all the way down to the floor.					X
92	022A						
92	023						
92	023A						
92	024						
92	024A						
92	025						
92	025A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *Jay Patis*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	026	All walls are covered in paper. The paper should be removed.					X
92	026A						
92	030	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide. The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	030A						
92	31						
92	032						
92	033						
92	034	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	034A						
92	035	Open electrical box above electrical panel, covered by construction paper must find plate					X
92	036	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	040	Emergency lights are not working.					X
92	041						
92	041A						
92	042	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: OAKLEAF HIGH SCHOOL - 0661

4035 PLANTATION OAKS BOULEVARD

ORANGE PARK, FL 32065

*Yang Park*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

3/25/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	042A						
92	043						
92	043A						
92	044	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	045						
92	046						
92	046A						
92	050						
92	051						X
92	051A	Receptacle by classroom sink is not GFCI.					
92	052						
92	053						
92	053A						
92	053B						
92	054	Electrical panel has knockouts fans turned out. Angle needs to be repaired.					X
92	054A						
92	055	An object is blocking access to the electrical panel, or the electrical panel was covered by an object. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	056	Emergency lights not working.					X
92	060						
92	060A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jay Paton*

3/25/2023

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	061	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	062						
92	062A						
92	063	The back exit door was blocked by an object. Leading up to the door, there must be an egress path as wide as the door (36").					X
92	063A						
92	064						
92	065						
92	066	No evacuation map and emergency light does not work. There must be a emergency evacuation sheet properly placed by door.					X
92	020A	REST ROOMS					
92	020B						
92	027	RESTROOMS					
92	027A						
92	027B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101**

**AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
DISTRICT: CLAY  
FACILITY: ORANGE PARK HIGH SCHOOL - 0252  
2300 KINGSLEY AVENUE  
ORANGE PARK, FL 32073

*Gay Ratts*

INSPECTOR SIGNATURE:  
BUILDING INSPECTION DATE:  
PORTABLE INSPECTION DATE:

1/2/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	035	Printer was in front of electrical panel. Need to keep electrical panel clear.					X
92	035A						
92	036						
92	036A						
92	037	Emergency lights still do not work. This is the second year.					X
92	037A						
92	038						
92	038A						
92	039						
92	039A						
92	040	Emergency lights did not work and desks need to be rearranged to have clear egress to both doors.					X
92	040A						
92	045	Desk need to be rearranged at back door to allow 36 inch passive egress to the door.					X
92	045A						
92	049	Both emergency lights do not work.					X
92	049A						
92	050	Fire extinguisher is still not by the door. This is a second year violation.					X
92	050A						
92	051						
92	051A						
92	052						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

1/2/2023

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	052A						
92	053						
92	053A						
92	054						
92	055						
92	055A						
92	056	Emergency light still does not work. This is a second year violation.					X
92	059	Back exit is still blocked by rolling cart and also boxes. This is a second year violation.					X
92	060						
92	061						
92	061A						
92	061B						
92	061C						
92	062						
92	062A						
92	063						
92	063A						
92	064						
92	064A						
92	065	Electrical panel was blocked by a poster board and the back door is blocked by a row desk. Must keep a clear path to the exit door.					X
92	065A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Patis*

1/2/2023

<b>FISCAL YEAR:</b> 2022/2023
<b>DISTRICT:</b> CLAY
<b>FACILITY:</b> ORANGE PARK HIGH SCHOOL - 0252 2300 KINGSLEY AVENUE ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	066	Emergency light by back door does not work.					X
92	066A						
92	067						
92	067A						
92	013	In section B light switch missing plate by door and emergency lights do not work.					X
92	013A						
92	048	Emergency light does not work by back door. Light still does not work in back office.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

*Jerry Rabe*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	4	2023 Back exit is blocked by desk and storage items. Path to exit must be kept clear at all times. Receiptal by tub sink is not GFCI. Replace receiptal with a GFCI. Emergency light does not work.					X
92	004A						
92	004B						
92	005						
92	005A						
92	005B						
92	006						
92	006A						
92	007						
92	007A						
92	007B						
92	008						
92	008A						
92	009						
92	009A						
92	009B						
92	010	Emergency light does not work and they have a gasoline rotor tiller, stored inside classroom, which is not allowed.					X
92	010A						
92	011						
92	012	Bathroom light is not working.					X
92	012A						
92	021						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

*Greg Parks*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021A						
92	022	Electrical panel is being blocked. Need to have a clear path to the electrical panel.					X
92	022A						
92	023	Emergency light does not work.					X
92	023A						
92	024						
92	025						
92	025A						
92	025B						
92	026	Emergency light does not work.					X
92	026A						
92	026B						
92	027						
92	027A						
92	027B						
92	028						
92	028A						
92	029	2023 back exit is still blocked by bean bag, chair and storage beads. Are hanging from front door. Must remove the beads create a hazard.					X
92	029A						
92	029B						
92	029C						
92	031						
92	031A						
92	032						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *Jeung Park*  
 BUILDING INSPECTION DATE: 1/29/2023  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	032A						
92	033	Fire extinguisher is blocked by rolling display.					X
92	033A						
92	034						
92	034A						
92	041	Emergency light does not work.					X
92	041A						
92	043	Emergency light does not work.					X
92	043A						
92	044	Emergency light does not work.					X
92	044A						
92	045	Back exit is blocked by teachers desk, and other small desk must keep clear path.					X
92	046	Emergency light does not work.					X
92	046A						
92	047						
92	047A						
92	048	Emergency light did not work.					X
92	048A						
92	049						
92	049A						
92	050						
92	051	Hazardous plant near front door needs to be removed.					X
92	052	Back door is blocked. Hazardous plants by the portable need to be removed.					X
92	052A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Greg Potts*  
 1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	061						
92	061A						
92	062	Receptacle underneath sink which has an extension cord plugged into it coming to the top of the cabinet is not GFCI protected.					X
92	062A						
92	064						
92	065						
92	066						
92	067	Back exit is blocked by a display fire extinguisher is blocked by metal cabinet.					X
92	069						
92	069A						
92	070	Emergency light does not.					X
92	071	Missing ceiling tile in bathroom bathroom being used for storage. No smoke detector.					X
92	071A						
92	072	Portable being used for storage.					X
92	072A						
92	073						
92	073A						
92	081						
92	081A						
92	081B						
92	082						
92	082A						
92	082B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Patten*

1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	083						
92	083A						
92	083B						
92	084						
92	084A						
92	084B						
92	085						
92	085A						
92	085B						
92	086						
92	086A						
92	086B						
92	087						
92	087A						
92	087B						
92	088						
92	088A						
92	088B						
92	089						
92	089A						
92	089B						
92	090						
92	090A						
92	090B						
92	090C						
92	090D						
92	091						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

*[Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

1/29/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	091A						
92	091B						
92	103						
92	103A						
92	001						
92	001A						
92	001B						
92	001C						
92	001D						
92	001E						
92	001F						
92	001G						
92	003	Back exit is blocked by couch. Receptacle by sink is not GFCI protected. Emergency light does not work.					X
92	003A						
92	003B						
92	030	back door has emergency latch employed. Emergency light does not work.					X
92	030A						
92	030B						
92	030C						
92	030D						
92	030F						
92	068						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE:   
 BUILDING INSPECTION DATE: 1/29/2023  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	092A	Back door is not accessible must pass through second room into third room, but all doors were locked. Could not get to back door.					X
92	092B						
92	101A	This room is being used as a weight room with heavy weights.					X
92	101B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2022/2023  
**DISTRICT:** CLAY  
**FACILITY:** BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043

*[Handwritten Signature]*

11/2/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	016	This is a portable shed did not inspect.					
92	062	Emergency lights need replacing.					X
92	001	Portable is being used for a weight room.					
92	001A						
92	001B						
92	002						
92	002A						
92	003						
92	003A						
92	004						
92	004A						
92	005	A non - approved rug is in front of the door causing a tripping hazard.					X
92	005A						
92	006A	Emergency light by the ramp door does not work.					X
92	006B						
92	006C						
92	007	Emergency light not working.					X
92	007A						
92	008	Emergency light not working.					X
92	008A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: BANNERMAN LEARNING CENTER - 0111

608 MILL STREET

GREEN/COVE SPRINGS, FL 32043



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

11/2/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	009	Electrical panel is blocked-must keep electrical panel clear at all times, emergency light does not work. Back door is blocked and covered up by a sheet. Must keep clear egress path to the exit at all times.					X
92	009A						
92	010	Emergency light not working.					X
92	010A						
92	012						
92	012A						
92	013	This portable is the library.					
92	030	Receptacle by sink is not a GFCI. See picture.					X
92	030A						
92	030B						
92	030C						
92	032	Portable does not have a fire extinguisher.					X
92	033						
92	033A						
92	034	Timeout room being used for storage. No smoke detector.					X
92	034A						
92	035	There is a computer cable on the floor in front of the door creating a trip hazard. Must relocate!!!					X
92	035A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: BANNERMAN LEARNING CENTER - 0111

608 MILL STREET

GREEN COVE SPRINGS, FL 32043



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

11/2/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	036	Desk blocking back exit. Exit must be kept clear at all times.					X
92	036A						
92	036B						
92	037						
92	037A						
92	038	Emergency light not working.					X
92	038A						
92	039						
92	039A						
92	039B						
92	039C						
92	039D						
92	039E						
92	040						
92	040A						
92	042						
92	042A						
92	042B						
92	043						
92	043A						X
92	044	GFCI by sink does not trip with tester.					
92	044A	Plants around building and ramp need to be removed for safety of the school and to keep from damaging the building. See pictures. Portable has no fire extinguisher.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023  
 DISTRICT: CLAY  
 FACILITY: BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043



**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

11/2/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	056	Plants around building and ramp need to be removed for school safety and to keep from damaging the building. See pictures.					X
92	056A						
92	58						
92	058A						
92	011	GFCI by kitchen sink does not trip. See picture. This is a culinary classroom. Kitchen needs a rated fire extinguisher.					X
92	011A	This classroom is the culinary class. Both emergency lights do not work and one is propped open with a marker because it buzzes all the time.					X
92	014	Plants around building and ramp need to be removed for school safety and to keep from damaging the building. See pictures.					X
92	014A						
92	014B						
92	031	Plants around building and ramp need to be removed for school safety and to keep from damaging the building. See pictures.					X
92	031A	Plants around building and ramp need to be removed for school safety and to keep from damaging the building. See pictures.					X
92	031B						
92	031C						
92	050						
92	050A	This portable is the teachers lounge.					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT:


FACILITY:

CLAY

BANNERMAN LEARNING CENTER - 0111

608 MILL STREET

GREEN COVE/SPRINGS, FL 32043



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

11/2/2022

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	050B						
92	050C						
92	052						
92	052A						
92	052B						
92	060A	This portable is a restroom.					
92	060B	Did not inspect.					
92	061A	This portable is a restroom.					
92	061B	Did not inspect.					