

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 2/20/2023
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: CHARLES E. BENNETT ELEM. - 0071
 1 SOUTH OAKRIDGE AVENUE
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Multiple classroom storage closets throughout. Buildings with fire sprinkler systems are to remove (and maintain) all storage within 18 inches from under fire sprinkler head deflectors.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained, qualified, and certified person(s) acceptable to the AHJ. Service was due in January 2023.				X
	Kitchen		Electrical panel doors must remain closed to guard live parts. Adjust or replace panel doors to meet code requirements.				X
	1 Stage in Café		Stage lift access blocked. Remove stored items blocking access.				X
	117 Mechanical Room		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. This includes portable equipment on rollers per NFPA 70 110.26.				X
	120 Electrical Room		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. This includes portable equipment on rollers per NFPA 70 110.26.				X
	1624 Electrical Room		Electrical panel doors must remain closed to guard live parts. Adjust or replace panel doors to meet code requirements.				X
	925 Electrical Room		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58


FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: DISCOVERY OAKS ELEMENTARY
 950 OAKLEAF PLANTATION PARKWAY
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *[Signature]*
 BUILDING INSPECTION DATE: 2/27/2023
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023 DISTRICT: CLAY FACILITY: S. BRYAN JENNINGS ELEMENTARY - 0331 215 CORONA DRIVE ORANGE PARK, FLORIDA 32073	INSPECTOR SIGNATURE:  BUILDING INSPECTION DATE: 3/1/2023 PORTABLE INSPECTION DATE:
---	---

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS ELEMENTARY -0301
 335 SW PECAN STREET
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 3/15/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	8		Remove storage from areas within 2 feet of ceiling.				X
	20A		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	20D		Cover open electric boxes.				X
	228		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	923		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
3			The emergency escape windows in building 3 need to have signage marking them.				X
3			Remove all combustible material items within 30" vertical clearance and 18" horizontal clearance of cooking surface. Relocate fire extinguisher to a location where it will not be subject to heat or damage from the appliance. Residential-type appliances, such as stoves, hoods, refrigerators, washers, dryers, ovens and unit kitchens when used in classrooms, laboratories, lounges or shops, shall be maintained in a safe and secure condition at all times.				X
	Cafetorium /Stage		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	Media Center		Repair/replace ceiling tiles.				X
	Stage Lift		Chair lift at state access is blocked and the certification is expired.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

SK

4/17/2023

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: LAKE ASBURY ELEMENTARY - 0451
 2901 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	215		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	301		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	530		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	737		Could not open door. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	738		Could not open door. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	Kitchen		Cover open electric boxes.				X
	Outdoor Covered Area		No hibachi, grill, or other similar devices used for cooking, heating, or any other purpose shall be used or kindled on any balcony, under any overhanging portion, or within 20 feet (6 m) of any structure.				X
	Stage Stairs at RR 204		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	Stage Stairs at RR 208		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	Stage Storage Room		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: LAKESIDE ELEMENTARY - 0352
2752 MOODY ROAD
ORANGE PARK, FL 32073

INSPECTOR SIGNATURE:  **BUILDING INSPECTION DATE:** 3/8/2022
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

**SANITATION INSPECTION REPORT
 RD OF EDUCATION
 ULES S.R.E.F. - CHAPTER 5**

**& SANITATION INSPECTION
 1013.20 & NFPA 101
 AND**

**INSPECTION REPORT
 013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: MCRAE ELEMENTARY - 0511
 6770 COUNTY ROAD 315 C
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 4/12/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	119		Remove multiplug adapters.				X
	120		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	211		Expired fire extinguisher. Have tested.				X
	229		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. All electrical panels are to have a clearance of 36" in front and 30" wide and all panels are to be properly closed.				X
	507		Remove storage from areas within 2 feet of ceiling.				X
	517		Streamers are very low - potentially blocking exit and combustible.				X
	626		Remove storage from areas within 2 feet of ceiling.				X
	Administration Corridor		The artwork and teaching materials shall not exceed 20 percent of each wall area in a building that is not protected throughout by an approved sprinkler system.				X
	Administration Corridor		Remove decorations blocking the exit sign. Access to exits shall be marked by approved, readily visible signs.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained, qualified, and certified person(s) acceptable to the AHJ.				X
	Stage Chair Lift		State certifications are expired. Put in ticket with maintenance to have unit inspected and apply for current operating permit.				X

**SANITATION INSPECTION REPORT
 RD OF EDUCATION
 ULES S.R.E.F. - CHAPTER 5
 & SANITATION INSPECTION
 1013.20 & NFPA 101
 AND
 INSPECTION REPORT
 013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: MCRAE ELEMENTARY - 0511
 6770 COUNTY ROAD 315 C
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 4/12/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Stairs 202		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	Stairs 209		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:



3/14/2023

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: MIDDLEBURG ELEMENTARY - 0271
 3958 MAIN STREET
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	104		Repair/replace ceiling tiles.				X
	118A		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	127		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	133		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. Cap and label electrical box shown in photo.				X
	2 Story Building		The 2nd floor exit access stairway has a locked gate. Exits shall not be locked or blocked and shall remain accessible at all times while the building is occupied NFPA 101-15.7.3.1: It shall be the duty of Principals, teachers, or staff to inspect all exits and means of egress daily to ensure that all stairways, doors, windows, and other exits are in proper condition.				X
	3		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. Move chair and desk out of exit access.				X
	612		Remove storage from areas within 2 feet of ceiling.				X


COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE:

3/14/2023

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: MIDDLEBURG ELEMENTARY - 0271

3958 MAIN STREET

MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	636		Expired fire extinguisher. Have tested. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. All electrical panels are to have a clearance of 36" in front & 30" wide, and all panels are to be closed properly.				X
	7122		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	7125		Remove all storage in boiler rooms, or electrical equipment rooms. All electrical panels are to have a clearance of 36" in front & 30" wide, and all panels are to be closed properly.				X
	7147		Expired fire extinguisher. Have tested.				X
	7224		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
4	29		Remove storage from areas within 2 feet of ceiling.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained, qualified, and certified person(s).				X
	Media Center		Provide access to all fire alarm pull stations.				X
	Near 117		Maintenance - repair drinking fountain. Drinking fountains shall be maintained in an operations condition at all times. Water fountain in administration corridor does not have proper water flow.			X	X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: PATTERSON ELEMENTARY - 0471
 5400 PINE AVENUE
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE: _____
 PORTABLE INSPECTION DATE: 3/26/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	113		No storage allowed in boiler, mechanical, or electrical equipment rooms. Fire panel is blocked and not readily accessible.				X
	204 wheelchair lift		State certifications are expired. Put in ticket with maintenance to have unit inspected and apply for current operating permit.				X
	215		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. Remove table and chairs to clear exit access area from stage stairs to exit doors.				X
	530 & 630		No storage allowed in boiler, mechanical, or electrical equipment rooms. All electrical panels are to have a clearance of 36" in front & 30" wide, and all panels are to be closed properly.				X
	603		Remove storage from areas within 2 feet of ceiling.				X
	624		Remove storage from areas within 2 feet of ceiling.				X
	627		Remove storage from areas within 2 feet of ceiling.				X
	Corridor 500		Extinguisher readiness.				X
	Kitchen		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. The exhaust system shall be cleaned by a properly trained, qualified, and certified person(s).				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 CLAY
 RIDEOUT ELEMENTARY - 0541
 2065 APALACHICOLA BOULEVARD
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 3/14/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	139		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	207		Remove storage from areas within 2 feet of ceiling.				X
	234		State certifications are expired. Put in tecket with maintenance to have unit inspected and apply for current operating permit.				X
	324		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. Additionally, come items ae blocking access to the fire extinguisher.				X
	325		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	419		Remove storage from areas within 2 feet of ceiling.				X
	430		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	443		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: RIDGEVIEW ELEMENTARY - 0401
421 JEFFERSON AVENUE
ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 3/1/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:



3/14/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: SHADOWLAWN ELEMENTARY - 0631

2945 COUNTY ROAD 218

GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	303		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	413		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	707A		Remove all storage within 18 inches from under fire sprinkler head deflectors.				X
	712		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	716A		Remove all storage within 18 inches from under fire sprinkler head deflectors.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained, qualified, and certified person(s).				X
	Stage		Stage curtains are due for testing per tag.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58


FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: SWIMMING PEN CREEK ELEMENTARY - 0571

1630 WOODPECKER LANE

MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

3/14/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	203		Remove storage from areas within 2 feet of ceiling.				X
	223		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. Fire extinguisher certification is expired. Have extinguisher recertified.				X
	307		Remove storage from areas within 2 feet of ceiling.				X
	318		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	319		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	405		Remove storage from areas within 2 feet of ceiling.				X
	429		Remove storage from areas within 2 feet of ceiling.				X
	430		Replace broken toilet seat.				X
	512		Remove storage from areas within 2 feet of ceiling.				X
	513		Remove storage from areas within 2 feet of ceiling.				X
	526		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	528		Remove storage from areas within 2 feet of ceiling.				X
	529		Remove storage from areas within 2 feet of ceiling.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Signature]

3/14/2023

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: SWIMMING PEN CREEK ELEMENTARY - 0571
 1630 WOODPECKER LANE
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	613		Remove storage from areas within 2 feet of ceiling.				X
	614		Remove storage from areas within 2 feet of ceiling.				X
	617		Repair outlet cover - install screw in opening.				X
	620		Fire extinguisher must be readily accessible. Rearrange chair to accomplish the requirement.				X
	622		Remove storage from areas within 2 feet of ceiling.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained, qualified, and certified person(s). Kitchen sink was leaking at the time of inspection. Repair as needed.				X
	Media Center		Remove extension cord. Extension cords shall not be used as a substitute for permanent wiring. Remove storage from areas within 2 feet of ceiling.				X
	Stage 202		Repair/replace ceiling tiles.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101
 AND

FIRE SAFETY INSPECTION REPORT
 F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:



3/13/2023

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: THUNDERBOLT ELEMENTARY - 0531
 2020 THUNDERBOLT ROAD
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	126		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	247A Wheelchair lift		State certifications are expired. Put in ticket with maintenance to have unit inspected and apply for current operating permit.				X
	304F & 308F		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	316F		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	320F		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	325		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained, qualified and certified person(s) acceptable to the AHJ.				X
	248		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: TYNES ELEMENTARY - 0501
1550 TYNES BOULEVARD
MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *Dave Eg*

2/28/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Building 3: Storage room 342 won't open				X
			Building 4: Electrical room 401 door won't open				X
			Building 7: Electrical room 701 not labeled, storage room 702 not labeled				X
			Building 5: Storage room 536 not labeled				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: W. E. CHERRY ELEMENTARY - 0241
420 EDSON DRIVE
ORANGE PARK, FLORIDA 32073

INSPECTOR SIGNATURE: *[Signature]*
BUILDING INSPECTION DATE: 3/1/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: WILKINSON ELEMENTARY - 0491

4965 COUNTY ROAD 218 W.

MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *[Signature]*

2/15/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101
 AND

FIRE SAFETY INSPECTION REPORT
 F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: GREEN COVE JUNIOR HIGH - 0021
 1220 BONAVENTURE AVENUE
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 2/20/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	909		Remove extension cord. Extension cords shall not be used as a substitute for permanent wiring. Repair/replace ceiling tiles. Also in 905.				X
	Band Area		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	803 Hallway		Artwork and teaching materials shall be permitted to be attached directly to the walls in accordance with the following: The artwork and teaching materials shall not exceed 20 percent of the wall area in a building that is not protected throughout by an approved automatic sprinkler system in accordance with Section 9.7.				X
	109 Science Lab		Mount fire extinguisher. Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. Every laboratory space that has electrical receptacles at student work stations shall have an unobstructed emergency shut-off switch strategically placed no more than 15 feet from the instructor's work station to allow for easy access by the instructor.				X
	116B		Paper towel dispenser is missing handle and the water closet has a loose seat. Repair or replace as needed.				X
	119		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	14		Repair/replace ceiling tiles.				X
	15		Emergency exit window covered.				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND**

**FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: GREEN COVE JUNIOR HIGH - 0021
1220 BONAVENTURE AVENUE
GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 2/20/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	19		Sink faucet has active drip. Repair or replace faucet.				X
	20		Repair/Replace ceiling tiles.				X
	402 Staff Restroom		Remove door wedge and repair water closet.				X
	404		Remove fueled equipment from within the building.				X
	Throughout		Corridor doors are propped open on all hallways.				X
	Throughout		Extension cords and flexible cords shall not be affixed to structures; extend through walls, ceilings, or floors, or under doors or floor coverings; or be subjected to environmental or physical damage.				X
	Throughout		Remove storage from areas within 2 feet of ceiling.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY JUNIOR HIGH - 0481
 2851 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE: 4/14/2023
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	111		Stage storage: Adjust door closer to proper speed for closing and opening pressure. See photo 1.1 Door hinge is sagging. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	203		Fire doors shall be self-closing. See photo 2.1. Remove added door propps.				X
	215		Adjust door closer to proper speed for closing and opening pressure. See photo 3.1. Door hinge is sagging. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	222		See photo 4.1. Electrical wiring and equipment shall be maintained in a safe and secure condition at all times.				X
	344		Repair drinking fountain. Kiln rooms shall not be used for storage. All electrical panels are to have a clearance of 36" in front & 30" wide and all panels are to be properly closed.				X
	511		Extension cords shall not be used as a substitute for permanent wiring. See photo 6.1. Remove extension cord. Extension cords shall not be used as a substitute for permanent wiring. Trip hazard.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:



4/14/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKE ASBURY JUNIOR HIGH - 0481

2851 SANDRIDGE ROAD

GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	524		Storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 7.1. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms				X
	603		Ceiling clearance from storage (non-sprinklered areas). See photo 8.1. Remove storage from areas within 2 feet of ceiling.				X
	607		Storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 9.1, 9.2. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms				X
	708		Storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 10.1. Remove all storage in boiler rooms. All electrical panels are to have a clearance of 36" in front & 30" wide and all panels are to be properly closed.				X
	708		Persons performing maintenance and recharging of extinguishers shall be certified. See photo 11.1. Portable fire extinguisher is expired. Have recertified by provider.				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

INSPECTOR SIGNATURE:



4/14/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: LAKE ASBURY JUNIOR HIGH - 0481

2851 SANDRIDGE ROAD

GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	8128		Storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 12.1, 12.2, 12.3. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment. All electrical panels are to have a clearance of 36" in front & 30" wide and all panels are to be properly closed. Mechanical equipment rooms and air-handler rooms shall be free of any type of storage except for filters required for the air-handling equipment in the room. Air conditioning filter storage shall not present a hazard.				X
	8129		Persons performing maintenance and recharging of extinguishers shall be certified. See photo 13.1. Portable fire extinguisher is expired. Have recertified by provider.				X
	811		Storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 14.1, 14.2, 14.3. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. Mechanical equipment rooms and air-handler rooms shall be free of any type of storage except for filters required for the air-handling equipment in the room. Air conditioning filter storage shall not present a hazard.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY JUNIOR HIGH - 0481
 2851 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

[Signature]

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE: 4/14/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Gym		Mechanical Mezzanine: Storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 15.1, 15.2, 15.2, 15.4. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. All electrical panels are to have a clearance of 36" in front & 30" wide and all panels are to be properly closed. Mechanical equipment rooms and air-handler rooms shall be free of any type of storage except for filters required for the air-handling equipment in the room. Air conditioning filter storage shall not present a hazard.				X
	Kitchen		Cleaning of hood system - list date of last cleaning. See photo 16.1. The exhaust system shall be cleaned by a properly trained, qualified, and certified persons(s).				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: OAKLEAF JUNIOR HIGH SCHOOL
4085 PLANTATION OAKS BOULEVARD
ORANGE PARK, FL 32065

**CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101**

**AND
INSPECTOR SIGNATURE: *[Signature]*
3/28/2023**

**FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**


**BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:**

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: ORANGE PARK JUNIOR HIGH - 0361
1500 GANO AVENUE
ORANGE PARK, FL 32073

**CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND**

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE: 3/9/2023
PORTABLE INSPECTION DATE:

**AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: WILKINSON JUNIOR HIGH - 0371
 5025 COUNTY ROAD 218
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *[Signature]*
BUILDING INSPECTION DATE: 2/15/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Building 7: Exit signs shall be in service				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:



4/17/2023


FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: CLAY HIGH SCHOOL - 0341
 2025 HIGHWAY 16 WEST
 GREEN COVE SPRINGS, FL 30243

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	1110		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied.				X
	1123		Repair/replace ceiling tiles.				X
	1124		Repair/replace ceiling tiles.				X
	1127		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	1128		Mechanical equipment located on the ground shall be enclosed by a fence that is maintained in a safe and secure condition at all times.				X
	128		Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used.				X
	134		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. Remove all items from stairway and landings. First floor door labeled 127B is blocked by wrestling mats and are blocking the second floor exit.				X
	201		Electric panels, cabinets and rooms shall be accessible only to authorized persons. Remove all storage in the electrical equipment room.				X
	209		Cover open electric boxes.				X
	212		Repair/replace ceiling tiles.				X
	220		Repair/replace ceiling tiles.				X
	303		The classrooms have a secondary emergency escape route through an adjoining room. The door must remain unlocked at all times.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:


BUILDING INSPECTION DATE:
 4/17/2023

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: CLAY HIGH SCHOOL - 0341
 2025 HIGHWAY 16 WEST
 GREEN COVE SPRINGS, FL 30243

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	404		Through-wall and window-type air-conditioning units shall be maintained in a clean, safe and secure condition at all times.				X
	404		Expired fire extinguisher. Have tested.				X
	404		Persons performing maintenance and recharging of extinguishers shall be certified.				X
	404		Gasoline must be kept in flammable storage building or approved spaces.				X
	404		Repair/replace outlets. Electrical conduit not to be used for anything other than electrical equipment. Remove the ropes from conduit and the fire extinguisher.				X
	601E		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	601A		Kiln rooms shall not be used for storage.				X
	602E		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	708		Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	916		Remove storage from areas within 2 feet of ceiling.				X
	920		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	921		Remove storage from areas within 2 feet of ceiling.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58


FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: CLAY HIGH SCHOOL - 0341

2025 HIGHWAY 16 WEST

GREEN COVE SPRINGS, FL 30243

INSPECTOR SIGNATURE: 

4/17/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Cafetorium		Draperies, curtains, and other similar loosely hanging furnishings and decorations shall be flame resistant and have a manufacturer's tag providing this information.				X
	Cafetorium		Fire extinguisher cabinet is bent and will not close. Repair cabinet and clear access to extinguisher. The second cabinet is in the hallway in front of the cafetorium.				X
	Corridor at Room 310		Fire extinguisher cabinet is broken and extinguisher exposed to potential damage. Replace cabinet.				X
	Discovery Way Hallway		Repair/replace exit sign at doors.				X
	Gym		Second floor weight room - Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. Move equipment out of exit area to create a minimum of 36" wide pathway.				X
	Kitchen		The exhaust system shall be cleaned by a properly trained qualified, and certified person(s).				X
	Stage Area		Remove added door props and clear area at bottom of the stairs. Remove all items at the top stair landing on side near 831 boy's dressing area.				X
	Stage Area		The owner or designated agent or occupant of a property in which fire extinguishers are located shall be responsible for inspection, maintenance, and recharging.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: CLAY HIGH SCHOOL - 0341
 2025 HIGHWAY 16 WEST
 GREEN COVE SPRINGS, FL 30243

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE: 4/17/2023
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Stage Area		Mechanical and fire suppression equipment is blocked and access must be provided. Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	Stage Area		Access to fire extinguisher and alarm pull station are blocked. Remove items.				X
	Stage Area		Draperies, curtains, and other similarly loose hanging furnishings and decorations shall be flame resistant and have a manufacturer's tag providing this information.				X
	Stage Chair Lift		Chair lift at stage has an expired certification.				X
	Water Fountain Outside Room 510		Repair water fountain.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Signature]
 3/13/2023

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551
 2233 VILLAGE SQUARE PARKWAY
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
Admin			Emergency bracket must not be utilized as a door lock. Photo is of administration area.				X
	1005		No storage allowed. Remove all contents. All electrical equipment must be readily accessible and have a clear space of 36" in front of the panels.				X
	1029		Mechanical/Electrical room - place fire extinguisher on wall bracket, add closer to electrical panel and remove all storage items.				X
	41		Remove device impeding door handle use. This door is part of the means of egress. Also, the exterior gate is locked and chained but is a means of egress.				X
	220		All ceiling tiles must be in place.				X
	Cafetorium		Update expired extinguisher by chair storage room 217. Stage right by room 207 - hang extinguisher. Repair of replace exit sign.				X
	223		Replace/reinstall ceiling hatch cover.				X
	169		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	84		Update expired fire extinguisher, remove and dispose of flammable rags, and replace the elevator equipment cover.				X
	Exterior Corridor		Exterior corridor exit lighting appeared to not be working multiple places. Check signs and replace as needed.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551
 2233 VILLAGE SQUARE PARKWAY
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE: 

3/13/2023

INSPECTOR SIGNATURE: _____
 BUILDING INSPECTION DATE: _____
 PORTABLE INSPECTION DATE: _____

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	R-142		No storage allowed. Remove all contents.				X
	Gymnasium		Repair/replace handrails on indoor bleachers.				X
	Interior Hallway		Update expired fire extinguisher in hallway near room 52. Drinking fountains shall be maintained in an operational condition at all times. Water fountain in administration corridor 4 does not have proper water flow. Admin hallway 4 - remove or relocate any obstructions reducing the width to below 44 inches.				X
	Kitchen		Expired certification on kitchen hood.				X
	R-304		CAT-5 cable is a trip hazard. Add outlet or relocate office furnishings to alleviate hazard.				X
	Stage area handrail		Handrails and ramp. Miscellaneous blocking; trim; handrails; guardrails; boardwalks; relocatable platforms, ramps and steps; stage and gymnasium flooring; casework; cabinets and paneling, where provided, shall be maintained in a safe condition and free from hazards, including loose fastenings, wood rot, chips, splits, cracks and wood-destroying insects.				X
	Stage door 202		Remove masonry block from fire door. Fire doors are not permitted to be hindered from closing.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551
 2233 VILLAGE SQUARE PARKWAY
 FLEMING ISLAND, FL 32003



INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE: 3/13/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Stair tower at 1019		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. Remove gates at top and bottom of stair tower. Gates are blocking means of egress from second floor at the top and bottom of the stair tower. This needs to be removed immediately along with the items being stored in the corridor.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL-0311
 900 S. ORCHID AVENUE
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 3/15/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	115		Remove storage from areas within 2 feet of ceiling. See photo 1.1				X
	171		Electrical wiring and equipment shall be maintained in a safe and secure condition at all times. See photo 2.1, 2.2, 2.3				X
	64 Science Room		Science laboratory fume hoods and laboratory emergency fans shall be maintained in an operable condition. Science laboratories shall maintain ventilation rates as designed. See photo 3.1				X
	722 Mechanical		Not able to access the mechanical room due to door. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projects, broken glass, broken hardware, etc.				X
	725 Mechanical		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 4.1, 4.2				X
	802 Electrical		Certification tag on fire extinguisher is expired. Have unit inspected and recertified. See photo 5.1				X
	802 Electrical		All electrical equipment must be readily accessible and have a clear space of 36" in front of the panels. Install electrical panel cover. See photo 6.1				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND


FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL-0311
 900 S. ORCHID AVENUE
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 

3/15/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	802 Electrical		Electrical wiring and equipment shall be maintained in a safe and secure condition at all times. Replace damage plug; cover the open electrical boxes. See photo 7.1, 7.2				X
	802 Electrical		Interior finishes shall be maintained in a satisfactory condition at all times and shall be free of hazards. Replace missing ceiling tiles. See photo 8.1				X
	905 Storage		Mechanical equipment rooms and air-handler rooms shall be free of any type of storage except for filters required for the air-handling equipment in the room. Air conditioning filter storage shall not present a hazard. Remove all contents and items stored on top of the HVAC unit. Correct wall sign to reflect mechanical room. See photo 9.1, 9.2				X
	912 Tool Room		Eye washing stations are to be kept operable and flushed monthly. See photo 10.1				X
	912 Tool Room		Remove storage from areas within 2 feet of ceiling. See photo 11.1				X
	917 Wrestling		Interior finishes shall be maintained in a satisfactory condition at all times and shall be free of hazards. Replace missing ceiling tiles. See photo 12.1				X
	928 Multi-Purpose		Certification tag on fire extinguisher is expired. Have unit inspected and recertified. See photo 13.1				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL-0311
 900 S. ORCHID AVENUE
 KEYSTONE HEIGHTS, FL 32656



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

3/15/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	933 Electrical		Not able to access the electrical room due to door. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	Band Room		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 14.1				X
	Band Storage Room		Remove storage from areas within 2 feet of ceiling. See photo 15.1, 15.2				X
	Gym Exit Hallway		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 16.1				X
	Hallway 155		Emergency exit sign is required to be illuminated. See photo 17.1				X
	Hallway 155		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 18.1				X
	Hallway 709 Band Area		Sign not visible from inside of building. Reset to face interior hallway. See photo 19.1				X
	Hallway at Room 506		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 20.1				X
	Hallway at Room 507		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 21.1				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL-0311
900 S. ORCHID AVENUE
KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE:



3/15/2023

BUILDING INSPECTION DATE:


PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Hallway Near Room 403		Drinking fountains shall be maintained in an operational condition at all times. Repair water fountain. See photo 22.1				X
	Hallway R918		Interior finishes shall be maintained in a satisfactory condition at all times and shall be free of hazards. Repair abandoned opening in wall. See photo 23.1				X
	Kitchen		Repair leaking faucet at hand-washing station. See photo 24.1				X
	Near 171		Masonry (walls) where provided, shall be maintained in a safe condition and free from hazards, including cracks, spalling and exposed reinforcing steel. See photo 25.2				X
	902 & 904 Restrooms		Repair doors on restrooms to original configuration. See photo 26.1, 26.2				X
	909 Electrical		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 27.1				X
	912 Weight Room		Interior finishers shall be maintained in a satisfactory condition at all times and shall be free of hazards. Replace missing ceiling tiles. See photo 28.1, 28.2				X
	918 Hallway Near 935		Certification tag on fire extinguisher is expired. Have unit inspected and recertified. See photo 29.1				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL-0311
 900 S. ORCHID AVENUE
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE: 3/15/2023
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	928 Multi-Purpose		Second year violation. Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 30.1				X
	940 Storage		Not able to access the storage room due to door. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
	4		Certification tag on fire extinguisher is expired. Have unit inspected and recertified. See photo 31.1				X
	64 Storage Closet		Remove storage from areas within 2 feet of ceiling and floor space. The room has storage items piled up on the floor. Access to the shut off valves and emergency shut off are blocked by the items on the floor. Panel doors to all valves and electrical cabinets are to be closed. There is a wire that is not properly secured. See photo 32.1, 32.2, 32.3, 32.4				X
	910 Shop Classroom		Exit shall not be locked or blocked and shall remain accessible at all times while the building is occupied. See photo 33.1				X
	910 Shop Classroom		Interior finishes shall be maintained in a satisfactory condition at all times and shall be free of hazards. Repair punctures in ceiling. Photo 34.1, 34.2				X


COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL-0311
 900 S. ORCHID AVENUE
 KEYSTONE HEIGHTS, FL 32656

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 3/15/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	505 Stage		Certification tag on fire extinguisher is expired. Have unit inspected and recertified. See photo 35.1				X
	Stage Chair Lift		Lifts shall be inspected by inspectors certified by the Bureau of Elevator Safety, Department of Business and Professional Regulation. Provide annual inspection certificate. See photo 36.1				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58


FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: MIDDLEBURG HIGH SCHOOL - 0391

3750 COUNTY ROAD 220

MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 2/14/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Fire extinguisher outside Room 24 expired (2021)				X
			Fire extinguisher outside Room 50 expired (2021)				X
			Student service missing fire extinguisher				X
			Fire extinguisher in Room 118 expired (2014)				X
			Exit sign corridor outside Room 139				X
			Fire extinguisher in Room 93 expired (2021)				X
			Fire hood suppression system expired (2017) not used				X
			Room 374 electrical room storage shall be removed (rubber muds)				X
			Fire extinguisher in Room 341 expired				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: OAKLEAF HIGH SCHOOL - 0661
4035 PLANTATION OAKS BOULEVARD
ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 2/22/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed Annual Inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: ORANGE PARK HIGH SCHOOL - 0252

2300 KINGSLEY AVENUE

ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *[Signature]*

3/15/2023

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Fire extinguishers in main building does not meet FFPC in travel distance for fire extinguisher - Replacement first and second floor.				X
			Library office fire extinguisher expired.				X
			Rooms 117 and Room 224A surge protectors running in series.				
			Gym exit sign in northwest exit is broken.				X
			Building 1 weight room and drama storage - all fire extinguisher expired.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

**F.S. 1013.12, 1013.20 & NFPA 101
 AND**

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

3/14/2023

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: RIDGEVIEW HIGH SCHOOL - 0431

466 MADISON AVENUE

ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Electrical room in corridor 136 shall have storage removed and cleaned. Door not labeled.				X
			Room 61: Fire extinguisher expired in Rooms 690, 691, 688.				X
			Building 7: Hood fire suppression in Room 705 expired (4/21).				X
			Room 701 and 714 surge protector connected in series.				X
			Room 17 fire extinguisher expired.				X
			Gym: Fire extinguisher missing outside Room 928.				X
			Exit signs broken in boys locker room.				X
			Emergency lights broken in boys locker room.				X
			Fire extinguisher expired in Room 917.				X
			Emergency light in corridor broken.				X
			1 fire extinguisher in gym area.				X
			Building 3: Fire extinguisher in Room 313 daycare expired.				X
			Fire extinguisher in Room 302 expired.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:



2/20/2023

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: BANNERMAN LEARNING CENTER - 0111
 608 MILL STREET
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			General locations throughout - exits shall not be blocked and shall remain visible and accessible at all times while the building is occupied.				X
	207 Electrical Room		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	320 Electrical Room		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.				X
	214 Daycare		Fire extinguisher needs to have updated inspection. (Done)				X
	207 Rear Side		Cover plates missing on conduit.				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: MAIN OFFICE PORTABLE
900 WALNUT STREET
GREEN COVE SPRINGS, FL 32043

[Handwritten Signature]

INSPECTOR SIGNATURE:

4/18/2023


BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
95	1		Passed annual inspection.				
95	2		Fire extinguisher tag is expired. Have tested.				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58


FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: MAINTENANCE DEPARTMENT
 905 CENTER STREET
 GREEN COVE SPRINGS, FL 32043

SIGNATURE: 
 DATE: 4/18/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
5			Hazard identification sign on exterior side wall is faded and needs to be replaced. See photo 1.1.			X	
5			Fire extinguishers located in the open bay area near the Plumbing department: one needs to be set in a bracket or cabinet and the other is missing the certification tag.			X	
5	21		Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in the designated places (placed on bracket or in cabinet) at all times when they are not being used.			X	
5	31		Fire extinguishers is expired. Have tested.			X	
5	6		Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in the designated places (placed on bracket or in cabinet) at all times when they are not being used.			X	
5	Training Room		The second floor training room does not have a fire extinguisher.			X	
2	10		Storage throughout the building should maintain 2 foot clearance from ceiling (without sprinklers). 2 portable fire extinguishers are expired. Have tested.			X	
4			Passed annual inspection.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: MAINTENANCE DEPARTMENT
 905 CENTER STREET
 GREEN COVE SPRINGS, FL 32043

SIGNATURE: 
 SIGNATURE DATE: 4/18/2023
 SIGNATURE DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
6	Pest Control		Portable fire extinguisher appears to be missing from hanger. Replace as needed.			X	
9			Remove propane fuel tank from within the building. See photo 1.1.			X	
10			Portable fire extinguishers are expired. One is near 114 and the other is near 107. Have tested. See photo 1.1, 1.2.			X	
11			Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms. See photo 1.1.			X	
12			Passed annual inspection.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

2/15/2023

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: FOOD SERVICES/OPERATIONS
 8300 GREEN STREET
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Electric panel access (see photo 1.1). Emergency light not working when test button is pushed.			X	X
			Address numbers must be legible and visible from the street (see photo 2.1).			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 202/2023
 DISTRICT: CLAY
 FACILITY: SUPERINTENDENT BUILDING
 900 WALNUT STREET
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE: 4/21/2023
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	Mechanical Room		Fire extinguisher is expired. Have it tested and re-certified.			X	
	Mechanical Room		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.			X	
	48		Remove all storage in boiler rooms, mechanical rooms, or electrical equipment rooms.			X	
	Statwell		SREF Chapter 5(10)4. The space under stairs and ramps shall be kept free of any storage or other purpose. See photo 4.1.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: VACANT BUILDING 2
 900 WALNUT STREET
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE:



BUILDING INSPECTION DATE:

4/18/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
2			Fire extinguisher tag is expired. Have tested.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: OPERATIONS
 925 CENTER STREET
 GREEN COVE SPRINGS, FL 32043

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: _____
BUILDING INSPECTION DATE: 2/8/2023
PORTABLE INSPECTION DATE: _____

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection.				

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND**

**FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

INSPECTOR SIGNATURE: *SR*
BUILDING INSPECTION DATE: 5/16/2023
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: KEYSTONE HEIGHTS TRANSPORTATION
6800 COUNTY ROAD 315
KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
95	2		Mount fire extinguisher per NFPA Requirements.				X
95	2		Repair door so that it closes properly. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
95	2		Tie down on structure are damaged and/or missing. Wind uplift forces shall be countered by providing anchors from the floor structure to the foundation.			X	
92	760		Fire extinguisher is expired. Have tested and certified.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT

STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: GREEN COVE SPRINGS BUS GARAGE
800 CENTER STREET
GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE:

4/21/2023

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	2		Fire extinguisher tag is expired. Have recertified.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:



BUILDING INSPECTION DATE:

5/16/2023

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2022/2023

DISTRICT: CLAY

FACILITY: KEYSTONE HEIGHTS TRANSPORTATION

6800 COUNTY ROAD 315

KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
95	2		Mount fire extinguisher per NFPA Requirements.				X
95	2		Repair door so that it closes properly. Doors and windows shall be maintained in an operable, safe and secure condition at all times and be free of splinters, sharp projections, broken glass, broken hardware, etc.				X
95	2		Tie down on structure are damaged and/or missing. Wind uplift forces shall be countered by providing anchors from the floor structure to the foundation.			X	
92	760		Fire extinguisher is expired. Have tested and certified.			X	

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58**

INSPECTOR SIGNATURE: _____
BUILDING INSPECTION DATE: _____
PORTABLE INSPECTION DATE: _____

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: PURCHASING DEPT./FUEL ISLAND
800 CENTER STREET
GREEN COVE SPRINGS, FL 32043

SR

4/21/2023

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
1	2nd Floor		Second floor fire extinguisher is expired. Have it tested and recertified.			X	
	16		Remove storage from areas within 2 feet of ceiling in hallways and storage room.				X
4			Building 4 is classified as "flammable storage." Flammable storage buildings cannot have electric in the building. Also install proper portable fire extinguisher compatible to the flammable contents within the building.				
4			Remove storage from areas within 2 feet of ceiling.				X
90	1		Provide clear access/unobstructed view of fire extinguisher(s) per Code. Mount unit per NFPA 10 requirements found in 6.1.3.8.2 no higher than 42" and no lower than 4" above the floor.			X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: H. C. LONG ADMINISTRATION
 23 GREEN STREET
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE: 4/18/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
1			Passed annual inspection.				
2			Remove storage from areas within 2 feet of ceiling. See photo 1.1.				X
2	201		Fire extinguisher is expired. Have tested.			X	
3			Passed annual inspection.				
4			Passed annual inspection.				
5			Passed annual inspection.				
95	1		Passed annual inspection.				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

FISCAL YEAR: 2022/2023
DISTRICT: CLAY
FACILITY: MIDDLEBURG TRANSPORTATION
 3674 CR 200
 MIDDLEBURG, FL 32068

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
 F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: 
BUILDING INSPECTION DATE: 3/9/2023
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2022/2023
 DISTRICT: CLAY
 FACILITY: ORANGE PARK HIGH SCHOOL W. CAMPUS
 2300 KINGSLEY AVENUE
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *[Signature]*
 3/16/2023

INSPECTOR SIGNATURE:
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
			Passed annual inspection				