

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101  
 AND

FIRE SAFETY INSPECTION REPORT  
 F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2019/20

DISTRICT: CLAY

FACILITY: Keystone Heights Elementary School - 0301

335 SW Pecan Street  
 Keystone Heights, FL 32656

INSPECTOR SIGNATURE: 

INSPECTION DATE: 6/10/20 & 6/23/20


Fire Drill Log:  Drills Performed: 6

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info Services	Maint	School
1		OK						
2		OK						
3		OK						
4		OK						
5		OK						
6		Outside drainage filled with sand.						X
7		OK						
8		OK						
9	901		Emergency Exit light is out.					X
	908		Emergency Exit light is out.					X
10	20N	Broken glass in hall door. ** Gym maintained by Jr. High.					X	
92	701	OK						
	702	OK						
	703	OK						
	704	OK						
	705 A/B		Emergency light is out.					X
	706	OK						
	707		Emergency light is out.					X
	708	OK						
	709	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2019/20  
**DISTRICT:** CLAY  
**FACILITY:** Keystone Heights Elementary School - 0301  
 335 SW Pecan Street  
 Keystone Heights, FL 32656

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 6/10/20 & 6/23/20

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>6</u>	Deficiency Not	Facilities	Info Services	Maint	School
					Corrected from Previous Inspection				
92 Cont.	710	OK							
	712		Emergency light is out.						X
	713	OK							
	714		Emergency light is out.						X
	715		Emergency light is out.						X
	716 A/B	OK							
	717		Emergency light is out.						X
	718	OK							
	719	OK							
	720	OK							
	721	OK							
	722	OK							
	724	OK							
	750	OK							
	751		Emergency light is out.						X
	760	OK							
	770		Emergency light is out.						X
	771	OK							
	772	OK							
	773	OK							
	774	OK							

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION  
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
 AND  
 FIRE SAFETY INSPECTION REPORT  
 F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2019/20

DISTRICT: CLAY  
 FACILITY: McRae Elementary School - 0511  
 6770 County Road 315C  
 Keystone Heights, FL 32656

INSPECTOR SIGNATURE:



INSPECTION DATE: 6/23/2020

Fire Drill Log: √ Drills Performed: 7

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info Services	Maint	School
1		Cut concrete at parking lot and create a ramp. <b>** The rise up to sidewalk is over 8 inches.</b>			X			
2		OK						
3		Add ramp up to sidewalk for deliveries.			X			
5		OK						
6		OK						
		<b>**By parent pickup Lane at the back of the school add a ramp from the parking lot for wheelchairs/walkers.</b>						
92	401	OK						
	402	OK						
	403	OK						
	404	OK						
	405 A/B	OK						
	406	OK						
	407	OK						
	408	OK						
	701	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2019/20

DISTRICT: CLAY  
FACILITY: McRae Elementary School - 0511  
6770 County Road 315C  
Keystone Heights, FL 32656

INSPECTOR SIGNATURE:



INSPECTION DATE: 6/23/2020

Fire Drill Log:   ✓   Drills Performed:   7  

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info Services	Maint	School
92 Cont.	702	OK						
	703	OK						
	704	OK						
	705	OK						
	706	OK						
	707	OK						
	708	OK						
	801	OK						
	803	OK						
	804	OK						
	806	OK						
	821	OK						
	823	OK						
	824	OK						
	825	OK						
	826	OK						
	827		Emergency light missing	2nd Time			X	
	828	OK						
	842	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58

**FISCAL YEAR:** 2019/20  
**DISTRICT:** CLAY  
**FACILITY:** Oakleaf High School - 0661  
4035 Plantation Oaks Boulevard  
Orange Park, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 2/13/20 & 6/24/20

Fire Drill Log: √ Drills Performed: 6

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info Services	Maint	School
1	149		Remove door wedges in stairwell doors.					X
	166		Remove door wedges in stairwell doors.					X
	188		Remove door wedges in stairwell doors.					X
3			Remove door wedges.					X
4	416		Remove all storage from electrical room.					X
	417		Remove all storage from electrical room.					X
5		OK						
6		OK						
7		OK						
10		OK						
11		OK						
92	10	OK						
	11	OK						
	15		Emergency light is out.					X
	16	OK						
	21		Emergency light is out.					X
	22	OK						
	23	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**FISCAL YEAR:** 2019/20

**DISTRICT:** CLAY

**FACILITY:** Oakleaf High School - 0661

4035 Plantation Oaks Boulevard  
Orange Park, FL 32065

**INSPECTOR SIGNATURE:**



**INSPECTION DATE:** 2/13/20 & 6/24/20

Fire Drill Log: √ Drills Performed: 6

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info Services	Maint	School
92 Cont.	24	**Siding and Paneling being replaced - no power.						
	25	OK						
	26	OK						
	30	OK						
	31	OK						
	32	OK						
	33	OK						
	34	OK						
	35	OK						
	36	**Siding and Paneling being replaced - no power.						
	40	OK						
	41	OK						
	42	OK						
	43	OK						
	44		Emergency light is out.	2nd Time				X
	45	OK						
	46	OK						
	50	OK						
	51		Emergency light is out.					X
	52	OK						
	53	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2019/20

DISTRICT: CLAY

FACILITY: Oakleaf High School - 0661

4035 Plantation Oaks Boulevard  
Orange Park, FL 32065

INSPECTOR SIGNATURE:



INSPECTION DATE: 2/13/20 & 6/24/20

Fire Drill Log:   ✓   Drills Performed:   6  

Bldg	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info Services	Maint	School
92 Cont.	54	OK						
	55	OK						
	56		Emergency light is out.					X
	60	OK						
	61	OK						
	62	OK						
	63	OK						
	64	OK						
	65	OK						
	66	OK						

\*\*\*\* GENERAL NOTE: Electrical/Mechanical Rooms - Are NOT storage rooms... \*\*\*\*

X
X