

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58
BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Argyle Elementary School
 2625 Spencer Plantation Boulevard
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/3/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21

DISTRICT: CLAY

FACILITY: Charles E. Bennett Elementary School

1 South Oakridge Avenue

Green Cove Springs, FL 32043

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/30/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Emergency light is out in cafeteria.*				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Clay Hill Elementary School
 6345 CR 218
 Jacksonville, FL 32234

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Coppergate Elementary School
 3460 Copper Colts Court
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/22/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	
		Building has backup generator.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58
BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Discovery Oaks Elementary School
 950 Oakleaf Plantation Parkway
 Orange Park, FL 32065

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	
		Building has backup generator.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Doctors Inlet Elementary School
 2634 County Road 220
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/5/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Emergency light out in media center.*				X	
		All classroom corridors have no emergency lighting.*				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Fleming Island Elementary School
 4425 Lakeshore Drive
 Fleming Island, FL 32003

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Fire sprinkler system for stage has no certification. Needs to be inspected.*				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Grove Park Elementary School
 1643 Miller Street
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/16/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Keystone Heights Elementary School
 335 SW Pecan Street
 Keystone Heights, FL 32656

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/3/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
7		Kitchen emergency lights are not working.*				X	
10	13	Emergency lights are not working.*				X	
	23	Emergency lights are not working.*				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Lake Asbury Elementary School
 2901 Sandridge Road
 Green Cove Springs, FL 32043

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/22/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	
		Building has backup generator.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Lakeside Elementary School
 2752 Moody Avenue
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/9/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Middleburg Elementary School
 3958 Main Street
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/12/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No violations found.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Montclair Elementary School
 2398 Moody Avenue
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58
BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Oakleaf Village Elementary School
 410 Oakleaf Village Parkway
 Orange Park, FL 32065

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/3/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Orange Park Elementary School
 1401 Plainfield Avenue
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/10/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
			Mechanical room 92 storing chemicals.				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58
BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Plantation Oaks Elementary School
 4150 Plantation Oaks Boulevard
 Orange Park, FL 32065

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58
BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Rideout Elementary School
 3065 Apalachicola Boulevard
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/17/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	
		Building has backup generator.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Ridgeview Elementary School
 421 Jefferson Avenue
 Orange Park, FL 32065

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		All fire extinguishers are expired.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: R.M. Paterson Elementary School
 5400 Pine Avenue
 Fleming Island, FL 32003

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: S. Bryan Jennings Elementary School
 215 Corona Drive
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/12/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
	45	Emergency light outside of office is inoperable.*				X	
		Emergency lights in kitchen are inoperable. No emergency lightgs in cafeteria.*				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Shadowlawn Elementary School
 1630 Woodpecker Lane
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/17/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	
		Fire extinguishers should be no higher than 5 feet.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58
BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Swimming Pen Creek Elementary School
 1630 Woodpecker Lane
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/5/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Thunderbolt Elementary School
 2020 Thunderbolt Road
 Fleming Island, FL 32003

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/24/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		Passed annual inspection.					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Tynes Elementary School
 1550 Tynes Boulevard
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
3	342	Fire sprinkler system for stage is expired since 2017 - needs annual inspection.				X	
		Storage room door is hard to open.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: W.E. Cherry Elementary School
 420 Edson Drive
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/12/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		2nd story exit stairwell, tape off west side.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

BUILDINGS ONLY

FISCAL YEAR: 2020/21
 DISTRICT: CLAY
 FACILITY: Wilkinson Elementary School
 4965 CR 218
 Middleburg, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 2/9/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.*	School
		No emergency lighting throughout all buildings.*				X	