

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Lakeside Junior High
 2750 Moody Avenue
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 
INSPECTION DATE: 11/14/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: 3					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1	1		No emergency evacuation sheet				X
	2		No emergency evacuation sheet				X
	3		No emergency evacuation sheet				X
	18		No emergency evacuation sheet				X
	20		No emergency evacuation sheet				X
	28		No emergency evacuation sheet				X
	29		No emergency evacuation sheet				X
2	44		No emergency evacuation sheet				X
3	56		No emergency evacuation sheet				X
	57		No emergency evacuation sheet				X
	67		No emergency evacuation sheet				X
5	131	Elevator certificate out of date					X
8	814	Broken outlet covers					X
9	819		Remove furniture from Exit Corridor				X
92	701	OK	Emergency light out				X
	702		Emergency light very weak				X
	703		Emergency light out				X
	704		Emergency light out				X
	705		Emergency light out				X

706	Emergency light out						X
707	Emergency light out						X
708	Emergency light out						X
710	Emergency light out						X
721	Emergency light out						X
722	Emergency light out						X
723	Emergency light out				X		X
731	Emergency light out						X
732	Emergency light out						X
733	Emergency light out				X		X
734	Emergency light out				X		X
735	Emergency light out						X
737	Emergency light out						X
745	Emergency light out				X (3 year)		X
791	Emergency light out						X
793	Emergency light out				X (3 year)		X
794	Emergency light out						X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Orange Park Junior High
 1500 Gano Avenue
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 
INSPECTION DATE: 11/28/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: 6					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1		OK					
2	258	No emergency evacuation sheet					X
3		OK					
4	402	No emergency evacuation sheet					X
	403	No emergency evacuation sheet					X
	453	No emergency evacuation sheet					X
	454	No emergency evacuation sheet					X
	458	No emergency evacuation sheet					X
5		OK					
6	604	No emergency evacuation sheet					X
92	501	OK					
	503	OK					
	504	Emergency light missing				X	
	505	OK					
	506	OK					

507	OK								
509A/B	OK								
510	OK								
511	Emergency light out							X	
516	OK								
702	Emergency light out							X	
703	OK								
704	OK								
706	Emergency light out							X	
708	OK								
710	OK								
712	OK								

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Bannerman Learning Center -0111
 608 Mill Street
 Green Cove Springs, FL 32043

INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/28/2016

Fire Drill Log: Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1		OK					
2		OK					
3		OK					
92	1		Emergency light out				X
	2						
	3						
	4						
	5		Emergency light out				X
	6A/B						
	7						
	8						
	9						
	10						
	11						
	12						
	13						
	14						
	30						
	31						
	32	Electrical wall strip needs strain-relief connector				X	

33		Emergency light out							X
34	OK								
35	OK								
36	OK								
37	OK								
38		Emergency light out							X
39	OK								
40	OK								
42	OK								
43	OK								
44	OK								
50	OK								
52		Remove gas bottle/grill stored in closet							X
56	OK								
58	OK								
60	OK								
61	OK								
62	OK								

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: CLAY HIGH SCHOOL
 2025 HIGHWAY 16, WEST
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 

INSPECTION DATE: 10/4/2016

Fire Drill Log: Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1	127B		Remove equipment blocking door/stairs				X
	134	Replace lens cover on lights					X
	134	Door sticks					X
2	140	Replace lens cover/ceiling tiles					X
		OK					
3	307		Emergency evacuation sheet missing				X
4	374		Repair power strip end-stain connector			X	
		OK					
5	510		Emergency light out				X
		OK					
7	719		Emergency evacuation sheet missing				X
	745		Emergency evacuation sheet missing				X
	747		Emergency evacuation sheet missing				X
	786	Ceiling tiles wet					X

787			Emergency evacuation sheet missing					X
788			Emergency evacuation sheet missing					X
836	8		Electric box cover missing					X
914	9		Emergency evacuation sheet missing					X
1104	11		Drums blocking exit					X
1108			Exit blocked with table					X
2	29		Emergency light out					X
3			Emergency light out					X
	30	OK						
	31	OK						
	35	OK						
	92	OK						
	7	OK						
	8	OK						
	17	OK						
	18	OK						
	19	OK						
	20	OK						
	31	OK						
	32	OK						
	33	OK						
	40	OK						
	41	1 bulb out in emergency light						X
	42	OK						
	43	OK						
	44	OK						
	45	Cover plate missing-intercom box by FA pull station						X
	46	Lens cover missing restroom						X
	47	OK						
	48		Emergency light out					X
	49	OK						
	54	OK						
	58	OK						

Football Stadium	<p>Stadium visitors bleachers - shall be removed for lack of proper handrails, guardrails improperly attached or supported seats and foot rests. The structural reports have asked that the wood planks be replaced with aluminum seats and foot beards. The aisles and surrounding handrail/guardrails are not sufficient.</p>				X	
------------------	---	--	--	--	---	--

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Fleming Island High School
 2233 Village Square Parkway
 Fleming Island, FL 32003

INSPECTOR SIGNATURE: 

INSPECTION DATE: 10/11/2016

Fire Drill Log: Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1	157	Ceiling tile over door missing					X
	173	Lens cover missing		X			X
	176		Remove material from room				X
	226	Door sticks				X	
	237	Lens cover missing					X
	260	Lens cover missing					X
	266		No evacuation sheet				X
2	228	Ceiling tile out					X
	240		No evacuation sheet				X
	262		Extinguisher out of date				X
	267		Remove stored materials			X	
10	1001		No evacuation sheet				X
	1002		No evacuation sheet				X
	1021A		Relocate exit sign to west end of 1021			X	
30	002	Remove pad lock					X
92	10	OK					
	11	Roof leak				X	
	12		Printer in front of electric panel				X
	12		Emergency light out			X	
	12	Rear door lock broken				X	
	13	Repair pier at ramp				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Keystone Heights High
 900 S.W. Orchid Avenue
 Keystone Heights, FL 32656

INSPECTOR SIGNATURE: 

INSPECTION DATE: 11/15/2016

Fire Drill Log: Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1	126	No evacuation sheet					X
	127	No evacuation sheet					X
	192	No evacuation sheet					X
2		OK					
4	407	No evacuation sheet					X
	408	No evacuation sheet					X
5	508B	Replace ceiling tile					X
6		OK					
9	928	Ceiling tiles falling					X
18		OK					
20		OK					
92	1	Remove cloth by emergency light					X
	2	OK					
	4	OK					
	6	Emergency light out				X	
	8	OK					
	11		Electric panel blocked by file cabinet	X (3 year)			X
	12	Emergency light out					
	13	OK				X	
	14	OK					

	80	OK							
	82	OK							
	84	OK							
	90	OK							
	91	OK							

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: MIDDLEBURG HIGH SCHOOL -0391
 3750 COUNTY ROAD-220
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/13/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: 4					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1	217		No emergency evacuation sheet				X
	263		No emergency evacuation sheet				X
	282	Wet ceiling/roof leak				X	
	302		No exit light			X	
	307	Electrical cover plate missing					X
	308		No exit light			X	
	314	Wet ceiling tiles					X
	374		Remove stored mats in electric room				X
10		Football concession soffit falling/repair				X	
90	4					X	
92	001	OK					
	5	Lens cover missing light					X
	7	OK					
	9	OK					
	31		Emergency light out	X			X
	32	OK					
	33	OK					
	34	OK					
	35	OK					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
 DISTRICT: CLAY
 FACILITY: OAKLEAF HIGH SCHOOL - 0661
 4035 PLANTATION OAKS BLVD.
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 
 INSPECTION DATE: 10/17/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: 3									
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Info. Services	Maint	School			
1	120A		No emergency evacuation sheet					X			
	531A		Door swing				X				
7	703		Remove Propane Tanks	X 3rd year				X			
92	10	OK									
	11	OK									
	15	Missing rail on landing					X				
	16	Outlet cover broken by closet							X		
	20	OK									
	21	Emergency light out					X				
	22	OK									
	23	OK									
	24	OK									
	25	Emergency light out					X				
	26	OK									
	30	OK									
	31	Lens cover missing									X
	31	Emergency light out					X				
	31	Junction box cover missing above panel									X
	32	OK									
	33	OK									
	34	Emergency light out					X				

35	Cover missing on I.S. hitching post								
36	OK							X	
40	OK								
41	OK								
42	OK								
43	OK								
44	OK								
45	OK								
46	Lens cover missing				X				X
50	Emergency light out							X	
51	Emergency light out							X	
52	Lens cover missing				X				X
53	Emergency light out							X	
54	OK								
60	Pain trim at entrance							X	
61	OK								
62	OK								
63	Emergency light out								
64	OK							X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Orange Park High School
 2300 Kingsley Avenue
 Orange Park, FL 32073

INSPECTOR SIGNATURE: 

INSPECTION DATE: 10/20/2016


Fire Drill Log: √ Drills Performed: 1

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1	*		Emergency evacuation sheet missing				X
	**		Typical throughout campus				
	166	Electrical gutter missing cover				X	
	166	Remove can by electrical panel					X
2	9		Emergency evacuation sheet missing				X
3		OK					
4	5h		Exit light out				X
	5	Change lock to school 0356					X
	8A	Lens cover missing					X
	10	Remove extension cord thru ceiling					X
	13	Light switch cover broken and cover plate at panel					X
	14		Emergency light broken by girls locker room				X
	22A	Remove filing cabinet at stair landing					X
10		OK					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
DISTRICT: CLAY
FACILITY: Ridgeview High School
 466 Madison Avenue
 Orange Park, FL 32065

INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/26/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: 1					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Maint	School
1		OK					
2	206	Wheel chair lift cert. out of date				X	
	214		Remove excessive combustibles				X
3		OK					
5		OK					
6		OK					
7	705		Remove propane tank				X
8	814		Remove security bars from doors - School states locks on doors are broke	X		X	
	819		Remove security bars from doors - School states locks on doors are broke	X		X	
9	903	Emergency light broke				X	
	910	Emergency light broke				X	
	941		All exit lights broken			X	
10		Room #'s don't match FISH			X		
11		OK					
12	1201		Remove propane tanks				X
	1205	Remove appliances					X
13	1301		Remove propane tanks				X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2016/17
 DISTRICT: CLAY
 FACILITY: Ancillary Buildings

INSPECTOR SIGNATURE: *W. J. [Signature]*
 INSPECTION DATE: 3/28/2017

Fire Drill Log: Drills Performed:
 N/A

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maint	School
School Board Main Office:								
2		OK						
3	7		Emergency light out	X			X	
	25	Split A/C unit not running--does it work?			X			
	30	Fire extinguisher tag not proper						X
	48	Paint new exterior landing					X	
	61		Emergency light out				X	
	61	Fire extinguisher old--replace						
	62		Emergency light out	X			X	
92	1	OK						
	2	OK						
H.C. Long Building:								
1	100		Emergency light out (near 119)	X (2nd year)			X	
2		OK						
3	300		Emergency light out (near 310)				X	
4	401	Stained ceiling tiles/and lights - Replace					X	
	404A		Add emergency lights	X (2nd year)			X	

