

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]
 10/9/2021

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: ARGYLE ELEMENTARY SCHOOL
 2625 SPENCER PLANTATION BLVD.
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701						
92	701A						
92	702	Bookshelf is blocking electrical panel. Must keep electric panel accessible at all times. Relocate book shelves.					X
92		2021 THIS VIOLATION HAS NOT BEEN CORRECTED.					
92	702A						
92	703						
92	704	Receptacle within 2 feet of sink must be GFCI. This was reported in 2021. THIS VIOLATION HAS NOT BEEN CORRECTED					X
92	705						
92	706						
92	706A						
92	707	No emergency evacuation map displayed by door.					X
92	707A						
92	708						
92	710						
92	710A						
92	710B						
92	711						
92	711A						
92	713						
92	713A						
92	713B						
92	713C						
92	713D						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

George J. [Signature]

10/9/2021

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: ARGYLE ELEMENTARY SCHOOL
 2625 SPENCER PLANTATION BLVD.
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	713E						
92	714						
92	714A						
92	801						
92	801A						
92	802						
92	802A						
92	803						
92	803A						
92	804						
92	804A						
92	805						
92	805A						
92	806						
92	806A						
92	807						
92	807A						
92	808						
92	808A						
92	901						
92	901A						
92	902	Emergency light did not work.					X
92	902A						
92	903	Vinyl in bathroom needs repairing. Emergency light did not work and emergency light was partially blocked by box.					X
92	903A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

Jerry [Signature]
 10/9/2021

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: ARGYLE ELEMENTARY SCHOOL
 2625 SPENCER PLANTATION BLVD.
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	904	Bookshelf is blocking electrical panel. Must keep electric panel accessible at all times. Relocate book shelf.					X
92	904A						
92	905	Bookshelf is blocking electrical panel. Must keep electric panel accessible at all times. Relocate book shelf.					X
92	905A						
92	906	Bookshelf is blocking electrical panel. Must keep electric panel accessible at all times. Relocate book shelf. No emergency evacuation map displayed by door. 2021 VIOLATIONS HAVE NOT BEEN CORRECTED.					X
92	906A						
92	907	Back door was locked by a non conforming device. This device is only to be used during an emergency situation. 2021 VIOLATIONS HAVE NOT BEEN CORRECTED.					X
92	908						
92	908A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

8/11/2021

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: CHARLES E. BENNETT ELEM. - 0071
 1 SOUTH OAKRIDGE AVENUE
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	040						
92	040A						
92	041						
92	041A						
92	042						
92	042A						
92	043						
92	045						
92	045A						
92	046						
92	047						
92	047A						
92	048						
92	048A						
92	049						
92	049A						
92	050						
92	050A						
92	051						
92	051A						
92	052						
92	052A						
92	053						
92	053A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: CHARLES E. BENNETT ELEM. - 0071
 1 SOUTH OAKRIDGE AVENUE
 GREEN COVE SPRINGS, FL 32043



INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 8/11/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	054						
92	055						
92	055A						
92	055B						
92	056						
92	056A						
92	056B						
92	057						
92	057A						
92	057B						
92	501						
92	502						
92	602A						
92	602B						
92	603A						
92	603B						
92	604						
92	604A						
92	604B						
92	605						
92	605A						
92	702						
92	702A						
92	703						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: CHARLES E. BENNETT ELEM. - 0071

1 SOUTH OAKRIDGE AVENUE

GREEN COVE SPRINGS, FL 32043

[Handwritten Signature]

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

8/11/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	703A						
92	703B						
92	803						
92	803A						
92	803B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: *[Signature]*
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE: 10/7/2021

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: CLAY HILL ELEMENTARY - 0411
 6345 COUNTY ROAD 218
 JACKSONVILLE, FL 32234

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	682						
92	682A						
92	682B						
92	701						
92	703						
92	704						
92	705						
92	705A						
92	706						
92	707						
92	707A						
92	707B						
92	708						
92	708A						
92	709						
92	709A						
92	709B						
92	710						
92	710A						
92	712						
92	712A						
92	760	Back exit is blocked by teachers desk. Must relocate desk to keep a clear egress path.					X
92	760A						
92	762						
92	762A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: COPPERGATE ELEMENTARY - 0601
 2250 COUNTY ROAD 209 N.
 MIDDLEBURG, FL 32068

[Signature]

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

8/12/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	511						
92	511A						
92	512						
92	512A						
92	514						
92	514A						
92	520						
92	520A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: CLAY
 DISTRICT: DOCTORS INLET ELEMENTARY - 0261
 FACILITY: 2634 COUNTY ROAD 220
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	836						
92	836A						
92	837	Large shrubs along building may cause damage to building and make an unsafe campus.					X
92	838	Large shrubs along building may cause damage to building and make an unsafe campus.					X
92	838A						
92	839	The emergency light is blocked by "hanging set up" to hang something from. MUST REMOVE ROPE FROM INFRONT OF EMERGENCY LIGHT. THIS IS THE SECOND YEAR OF THIS VIOLATION!!!					X
92	840						
92	843						
92	844	Back door exit is blocked by trees and shrubs. Life safety issue - MUST MOVE ASAP.					X
92	845						
92	845A						
92	847						
92	847A						
92	849						
92	849A						
92	869						
92	869A						
92	869B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: CLAY
 DISTRICT: DOCTORS INLET ELEMENTARY - 0261
 FACILITY: 2634 COUNTY ROAD 220
 MIDDLEBURG, FL 32068

[Handwritten Signature]

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	870						
92	870A						
92	870B						
92	871	Large shrubs along building may cause damage to siding.					X
92	871A						
92	871B						
92	872						
92	872A						
92	873						
92	874	No DCA sticker and no documentation.		X			
92	876	Emergency light does not work.					X
92	888	Plants need to be trimmed away from ramp walkway.					X
92	888A						
92	889						
92	889A						
92	890						
92	890A						
92	890B						
92	891						
92	891A						
92	893	Custodial person reported a soft spot in the floor where they have an "X" over it.				X	
92	893A						
92	894						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: CLAY
DISTRICT: DOCTORS INLET ELEMENTARY - 0261
FACILITY: 2634 COUNTY ROAD 220
MIDDLEBURG, FL 32068

[Handwritten Signature]

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	895						
92	895A						
92	895B						
92	896						
92	896A						
92	897						
92	897A						
92	899						
92	899A						
92	899B						
92	921						
92	921A						
92	923						
92	923A						
92	842A						
92	842B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/20122
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521
 4425 LAKESHORE DRIVE
 FLEMING ISLAND, FL 32003

[Signature]

INSPECTOR SIGNATURE:
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

7/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	601	Emergency light battery weak.					X
92	601A						
92	601B						
92	602						
92	602A						
92	602B						
92	603						
92	603C						
92	603D						
92	604						
92	604A						
92	605						
92	605A						
92	605B						
92	606						
92	606A						
92	606B						
92	607	Large shrubs along building may cause damage to siding.					X
92	607A						
92	607B						
92	608						
92	608A						
92	608B						
92	801						
92	801A						


COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/20122
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521
 4425 LAKESHORE DRIVE
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 7/23/2021

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	801B						
92	802						
92	802A						
92	802B						
92	803						
92	803A						
92	803B						
92	804						
92	804A						
92	804B						
92	805						
92	805A						
92	806						
92	806A						
92	807	Siding along ramp is rotting.				X	
92	807A						
92	807B						
92	812						
92	812A						
92	812B						
92	821						
92	824	Backdoor egress is partially blocked by filing cabinet. Must relocate cabinet. See picture.					X
92	824A						
92	824B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/20122
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521
 4425 LAKESHORE DRIVE
 FLEMING ISLAND, FL 32003

[Signature]

INSPECTOR SIGNATURE:
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE: 7/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	826	Large shrubs along building may cause damage to siding.					X
92	826A						
92	826B						
92	828						
92	828A						
92	830						
92	830A						
92	830B						
92	832						
92	832A						
92	832B						
92	843						
92	843A						
92	844						
92	844A						
92	846						
92	846A						
92	848	Large shrubs along building may cause damage to siding.					X
92	848A						
92	848B						
92	850						
92	850A						
92	850B						
92	860						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/20122
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521
 4425 LAKESHORE DRIVE
 FLEMING ISLAND, FL 32003

[Signature]

INSPECTOR SIGNATURE:
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

7/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	860A						
92	860B						
92	861						
92	861A						
92	861B						
92	862	Vines growing up the side of the building.					X
92	862A						
92	899	No portable.		X			
92	901						
92	901A						
92	904						
92	904A						
92	904B						
92	905						
92	905A						
92	906						
92	906A						
92	906B						
92	907						
92	907A						
92	907B						
92	908						
92	908A						
92	908B						
92	909						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/20122
 DISTRICT: CLAY
 FACILITY: FLEMING ISLAND ELEMENTARY - 0521
 4425 LAKESHORE DRIVE
 FLEMING ISLAND, FL 32003

[Handwritten Signature]

INSPECTOR SIGNATURE:
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

7/23/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	909A						
92	909B						
92	910						
92	910A						
92	910B						
92	842						
92	842A						
92	842B						
92	842C						
92	842D						
92	842E						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT:

FACILITY:

CLAY
 GROVE PARK ELEMENTARY - 0232
 1643 MILLER STREET
 ORANGE PARK, FL 32073

[Signature]

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

10/9/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	009						
92	009A						
92	010						
92	010A						
92	010B						
92	027						
92	029						
92	029A						
92	029B						
92	030						
92	030A						
92	030B						
92	031						
92	031A						
92	031B						
92	043						
92	043A						
92	043B						
92	044						
92	044A						
92	044B						
92	071						
92	071A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: GROVE PARK ELEMENTARY - 0232
 1643 MILLER STREET
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: 

10/9/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	500	Bathroom does not have an exhaust fan. Per the FMC (403.3.2.3) all restrooms must have a exhaust fan.					X
92	500A						
92	501						
92	501A						
92	501B						
92	504						
92	505						
92	506						
92	506A						
92	506B						
92	507						
92	507A						
92	522						
92	523	The back door was blockd by desk and chairs. Exits must be kept clear at all times. Electrical panel was blocked by filing cabinets and boxes. Per the NEC (110.26) you must maitain a clear area in front of the electrical panel 36" deep and 30" wide.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: GROVE PARK ELEMENTARY - 0232

1643 MILLER STREET

ORANGE PARK, FL 32073

[Signature]

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 10/9/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	524	The back door was blocked by small stools. Exits must be kept clear at all times. Electrical panel was blocked by storage boxes. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	525						
92	525A						
92	005	Electrical panel was blocked by rolling cart and storage. Per the NEC (110.26) you must maintain a clear area in front of the electrical panel 36" deep and 30" wide.					X
92	005A						
92	005B						
92	005C						
92	006						
92	006A						
92	006B						
92	006C						
92	006D						
92	006E						
92	007						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: GROVE PARK ELEMENTARY - 0232

1643 MILLER STREET

ORANGE PARK, FL 32073

INSPECTOR SIGNATURE:

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

10/9/2021

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	007A						
92	007B						
92	007C						
92	007D						
92	520A	Emergency lights not working. Portable has no fire extinguisher.					X
92	520B						
92	521A						
92	521B						
92	008						
92	008A						
92	008B						
92	008C						
92	008D						
92	008E						
92	008F						
92	008G						
92	008H						
92	008J						
92	008K						
92	008L						
92	008M						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS ELEMENTARY -0301
 335 SW PECAN STREET
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: *[Signature]*
 BUILDING INSPECTION DATE: 10/14/21
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701						
92	702	Back door exit was blocked by emergency bracket. You can not use the emergency bracket to block egress on a regular basics. See picture					X
92	702A						
92	703						
92	703A						
92	704						
92	704A						
92	705A	Electric panel was blocked by cabinet. Electrical panel must be visible and have clear access at all times. Must relocate cabinet.					X
92	705B						
92	706						
92	706A						
92	707						
92	707A						
92	707B						
92	708						
92	708A						
92	708B						
92	709						
92	709A						
92	710						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: KEYSTONE HEIGHTS ELEMENTARY -0301
 335 SW PECAN STREET
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: *[Signature]*
 BUILDING INSPECTION DATE: 10/16/21
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	710A						
92	712						
92	712A						
92	713						
92	713A						
92	714						
92	714A						
92	714B						
92	715						
92	716A						
92	716B						
92	716C						
92	717						
92	717A						
92	718						
92	718A						
92	719						
92	719A						
92	720						
92	720A						
92	721						
92	724						
92	724A						
92	750						
92	750A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

[Handwritten Signature]

BUILDING INSPECTION DATE:

10/11/21

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: KEYSTONE HEIGHTS ELEMENTARY -0301
 335 SW PECAN STREET
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	751						
92	751A						
92	751B						
92	751C						
92	760						
92	760A						
92	770						
92	770A						
92	771						
92	771A						
92	772						
92	772A						
92	773						
92	773A						
92	774						
92	774A						
92	722						
92	722A						
92	722B						
92	722C						
92	722D						
92	001A	This portable is a restroom. Did not inspect.					
92	001B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY ELEMENTARY - 0451
 2901 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *[Signature]*
 BUILDING INSPECTION DATE: *[Date]*
 PORTABLE INSPECTION DATE: 7/30/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	009						
92	009A						
92	010						
92	010A						
92	010B						
92	011	BATHROOM FAN DOES NOT WORK				X	
92	011A						
92	012	EMERGENCY LIGHTS NOT WORKING					X
92	012A						
92	013	Fire extinguisher is not by exit, must be within 5' of exit.					X
92	013A						
92	013B						
92	014						
92	014A						
92	015	CABINET BY DOOR IS BLOCKING FIRE ALARM PULL STATION. PULL STATION MUST BE ACCESSIBLE AT ALL TIMES.					X
92	015A						
92	015B						
92	016						
92	016A						
92	018						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

7/30/2021

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY ELEMENTARY - 0451
 2901 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	018A						
92	018B						
92	039A						
92	039B						
92	039C						
92	040						
92	040A						
92	041						
92	041A						
92	042						
92	042A						
92	043						
92	043A						
92	044						
92	044A						
92	045						
92	046						
92	046A						
92	046B						
92	048						
92	048A						
92	048B						
92	069						
92	069A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

7/30/2021

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY ELEMENTARY - 0451
 2901 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	071						
92	071A						
92	071B						
92	072						
92	072A						
92	073	Emergency light does not work					X
92	073A						
92	074	Back door hangs up and is hard to open					X
92	075						
92	075A						
92	075B						
92	076	Need to remove bush going up ramp in between ramp and building					X
92	076A						
92	077						
92	077A						
92	079						
92	079A						
92	079B						
92	079C						
92	080						
92	080A						
92	081						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY ELEMENTARY - 0451
 2901 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *[Signature]*

INSPECTION DATE: 7/30/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	081A						
92	082						
92	082A						
92	084	Has no DCA sticker and no documentation of missing sticker nothing. Holes by electrical panel has not been repaired and teacher still blocking electrical panel the GFCI by sink has been repaired		X		X	X
92	084A						
92	086						X
92	086A	Umbrella by the door blocking exit. See pic					
92	087						
92	087A						
92	088						
92	088A						
92	089						
92	089A						
92	090						
92	090A						
92	091						
92	091A						
92	093						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKE ASBURY ELEMENTARY - 0451
 2901 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *Youn Park*

BUILDING INSPECTION DATE: *7/30/2021*
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	093A						
92	094						
92	094A						
92	094B						
92	095						
92	095A						
92	096						
92	096A						
92	085	Emergency light and bathroom A does not work					X
92	085A						
92	085B						
92	085C						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKESIDE ELEMENTARY - 0352
 2752 MOODY ROAD
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *Jerry Pate*
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE: 8/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010	Fire extinguisher was not located within five feet of a door. Electrical panel was blocked by fake tree. Electrical panel must be visible at all times and a Three foot area must be kept clear in front of electrical panel.					X
92	011	Fire extinguisher was not located within five feet of a door.					X
92	012						
92	012A						
92	013						
92	014						
92	015	Trim around one window needs re-attaching/replacing.					X
92	016						
92	017						
92	018						
92	018A						
92	019						
92	019A						
92	020						
92	021						
92	021A						
92	022	Fire extinguisher was not located within five feet of a door. Emergency light does not work.					X
92	023						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKESIDE ELEMENTARY - 0352
 2752 MOODY ROAD
 ORANGE PARK, FL 32073

[Inspector Signature]

INSPECTOR SIGNATURE:
 BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

8/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	024						
92	025						
92	026						
92	027						
92	042A	Emergency light is not working.					X
92	042B						
92	044						
92	044A						
92	045						
92	045A						
92	046						
92	046A						
92	047						
92	047A						
92	047B						
92	047C						
92	048	GFCI by classroom sink does not trip.					X
92	048A						
92	051A						
92	051B						
92	051C						
92	052						
92	052A						
92	053	Corner support block by back door steps is washing away.					X
92	053A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

8/7/2021

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: LAKESIDE ELEMENTARY - 0352
 2752 MOODY ROAD
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	054						
92	054A						
92	055						
92	055A						
92	056						
92	056A						
92	060						
92	060A						
92	061						
92	061A						
92	062						
92	062A						
92	063						
92	063A						
92	043						
92	57						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: MCRAE ELEMENTARY - 0511
 6770 COUNTY ROAD 315 C
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: *[Signature]*

BUILDING INSPECTION DATE: 10/12/21
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	401						
92	401A						
92	401B						
92	402						
92	402A						
92	403						
92	403A						
92	403B						
92	404						
92	405						
92	406						
92	406A						
92	407						
92	407A						
92	408	Electrical panel is blocked by items on top of cabinet must keep clear at all times					X
92	408A						
92	701						
92	702	Back door was blocked by desk protruding into egress path. Relocate desk. Must keep the full width of the exit path clear at all times.					X
92	702A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: *Greg Peters*
BUILDING INSPECTION DATE: 10/11/21
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: MCRAE ELEMENTARY - 0511
 6770 COUNTY ROAD 315 C
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	703	Electrical panel was blocked by items on top of the filing cabinet. Electrical panel must be accessible at all times.					X
92	703A						
92	704	Back door exit was blocked by emergency bracket. You can not use the emergency bracket to block egress on a regular basis. See picture.					X
92	704A						
92	705						
92	706						
92	707						
92	708						
92	708A						
92	801						
92	801A						
92	802						
92	802A						
92	803						
92	803A						
92	804						
92	804A						
92	806	This unit being used for storage back exit is blocked need to have a clear path to the back door.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: MCRAE ELEMENTARY - 0511
 6770 COUNTY ROAD 315 C
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: *[Signature]*
 BUILDING INSPECTION DATE: 10/16/21
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	806A						
92	821	There was no fire extinguisher in portable. Needs to be a fire extinguisher within 5 feet of a exit door					X
92	821A						
92	821B						
92	823	Fire alarm pull station shield is blocked by cabinet and cannot open it. Must relocate cabinet so you have full access to pull station.					X
92	823A						
92	823B						
92	824						
92	825	The fire extinguisher was not within 5 feet of a exit door. relocate the fire extinguisher to be within 5 feet of a exit door					X
92	825A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: MCRAE ELEMENTARY - 0511
 6770 COUNTY ROAD 315 C
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: *Yoush Lats*
 BUILDING INSPECTION DATE: 10/16/21
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint	School
92	826	Back door is blocked by small items. Must keep a clear path to the exit door at all times. The fire extinguisher was blocked by balls hanging on the wall. Please relocate rubber balls so the fire extinguisher is assessable at all times.					X
92	827	Electrical panel was blocked by weight machine. Electrical panel must be assessable at all times.					X
92	828A						
92	828B						
92	842						
92	842A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: MIDDLEBURG ELEMENTA.
 3958 MAIN STREET
 MIDDLEBURG, FL 32068

[Handwritten Signature]

8/25/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	23						
92	023A						
92	024						
92	024A						
92	025	Storage room.					
92	025A						
92	035						
92	037	2021 bathroom fan bearings are going bad - excessive noise. Need to replace fan.					X
92	037A						
92	038						
92	039						
92	040						
92	040A						
92	041						
92	041A						
92	043						
92	043A						
92	055						
92	055A						
92	057						
92	057A						
92	059						
92	059A						
92	064						
92	064A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

8/25/2021

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: MIDDLEBURG ELEMENTARY - 0271
 3958 MAIN STREET
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	065A						
92	065B						
92	068						
92	068A						
92	069						
92	069A						
92	026A						
92	026B						
92	029A						
92	029B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: MONTCLAIR ELEMENTARY - 0381
 2398 MOODY ROAD
 ORANGE PARK, FL 32073

Jay Pate

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE: 8/7/2021
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021						
92	022						
92	023						
92	023A						
92	024	One of the exits is blocked by a desk. Must keep egress path clear at all times.					X
92	024A						
92	025A						
92	025B						
92	026	The wood ramp does not have the correct handrail. Install correct handrail to meet ADA.				X	
92	027						
92	028						
92	028A						
92	029						
92	029A						
92	030	Emergency lights not working.					X
92	030A						
92	031	Teacher has made a storage area with curtains and no smoke alarm. This is a violation and must be removed. If the teacher is unwilling to remove the violation, I will notify the fire marshal to come and write up his violation and we will have it removed.					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT

STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

MONTCLAIR ELEMENTARY - 0381
2398 MOODY ROAD
ORANGE PARK, FL 32073

[Handwritten Signature]

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 8/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	032	Teacher has made a storage area with curtains and no smoke alarm. This is a violation and must be removed. If the teacher is unwilling to remove the violation, I will notify the fire marshal to come and write up his violation and we will have it removed.					X
92	032A						
92	033						
92	033A						
92	034	Back door is blocked by table, remove table or make opening bigger in front of door, need at least 36 inch clear access.					X
92	035						
92	036						
92	036A						
92	036B						
92	037						
92	037A						
92	038						
92	039	Emergency lights not working.					X
92	039A						
92	039B						
92	040	Emergency light above electrical panel does not work.					X
92	041						
92	042						
92	043						
92	044						
92	045						
92	046A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT

STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: MONTCLAIR ELEMENTARY - 0381

2398 MOODY ROAD

ORANGE PARK, FL 32073

[Handwritten Signature]

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 8/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	046B						
92	047						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: _____
BUILDING INSPECTION DATE: _____
PORTABLE INSPECTION DATE: _____

[Handwritten Signature]

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: OAKLEAF VILLA
 410 OAKLEAF VILLA
 ORANGE PARK, FL 3206

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	901	Electric panel is blocked by hanging posters. Must keep electric panel accessible at all times. Remove all hanging posters from in front of panel. Bathroom is being used for storage with no heat detector.					X
92	901A						
92	903	DCA sticker should be IV E 007448 Bathroom has loose storage materials outside of metal cabinets. All storage must be kept inside metal storage cabinets with doors closed.		X			X
92	903A						
92	905						
92	905A	Bathroom being used for storage with no heat detector.					X
92	906						
92	906A						
92	907						
92	907A						
92	908						
92	908A	DCA sticker should be MB E 010902.		X			
92	909						
92	909A						
92	910						
92	910A	Electric panel is blocked by hanging posters. Must keep electric panel accessible at all times. Remove all hanging posters from in front of panel Emergency lights do not work.					X
92	911						
92	911A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: OAKLEAF VILLAGE ELEMENTARY - 0621
 410 OAKLEAF VILLAGE PARKWAY
 ORANGE PARK, FL 32065



Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	912						
92	912A						X
92	913						
92	913A						X
92	914						
92	914A						
92	916						
92	916A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

10/9/2021

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: ORANGE PARK ELEMEN,
 1401 PLAINFIELD AVENUE
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021						
92	021A						
92	022A						
92	022B						
92	023						
92	023A						
92	024						
92	034						
92	034A						
92	035						
92	035A						
92	036						
92	036A						
92	037						
92	038						
92	038A						
92	041						
92	041A						
92	042						
92	042A						
92	043	Electrical panel was hidden from view by cloth material. Electrical panel must be visible at all times.					X
92	044						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: ORANGE PARK ELEMENTARY - 0201
 1401 PLAINFIELD AVENUE
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: 
 BUILDING INSPECTION DATE: _____
 PORTABLE INSPECTION DATE: 10/9/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint	School
92	044A						
92	045						
92	050						
92	050A						
92	051						
92	051A						
92	052						
92	052A						
92	053						
92	054						
92	039A						
92	039B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: CLAY
 DISTRICT: PATTERSON ELEMENTARY - 0471
 FACILITY: 5400 PINE AVENUE
 FLEMING ISLAND, FL 32003
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
91	1						
91	1A						
92	2						
92	2A						
91	3						
92	3A	No heat detectors in big closet. Fan does not work and light on fan is broken.				X	
92	3B						
92	4A						
92	4B						
92	5	No heat detector in storage room. No DCA Sticker in portable and did not see any DCA sticker documents posted.		X			
92	6	Outside GFCI not working. Emergency lights not working.				X	
92	6A						
92	7						
92	7A						
92	8	Emergency light does not work. The bathroom fan does not work. No heat detectors in large storage room.				X	
92	11	No DCA sticker in portable and did not see any DCA sticker documents posted.		X			
92	11A						
92	13						
92	13A						
92	14						
92	14A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: CLAY
 DISTRICT: PATTERSON ELEMENTARY - 0471
 FACILITY: 5400 PINE AVENUE
 FLEMING ISLAND, FL 32003
 MIDDLEBURG, FL 32068

[Handwritten Signature]

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	14B						
92	15	No heat detectors in big closet.					X
92	15A						
92	15B						
92	16	No heat detectors in big closet. Rotting siding at ramp.				X	X
92	16A						
92	16B						
92	17						
92	17A						
92	18	No heat detectors in big closet.					X
92	18A						
92	21						
92	21A						
92	22						
92	22A						
92	23						
92	23A						
92	24	Rotting siding in several places.				X	
92	24A						
92	25						
92	25A						
92	26	No heat detectors in big closet. Emergency light does not work.				X	X
92	26A						
92	26B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: CLAY
 DISTRICT: PATTERSON ELEMENTARY - 0471
 FACILITY: 5400 PINE AVENUE
 FLEMING ISLAND, FL 32003
 MIDDLEBURG, FL 32068

Greg Pitts
 INSPECTOR SIGNATURE:

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	27						
92	27A						
92	27B						
92	28	Need heat detector in storage room. Back door exit is blocked! Clear Exit path.					X
92	28A						
92	28B						
92	29	Siding is rotting along ramp.				X	
92	29A						
92	30						
92	30A						
92	41						
92	41A						
92	42A						
92	42						
92	43	Bathroom fan does not work. There is water on the floor by filing cabinet. Could not see where the water is coming from.				X	
92	43A						
92	43A						
92	44	Emergency light battery is very weak.					X
92	44A						
92	44B						
92	45						
92	45A						
92	45B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

[Handwritten Signature]

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

FISCAL YEAR: CLAY
 DISTRICT: PATTERSON ELEMENTARY - 0471
 FACILITY: 5400 PINE AVENUE
 FLEMING ISLAND, FL 32003
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	46						
92	46A						
92	46B						
92	47						
92	47A						
92	48						
92	48A						
92	48B						
92	49						
92	49A						
92	50						
92	50A						
92	50B						
92	51	No heat detector in storage room.				X	
92	51A						
92	51B						
92	52						
92	53						
92	53A						
92	54						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 7/30/2021

FISCAL YEAR: 2021/2022

CLAY

RIDEOUT ELEMENTARY - 0541

2065 APALACHICOLA BOULEVARD

MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010	None					
92	010A	None					
92	011	None					
92	011A	None					
92	012	None					
92	012A	None					
92	013	None					
92	013A	None					
92	014	None					
92	014A	None					
92	020	None					
92	020A	None					
92	021	None					
92	021A	None					
92	022	None					
92	022A	None					
92	022B	None					
92	022C	None					
92	025	None					
92	025A	None					
92	025B	None					
92	023A	None					
92	023B	None					
92	023C	None					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 7/30/2021

FISCAL YEAR: 2021/2022

CLAY

RIDEOUT ELEMENTARY - 0541

2065 APALACHICOLA BOULEVARD

MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	023D	None					
92	023E	None					

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]
 9/8/2021

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: RIDGEVIEW ELEMENTARY - 0401
 421 JEFFERSON AVENUE
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	711A	Emergency light by electrical panel does not work.					X
92	711B						
92	711C						
92	712						
92	712A						
92	714						
92	714A						
92	715	2021 Receptacle next to sink with brown cover is not GFCI protected. Replace with GFCI receptacle.					X
92	715A						
92	717	Outside GFCI is missing the cover.					X
92	717A						
92	718						
92	718A						
92	728						
92	728A						
92	729						
92	729A						
92	730	2021 emergency light does not work NEEDS IMMEDIATE ATTENTION !!! Palm trees in front of ramp need to be removed they have needles on the palms branch.					X
92	730A						
92	731						
92	731A						
92	732						
92	732A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:



BUILDING INSPECTION DATE:

9/8/2021

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
DISTRICT: CLAY
FACILITY: RIDGEVIEW ELEMENTARY - 0401
 421 JEFFERSON AVENUE
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	733						
92	734						
92	734A						
92	735						
92	735A						
92	737						
92	737A						
92	741						
92	742						
92	742B						
92	743	.20221 Emergency light does not work					X
92	744						
92	745						
92	746						
92	749						
92	751						
92	754	2021 emergency light does not work.					X
92	754A						
92	755						
92	755A						
92	756						
92	756A						
92	758						
92	758A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: RIDGEVIEW ELEMENTARY - 0401
 421 JEFFERSON AVENUE
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *Jan Pak*

BUILDING INSPECTION DATE: 9/8/2021

PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	759	2021 GFCI by sink and bathroom does not work back door is blocked by cabinet. A clear path to the exit must be kept at all times.					X
92	759A						
92	760						
92	760A						
92	760B						
92	772						
92	772A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: S. BRYAN JENNINGS ELEMENTARY - 0331
 215 CORONA DRIVE
 ORANGE PARK, FLORIDA 32073

[Handwritten Signature]

10/5/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	026						
92	027	Electrical panel is blocked by materials. Area in front of electrical panel must be kept clear at all times.					X
92	028A						
92	028B						
92	028C						
92	029						
92	029A						
92	030	Emergency light does not work.					X
92	032	Emergency light does not work.					X
92	033	Electrical panel is blocked by materials. Area in front of electrical panel must be kept clear at all times.					X
92	033A						
92	035	Emergency light does not work.					X
92	036						
92	037						
92	037A						
92	039						
92	039A						
92	042						
92	042A						
92	042B						
92	043						
92	043A						
92	043B						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: S. BRYAN JENNINGS ELEMENTARY - 0331
 215 CORONA DRIVE
 ORANGE/PARK, FLORIDA 32073

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 10/5/2021
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	044						
92	044A						
92	044B						
92	075						
92	075A						
92	075B						
92	077	GFCI by classroom sink does not work.					X
92	077A						
92	077B						
92	078						
92	078A						
92	078B						
92	080A						
92	080B						
92	076						
92	076A						
92	076B						
92	076C						
92	076D						
92	076E						
92	076F						
92	076G						
92	076H						
92	076J						
92	076K						


COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: SWIMMING PEN CREEK ELEMENTARY - 0571
 1630 WOODPECKER LANE
 MIDDLEBURG, FL 32068



Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701						
92	703	Electrical panel was blocked Must keep it clear at all times.					X
92	703A						
92	705	Light bulb is out in restrooms.					X
92	705A						
92	707						
92	707A						
92	801						
92	801A						
92	803	Light bulb in restroom does not work and no cover over lightbulb.				X	
92	803A						
92	806						
94	702						
94	704						
94	706A	Emergency light does not work.				X	
94	706B						
94	706C						
94	706D						
94	706E						
94	706F						
94	708	Emergency light not working.				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

[Handwritten Signature]

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: THUNDERBOLT ELEMENTARY - 0531
 2020 THUNDERBOLT ROAD
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701		Electrical panel blocked.				X
92	701A						
92	702						
92	702A						
92	703						
92	703A						
92	704						
92	704A						
92	705						
92	705A						
92	706						
92	706A						
92	707		Need Cover for light fixture in restroom.				X
92	707A						
92	710						
92	711						
92	711A						
92	713						
92	721						
92	721A						
92	721B						
92	722						
92	722A						
92	722B						
92	723						
92	723A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: THUNDERBOLT ELEMENTARY - 0531
 2020 THUNDERBOLT ROAD
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE:


BUILDING INSPECTION DATE:
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	723B						
92	724A						
92	724B						
92	724C						
92	725						
92	725A						
92	726						
92	726A						
92	727						
92	727A						
92	728						
92	728A						
92	729						
92	730						
92	731	Laminate baseboard in bathroom coming off wall. Needs repair.				X	
92	731A						
92	732	Baseboard laminate in restroom coming off wall. Needs repair.				X	
92	732A						
92	733						
92	733A						
92	734						
92	734A						
92	735	Emergency light over main door not working.				X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: THUNDERBOLT ELEMENTARY - 0531
 2020 THUNDERBOLT ROAD
 FLEMING ISLAND, FL 32003

[Handwritten Signature]

INSPECTOR SIGNATURE:
BUILDING INSPECTION DATE:
PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	735A						
92	736	Deteriorating siding around portable.				X	
92	737	Outlet by sink in classroom is incorrect. Needs to be GFCI.				X	
92	737A						
92	738						
92	738A						
92	739	Outlet by sink needs to be GFCI.				X	
92	739A						
92	740						
92	740A						
92	741						
92	741A						
92	742	Outlets by bathroom sink and classroom sink need to be GFCI.				X	
92	742A						
92	744						
92	744A						
92	995	No portable.		X			
92	712A	Restrooms - did not inspect.					
92	712B						


COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022
 DISTRICT: CLAY
 FACILITY: TYNES ELEMENTARY - 0501
 1550 TYNES BOULEVARD
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 10/5/21

PORTABLE INSPECTION DATE: 10/5/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001						
92	001A						
92	001B						
92	002	There's no bathroom exhaust fan in the restroom. Per the Florida Building Code there must be an exhaust fan in the restroom.					X
92	002A						
92	002B						
92	003						
92	004						
92	004A						
92	005						
92	005A						
92	006	Electrical panel was covered by paper. Must remove and keep electrical panel visible at all times. See picture					X
92	006A						
92	007	Bathroom exhaust fan does not work.					X
92	007A						
92	008						
92	008A						
92	009	Electrical panel is still blocked by cards and not visible. Electrical panel must be visible at all times					X
92	009A						
92	010	Electrical panel is blocked by posterboard. Electrical panel must be visible at all times					X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:



BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

10/5/21

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: TYNES ELEMENTARY - 0501

1550 TYNES BOULEVARD

MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	022	Electrical panel was blocked. Must remove and keep clear all items in front of electrical panel. See picture					X
92	022A						
92	022B						
92	023						
92	023A						
92	023B						
92	024	Filing cabinets by the back door is impeding into egress path. Must have a full 36 inches leading up to door. You must relocate both filing cabinets away from egress path.					X
92	024A						
92	024B						
92	025						
92	025A						
92	025B						
92	026						
92	026A						
92	026B						
92	027	Multiple power strips have been daisychained together. It is against National Electrical Code to plug a powerstrip into another power strip. Unplug the one powerstrip from and relocate to another wall plug.					X
92	027A						
92	028						
92	028A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: TYNES ELEMENTARY - 0501

1550 TYNES BOULEVARD

MIDDLEBURG, FL 32098



10/5/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	029						X
92	029A	Damaged Ceiling tile in restroom needs to be replaced					
92	030						
92	030A						
92	041						
92	042						
92	042A						
92	043						
92	044						
92	044A						
92	045	Electrical panel was covered by posterboard. Must remove and keep electrical panel visible at all times. See picture					X
92	045A						
92	046						
92	046A						
92	046B						
92	047						
92	048	Students desk are blocking the exit path to the back door. Must relocate desk to have a clear path to door.					X
92	048A						
92	049						
92	049A						
92	061						
92	061A						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: TYNES ELEMENTARY - 0501

1550 TYNES BOULEVARD

MIDDLEBURG, FL 32068

[Handwritten Signature]
 10/5/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	063						
92	063A						
92	065						
92	065A						
92	066	Emergency light did not work. The emergency light is blocked by boxes on top of cabinet. Must relocate boxes so that the emergency light can light up egress path.					X
92	066A						
92	067						
92	067A						
92	068						
92	068A						
92	062						
92	062A						