

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

10/7/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint	School
92	027						X
92	029						
92	029A						
92	031						
92	031A						
92	032	Electrical panel is blocked. Electrical must be kept clear at all times. Relocate all items in front of electrical panel.					X
92	032A						
92	033	Electrical panel is blocked by rolling cart and hanging books. Electrical must be kept clear at all times. Relocate rolling cart. THIS IS THE SECOND YEAR WITH THIS VIOLATION					X
92	033A						
92	034A						
92	034B						
92	036	Emergency light does not work.					X
92	036A						
92	037						
92	037A						
92	038						
92	038A						
92	039						
92	039A						
92	040						
92	040A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

*[Handwritten Signature]*

10/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	041	Electrical panel is blocked. Electrical must be kept clear at all times.					X
92	041A						
92	042A						
92	042B						
92	042C						
92	043	Emergency light did not work.					X
92	043A						
92	044						
92	044A						
92	044B						
92	045	DCA sticker should be E - 002131 Back exit is blocked by teachers desk and tables. Need to keep a clear path to back door. See picture.					X
92	045A						
92	045B						
92	048						
92	049	Non approved rug by front door can be a tripping hazard.					X
92	050						
92	050A						
92	051						
92	051A						
92	053						
92	053A						
92	054						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

*[Handwritten Signature]*

10/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	054A						
92	054B						
92	055						
92	055A						
92	056	Fire alarm pull station by door is blocked. MUST REMOVE ALL ITEMS AROUND THE FIRE ALARM PULL STATION SO IT IS ACCESSIBLE AT ALL TIMES. Handi cap ramp railing is blocked by vines growing on parts of hand rail.railing. Remove all vines from railing.					X
	056A						
	057						
	057A						
	058						
	058A						
	059	Both timeout rooms are being used for storage with no smoke/heat detector. Either remove items out of timeout room or have smoke/heat detector installed. Emergency light is blocked by the basketball hoop. Keep emergency light clear at all times.					
	059A						X
	060	Back exit is blocked by desk. Remove desk and keep egress path clear at all times. THIS VIOLATION HAS NOT BEEN CORRECTED FROM LAST YEAR.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE/PARK, FLORIDA 32073

*[Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

10/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	061	Back exit is blocked by desk. Remove desk and keep egress path clear at all times. Light does not work in bathroom. Lock on the bathroom door is not a handi cap lock.					X
	061A						
	062	Receptacle to the right of sink needs to be a GFCI.					X
	062A						
	063	Emergency light is blocked by items on top of the cabinet. Electrical panel is blocked by posterboard. Remove items from top of cabinet and keep clear at all times. THESE VIOLATIONS HAVE NOT BEEN CORRECTED FROM LAST YEAR.					X
	063A						
	064						
	064A						
	065						
	065A						
	066						
	066A						
	067						
	067A						
	068						
	068A						
	069	Bathroom light does not work.					X
	069A						
	070						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

*[Handwritten Signature]*

10/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
	070A						
	026A						
	026B						
	026C						
	030						
	030A						
	030B						
	030C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

9/15/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001	Boxes and items stacked in front of electrical panel and blocking the fire alarm pull station. Area in front of electrical must be kept clear at all times. Fire alarm pull station must be visible and clear at all times. Relocate all boxes and items blocking area.					X
92	002						
92	003	Back door exit path is blocked by desk. Relocate desk.					X
92	003A						
92	004						
92	004A						
92	005						
92	005A						
92	006						
92	006A						
92	007						
92	007A						
92	008						
92	008A						
92	010	Electrical panel is blocked by cabinet. Relocate cabinet so electrical panel is accessible.					X
92	010A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

*[Handwritten Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

9/15/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	011	Electrical panel, pull station and emergency light is blocked by materials and flags. Must remove all items so the area is visible and clear at all times.					X
92	012						
92	013						
92	013A						
92	014						
92	014A						
92	016						
92	016A						
92	017						
92	017A						
92	017B						
92	018						
92	020						
92	020A						
92	022						
92	031						
92	031A						
92	033						
92	033A						
92	034						
92	034A						
92	035						
92	035A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE: 9/15/2021  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	035B						
92	036						
92	036A						
92	037						
92	037A						
92	038						
92	038A						
92	039						
92	039A						
92	040						
92	040A						X
92	041	Bathroom fan needs replacing.					X
92	041A						
92	042	Bathroom fan needs replacing.					X
92	042A						
92	043						
92	043A						
92	044	Bathroom exhaust fan needs replacing makes a screeching noise.					X
92	044A						
92	045	Back exit is blocked by rolling cart. Exit must be kept cleared all times. Relocate cart.					X
92	045A						
92	045B						
92	046						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*  
 9/15/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	046A						
92	047	.Back door is blocked by mat and pillows. Back exit must be kept clear at all times, this is the second year of this violation					X
92	047A						
92	047B						
92	048						
92	048A						
92	048B						
92	049						
92	049A						
92	049B						
92	050						
92	050A						
92	050B						
92	051						
92	051A						
92	052	Back door had emergency bracket holding door lock. Emergency bracket is for emergency situations only.					X
92	052A						
92	052B						
92	061						
92	061A						
92	063						
92	063A						
92	066	GFCI by classroom sink does not work.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

*[Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:** 9/15/2021  
**PORTABLE INSPECTION DATE:**

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	066A						
92	066B						
92	068	GFCI's did not trip by sink.					X
92	068A						
92	062	GFCI's by Sink did not trip.					
92	062A						
92	062B						
92	062C						
92	064						
92	064A						
92	064B						
92	064C						X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: GREEN COVE JUNIOR HIGH - 0021  
 1220 BONAVENTURE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:** *[Signature]*  
**BUILDING INSPECTION DATE:** \_\_\_\_\_  
**PORTABLE INSPECTION DATE:** \_\_\_\_\_

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	70						
92	70A						
92	71						
92	71A						
92	74						
92	75						
92	75A						
92	76						
92	104						
92	105						
92	105A						
93	106						
92	106A						
92	106B						
92	106C						
93	107						
92	107A						
92	107B						
92	107C						
93	112						
93	113						
93	113A						
93	113B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

7/30/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	390						
92	390A						
92	391						
92	391A						
92	392	BACK EXIT IS BLOCKED BY ROW OF DESK. MOVE ROW OF DESK OUT OF PATH OF EGRESS TO DOOR. MUST KEEP A 3 FOOT PATH TO DOOR.					X
92	392A						
92	393						
92	393A						
92	394	FIRE EXTINGUISHER BLOCKED BY PLANT/TREE FOR SECOND YEAR!!					X
92	394A						
92	401						
92	401A						
92	402						
92	402A						
92	403						
92	403A						
92	404	EMERGENCY LIGHTS NOT WORKING					X
92	404A						
92	405						
92	405A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**

**BUILDING INSPECTION DATE:**

**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

7/30/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	406						
92	406A						
92	407						
92	407A						
92	408						
92	408A						
92	409						
92	409A						
92	410						
92	410A						
92	421						
92	421A						
92	422	EVACUATION MAP NOT BY DOOR.					X
92	423	EMERGENCY LIGHTS NOT WORKING. DOOR NEED REPAINTING.				X	X
92	423A						
92	424					X	X
92	425	Emergency light does not work. Ceiling tile needs repairing.					
92	425A						
92	426	EMERGENCY LIGHTS NOT WORKING					X
92	426A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*  
 7/30/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	427	Fire extinguisher is on the floor by teacher desk. Needs to be hung within 5 feet of exit door					X
92	427A						
92	428	Emergency light by exit door does not work and light fixture is coming apart. Both lights emergency lights not work				X	X
92	428A						
92	430						
92	430A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/20122  
 DISTRICT: CLAY  
 FACILITY: LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *James Parks*  
 BUILDING INSPECTION DATE: 8/7/2021  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	701						
92	701A						
92	701B						
92	702						
92	702A						
92	703						
92	703A						
92	703B						
92	704						
92	704A						X
92	705	Light fixture in restroom needs cover.					
92	705A						
92	705B						
92	705C						
92	706	Had sign on back door saying not an exit check sign down put on teachers desk. All exits must be kept clear and useable at all times.					X
92	706A						
92	707					X	
92	707A	Baseboard and restroom needs to be repaired.					
92	708	There was no fire extinguisher within 5' of door.					X
92	708A						
92	708B						
92	721	Exit door leading to ramp was blocked by row of desk. Must keep the path of egress open and clear at all times.					X
92	722						
92	723						
92	723A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
 AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/20122  
 DISTRICT: CLAY  
 FACILITY: LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *Jerry Pate*  
 BUILDING INSPECTION DATE: 8/7/2021  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	731	Electrical panel was blocked. Must keep area in front of electrical panel clear at all times.					X
92	731A						
92	732						
92	732A						
92	733	Emergency light does not work and shrubs growing into ramp.					X
92	733A						
92	734	No evacuation map. Back door was blocked by treadmill. Must relocate treadmill.					X
92	735						
92	791	Emergency light does not work above panel. Restrooms being used for storage also and they do not have heat detectors. Receptacle next to water fountain is not a GFCI.					X
92	791A						
92	791B						
92	791C						
92	793						
92	793A						
92	794						
92	794A						
92	794B						
92	794C						
92	710	Electrical leading to exterior box wires are exposed.					X
92	710A						
92	710B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/20122  
 DISTRICT: CLAY  
 FACILITY: LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

*Jaw Fato*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE: 8/7/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	737	Emergency light does not work and receptacle on wall by sink needs to be a GFCI					X
92	737A						
92	737B						
92	745						
92	745A						
92	745B	745B does not have an evacuation map by door.					X
92	745C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 10/2/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	601	Bathroom being used for storage with no smoke detector					X
92	601A						
92	602	Bathroom being used for storage with no smoke detector					X
92	602A						
92	603	Bathroom being used for storage with no smoke detector					X
92	603A						
92	604	Bathroom being used for storage with no smoke detector					X
92	604A						
92	605	Electrical panel was blocked by poster board must be visible at all times bathroom being used for storage with no heat detector and bathroom light fixture missing cover					X
92	605A						
92	606	Bathroom being used for storage with no smoke detector					X
92	606A						
92	607						
92	607A						
92	608						
92	608A						
92	609	Bathroom being used for storage with no smoke detector					X
92	609A						
92	610	Bathroom being used for storage with no smoke detector					X
92	610A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

10/2/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	611	SECONDARY EXIT IS BLOCKED. MUST KEEP A CLEAR EGRESS PATH AT ALL TIMES.					X
92	611A						
92	612	Bathroom being used for storage with no smoke detector					X
92	612A						
92	613	GFCI located in bathroom has ground prong broke off in the receptacle					X
92	613A						
92	614						
92	614A						
92	615						
92	615A						
92	616	Bathroom being used for storage with no smoke detector					X
92	616A						
92	617	Bathroom being used for storage with no smoke detector					X
92	617A						
92	618	Bathroom being used for storage with no smoke detector					X
92	618A						
92	619	Bathroom being used for storage with no smoke detector					X
92	619A						
92	620						
92	620A						
92	702						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
 AND

**FIRE SAFETY INSPECTION REPORT**  
 F.S. 1013.12, 1013.20 & RULE 69A-58

**INSPECTOR SIGNATURE:**

*[Handwritten Signature]*

**BUILDING INSPECTION DATE:**

**PORTABLE INSPECTION DATE:** 10/2/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	704	Bathroom being used for storage with no smoke detector					X
92	704A						
92	708						
92	708A						
92	709	Bathroom being used for storage with no smoke detector					X
92	709A						
92	710						
92	710A						
92	711	Bathroom being used for storage with no smoke detector					X
92	711A						
92	712						
92	712A						
92	713	Electrical panel is blocked by refrigerator light cover missing on bathroom light					X
92	713A						
92	714						
92	714A						
92	801						
92	807	Emergency lights do not work.					X
92	807A						
92	809						
92	809A						
92	810						
92	810A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 10/2/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	811						
92	811A						
92	821						
92	821A						
92	823	Emergency light does not work					
92	823A						
92	824	Electrical panel was blocked by paper. Must keep electrical panel visual at all times					
92	824A						
92	808A	RESTROOM					
92	808B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: ORANGE PARK JUNIOR H.

1500 GANO AVENUE

ORANGE PARK, FL 32073

*Yves Patis*

INSPECTOR SIGNATURE:

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 10/7/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	501						
92	505						
92	505A						
92	505B						
92	510						
92	511						
92	703	Electrical panel is blocked by extra chairs MUST REMOVE AND KEEP CLEAR ALL ITEMS IN FRONT OF ELECTRICAL PANEL. Back door is blocked by desk. Relocate desk to keep a clear path to the door.					X
92	503						
92	503A						
92	503B						
92	504	Receptacle by sink in classroom is not GFCI and has ground prong broke off in the ground. Replace with GFCI.					X
92	504A						
92	507						
92	507A						
92	507B						
92	509A						
92	509B						
92	516						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Greg Pate*

10/12/21

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK JUNIOR HIGH - 0361  
 1500 GANO AVENUE  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	706	Receptacle by sink in classroom was not a GFCI. Must replace with GFCI. Back bathroom being used for storage with no smoke detector. Either install smoke detector or remove storage					X
92	706A						
92	706B						
92	708						
92	708A						
92	708B						
92	710	GFCI does not trip by classroom sink. Replace GFCI					X
92	710A						
92	710B						
92	702						
92	704	Power strip by sink is not connected to a GFCI receptacle. Must remove power strip away from sink area. GFCI receptacle in girls bathroom tripped and lights in both restrooms lost power. GFCI would not reset. Emergency light does not work					X
92	704A						
92	704B						
92	704C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: WILKINSON JUNIOR HIGH - 0371  
 5025 COUNTY ROAD 218  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

9/15/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	002	Electrical panel was blocked. Area in front of electrical panel must be kept clear at all times. Relocate all items in front of electrical panel. Emergency lights did not work.					X
92	003	Receptacle by classroom sink needs to be a GFCI.					X
92	004						
92	005						
92	005A						
92	006						
92	007						
92	007A						
92	008						
92	009						
92	009A						
92	010						
92	011						
92	011A						
92	011B						
92	021						
92	022						
92	022A						
92	023						
92	024						
92	025						
92	026						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON JUNIOR HIGH - 0371  
 5025 COUNTY ROAD 218  
 MIDDLEBURG, FL 32068



9/15/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	027						
92	040	Floor is missing floor tile in the corner of the room.					X
92	041						
92	041A						
92	043						
92	043A						
92	042						
92	042A						
92	042B						
92	042C						
92	048						
92	048A						
92	048B						
92	096						
92	096A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*John Pater*

8/7/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30243

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	007						
92	007A						
92	007B						
92	017	No emergency map properly placed by door .					X
92	018						
92	018A						
92	019						
92	020	Palm tree growing up next to building needs to be removed.					X
92	032	Front door is blocked by desk/tables. Need to have 36 inch clear egress all the way to the door. Both exit lights do not work.					X
92	032A						
92	033						
92	033A						
92	033B						
92	040	No DCA sticker and no documentation.		X			
92	041	2021 - This makeshift closet is still there and is a major violation. If the teacher is not willing to take down makeshift closet, I will bring in the Fire Marshall and we will remove the violation and any other violations we see.					X
92	041A						
92	042						
92	042A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**

*Jerry Pate*

**BUILDING INSPECTION DATE:**

8/7/2021

**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30243

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	043	One bulb is burned out in the emergency light fixture.					X
92	043A						
92	043B						
92	044						
92	044A						
92	045						
92	045A						
92	046						
92	046A						
92	046B						
92	047						
92	047A						
92	048						
92	048A						
92	049	Emergency light batteries are weak need to be replaced.					X
92	049A						
92	054	The outside door of portable says Room 56 but the paperwork says Room 54. No DCA Sticker or documentation.		X			
92	054A						
92	058	Missing two 2 X 4 ceiling tiles see pictures.					X
92	005A						
92	005B	Emergency light at ramp door does not work. No emergency evacuation map by door.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

AND

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

7/29/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010						
92	010A						
92	011						
92	011A						
92	012						
92	012A						
92	013						
92	014						
92	015						
92	020	GFCI receptacle at sink not working. It is a regular rec could be tied into GFCI down run.				X	
92	021						
92	022						
92	022A						
92	023	Fire extinguisher is missing. Pull station by door is blocked see picture. <u>These items have not been fixed from last year</u>				X	X
92	024						
92	025						
92	030						
92	031						
92	032						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jean Pate*

7/29/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	033						
92	034						
92	035						
92	041	Water is undermining portable has cracked sidewalk something will have to be done soon				X	
92	042						
92	043						
92	044						
92	045						
92	046						
92	046A						
92	046B						
92	046C						
92	047						
92	047A						
92	047B						
92	047C						
92	047D						
92	049						
92	050						
92	050A						
92	051	Emergency light did not work					X
92	051A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

Inspector Signature: *[Handwritten Signature]*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

7/29/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	052						
92	052A						
92	053						
92	053A						
92	060						
92	060A						
92	061						
92	061A						
92	062						
92	062A						
92	063						
92	063A						
92	070						
92	070A						
92	071						
92	071A						
92	072						
92	072A						
92	073	Emergency light not working					X
92	073A						
92	080						
92	080A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*  
 7/29/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	081	Back exit is blocked by a row of desk. Path of egress must be kept clear at all times. Relocate row of desk.					X
92	081A						
92	082						
92	082A						
92	083	Back exit is blocked by a row of desk. Path of egress must be kept clear at all times. Relocate row of desk.					X
92	083A						
92	084						
92	084A						
92	085	Back exit is blocked by a row of desk. Path of egress must be kept clear at all times. Relocate row of desk.					X
92	085A						
92	086						
92	086A						
92	087						
92	087A						
92	090	Back door is blocked by desk. Must relocate desk.					X
92	090A						
92	091						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

*[Handwritten Signature]*

7/29/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	092	Electrical panel is missing breaker knock out cover. This is a life and safety issue. correct ASAP.				X	
92	093	Back exit is blocked by a row of desk. Path of egress must be kept clear at all times. Relocate row of desk.					X
92	093A						
92	094						
92	094A						
92	095	Both emergency lights do not work					X
92	095A						
92	096						
92	096A						X
92	097	Back exit is blocked by a row of desk. Path of egress must be kept clear at all times. Relocate row of desk.					
92	097A						
92	040						
92	048	Need covers over flourscent light fixtures.					X
92	027A	RESTROOMS-DID NOT INSPECT					
92	027B						
92	064A	RESTROOMS- DID NOT INSPECT					
92	064B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: KEYSTONE HEIGHTS  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 321

INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE: 10/10/21  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001						
92	002						
92	004						
92	006	Emergency light not working					X
92	006A						
92	006B						
92	011						
92	012	Carpet trim is coming up by the back door needs to be replaced or repaired					X
92	012A						
92	013						
92	014						
92	015						
92	016						
92	017						
92	017A						
92	017B						
92	018	Emergency light not working					X
92	018A						
92	019						
92	019A						
92	019B						
92	020	Back door is blocked by boxes, need to keep the path of egress open at all times.					X
92	020A						
92	020B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*  
 10/12/21

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021	Emergency light not working					X
92	021A						
92	022						
92	022A						
92	023						
92	023A						
92	024	Emergency light not working					X
92	024A						
92	025						
92	025A						
92	026						
92	026A						
92	027	Emergency light not working					X
92	027A						
92	028						
92	028A						
92	028B						
92	050						
92	050A						
92	051						
92	051A						
92	052						
92	052A						
92	053						
92	053A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR: 2021/2022**  
**DISTRICT: CLAY**  
**FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL - 0311**  
**900 S. ORCHID AVENUE**  
**KEYSTONE HEIGHTS, FL 32656**

*[Handwritten Signature]*  
 10/16/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint	School
92	054	Emergency light not working					X
92	054A						
92	055	Back door is blocked by desk must arranged desk so you will have an clear path to the door.					X
92	055A						
92	056						
92	056A						
92	057	Emergency light battery is good but one bulb is burned out					X
92	057A						
92	058						
92	058A						
92	058B						
92	059						
92	060						
92	060A						
92	060B						
92	061						
92	062						
92	062A						
92	062B						
92	063						
92	063A						
92	064	Emergency light not working					X
92	064A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE: 10/10/21  
 PORTABLE INSPECTION DATE:

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	065						
92	072	Back door is blocked by desk and fire extinguisher is not within 5 feet of door. Relocate desk to keep a clear path to the door. Relocate fire extinguisher to be within 5' of door.					X
92	072A						
92	074	Bathroom GFCI does not trip - Emergency light not working					X
92	074A						
92	078	Electrical panel is blocked by items on top of cabinet, back door is blocked by rolling cart.					X
92	078A						
92	080						
92	082						
92	082A						
92	084						
92	084A						
92	090	Back door had rolling cart in front of it. Fire Alarm Pull station by front door was blocked by cabinet.. Relocate rolling cart to keep a clear path to door at all times. Relocate cabinet so Fire Alarm is accessible and operable at all times.					X
92	090A						
92	090B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR: 2021/2022**  
**DISTRICT: CLAY**  
**FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL - 0311**  
**900 S. ORCHID AVENUE**  
**KEYSTONE HEIGHTS, FL 32656**

*[Handwritten Signature]*  
 10/10/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	091						
92	091A						
92	091B						
92	029						
92	029A						
92	029B						
92	029C						
92	056A	Restrooms - did not inspect					
92	056B						
92	076A	Restrooms - did not inspect					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Jerry Parks*

8/25/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	001						
92	007						
92	009						
92	009A						
92	031						
92	031A						
92	031B						
92	032						
92	032A						
92	032B						
92	033						
92	033A						
92	034	Back exit is blocked by teachers desk chair. Must relocate desk so chair cannot roll into the exit path.					X
92	035	2021 emergency light does not work.					X
92	036						
92	036A						
92	036B						
92	041	2021 back door was blocked by plastic screen and cabinet. Must relocate plastic screen and cabinet.					X
92	041A						
92	041B						
92	042						
92	042A						
92	042B						
92	043						
92	044						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: *Jon Pat*

INSPECTOR SIGNATURE: \_\_\_\_\_  
 BUILDING INSPECTION DATE: \_\_\_\_\_  
 PORTABLE INSPECTION DATE: 8/25/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	044A						
92	044B						
92	045						
92	045A						
92	045B						
92	046						
92	046A						
92	046B						
92	051						
92	051A						
92	051B						
92	052						
92	052A						
92	052B						
92	053						
92	053A						
92	053B						
92	055						
92	055A						
92	060	Backed exit blocked by desk. Must keep a clear egress path to door. Must relocate desk out of the exit path.					X
92	061	2021 both exit lights do not work.					X
92	061A						X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

*[Handwritten Signature]*

8/25/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	062	Fire extinguisher is blocked by fake tree. Must relocate tree so fire extinguisher is visible and assessable. THIS IS A SERIOUS VIOLATION AND IS A CARRY OVER FROM LAST YEAR.					X
92	062A						
92	063						
92	063A	2021 outside GFCI is missing cover.					
92	064						
92	064A						
92	065						
92	065A						
92	066	2021 ceiling tile has two holes in it. Need to replace ceiling tiles.					X
92	066A						
92	067						
92	067A						
92	070						
92	071	Backed exit blocked by desk. Must keep a clear egress path to door. Must relocate desk out of the exit path.					X
92	071A						
92	072						
92	073						
92	073A						
92	073B						
92	074						
92	074A						
92	074B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

BUILDING INSPECTION DATE: 8/25/2021  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	075	2021 TV blocking back exit. Must relocate TV out of exit path way.					X
92	075A						
92	076	2021 emergency light does not work.					X
92	076A						
92	076B						
92	077						
92	077A						
92	077B						
92	077C						
92	077D						
92	078						
92	078A						
92	079	DCA Sticker in portable is MB E 001975. Need to change on FISH report.		X			
92	079A						
92	079B						
92	079C						
92	080						
92	080A						
92	081						
92	082						
92	084						
92	084A						
92	086						
92	088						
92	005						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

8/25/2021

INSPECTOR SIGNATURE: \_\_\_\_\_  
 BUILDING INSPECTION DATE: \_\_\_\_\_  
 PORTABLE INSPECTION DATE: \_\_\_\_\_

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	005A						
92	005B						
92	005C						
92	054A						
92	054B						
92	054C						
92	054D						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF HIGH SC.  
 4035 PLANTATION OA.  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *[Signature]*  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE: 10/2/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010						
92	010A						
92	011						
92	011A						
92	015						
92	015A						
92	015B						
92	015C						
92	015D						
92	016	Cabinet blocking front door with ramp fire stinger sure electrical panel and pull station being blocked by cabinet by the back door for tile is missing need repairs					X
92	016A						
92	021	Emergency light did not work					X
92	021A						
92	022						
92	022A						
92	023						
92	023A						
92	024	Secondary exit was blocked. Must keep path of egress clear at all times. Emergency light did not work. Electrical panel was blocked. Must keep electrical panel accessible and visible at all times.					X
92	024A						
92	025	Secondary exit was blocked by desk. Must keep path of egress clear at all times.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: *[Signature]*

BUILDING INSPECTION DATE:

10/2/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	025A						
92	026	Electrical panel w/s blocked. Must keep electrical panel accessible and visible at all times.					X
92	026A						
92	030						
92	030A						
92	31						
92	032						
92	033						
92	034						
92	034A						
92	035						
92	036						
92	040						
92	041						
92	041A						
92	042						
92	042A						
92	043						
92	043A						
92	044						
92	045						
92	046						
92	046A						
92	050						
92	051						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
 AND

FIRE SAFETY INSPECTION REPORT  
 F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: *[Signature]*

BUILDING INSPECTION DATE: 10/2/2021  
 PORTABLE INSPECTION DATE:

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	051A						
92	052						
92	053						
92	053A						
92	053B						
92	054	Emergency lights not working.					X
92	054A						
92	055						
92	056	Emergency lights not working.					X
92	060						
92	060A						
92	061						
92	062						
92	062A						
92	063	Door is blocked by desk and broken tile at back door. Must keep a clear egress path at all times.					X
92	063A						
92	064						
92	065	Emergency lights not working.					X
92	066	No evacuation map and emergency light does not work. There must be a emergency evacuation sheet properly placed by door.					X
92	020A	REST ROOMS					
92	020B						
92	027	RESTROOMS					
92	027A						
92	027B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:** *[Signature]*  
**BUILDING INSPECTION DATE:** 10/5/21  
**PORTABLE INSPECTION DATE:**


**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	035						
92	035A						
92	036						
92	036A						
92	037	Both emergency lights do not work					X
92	037A						
92	038	Remove items in front of electrical panel. Electrical panel must be visible at all times.					X
92	038A						
92	039	Emergency light globes are hanging off the fixture and does not work					X
92	039A						
92	040						
92	040A						
92	045						
92	045A						
92	049						
92	049A						
92	050	FIRE EXTINGUISHER IS STILL NOT PLACED WITH-IN 5' OF DOOR. SEE PICTURE					
92	050A						
92	051	Emergency light does not work					X
92	051A						
92	052						
92	052A						
92	053	Back door is blocked by desk. Must relocate desk to create a clear path to door.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32074

INSPECTOR SIGNATURE:   
 BUILDING INSPECTION DATE: 10/5/21  
 PORTABLE INSPECTION DATE:


Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	053A						
92	054	Electrical panel was blocked by lamp and boxes. The electrical panel must be visible and assessable at all times.					X
92	055						
92	055A						
92	056	Emergency light did not work					X
92	059	Back exit was blocked by rolling cart. Must keep exit path clear at all times.					X
92	060						
92	061						
92	061A						
92	061B						
92	061C						
92	062						
92	062A						
92	063						
92	063A						
92	064						
92	064A						
92	065	Emergency light by front door with ramp does not work					X
92	065A						
92	066	Emergency light by back door does not work.					X
92	066A						
92	067	Emergency light by front door did not work					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE:   
 BUILDING INSPECTION DATE: 10/5/21  
 PORTABLE INSPECTION DATE: 10/5/21

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	067A						
92	013	Popcorn ceiling still falling off both portables A and B. One is storage, the other is a office/storage					X
92	013A						
92	048	Emergency light does not work by back door GFCI does not work sparks flew out of it. Must replace with another GFCI					X
92	058A						
92	058B						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*[Handwritten Signature]*

9/8/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	4	2021 Has a extension cord hooked to coffee pot plugged in to receptacle that is not GFCI protected by sink. Need to remove extension cord or have the receptacle replaced by a GFCI.					X
92	004A						
92	004B						
92	005	2021 Back exit is blocked by cabinet and boxes. Exit must be kept clear at all times.					X
92	005A						
92	005B						
92	006	2021 Emergency lights not working.					X
92	006A						
92	007						
92	007A						
92	007B						
92	008						
92	008A						
92	009	2021 Front and back exit was blocked by desk and tables. Must arrange furniture as to have a 3' path to each door.					X
92	009A						
92	009B						
92	010						
92	010A						
92	011						
92	012						
92	012A						
92	021						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

*[Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

9/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	021A						
92	022	21 Back exit is blocked. Clear area between rows of clothes for egress to back door.					X
92	022A						
92	023						
92	023A						
92	024	2021 emergency light not working. Emergency evacuation map by door.					X
92	025	2021 emergency light not working.					X
92	025A						
92	025B						
92	026						
92	026A						
92	026B						
92	027	2021 back exit is blocked by desk. Must keep clear path to exit at all times.					X
92	027A						
92	027B						
92	028	2021 back exit is blocked by desk. Must keep clear path to exit at all times.					X
92	028A						
92	029	2021 back exit is blocked by cabinet. Must keep clear path to exit at all times.					X
92	029A						
92	029B						
92	029C						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Greg Parks*

9/8/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint	School
92	031	Back exit is blocked by school desk. Must have a clear path of egress. Emergency lights not working.					X
92	031A						
92	032	Back exit is blocked by school desk. Must have a clear path of egress. Emergency lights not working.					X
92	032A						
92	033						
92	033A						
92	034	2021 bean bag by the back door blocking exit. Receptacle left the sink receptacle is not a GFCI. Replace with GFCI.					X
92	034A						
92	041						
92	041A						
92	043						
92	043A						
92	044						
92	044A						
92	045						
92	046	2021 back exit is blocked by desk. Must keep clear path to exit at all times.					X
92	046A						
92	047						
92	047A						
92	048						
92	048A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGÉ PARK, FL 32065

*[Signature]*

INSPECTOR SIGNATURE:  
 BUILDING INSPECTION DATE:  
 PORTABLE INSPECTION DATE:

9/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	049						
92	049A						
92	050						
92	051	2021 emergency light does not work.					X
92	052						
92	052A						
92	061	2021 emergency light not working.					X
92	061A						
92	062						
92	062A						
92	064	2021 emergency lights do not work.					X
92	065						
92	066	2021 back exit is blocked by desk. Must keep clear path to exit at all times.					X
92	067	2021 Fire extinguisher is behind metal pan and fan. Fire extinguisher must be assessable at all times.					X
92	069	2021 emergency light does not work.					X
92	069A						
92	070	2021 Desk blocking back door. Exit must be clear at all times.					X
92	071						
92	071A						
92	072						
92	072A						
92	073	Outside GFCI cover is missing.					X
92	073A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

*Jerry Park*

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

9/8/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	081						
92	081A						
92	081B						
92	082						
92	082A						
92	082B						
92	083						
92	083A						
92	083B						
92	084						
92	084A						
92	084B						
92	085						
92	085A						
92	085B						
92	086	Doormap is a trip hazard in the egress path. Remove doormap by front door.					X
92	086A						
92	086B						
92	087	2021 back door is blocked by desk and American flag. Must keep path to door clear at all times.					X
92	087A						
92	087B						
92	088						
92	088A						
92	088B						
92	089	2021 emergency light not working. Emergency evacuation map by door.					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**   
**BUILDING INSPECTION DATE:** 9/8/2021  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	089A						
92	089B						
92	090	2021 violations have not been corrected. Electrical panel block by uniform storage rack. Portable being used for uniform storage.					X
92	090A						
92	090B						
92	090C						
92	090D						
92	091	Trophies are blocking electrical panel. Relocate trophies.					X
92	091A						
92	091B						
92	103	Roll around cart is blocking electrical panel. Relocate cart for storage.					X
92	103A						
92	001	2021. Rolling cabinet blocking electrical panel. Relocate rolling cabinet.					X
92	001A						
92	001B						
92	001C						
92	001D						
92	001E						
92	001F						
92	001G						
92	003						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**INSPECTOR SIGNATURE:**



**BUILDING INSPECTION DATE:**

9/8/2021

**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022

**DISTRICT:** CLAY

**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431

466 MADISON AVENUE

ORANGE PARK, FL 32065

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	003A						
92	003B						
92	030	2021 back exit is blocked by chair. Time out room being used for storage with no heat detector. Bathroom being used for storage with no heat detector.					X
92	030A						
92	030B						
92	030C						
92	030D						
92	030F						
92	068	2021 emergency light does not work.					X
92	092A						
92	092B						
92	101A	2021 emergency light does not work.					X
92	101B						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *Jerry Patis*

8/6/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	016	This is a portable shed did not inspect.					
92	062	Teacher had emergency door bracked in place blocking egress. Egress must be kept clear at all times.					X
92	001	Receptacle by sink needs to be a GFCI.					X
92	001A						
92	001B						
92	002	Heat detector and restroom is falling off box.					X
92	002A						
92	003						
92	003A						
92	004						
92	004A						
92	005						
92	005A						X
92	006A	Emergency light by the ramp door does not work.					
92	006B						
92	006C						
92	007	Emergency light not working.					X
92	007A						
92	008						
92	008A						
92	009						
92	009A						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*John Pato*  
 8/6/2021

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	010						
92	010A						
92	012						
92	012A						
92	013	Make sure switch and receptacle plates have been reinstalled after painting.					X
92	030	Receptacle by sink is not a GFCI.					X
92	030A						
92	030B						
92	030C						
92	032						
92	033						
92	033A						
92	034						
92	034A						
92	035						
92	035A						
92	036	Desk blocking back exit. Exit must be kept clear at all times.					X
92	036A						
92	036B						
92	037	Emergency light not working.					X
92	037A						
92	038						
92	038A						
92	039						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

*Yang Park*

8/6/2021

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	039A						
92	039B						
92	039C						
92	039D						
92	039E						
92	040						
92	040A						
92	042						
92	042A						
92	042B						
92	043						
92	043A						
92	044						
92	044A						
92	056	Plants around building and ramp need to be removed for school safety and to keep from damaging the building.					X
92	056A						
92	058	Back door latch does not work. So teacher is using emergency lock on floor to keep it shut. Door needs to be repaired.					X
92	058A						
92	011	GFCI by kitchen sink does not trip. This is a culinary classroom kitchen. It needs a K rated fire extinguisher.					X
92	011A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**INSPECTOR SIGNATURE:**  
**BUILDING INSPECTION DATE:**  
**PORTABLE INSPECTION DATE:**

**FISCAL YEAR:** 2021/2022  
**DISTRICT:** CLAY  
**FACILITY:** BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043

*Geo Pate*

8/6/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	014	LIBRARY PORTABLE. Plants around building and ramp need to be removed for school safety and to keep from damaging the building.					X
92	014A						
92	014B						
92	031	Plants around building and ramp need to be removed for school safety and to keep from damaging the building. See pictures					X
92	031A						
92	031B						
92	031C						
92	050	Emergency light does not work. GFCI by sink does not work.					X
92	050A						
92	050B						
92	050C						
92	052						
92	052A						
92	052B						
92	060A	This portable is a restroom.					
92	060B	Did not inspect.					
92	061A	This portable is a restroom.					
92	061B	Did not inspect.					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101  
 AND

FIRE SAFETY INSPECTION REPORT  
 F.S. 1013.12, 1013.20 & RULE 69A-58

INSPECTOR SIGNATURE: *[Signature]*

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 2/15/2022

FISCAL YEAR: 2021/2022

DISTRICT: CLAY

FACILITY: GREEN COVE SPRINGS BUS GARAGE  
 800 CENTER STREET  
 GREEN COVE SPRINGS, FL 32043

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	012	Portable not found		X			
92	012A						
92	012B						
92	012C						
92	012D						
92	012E						
92	012F						
92	012G						
92	012H						
92	012J						
92	012K						
93	012L						
92	012M						
92	002	Exit light by front door does not work.					X
92	002A						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

FISCAL YEAR: 2021/2022  
 DISTRICT: CLAY  
 FACILITY: KEYSTONE HEIGHTS TRANSPORTATION  
 6800 COUNTY ROAD 315  
 KEYSTONE HEIGHTS, FL 32656

**CASUALTY SAFETY & SANITATION INSPECTION**

**F.S. 1013.12, 1013.20 & NFPA 101**

AND

**FIRE SAFETY INSPECTION REPORT**

**F.S. 1013.12, 1013.20 & RULE 69A-58**

INSPECTOR SIGNATURE: *Joseph*

BUILDING INSPECTION DATE:

PORTABLE INSPECTION DATE: 10/2/2021

Building Number	Room Number	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Info Services	Maint.	School
92	2	OK					
92	002A	OK					