

FISCAL YEAR 2011-2012

DISTRICT: CLAY FACILITY: 0036

FACILITY: CLAY SUPERINTENDENT'S OFFICE
900 WALNUT STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: MARCH 7, 2012

Ted Sweatland
 INSPECTOR'S SIGNATURE 3-7-12
 DATE



**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|---------------------|------|--|---------------|--------------|-------------|--------------------------|------|----------------------------------|--------------------------------|----------------|
| 2 | 22 | OUTLET TO PROJECTOR ABOVE CEILING | | | X | | | | | NFPA 70-210 |
| 3 | 13 | EXTENSION CORD TO MICROWAVE – ADD PLUG | X | | | | | | | NFPA 70-400.8 |
| 3 | 13 | EXTERIOR STAIR/LANDING RAILING RUSTY | X | | | | | | | FBC 1005 |
| 3 | 62 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| RELOCATABLES | | | | | | | | | | |
| 95 | 1 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 95 | 1 | EMERGENCY LIGHT NOT WORKING | X | | | | | | | FBC 423.17.1 |
| 95 | 1 | NO ROOM NUMBER | | X | | | | | | FBC 423.14.2.1 |
| 95 | 2 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| 95 | 2 | NO ROOM NUMBER | | X | | | | | | FBC 423.14.2.1 |


FISCAL YEAR 2011-2012

DISTRICT: CLAY FACILITY: 0027

FACILITY: H. C. LONG ADMINISTRATION
23 SOUTH GREEN STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: MARCH 7, 2012

Ted Sweatt
 INSPECTOR'S SIGNATURE 3-7-12
 DATE



**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|---|---------------|--------------|-------------|--------------------------|------|----------------------------------|--------------------------------|--------------|
| 1 | 100 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 2 | 201B | ROMEX COMING OUT OF ELECTRICAL PANEL TO A PLUG FOR OLD AC UNIT - REMOVE | X | | | | | | | |
| 3 | 300 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 4 | 404A | ADD EXIT LIGHT - EMERGENCY LIGHT | X | | | | | | | FBC 423.17.1 |
| 4 | 405A | STAINED CEILING TILE | | X | | | | | | FBC 804.2.3 |
| 4 | 405A | HOLE IN CEILING | X | | | | | | | FBC 804.2.3 |
| 4 | 407A | OUTLET COVER MISSING ABOVE ELECTRIC PANEL | | X | | | | | | NFPA 70 |
| 4 | 415 | CEILING TILE MISSING | | X | | | | | | FBC 804.2.3 |
| 5 | | OK | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2011-2012

DISTRICT: CLAY FACILITY: 0033

FACILITY: MIDDLEBURG TRANSPORTATION
3674 COUNTY ROAD 220
MIDDLEBURG, FLORIDA 32043

INSPECTION DATE: MARCH 6, 2012

[Handwritten Signature]
 INSPECTOR'S SIGNATURE 3-6-12
 DATE



**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|--------------------------|------|----------------------------------|--------------------------------|------|
| 92 | 201 | OK | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2011-2012

DISTRICT: CLAY FACILITY: 0030



**COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**

FACILITY: SCHOOL BUS GARAGE - TRANSPORTATION
800 CENTER STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: MARCH 7, 2012

Tod Swearingen
INSPECTOR'S SIGNATURE 3-7-12
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|---------------------|------|--|---------------|--------------|-------------|--------------------------|------|----------------------------------|--------------------------------|--------------|
| 1 | 11 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 1 | 6A | CEILING TILES MISSING – STAIRWELL | | X | | | | | | FBC 804.2.3 |
| 1 | 200 | FIRE EXTINGUISHER NOT SIGNED | | X | | | | | | FAC 69A-58 |
| 1 | 200 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| RELOCATABLES | | | | | | | | | | |
| 95 | 1 | OK | | | | | | | | |
| 95 | 2 | OK | | | | | | | | |
| 91 | 3 | EMERGENCY LIGHT NOT WORKING | | X | | | | | | FBC 423.17.1 |
| | | | | | | | | | | |
| | | | | | | | | | | |

FISCAL YEAR 2011-2012

DISTRICT: CLAY FACILITY: 0003



**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**

FACILITY: SUPPORT SERVICE CENTER
925 WEST CENTER STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: MARCH 7, 2012

Joel Sweathart
 INSPECTOR'S SIGNATURE 3-7-12
DATE

| Building | Room | Deficiency Description and Corrective Action Required: | Maint. "M" | Oper. "O" | Fac. "C" | Info. Serv. "I.S." | Cost | No. of times Def. Cited | Scheduled for Correction | Rule |
|----------|------|--|---------------|--------------|-------------|--------------------------|------|----------------------------------|--------------------------------|--------------|
| 1 | 11A | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 2 | | OK | | | | | | | | |
| 4 | 2 | EQUIPMENT IN FRONT OF ELECTRICAL PANEL | | X | | | | | | NFPA 70 |
| 5 | | OK | | | | | | | | |
| 6 | | OK | | | | | | | | |
| 9 | | OK | | | | | | | | |
| 10 | 104 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 10 | 107 | EMERGENCY LIGHT OUT | | X | | | | | | FBC 423.17.1 |
| 11 | 107A | MOVE FIRE EXTINGUISHER TO LEFT OF DOOR | | X | | | | | | |
| 12 | | OK | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |