


**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** ARGYLE ELEMENTARY SCHOOL  
 2625 SPENCER PLANTATION BOULEVARD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** 12/9/2015

		Fire Drill Log: <input checked="" type="checkbox"/> 5 Drills Performed: <u>5</u>						
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2		OK					X	
3		OK						
4	433		Exit light missing					X
5	536	A/C-drain may be clogged. Lots of water on floor					X	
6	620		Exit light missing				X	
6	626		Exit light missing				X	
92	701	OK						
92	702	OK						X
92	703		Emergency light out					X
92	704		Emergency light out					X
92	705	OK						
92	706	OK						
92	711	OK						
92	713	OK						
92	714	OK						
92	801	OK						
92	802	OK						
92	803	OK						
92	804	OK						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** CHARLES E. BENNETT ELEMENTARY - 0071  
 1 SOUTH OAKRIDGE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 12/8/2015


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>4</u>	
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency
4	16	No exit light	
5	17	No exit light	
5	18	No exit light	
5	19	No exit light	
5	20	No exit light	
9		OK	
10	1A	Elevator Certificate out of date	
11	113	No exit light	
11	116	No exit light	
14		OK	
16		OK	
92	40	OK	
92	41	OK	
92	42	OK	
92	43	OK	
92	45	OK	
92	46	OK	
92	47	OK	
92	48	OK	
92	49	OK	
92	50	OK	
			Deficiency Not Corrected from Previous Inspection
			Facilities
			Information Services
			Maintenance
			School



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HILL ELEMENTARY - 0411  
 6345 COUNTY ROAD 218  
 JACKSONVILLE, FL 32234

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** 12/11/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2		OK						
3		OK						
4		OK						
5		OK						
6		OK						
7		OK						
92	682	OK						
92	701	OK						
92	702	OK						
92	703	OK						
92	704	OK						
92	705	OK						
92	706	OK						
92	707	OK						
92	708	OK						
92	709	OK						
92	710	OK						
92	712	OK						
92	760	OK						
92	762	OK						
92	764	OK						
92	766	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** COPPERGATE ELEMENTARY - 0601  
 2250 COUNTY ROAD 269 N.  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 12/11/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Drill Log: <input checked="" type="checkbox"/> 4	Drills Performed: <u>4</u>					
1		OK							
92	501	OK							
92	511	OK							
92	512	OK							
92	513	OK							
92	514	OK							
92	516	OK							
92	518	OK							
92	520	OK							

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** DOCTORS INLET ELEMENTARY - 0261  
 2634 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 1/7/2016

Fire Drill Log:    
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
4		OK						
5		OK						
7		OK						
8		OK						
9		OK						
92	836	OK						
92	837	OK						
92	838	OK						
92	839		Emergency light out				X	
92	840	OK						
92	842	OK						
92	843	OK						
92	844	OK						
92	845	OK						
92	847	OK						
92	849	OK						
92	869	OK						
92	870	Lens cover missing on light						X
92	871	OK						
92	872	Lens cover missing on light						X
92	873	OK						


92	874	OK								
92	876	OK								
92	888	OK								
92	889	OK								
92	890	OK								
92	891	OK								
92	892	OK								
92	893	OK								
92	894	OK								
92	895		Emergency light out						X	
92	896	OK								
92	897	OK								
92	899	OK								
92	921	OK								
92	923	OK								



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** 1/8/2016


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>						
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	**	Campus Wide - Intercom	weak in spots				X	
2	211	Room number missing						X
3		OK						
4	409		Exit light out					X
5		OK						
7		OK						
92	601		Emergency light out					X
92	602	OK						
92	603	OK						
92	604	OK						
92	605	OK						
92	606	OK						
92	607	OK						
92	608	OK						
92	801	Lens cover missing-closet						X
92	802	AC/drain clogged rotting out siding					X	
92	803		Emergency light out					X
92	804	AC/drain clogged rotting out siding					X	
92	805		Emergency light out					X



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** GROVE PARK ELEMENTARY - 0232  
 1643 MILLER STREET  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** 12/16/2015

Fire Drill Log:   
 Drills Performed: 4


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2	123		Emergency light out					X
6	605		Emergency evacuation sheet missing					X
6	611		Emergency light out	X				X
7	706		Emergency evacuation sheet missing					X
7	712		Emergency light out					X
8		OK						
9	4		Emergency light out					X
9	136		Emergency light out					X
9	137		Emergency light out					X
9	140		Emergency light out					X
9	142		Emergency light out					X
92	5	OK						
92	6	OK						
92	7	OK						
92	8	OK						
92	9	OK						
92	10	OK						
92	27	OK						
92	29	OK						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY - 0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** 2/22/2016

Fire Drill Log:   
 Drills Performed: 8

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2	225	Exhaust hood not working					X	
3	425	No evacuation sheet						X
3	426	No evacuation sheet						X
6		OK						
7		OK						
8	8		Identify emergency exit					X
9		OK						
10		OK						
11		OK						
12		OK						
92	1	OK						
92	701	OK						
92	702	OK						
92	703	Lens cover missing on lights						X
92	704	OK						
92	705	OK						
92	706	OK						
92	707		Emergency light out				X	
92	708	OK						
92	709	OK						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY ELEMENTARY - 0451  
 2901 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 2/2/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>5</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
1		OK							
2		OK							
3		OK							
4		OK							
5		OK							
6		OK							
7		OK							
92	9	OK							
92	10	OK							
92	11	OK							
92	12		Emergency light out						X
92	13	OK							
92	14	OK							
92	15	OK							
92	16	OK							
92	18	OK							
92	39	OK							
92	40	OK							
92	41	OK							
92	42	OK							
92	43		Emergency light out						X
92	44	Lens cover missing							X





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE ELEMENTARY SCHOOL - 0352  
 2752 MOODY ROAD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 2/3/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>5</u>	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	105		Emergency light out					X	
2	128		Emergency light out					X	
6		OK							
7		OK							
8		OK							
92	10	OK							
92	11	OK							
92	12	OK							
92	13	OK							
92	14	OK							
92	15	OK							
92	16		Excessive combustibles						X
92	17	OK							
92	18	OK							
92	19	OK							
92	20	OK							
92	21		Emergency light out					X	
92	22	OK							
92	23	OK							
92	24	OK							
92	25	OK							
92	26	OK							



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG ELEMENTARY - 0271  
 3958 MAIN STREET  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 1/26/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>7</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
1		OK							
2	4	Remove floor stripper							X
3		OK							
4		OK							
6		OK							
7	7220		No evacuation sheet						X
9		OK							
92	23	OK							
92	24	OK							
92	25	OK							
92	26	OK							
92	29	OK							
92	35	OK							
92	37	OK							
92	38	OK							
92	39	OK							
92	40	OK							
92	41	OK							
92	43	OK							
92	55	OK							
92	57	OK							
92	64	OK							



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** MCRAE ELEMENTARY - 0511  
 6770 COUNTY ROAD 315C  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 2/17/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>6</u>						
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2		OK						
3	320	Telephone cord on floor						X
5		OK						
6		OK						
92	401	OK						
92	402	OK						
92	403	OK						
92	404	OK						
92	405	OK						
92	406	OK						
92	407	OK						
92	408	OK						
92	801	OK						
92	702	OK						
92	703	OK						
92	704	OK						
92	705	OK						
92	706	OK						
92	707	OK						
92	708	OK						
92	801	OK						



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** MONTCLAIR ELEMENTARY - 0381  
 2398 MOODY ROAD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 1/26/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>5</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
1	104	Sewer gas problem in floor drain						X	
2	151	Freezer makes wall sweat/mildew/needs vapor barrier						X	
4		OK							
5		OK							
92	21	OK							
92	22	OK							
92	23	OK							
92	24	OK							
92	25	Pour concrete at end of ramp						X	
92	26	OK							
92	27	OK							
92	28	OK							
92	29	OK							
92	30	OK							
92	31	OK							
92	32	OK							
92	33	OK							
92	34	OK							

92	35	OK								
92	36	Trip hazard at stairs/ settled below concrete							X	
92	37	OK								
92	38	OK								
92	39	Lens cover missing								X
92	40	OK								
92	41	OK								
92	44	OK								
92	45	OK								
92	46A	OK								
92	46B	OK								
96	36	OK								



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF VILLAGE ELEMENTARY - 0621  
 410 OAKLEAF VILLAGE PARKWAY  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 1/13/2016

Fire Drill Log:   
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	303		Stage - Fire hose out of date- Red tag on riser- missing sprinkler head in spare box				X	
1	500	Ongoing roof leak-work order already in place						
20	2000		red tag on riser for same problem on stage				X	
25	2500	Thumb latch missing doors						
25	2503	Add exit lights					X	
25	2506	Add exit lights					X	
92	905	Missing lens cover						X
92	906	OK						
92	907	OK						
92	908	OK						
92	909	OK						
92	910	OK						
92	911	OK						
92	912	OK						
92	913	OK						
92	914	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK ELEMENTARY - 0201  
 1401 PLAINFIELD AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 1/20/2016


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>4</u>													
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School							
1	4	Clean up at handicap ramp						X							
2	5		Emergency windows not labeled					X							
2	6		Emergency windows not labeled					X							
2	7		Emergency windows not labeled					X							
3		OK													
4		OK													
5		OK													
7	10		No secondary exit				X								
7	11		No secondary exit				X								
7	11		No evacuation sheet	X											
7	12		No secondary exit				X								
7	13		No secondary exit				X								
7	14		No secondary exit				X								
7	15		No secondary exit				X								
92	21	OK													
92	22	OK													
92	23	OK													
92	24	OK													

92	34	OK																						
92	35	OK																						
92	36	OK																						
92	37	OK																						
92	38	OK																						
92	39								Emergency light out															X
92	41	OK																						
92	42	OK																						
92	43	OK																						
92	44								Emergency light out															X
92	45	OK																						
92	50	Lens cover missing on lights																						X
92	51								Emergency light out															X
92	52	OK																						
92	53	OK																						
92	54	OK																						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** PATERSON ELEMENTARY - 0471  
 5400 PINE AVENUE  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** 2/16/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>6</u>								
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School		
1	146		Evacuation sheet missing					X		
1	146		Emergency light out					X		
1	140		Exit light out					X		
2	201		Exit light out					X		
2	208	Red tag on fire sprinkler riser "Missing Hydrolic Placard"		X			X			
2	232		Exit light out					X		
3	301	Add outlet covers						X		
3	302	Excessive storage - room is refuge area for portable classrooms						X		
3	309	Remove storage Electric Room						X		
4	400	Move banner in hall-blocks exit light						X		
4	410	Too much storage-room is used for emergency refuge for children						X		
4	427	Too much storage-room is used for emergency refuge for children						X		




92	49	Ok								
92	50	Ok								
92	51	Ok								
92	52	Ok								
92	53	Ok								

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** PLANTATION OAKS ELEMENTARY - 0651  
 4150 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 1/12/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>4</u>	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	405		Surge detector loose					X	
20		OK							
21	2502		No exit light					X	
21	2502		No emergency light					X	
21	2505		No exit light					X	
21	2505		No emergency light					X	
92	901	OK							
92	902	OK							
92	903	OK							
92	904	OK							
92	905	OK							
92	906	OK							
92	907	OK							
92	908	OK							
92	909	OK							
92	910	OK							
92	911	OK							
92	912	OK							
92	913	OK							
92	914	OK							
92	915	OK							
92	916	Lens cover missing							X

92	917	OK								
92	918	OK								
92	919	OK								
92	920	OK								
92	921	OK								
92	922	OK								
92	923	OK								





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW ELEMENTARY - 0401  
 421 JEFFERSON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 3/23/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>6</u>	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK							
2		OK							
3		OK							
4		OK							
6		OK							
7		OK							
92	711	OK							
92	712	OK							
92	714	OK							
92	715		Emergency light out						X
92	717	Trip hazard at end ramp	Emergency light out		X			X	X
92	718	Trip hazard at end ramp						X	
92	728	OK							
92	729		Emergency light out						X
92	730		Emergency light out		X				X
92	731	OK							
92	732	OK							
92	733	OK							
92	734	OK							
92	735	OK							
92	737	OK							
92	738	OK							



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** S. BRYAN JENNINGS ELEMENTARY - 0331  
 215 CORONA DRIVE  
 ORANGE PARK, FLORIDA 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 2/1/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>4</u>	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK							
2		OK							
3		OK							
4		OK							
5		OK							
6		OK							
7		OK							
8	17E	Cover fire alarm box						X	
9		OK							
92	26	OK							
92	27	OK							
92	28	OK							
92	29	OK							
92	30	OK							
92	32	OK							
92	33	OK							
92	35	OK							
92	36	Lens cover missing on light							X
92	37	OK							
92	39	OK							
92	42	OK							






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** SWIMMING PEN CREEK ELEMENTARY - 0571  
 1630 WOODPECKER LAND  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 


**INSPECTION DATE:** 1/21/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>6</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK								
2		OK								
3		OK								
4		OK								
5		OK								
6		OK								
92	701	OK								
92	702		Excessive combustibles 20% max wall coverage		X					X
92	703	OK								
92	704	OK								
92	705	OK								
92	706	OK								
92	707	OK								
92	708	OK								
92	801		Emergency light out							X
92	803	OK								
92	804	OK								
92	806	OK								
92	808	OK								

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2015/2016  
**DISTRICT:** CLAY  
**FACILITY:** TYNES ELEMENTARY - 0501  
 1550 TYNES BOULEVARD  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** 2/18/2016

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>7</u>						
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
*		Unpermitted wood structure (pergola) by Cafeteria-needs to be removed.						X
1		OK						
2	203	Fire riser red tag		X			X	
3	301	Add outlet covers to Pre-K classrooms						X
3	315	Add outlet covers to Pre-K classrooms						X
4		OK						
5	518		Emergency evacuation sheet missing					X
6		OK						
92	1	OK						
92	2	OK						
92	3	OK						
92	4	OK						
92	5	OK						
92	6	OK						
92	7	OK						
92	8	OK						



