


**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** ARGYLE ELEMENTARY SCHOOL  
 2625 SPENCER PLANTATION BOULEVARD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** DECEMBER 2, 2013

Fire Drill Log: ✓  
 Drills Performed: 3


| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                        |            |                      |             |        |
| 2        | 200  | Secure TV with strap                    |                        |            |                      |             | X      |
| 2        | 201  | Microphone jack broken                  |                        |            |                      | X           |        |
| 3        |      | OK                                      |                        |            |                      |             |        |
| 4        |      | OK                                      |                        |            |                      |             |        |
| 5        | 510  |   | No evacuation sheet    |            |                      |             | X      |
| 6        | 603  |   | No evacuation sheet    |            |                      |             | X      |
| 92       | 701  | OK                                      |                        |            |                      |             |        |
| 92       | 702  | Replace ceiling tiles in restroom       |                        |            |                      |             | X      |
| 92       | 703  | OK                                      |                        |            |                      |             |        |
| 92       | 704  | OK                                      |                        |            |                      |             |        |
| 92       | 705  | OK                                      |                        |            |                      |             |        |
| 92       | 706  | OK                                      |                        |            |                      |             |        |
| 92       | 711  | OK                                      |                        |            |                      |             |        |
| 92       | 713  | OK                                      |                        |            |                      |             |        |
| 92       | 714  | OK                                      |                        |            |                      |             |        |
| 92       | 801  | Replace ceiling tiles in restroom       |                        |            |                      |             | X      |
| 92       | 802  | OK                                      |                        |            |                      |             |        |
| 92       | 803  | OK                                      |                        |            |                      |             |        |
| 92       | 804  | OK                                      |                        |            |                      |             |        |
| 92       | 805  | OK                                      |                        |            |                      |             |        |



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** CHARLES E. BENNETT ELEMENTARY - 0071  
 1 SOUTH OAKRIDGE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** December 4, 2013


Fire Drill Log:    
 Drills Performed: 3

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency               | Facilities | Information Services | Maintenance | School |
|----------|------|---|--------------------------------------|------------|----------------------|-------------|--------|
| 4        |      | OK                                      |                                      |            |                      |             |        |
| 5        |      | OK                                      |                                      |            |                      |             |        |
| 9        |      | OK                                      |                                      |            |                      |             |        |
| 10       | 1C   | Open fire alarm box at ceiling          |                                      |            |                      |             | X      |
| 11       | 107  |   | TV not strapped to bracket           |            |                      |             | X      |
| 11       | 112  |   | Exit light out                       |            |                      |             | X      |
| 11       | 112  |   | Remove extension cord across doorway |            |                      |             | X      |
| 14       | 1430 |   | Exit light out                       |            |                      |             | X      |
| 16       | 1530 | Outlet loose in wall                    |                                      |            |                      |             | X      |
| 92       | 40   | OK                                      |                                      |            |                      |             |        |
| 92       | 43   | OK                                      |                                      |            |                      |             |        |
| 92       | 46   | OK                                      |                                      |            |                      |             |        |
| 92       | 47   | OK                                      |                                      |            |                      |             |        |
| 92       | 48   | OK                                      |                                      |            |                      |             |        |
| 92       | 49   | OK                                      |                                      |            |                      |             |        |
| 92       | 50   | OK                                      |                                      |            |                      |             |        |
| 92       | 51   | OK                                      |                                      |            |                      |             |        |
| 92       | 52   | OK                                      |                                      |            |                      |             |        |
| 92       | 53   | OK                                      |                                      |            |                      |             |        |
| 92       | 54   | OK                                      |                                      |            |                      |             |        |
| 92       | 55   | OK                                      |                                      |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** CHARLES E. BENNETT ELEMENTARY - 0071  
 1 SOUTH OAKRIDGE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** December 4, 2013


Fire Drill Log:   
 Drills Performed: 3

| Building | Room | Casualty Safety & Sanitation Deficiency              | Fire Safety Deficiency          | Facilities | Information Services | Maintenance | School |
|----------|------|--|---------------------------------|------------|----------------------|-------------|--------|
| 92       | 56   | OK   |                                 |            |                      |             |        |
| 92       | 57   | OK   |                                 |            |                      |             |        |
| 92       | 59   | OK   |                                 |            |                      |             |        |
| 92       | 501  | OK   |                                 |            |                      |             |        |
| 92       | 502  | OK   |                                 |            |                      |             |        |
| 92       | 602  |  |                                 |            |                      |             |        |
| 92       | A&B  | OK   |                                 |            |                      |             |        |
| 92       | 603  |  |                                 |            |                      |             |        |
| 92       | A&B  | OK   |                                 |            |                      |             |        |
| 92       | 604  | OK   |                                 |            |                      |             |        |
| 92       | 702  | OK   |                                 |            |                      |             |        |
| 92       | 703  | OK   |                                 |            |                      |             |        |
| 92       | 803  | OK   |                                 |            |                      |             |        |
| 92       | 41   |  | Emergency light out             |            |                      |             | X      |
| 92       | 42   |  | Emergency light out             |            |                      |             | X      |
| 92       | 45   |  | Exit light needs to be put back |            |                      | X           |        |
| 91       | 503  | Ceiling tiles missing or damaged - repair or replace |                                 |            |                      | X           |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HILL ELEMENTARY - 0411  
 6345 COUNTY ROAD 218  
 JACKSONVILLE, FL 32234

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** December 6, 2013

Fire Drill Log:  4  
 Drills Performed: 4

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                        |            |                      |             |        |
| 2        |      | OK                                      |                        |            |                      |             |        |
| 5        | 502  |   | No evacuation sheet    |            |                      |             | X      |
| 6        | 603  |   | No evacuation sheet    |            |                      |             | X      |
| 7        |      | OK                                      |                        |            |                      |             |        |
| 92       | 682  | OK                                      |                        |            |                      |             |        |
| 92       | 688  | OK                                      |                        |            |                      |             |        |
| 92       | 701  | Projector plug above ceiling            |                        | X          |                      |             |        |
| 92       | 702  | OK                                      |                        |            |                      |             |        |
| 92       | 703  | OK                                      |                        |            |                      |             |        |
| 92       | 704  | OK                                      |                        |            |                      |             |        |
| 92       | 705  | OK                                      |                        |            |                      |             |        |
| 92       | 706  | OK                                      |                        |            |                      |             |        |
| 92       | 707  | OK                                      |                        |            |                      |             |        |
| 92       | 708  | OK                                      |                        |            |                      |             |        |
| 92       | 709  | Redirect downspout - eroding pier       |                        |            |                      | X           |        |
| 92       | 710  | OK                                      |                        |            |                      |             |        |
| 92       | 711  | OK                                      |                        |            |                      |             |        |
| 92       | 712  | Projector plug above ceiling            |                        | X          |                      |             |        |
| 92       | 760  | OK                                      |                        |            |                      |             |        |
| 92       | 762  | OK                                      |                        |            |                      |             |        |





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** DOCTORS INLET ELEMENTARY - 0261  
 2634 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** December 11, 2013

Fire Drill Log:   
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency        | Facilities | Information Services | Maintenance | School |
|----------|------|---|-------------------------------|------------|----------------------|-------------|--------|
| 4        |      | OK                                      |                               |            |                      |             |        |
| 5        | 112  |   | Open junction box at Room 118 |            |                      | X           |        |
| 7        | 704  |   | No evacuation sheet           |            |                      |             | X      |
| 8        | 801  |   | No evacuation sheet           |            |                      |             | X      |
| 8        | 803  |   | No evacuation sheet           |            |                      |             | X      |
| 8        | 808  |   | No evacuation sheet           |            |                      |             | X      |
| 9        |      | OK                                      |                               |            |                      |             |        |
| 92       | 836  | OK                                      |                               |            |                      |             |        |
| 92       | 837  | OK                                      |                               |            |                      |             |        |
| 92       | 838  | OK                                      |                               |            |                      |             |        |
| 92       | 839  | OK                                      |                               |            |                      |             |        |
| 92       | 840  |   | Exposed wires at clock outlet |            |                      | X           |        |
| 92       | 842  | OK                                      |                               |            |                      |             |        |
| 92       | 843  | OK                                      |                               |            |                      |             |        |
| 92       | 844  | OK                                      |                               |            |                      |             |        |
| 92       | 845  | OK                                      |                               |            |                      |             |        |
| 92       | 847  | OK                                      |                               |            |                      |             |        |
| 92       | 849  | OK                                      |                               |            |                      |             |        |
| 92       | 869  | OK                                      |                               |            |                      |             |        |
| 92       | 870  | OK                                      |                               |            |                      |             |        |
| 92       | 871  | OK                                      |                               |            |                      |             |        |
| 92       | 872  | OK                                      |                               |            |                      |             |        |






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** December 11, 2013

Fire Drill Log:    
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency             | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------------------|------------|----------------------|-------------|--------|
|          |      |   |                                    |            |                      |             |        |
| 1        |      | OK                                      |                                    |            |                      |             |        |
| 2        |      | OK                                      |                                    |            |                      |             |        |
| 3        | 304  |   | Emergency evacuation sheet missing |            |                      |             | X      |
| 3        | 313  |   | Emergency evacuation sheet missing |            |                      |             | X      |
| 3        | 320  |   | Emergency evacuation sheet missing |            |                      |             | X      |
| 3        | 323  |   | Emergency evacuation sheet missing |            |                      |             | X      |
| 4        |      | OK                                      |                                    |            |                      |             |        |
| 5        |      | OK                                      |                                    |            |                      |             |        |
| 7        |      | OK                                      |                                    |            |                      |             |        |
| 92       | 601  | OK                                      |                                    |            |                      |             |        |
| 92       | 604  | OK                                      |                                    |            |                      |             |        |
| 92       | 605  | OK                                      |                                    |            |                      |             |        |
| 92       | 606  | OK                                      |                                    |            |                      |             |        |
| 92       | 607  | OK                                      |                                    |            |                      |             |        |
| 92       | 801  | OK                                      |                                    |            |                      |             |        |
| 92       | 802  | OK                                      |                                    |            |                      |             |        |
| 92       | 803  | OK                                      |                                    |            |                      |             |        |
| 92       | 602  |   | Emergency light out                |            |                      |             | X      |
| 92       | 603  |   | Emergency light out                |            |                      |             | X      |
| 92       | 804  | OK                                      |                                    |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND ELEMENTARY - 0521  
 4425 LAKESHORE DRIVE  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** December 11, 2013

Fire Drill Log:    
 Drills Performed: 5


| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency             | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------------------|------------|----------------------|-------------|--------|
|          |      |   |                                    |            |                      |             |        |
| 92       | 805  | OK                                      |                                    |            |                      |             |        |
| 92       | 807  | OK                                      |                                    |            |                      |             |        |
| 92       | 808  | OK                                      |                                    |            |                      |             |        |
| 92       | 809  | OK                                      |                                    |            |                      |             |        |
| 92       | 812  | OK                                      |                                    |            |                      |             |        |
| 92       | 821  | OK                                      |                                    |            |                      |             |        |
| 92       | 826  | OK                                      |                                    |            |                      |             |        |
| 92       | 828  | OK                                      |                                    |            |                      |             |        |
| 92       | 806  |   | Excessive combustible on ceiling   |            |                      |             | X      |
| 92       | 824  |   | Emergency evacuation sheet missing |            |                      |             | X      |
| 92       | 830  | OK                                      |                                    |            |                      |             |        |
| 92       | 832  | OK                                      |                                    |            |                      |             |        |
| 92       | 841  | OK                                      |                                    |            |                      |             |        |
| 92       | 842  | OK                                      |                                    |            |                      |             |        |
| 92       | 843  | OK                                      |                                    |            |                      |             |        |
| 92       | 844  | OK                                      |                                    |            |                      |             |        |
| 92       | 846  | OK                                      |                                    |            |                      |             |        |
| 92       | 848  | OK                                      |                                    |            |                      |             |        |
| 92       | 850  | OK                                      |                                    |            |                      |             |        |
| 92       | 860  | OK                                      |                                    |            |                      |             |        |
| 92       | 861  | OK                                      |                                    |            |                      |             |        |
| 92       | 862  | OK                                      |                                    |            |                      |             |        |



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** GROVE PARK ELEMENTARY - 0232  
 1643 MILLER STREET  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** DECEMBER 18, 2013


Fire Drill Log:   
 Drills Performed: 1

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency              | Facilities | Information Services | Maintenance | School |
|----------|------|---|-------------------------------------|------------|----------------------|-------------|--------|
|          |      |   |                                     |            |                      |             |        |
| 1        |      | OK                                      |                                     |            |                      |             |        |
| 2        | 131A |   | Missing exit sign (light)           |            |                      | X           |        |
| 2        | 131  |   | Missing exit sign (light)           |            |                      | X           |        |
| 6        | 602  |   | No evacuation sheet                 |            |                      |             | X      |
| 6        | 606  |   | No evacuation sheet                 |            |                      |             | X      |
| 7        | 704  |   | No evacuation sheet                 |            |                      |             | X      |
| 7        | 706  |   | No evacuation sheet                 |            |                      |             | X      |
| 7        | 707  |   | No evacuation sheet                 |            |                      |             | X      |
| 8        | 11   |   | No exit light                       |            |                      | X           |        |
| 8        | 14A  |   | No exit light                       |            |                      | X           |        |
| 9        | 1    |   | No exit light. No evacuation sheet  |            |                      | X           | X      |
| 9        | 2    |   | No exit light. No evacuation sheet. |            |                      | X           | X      |
| 9        | 3    |   | No exit light. No evacuation sheet. |            |                      | X           | X      |
| 9        | 4    |   | No exit light.                      |            |                      | X           |        |
| 92       | 501  | OK                                      |                                     |            |                      |             |        |
| 92       | 504  |   | Emergency light out                 |            |                      | X           |        |
| 92       | 505  | OK                                      |                                     |            |                      |             |        |
| 92       | 506  |   | Emergency light out                 |            |                      | X           |        |
| 92       | 507  | OK                                      |                                     |            |                      |             |        |
| 92       | 520  |   | Knockout missing in electric panel  |            |                      | X           |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** GROVE PARK ELEMENTARY - 0232  
 1643 MILLER STREET  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** DECEMBER 18, 2013

Fire Drill Log:   
 Drills Performed: 1

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 92       | 521  | OK                                      |                        |            |                      |             |        |
| 92       | 522  | OK                                      |                        |            |                      |             |        |
| 92       | 523  | OK                                      |                        |            |                      |             |        |
| 92       | 524  |   | Emergency light out    |            |                      | X           |        |
| 92       | 525  | OK                                      |                        |            |                      |             |        |
| 92       | 526  | OK                                      |                        |            |                      |             |        |
| 92       | 527  | OK                                      |                        |            |                      |             |        |
| 92       | 528  | OK                                      |                        |            |                      |             |        |
| 92       | 5    | OK                                      |                        |            |                      |             |        |
| 92       | 6    |   | Emergency light out    |            |                      | X           |        |
| 92       | 7    | OK                                      |                        |            |                      |             |        |
| 92       | 8    | OK                                      |                        |            |                      |             |        |
| 92       | 9    | OK                                      |                        |            |                      |             |        |
| 92       | 71   |   | Emergency light out    |            |                      | X           |        |
| 92       | 10   | OK                                      |                        |            |                      |             |        |
| 92       | 27   |   | No evacuation sheet    |            |                      |             | X      |
| 92       | 29   | OK                                      |                        |            |                      |             |        |
| 92       | 30   | OK                                      |                        |            |                      |             |        |
| 92       | 31   | OK                                      |                        |            |                      |             |        |
| 92       | 43   | OK                                      |                        |            |                      |             |        |
| 92       | 44   | OK                                      |                        |            |                      |             |        |
| 92       | 500  | OK                                      |                        |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY - 0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** January 9, 2014

Fire Drill Log:    
 Drills Performed: 3

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency         | Facilities | Information Services | Maintenance | School |
|----------|------|---|--------------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                                |            |                      |             |        |
| 2        |      | OK                                      |                                |            |                      |             |        |
| 3        |      | OK                                      |                                |            |                      |             |        |
| 4        |      | Re paint peeling, mold under window     |                                |            |                      | X           |        |
| 5        |      | OK                                      |                                |            |                      |             |        |
| 6        |      | OK                                      |                                |            |                      |             |        |
| 7        |      | OK                                      |                                |            |                      |             |        |
| 8        | 8    |   | Remove paper from ceiling      |            |                      |             | X      |
| 9        | 912  | Lens missing on light                   |                                |            |                      |             | X      |
| 10       | 20M  |   | Install exit sign              |            |                      | X           |        |
| 10       | 26   |   | No evacuation sheet            |            |                      |             | X      |
| 10       | 27   |   | Add exit sign to exterior door |            |                      |             | X      |
| 10       | 28   |   | Add exit sign to exterior door |            |                      |             | X      |
| 32       | 32   |   | No evacuation sheet            |            |                      |             | X      |
| 11       |      | OK                                      |                                |            |                      |             |        |
| 12       | 1205 | Rotted wood at exterior window          |                                |            |                      | X           |        |
| 12       | 1206 | Rotted wood at exterior window          |                                |            |                      | X           |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS ELEMENTARY - 0301  
 335 SW PECAN STREET  
 KEYSTONE HEIGHTS/FL 32656

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** January 9, 2014

Fire Drill Log:    
 Drills Performed: 3

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
|          |      |   |                        |            |                      |             |        |
| 92       | 001  | OK                                      |                        |            |                      |             |        |
| 92       | 701  | OK                                      |                        |            |                      |             |        |
| 92       | 702  | OK                                      |                        |            |                      |             |        |
| 92       | 703  | OK                                      |                        |            |                      |             |        |
| 92       | 704  | OK                                      |                        |            |                      |             |        |
| 92       | 705  | OK                                      |                        |            |                      |             |        |
| 92       | 706  | OK                                      |                        |            |                      |             |        |
| 92       | 707  | OK                                      |                        |            |                      |             |        |
| 92       | 708  | OK                                      |                        |            |                      |             |        |
| 92       | 709  | OK                                      |                        |            |                      |             |        |
| 92       | 710  | OK                                      |                        |            |                      |             |        |
| 92       | 713  | OK                                      |                        |            |                      |             |        |
| 92       | 714  |   | No evacuation sheet    |            |                      |             | X      |
| 92       | 715  | OK                                      |                        |            |                      |             |        |
| 92       | 716  | OK                                      |                        |            |                      |             |        |
| 92       | 717  | OK                                      |                        |            |                      |             |        |
| 92       | 718  | OK                                      |                        |            |                      |             |        |
| 92       | 719  | OK                                      |                        |            |                      |             |        |
| 92       | 721  | OK                                      |                        |            |                      |             |        |
| 92       | 722  | OK                                      |                        |            |                      |             |        |
| 92       | 724  | OK                                      |                        |            |                      |             |        |
| 92       | 750  |   | Emergency light out    |            |                      | X           |        |
| 92       | 751  | OK                                      |                        |            |                      |             |        |






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY ELEMENTARY - 0451  
 2901 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043


**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** January 14, 2014

| Building | Room | Casualty Safety & Sanitation Deficiency     | Fire Drill Log: <input checked="" type="checkbox"/> / Drills Performed: <u>3</u> |                        | Fire Safety Deficiency         | Facilities | Information Services | Maintenance | School |
|----------|------|---|--|------------------------|--------------------------------|------------|----------------------|-------------|--------|
|          |      |   | Fire Safety Deficiency   | Fire Safety Deficiency |                                |            |                      |             |        |
| 1        | 117  |   |  |                        | Remove material from top shelf |            |                      |             | X      |
| 2        |      | OK  |  |                        |                                |            |                      |             |        |
| 5        | 524  |   |  |                        | Add fire extinguisher by range |            |                      |             | X      |
| 6        | 630  | Ants by door                                |  |                        |                                |            |                      |             |        |
| 7        |      | OK  |  |                        |                                |            |                      |             |        |
| 92       | 9    | OK  |  |                        |                                |            |                      |             |        |
| 92       | 10   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 11   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 12   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 13   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 14   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 15   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 16   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 18   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 39   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 40   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 42   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 43   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 44   | Hose bib at bottom of ramp needs protection |  |                        |                                |            |                      | X           |        |
| 92       | 46   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 48   | OK  |  |                        |                                |            |                      |             |        |
| 92       | 69   |   |  |                        | Emergency light out            |            |                      | X           |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY ELEMENTARY - 0451  
 2901 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** January 14, 2014


Fire Drill Log:   
 Drills Performed: 3

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 92       | 70   | OK                                      |                        |            |                      |             |        |
| 92       | 71   |   | Emergency light out    |            |                      | X           |        |
| 92       | 72   |   | Emergency light out    |            |                      | X           |        |
| 92       | 73   | OK                                      |                        |            |                      |             |        |
| 92       | 74   | OK                                      |                        |            |                      |             |        |
| 92       | 75   | OK                                      |                        |            |                      |             |        |
| 92       | 76   | OK                                      |                        |            |                      |             |        |
| 92       | 77   | OK                                      |                        |            |                      |             |        |
| 92       | 79   | Light out in storage/electrical room    |                        |            |                      |             | X      |
| 92       | 80   | OK                                      |                        |            |                      |             |        |
| 92       | 81   | OK                                      |                        |            |                      |             |        |
| 92       | 82   | OK                                      |                        |            |                      |             |        |
| 92       | 84   | OK                                      |                        |            |                      |             |        |
| 92       | 85   | OK                                      |                        |            |                      |             |        |
| 92       | 86   | OK                                      |                        |            |                      |             |        |
| 92       | 87   | OK                                      |                        |            |                      |             |        |
| 92       | 88   | OK                                      |                        |            |                      |             |        |
| 92       | 89   | OK                                      |                        |            |                      |             |        |
| 92       | 90   | OK                                      |                        |            |                      |             |        |
| 92       | 91   | OK                                      |                        |            |                      |             |        |
| 92       | 93   |   | Emergency light out    |            |                      |             | X      |
| 92       | 94   | OK                                      |                        |            |                      |             |        |
| 92       | 95   | OK                                      |                        |            |                      |             |        |
| 92       | 96   | OK                                      |                        |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE ELEMENTARY - 0352  
 2752 MOODY ROAD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** January 21, 2014

Fire Drill Log:   
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency          | Facilities | Information Services | Maintenance | School |
|----------|------|---|---------------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                                 |            |                      |             |        |
| 2        |      | OK                                      |                                 |            |                      |             |        |
| 4        |      | OK                                      |                                 |            |                      |             |        |
| 5        |      | OK                                      |                                 |            |                      |             |        |
| 6        | 613  | Lens missing on light                   |                                 |            |                      |             | X      |
| 7        |      | OK                                      |                                 |            |                      |             |        |
| 8        | 804  |   | Excessive combustibles on walls |            |                      |             | X      |
| 92       | 10   |   | Emergency light out             |            |                      | X           |        |
| 92       | 11   | OK                                      |                                 |            |                      |             |        |
| 92       | 12   | OK                                      |                                 |            |                      |             |        |
| 92       | 13   | OK                                      |                                 |            |                      |             |        |
| 92       | 14   | OK                                      |                                 |            |                      |             |        |
| 92       | 15   | OK                                      |                                 |            |                      |             |        |
| 92       | 16   | OK                                      |                                 |            |                      |             |        |
| 92       | 17   | OK                                      |                                 |            |                      |             |        |
| 92       | 18   | OK                                      |                                 |            |                      |             |        |
| 92       | 19   | Ramp not attached to building           |                                 |            |                      | X           |        |
| 92       | 20   | OK                                      |                                 |            |                      |             |        |
| 92       | 21   | OK                                      |                                 |            |                      |             |        |
| 92       | 22   | OK                                      |                                 |            |                      |             |        |
| 92       | 23   | OK                                      |                                 |            |                      |             |        |
| 92       | 24   | OK                                      |                                 |            |                      |             |        |
| 92       | 25   | OK                                      |                                 |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE ELEMENTARY - 0352  
 2752 MOODY ROAD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** January 21, 2014

Fire Drill Log:   ✓    
 Drills Performed:   5  

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency                    | Facilities | Information Services | Maintenance | School |
|----------|------|---|---|------------|----------------------|-------------|--------|
| 92       | 26   | OK                                      |   |            |                      |             |        |
| 92       | 27   | OK                                      |   |            |                      |             |        |
| 92       | 42   |   | Emergency light out (B)                   |            |                      | X           |        |
| 92       | 43   | OK                                      |   |            |                      |             |        |
| 92       | 44   | OK                                      |   |            |                      |             |        |
| 92       | 45   | OK                                      |   |            |                      |             |        |
| 92       | 46   | OK                                      |   |            |                      |             |        |
| 92       | 47   | OK                                      |   |            |                      |             |        |
| 92       | 48   | OK                                      |   |            |                      |             |        |
| 92       | 51   |   | File cabinet in front of electrical panel |            |                      |             | X      |
| 92       | 52   | OK                                      |   |            |                      |             |        |
| 92       | 53   | OK                                      |   |            |                      |             |        |
| 92       | 54   | Conduit loose at exterior box           |   |            |                      | X           |        |
| 92       | 55   | OK                                      |   |            |                      |             |        |
| 92       | 56   | OK                                      |   |            |                      |             |        |
| 92       | 57   | OK                                      |   |            |                      |             |        |
| 92       | 58   | OK                                      |   |            |                      |             |        |
| 92       | 59   | OK                                      |   |            |                      |             |        |
| 92       | 60   |   | Emergency light out                       |            |                      | X           |        |
| 92       | 61   | OK                                      |   |            |                      |             |        |
| 92       | 62   | OK                                      |   |            |                      |             |        |
| 92       | 63   | OK                                      |   |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** MCRAE ELEMENTARY - 0511  
 6770 COUNTY ROAD 315 C  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** January 9, 2014

Fire Drill Log:    
 Drills Performed: 3


| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency                     |            |                      |             | School |
|----------|------|---|--|------------|----------------------|-------------|--------|
|          |      |   | Fire Safety Deficiency                     | Facilities | Information Services | Maintenance |        |
| **       |      |   | All fire extinguishers out of date         |            |                      |             |        |
| 1        |      | OK                                      |  |            |                      |             |        |
| 2        | 213  |   | Remove material in front of electric panel |            |                      |             | X      |
| 3        | 320  | Reroute data from doorway               |  |            | X                    |             |        |
| 5        |      | OK                                      |  |            |                      |             |        |
| 6        |      | OK                                      |  |            |                      |             |        |
| 92       | 401  | OK                                      |  |            |                      |             |        |
| 92       | 402  | OK                                      |  |            |                      |             |        |
| 92       | 403  | OK                                      |  |            |                      |             |        |
| 92       | 404  | OK                                      |  |            |                      |             |        |
| 92       | 406  | OK                                      |  |            |                      |             |        |
| 92       | 407  | OK                                      |  |            |                      |             |        |
| 92       | 408  | OK                                      |  |            |                      |             |        |
| 92       | 701  | OK                                      |  |            |                      |             |        |
| 92       | 702  | OK                                      |  |            |                      |             |        |
| 92       | 703  | OK                                      |  |            |                      |             |        |
| 92       | 704  | OK                                      |  |            |                      |             |        |
| 92       | 705  | OK                                      |  |            |                      |             |        |
| 92       | 706  | OK                                      |  |            |                      |             |        |
| 92       | 707  | OK                                      |  |            |                      |             |        |



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG ELEMENTARY - 0271  
 3958 MAIN STREET  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** January 21, 2014

Fire Drill Log:    
 Drills Performed: 6

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency                    | Facilities | Information Services | Maintenance | School |
|----------|------|---|---|------------|----------------------|-------------|--------|
|          |      |   |   |            |                      |             |        |
| 1        |      | OK                                      |   |            |                      |             |        |
| 2        |      | OK                                      |   |            |                      |             |        |
| 3        | 2    |   | No strain-relief/electrical strip outlets |            |                      | X           |        |
| 3        | 3    |   | No strain-relief/electrical strip outlets |            |                      | X           |        |
| 4        | 17   |   | No emergency evacuation sheet             |            |                      |             | X      |
| 4        | 18   |   | No emergency evacuation sheet             |            |                      |             | X      |
| 6        | 636  |   | Remove gas powered equipment              |            |                      |             | X      |
| 7        |      | OK                                      |   |            |                      |             |        |
| 9        |      | OK                                      |   |            |                      |             |        |
| 92       | 23   | OK                                      |   |            |                      |             |        |
| 92       | 25   | OK                                      |   |            |                      |             |        |
| 92       | 28   | OK                                      |   |            |                      |             |        |
| 92       | 29   | OK                                      |   |            |                      |             |        |
| 92       | 35   | OK                                      |   |            |                      |             |        |
| 92       | 38   | OK                                      |   |            |                      |             |        |
| 92       | 39   | OK                                      |   |            |                      |             |        |
| 92       | 40   | OK                                      |   |            |                      |             |        |
| 92       | 41   | OK                                      |   |            |                      |             |        |
| 92       | 43   | OK                                      |   |            |                      |             |        |
| 92       | 55   | OK                                      |   |            |                      |             |        |






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** MONTCLAIR ELEMENTARY - 0381  
 2398 MOODY ROAD  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** January 16, 2014

|          |      | Fire Drill Log: <input checked="" type="checkbox"/><br>Drills Performed: <u>4</u> |  |            |                      |             |        |
|----------|------|---|--|------------|----------------------|-------------|--------|
| Building | Room | Casualty Safety & Sanitation Deficiency   | Fire Safety Deficiency                 | Facilities | Information Services | Maintenance | School |
| 1        |      | OK  |  |            |                      |             |        |
| 2        | 135  |   | Excessive materials in electrical room |            |                      |             | X      |
| 4        | 422  |   | Excessive combustibles in classroom    |            |                      |             | X      |
| 5        |      | General note to remove storage from top shelf in all closets                      |  |            |                      |             | X      |
| 5        | 523  | Electrical panel knock out/open both sides of electrical panel                    |  |            |                      | X           |        |
| 5        | 524  |   | Remove material from office            |            |                      |             | X      |
| 92       | 21   | OK  |  |            |                      |             |        |
| 92       | 22   | OK  |  |            |                      |             |        |
| 92       | 23   | OK  |  |            |                      |             |        |
| 92       | 24   | OK  |  |            |                      |             |        |
| 92       | 25   | OK  |  |            |                      |             |        |
| 92       | 26   | OK  |  |            |                      |             |        |
| 92       | 27   | OK  |  |            |                      |             |        |
| 92       | 28   | OK  |  |            |                      |             |        |
| 92       | 29   | OK  |  |            |                      |             |        |
| 92       | 30   | OK  |  |            |                      |             |        |
| 92       | 31   | OK  |  |            |                      |             |        |
| 92       | 32   | OK  |  |            |                      |             |        |






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014

**DISTRICT:** CLAY

**FACILITY:** ORANGE PARK ELEMENTARY - 0201  
 1401 PLAINFIELD AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** JANUARY 27, 2014

Fire Drill Log:    
 Drills Performed: 4

| Building | Room  | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency  | Facilities | Information Services | Maintenance | School |
|----------|-------|---|---|------------|----------------------|-------------|--------|
| 1        |       | OK                                      |   |            |                      |             |        |
| 2        |       | OK                                      |   |            |                      |             |        |
| 3        |       | OK                                      |   |            |                      |             |        |
| 4        | 92    | Insulation loose on duct                |   |            |                      |             | X      |
| 4        | 91    | Open electrical junction box            |   |            |                      |             | X      |
| 5        | 19A   | Lense missing light                     |   |            |                      |             | X      |
| 7        |       | OK                                      |   |            |                      |             |        |
| 92       | 21    | OK                                      |   |            |                      |             |        |
| 92       | 22    | OK                                      |   |            |                      |             |        |
| 92       | 23    | OK                                      |   |            |                      |             |        |
| 92       | 24    | OK                                      |   |            |                      |             |        |
| 92       | 34    | OK                                      |   |            |                      |             |        |
| 92       | 35    | OK                                      |   |            |                      |             |        |
| 92       | 36    | OK                                      |   |            |                      |             |        |
| 92       | 37    | OK                                      |   |            |                      |             |        |
| 92       | 38    | OK                                      |   |            |                      |             |        |
|          |       |   | Emergency light missing - side B. Conduit at base of ramp loose. Disconnected from LB/conduit |            |                      |             |        |
| 92       | 39A&B |   |   |            |                      | X           |        |
| 92       | 41    | OK                                      |   |            |                      |             |        |
| 92       | 42    | OK                                      |   |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** PATTERSON ELEMENTARY - 0471  
 5400 PINE AVENUE  
 FLEMING ISLAND, FL 32003


**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** FEBRUARY 3, 2014

|          |      | Fire Drill Log: <input checked="" type="checkbox"/><br>Drills Performed: <u>4</u> |  |            |                      |             |        |
|----------|------|---|--|------------|----------------------|-------------|--------|
| Building | Room | Casualty Safety & Sanitation Deficiency   | Fire Safety Deficiency                                       | Facilities | Information Services | Maintenance | School |
| 1        | 142  |   | Extension cord to extension cord - plug directly into outlet |            |                      |             | X      |
| 2        |      | OK  |  |            |                      |             |        |
| 3        |      | OK  |  |            |                      |             |        |
| 4        | 412  |   | Emergency evacuation sheet missing                           |            |                      |             | X      |
| 5        |      | OK  |  |            |                      |             |        |
| 6        | 601  |   | Knock out missing electric panel                             |            |                      |             | X      |
| 95       |      | Restroom - OK   |  |            |                      |             |        |
| 92       | 1    | OK  |  |            |                      |             |        |
| 92       | 2    | OK  |  |            |                      |             |        |
| 92       | 3    | OK  |  |            |                      |             |        |
| 92       | 4    | OK  |  |            |                      |             |        |
| 92       | 5    | OK  |  |            |                      |             |        |
| 92       | 6    | OK  |  |            |                      |             |        |
| 92       | 8    | OK  |  |            |                      |             |        |
| 92       | 11   | OK  |  |            |                      |             |        |
| 92       | 13   | OK  |  |            |                      |             |        |
| 92       | 14   | OK  |  |            |                      |             |        |
| 92       | 15   | OK  |  |            |                      |             |        |
| 92       | 16   | OK  |  |            |                      |             |        |
| 92       | 21   | OK  |  |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** PATTERSON ELEMENTARY - 0471  
5400 PINE AVENUE  
FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** FEBRUARY 3, 2014

Fire Drill Log:   
Drills Performed: 4

| Building | Room | Casualty Safety & Sanitation Deficiency |  | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|--|------------------------|------------|----------------------|-------------|--------|
|          |      |   |  |                        |            |                      |             |        |
| 92       | 22   | OK                                      |  |                        |            |                      |             |        |
| 92       | 23   | OK                                      |  |                        |            |                      |             |        |
| 92       | 24   | OK                                      |  |                        |            |                      |             |        |
| 92       | 25   | OK                                      |  |                        |            |                      |             |        |
| 92       | 26   | OK                                      |  |                        |            |                      |             |        |
| 92       | 27   | OK                                      |  |                        |            |                      |             |        |
| 92       | 28   | OK                                      |  |                        |            |                      |             |        |
| 92       | 41   | OK                                      |  |                        |            |                      |             |        |
| 92       | 42   | OK                                      |  |                        |            |                      |             |        |
| 92       | 43   | OK                                      |  |                        |            |                      |             |        |
| 92       | 44   | OK                                      |  |                        |            |                      |             |        |
| 92       | 45   | OK                                      |  |                        |            |                      |             |        |
| 92       | 46   | OK                                      |  |                        |            |                      |             |        |
| 92       | 47   | OK                                      |  |                        |            |                      |             |        |
| 92       | 48   | OK                                      |  |                        |            |                      |             |        |
| 92       | 49   | OK                                      |  |                        |            |                      |             |        |
| 92       | 52   | OK                                      |  |                        |            |                      |             |        |
| 92       | 53   | OK                                      |  |                        |            |                      |             |        |
| 92       | 18   | Heat detector hanging by cord in closet |  |                        |            |                      |             |        |
| 92       | 51   |   |  | Emergency light out    |            |                      |             | X      |
|          |      |   |  |                        |            |                      |             |        |
|          |      |   |  |                        |            |                      |             | X      |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** PLANTATION OAKS ELEMENTARY - 0651  
4150 PLANTATION OAKS BOULEVARD  
ORANGE PARK, FL 32066

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** JANUARY 28, 2014

Fire Drill Log:    
Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency                                | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|--|------------------------|------------|----------------------|-------------|--------|
| *        |      | General note: Excessive combustibles on walls and hanging from ceiling |                        |            |                      |             |        |
| 1        |      | OK   |                        |            |                      |             | X      |
| 20       |      | OK   |                        |            |                      |             |        |
| 25       |      | OK   |                        |            |                      |             |        |
| 92       | 905  | OK   |                        |            |                      |             |        |
| 92       | 906  | OK   |                        |            |                      |             |        |
| 92       | 907  | OK   |                        |            |                      |             |        |
| 92       | 908  | OK   |                        |            |                      |             |        |
| 92       | 909  | OK   |                        |            |                      |             |        |
| 92       | 910  | OK   |                        |            |                      |             |        |
| 92       | 911  | OK   |                        |            |                      |             |        |
| 92       | 912  | OK   |                        |            |                      |             |        |
| 92       | 913  | OK   |                        |            |                      |             |        |
| 92       | 914  | OK   |                        |            |                      |             |        |
| 92       | 915  | OK   |                        |            |                      |             |        |
| 92       | 916  | OK   |                        |            |                      |             |        |






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW ELEMENTARY - 0401  
 421 JEFFERSON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** FEBRUARY 4, 2014

Fire Drill Log:   
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                        |            |                      |             |        |
| 2        |      | OK                                      |                        |            |                      |             |        |
| 3        |      | OK                                      |                        |            |                      |             |        |
| 4        | 401  | Remove propane tank                     |                        |            |                      |             | X      |
| 6        | 617  | Put cover on air handler                |                        |            |                      | X           |        |
| 7        | 705  | End cap missing on panduit              |                        |            |                      | X           |        |
| 7        | 707  | Floor tile missing                      |                        |            |                      | X           |        |
| 92       | 711  |   | Emergency light out    |            |                      | X           |        |
| 92       | 712  | Ramp edge - flatten                     |                        |            |                      | X           |        |
| 92       | 713  | OK                                      |                        |            |                      |             |        |
| 92       | 714  | OK                                      |                        |            |                      |             |        |
| 92       | 715  | Projector plug above ceiling            |                        | X          |                      |             |        |
| 92       | 717  |   | Emergency light out    |            |                      | X           |        |
| 92       | 718  | OK                                      |                        |            |                      |             |        |
| 92       | 728  | OK                                      |                        |            |                      |             |        |
| 92       | 729  | OK                                      |                        |            |                      |             |        |
| 92       | 730  |   | Emergency light out    |            |                      | X           |        |
| 92       | 731  | OK                                      |                        |            |                      |             |        |
| 92       | 732  | OK                                      |                        |            |                      |             |        |
| 92       | 733  | OK                                      |                        |            |                      |             |        |
| 92       | 734  | OK                                      |                        |            |                      |             |        |
| 92       | 735  | OK                                      |                        |            |                      |             |        |



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** S. BRYAN JENNINGS ELEMENTARY - 0331  
 215 CORONA DRIVE  
 ORANGE PARK, FLORIDA 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** February 11, 2014

Fire Drill Log:   
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency          | Facilities | Information Services | Maintenance | School |
|----------|------|---|---------------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                                 |            |                      |             |        |
| 2        |      | OK                                      |                                 |            |                      |             |        |
| 3        |      | OK                                      |                                 |            |                      |             |        |
| 4        |      | OK                                      |                                 |            |                      |             |        |
| 5        | 5A   |   | No evacuation sheet             |            |                      |             | X      |
| 6        | 9A   |   | No evacuation sheet             |            |                      |             | X      |
| 7        | 14A  |   | Cover missing on outlet         |            |                      |             | X      |
| 8        |      | OK                                      |                                 |            |                      |             |        |
| 9        | 21A  |   | No evacuation sheet             |            |                      |             | X      |
| 9        | 22A  |   | No evacuation sheet             |            |                      |             | X      |
| 92       | 26   | OK                                      |                                 |            |                      |             |        |
| 92       | 27   | OK                                      |                                 |            |                      |             |        |
| 92       | 28   | OK                                      |                                 |            |                      |             |        |
| 92       | 29   | OK                                      |                                 |            |                      |             |        |
| 92       | 30   | OK                                      |                                 |            |                      |             |        |
| 92       | 32   | OK                                      |                                 |            |                      |             |        |
| 92       | 33   | OK                                      |                                 |            |                      |             |        |
| 92       | 35   | OK                                      |                                 |            |                      |             |        |
| 92       | 36   |   | Cabinet blocking electric panel |            |                      |             | X      |
| 92       | 37   | OK                                      |                                 |            |                      |             |        |
| 92       | 39   |   | Emergency light out             |            |                      | X           |        |
| 92       | 42   | OK                                      |                                 |            |                      |             |        |
| 92       | 43   | OK                                      |                                 |            |                      |             |        |
| 92       | 44   | OK                                      |                                 |            |                      |             |        |





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** SWIMMING PEN CREEK ELEMENTARY - 0571  
 1630 WOODPECKER LANE  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** FEBRUARY 5, 2014


Fire Drill Log:   
 Drills Performed: 6

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                        |            |                      |             |        |
| 2        | 200  | Roof leak - stained tiles               |                        |            |                      | X           |        |
| 3        | 301  | Roof leak - stained tiles               |                        |            |                      | X           |        |
| 3        | 302  | Roof leak - stained tiles               |                        |            |                      | X           |        |
| 4        |      | OK                                      |                        |            |                      |             |        |
| 5        |      | OK                                      |                        |            |                      |             |        |
| 6        |      | OK                                      |                        |            |                      |             |        |
| 92       | 701  | OK                                      |                        |            |                      |             |        |
| 92       | 702  | OK                                      |                        |            |                      |             |        |
| 92       | 703  | OK                                      |                        |            |                      |             |        |
| 92       | 704  | OK                                      |                        |            |                      |             |        |
| 92       | 705  | OK                                      |                        |            |                      |             |        |
| 92       | 706  | OK                                      |                        |            |                      |             |        |
| 92       | 707  | OK                                      |                        |            |                      |             |        |
| 92       | 708  | OK                                      |                        |            |                      |             |        |
| 92       | 801  | OK                                      |                        |            |                      |             |        |
| 92       | 803  | OK                                      |                        |            |                      |             |        |
| 92       | 804  | OK                                      |                        |            |                      |             |        |
| 92       | 805  | OK                                      |                        |            |                      |             |        |
| 92       | 806  | OK                                      |                        |            |                      |             |        |
| 92       | 807  | OK                                      |                        |            |                      |             |        |
| 92       | 808  | Emergency light out                     |                        |            |                      |             | X      |
| 92       | 810  | OK                                      |                        |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** THUNDERBOLT ELEMENTARY - 0531  
 2020 THUNDERBOLT ROAD  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** February 20, 2014

Fire Drill Log:    
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency  | Facilities | Information Services | Maintenance | School |
|----------|------|---|---|------------|----------------------|-------------|--------|
| *        |      |   | General note: excessive combustibles and storage too high in closets - must be minimum 18" from ceiling |            |                      |             |        |
| 1        | 125  |   | Fire sprinkler riser red tag  |            |                      | X           | X      |
| 1        | 312  | Projector electrical plug above ceiling |   | X          |                      |             |        |
| 92       | 701  | OK                                      |   |            |                      |             |        |
| 92       | 702  | OK                                      |   |            |                      |             |        |
| 92       | 703  | OK                                      |   |            |                      |             |        |
| 92       | 704  | OK                                      |   |            |                      |             |        |
| 92       | 705  | OK                                      |   |            |                      |             |        |
| 92       | 706  | OK                                      |   |            |                      |             |        |
| 92       | 707  | OK                                      |   |            |                      |             |        |
| 92       | 708  | OK                                      |   |            |                      |             |        |
| 92       | 709  | OK                                      |   |            |                      |             |        |
| 92       | 710  | OK                                      |   |            |                      |             |        |
| 92       | 711  | OK                                      |   |            |                      |             |        |
| 92       | 713  | OK                                      |   |            |                      |             |        |
| 92       | 721  | OK                                      |   |            |                      |             |        |
| 92       | 722  | OK                                      |   |            |                      |             |        |
| 92       | 723  | OK                                      |   |            |                      |             |        |
| 92       | 724  | OK                                      |   |            |                      |             |        |
| 92       | 725  | OK                                      |   |            |                      |             |        |



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** THUNDERBOLT ELEMENTARY - 0531  
 2020 THUNDERBOLT ROAD  
 FLEMING ISLAND, FL 32063

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** February 20, 2014

|          |      | Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: 5 |                             |            |                      |             |        |
|----------|------|---|-----------------------------|------------|----------------------|-------------|--------|
| Building | Room | Casualty Safety & Sanitation Deficiency                                 | Fire Safety Deficiency      | Facilities | Information Services | Maintenance | School |
| Building | Room | Casualty Safety & Sanitation Deficiency                                 | Fire Safety Deficiency      | Facilities | Information Services | Maintenance | School |
| 92       | 726  | OK  |                             |            |                      |             |        |
| 92       | 727  | OK  |                             |            |                      |             |        |
| 92       | 728  | OK  |                             |            |                      |             |        |
| 92       | 729  | OK  |                             |            |                      |             |        |
| 92       | 730  | OK  |                             |            |                      |             |        |
| 92       | 731  | OK  |                             |            |                      |             |        |
| 92       | 732  | OK  |                             |            |                      |             |        |
| 92       | 733  | OK  |                             |            |                      |             |        |
| 92       | 734  | OK  |                             |            |                      |             |        |
| 92       | 735  | OK  |                             |            |                      |             |        |
| 92       | 737  | OK  |                             |            |                      |             |        |
| 92       | 738  | OK  |                             |            |                      |             |        |
| 92       | 739  | OK  |                             |            |                      |             |        |
| 92       | 740  | OK  |                             |            |                      |             |        |
| 92       | 741  | OK  |                             |            |                      |             |        |
| 92       | 743  | OK  |                             |            |                      |             |        |
| 92       | 744  | OK  |                             |            |                      |             |        |
| 92       | 742  |   | Emergency light not working |            |                      |             | X      |
| 92       | 736  | Siding damaged - cond. Line from A/C                                    |                             |            |                      | X           |        |
| 96       | 712  | OK  |                             |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** TYNES ELEMENTARY - 0501  
 1550 TYNES BOULEVARD  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** February 18, 2014


Fire Drill Log:    
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency                       | Facilities | Information Services | Maintenance | School |
|----------|------|---|--|------------|----------------------|-------------|--------|
|          |      |   |  |            |                      |             |        |
| 1        |      | OK                                      |  |            |                      |             |        |
| 2        | 203  |   | Red tag on fire sprinkler riser - no placard |            |                      | X           |        |
| 3        |      | OK                                      |  |            |                      |             |        |
| 4        |      | OK                                      |  |            |                      |             |        |
| 5        |      | OK                                      |  |            |                      |             |        |
| 6        |      |   | Exit light out                               |            |                      |             | X      |
| 92       | 1    | OK                                      |  |            |                      |             |        |
| 92       | 2    | OK                                      |  |            |                      |             |        |
| 92       | 3    | OK                                      |  |            |                      |             |        |
| 92       | 4    | OK                                      |  |            |                      |             |        |
| 92       | 7    | OK                                      |  |            |                      |             |        |
| 92       | 8    | OK                                      |  |            |                      |             |        |
| 92       | 9    | OK                                      |  |            |                      |             |        |
| 92       | 10   | OK                                      |  |            |                      |             |        |
| 92       | 22   | OK                                      |  |            |                      |             |        |
| 92       | 23   | OK                                      |  |            |                      |             |        |
| 92       | 24   | OK                                      |  |            |                      |             |        |
| 92       | 25   | OK                                      |  |            |                      |             |        |
| 92       | 26   | OK                                      |  |            |                      |             |        |
| 92       | 27   | OK                                      |  |            |                      |             |        |
| 92       | 29   | OK                                      |  |            |                      |             |        |
| 92       | 30   | OK                                      |  |            |                      |             |        |
| 92       | 42   | OK                                      |  |            |                      |             |        |
| 92       | 43   | OK                                      |  |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** TYNES ELEMENTARY - 0501  
 1550 TYNES BOULEVARD  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** February 18, 2014

Fire Drill Log:  \_\_\_\_\_  
 Drills Performed: 5

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency                               | Facilities | Information Services | Maintenance | School |
|----------|------|---|--|------------|----------------------|-------------|--------|
| 92       | 44   | OK                                      |  |            |                      |             |        |
| 92       | 45   | OK                                      |  |            |                      |             |        |
| 92       | 46   | OK                                      |  |            |                      |             |        |
| 92       | 47   | OK                                      |  |            |                      |             |        |
| 92       | 49   | OK                                      |  |            |                      |             |        |
| 96       | 21   |   | Boys emergency light not working - check girls       |            |                      |             | X      |
| 92       | 5    |   | Emergency light not working                          |            |                      | X           | X      |
| 92       | 2    | Exhaust fan missing in restroom         |  |            |                      | X           |        |
| 92       | 6    |   | Electrical box - exterior knockout missing           |            |                      | X           |        |
| 92       | 28   |   | Electrical box - exterior knockout missing           |            |                      | X           |        |
| 92       | 41   |   | Emergency light out                                  |            |                      |             | X      |
| 92       | 48   |   | Emergency light out - move bookshelf 6" into doorway |            |                      |             | X      |
| 92       | 61   |   |  |            |                      |             |        |
| 92       | 62   | OK                                      |  |            |                      |             |        |
| 92       | 63   | OK                                      |  |            |                      |             |        |
| 92       | 64   | OK                                      |  |            |                      |             |        |
| 92       | 65   | OK                                      |  |            |                      |             |        |
| 92       | 66   | OK                                      |  |            |                      |             |        |



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** March 3, 2014

Fire Drill Log:    
 Drills Performed: 7

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency          | Facilities | Information Services | Maintenance | School |
|----------|------|---|---------------------------------|------------|----------------------|-------------|--------|
| 1        |      | OK                                      |                                 |            |                      |             |        |
| 2        |      | OK                                      |                                 |            |                      |             |        |
| 3        |      | OK                                      |                                 |            |                      |             |        |
| 3        | 16   |   | No evacuation sheet             |            |                      |             | X      |
| 4        | 11   |   | No evacuation sheet             |            |                      |             | X      |
| 4        | 22   |   | No evacuation sheet             |            |                      |             | X      |
| 92       | 26   | OK                                      |                                 |            |                      |             |        |
| 92       | 27   | OK                                      |                                 |            |                      |             |        |
| 92       | 29   | OK                                      |                                 |            |                      |             |        |
| 92       | 31   | OK                                      |                                 |            |                      |             |        |
| 92       | 31   | OK                                      |                                 |            |                      |             |        |
| 92       | 32   |   | Fire alarm pull station covered |            |                      |             | X      |
| 92       | 33   |   | No evacuation sheet             |            |                      |             | X      |
| 92       | 34   | OK                                      |                                 |            |                      |             |        |
| 92       | 36   |   | No evacuation sheet             |            |                      |             | X      |
| 92       | 37   | OK                                      |                                 |            |                      |             |        |
| 92       | 38   | OK                                      |                                 |            |                      |             |        |
| 92       | 39   | OK                                      |                                 |            |                      |             |        |
| 92       | 40   | OK                                      |                                 |            |                      |             |        |
| 92       | 41   | OK                                      |                                 |            |                      |             |        |
| 92       | 42   | OK                                      |                                 |            |                      |             |        |
| 92       | 43   | OK                                      |                                 |            |                      |             |        |
| 92       | 48   | OK                                      |                                 |            |                      |             |        |
| 92       | 49   | OK                                      |                                 |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** W. E. CHERRY ELEMENTARY - 0241  
 420 EDSON DRIVE  
 ORANGE PARK, FLORIDA 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** March 3, 2014


Fire Drill Log:    
 Drills Performed: 7

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency         | Facilities | Information Services | Maintenance | School |
|----------|------|---|--------------------------------|------------|----------------------|-------------|--------|
| 92       | 50   |   | Electrical panel blocked       |            |                      |             | X      |
| 92       | 51   | OK                                      |                                |            |                      |             |        |
| 92       | 53   | OK                                      |                                |            |                      |             |        |
| 92       | 54   | OK                                      |                                |            |                      |             |        |
| 92       | 55   | Roof leak in closet                     |                                |            |                      | X           |        |
| 92       | 56   | OK                                      |                                |            |                      |             |        |
| 92       | 57   |   | Fire extinguisher not by range |            |                      |             | X      |
| 92       | 58   |   | Fire extinguisher not by range |            |                      |             | X      |
| 92       | 59   | OK                                      |                                |            |                      |             |        |
| 92       | 60   | OK                                      |                                |            |                      |             |        |
| 92       | 61   |   | Fire extinguisher not by range |            |                      |             | X      |
| 92       | 63   |   | Fire extinguisher not by range |            |                      |             | X      |
| 92       | 64   | OK                                      |                                |            |                      |             |        |
| 92       | 65   | OK                                      |                                |            |                      |             |        |
| 92       | 66   |   | Fire extinguisher not by range |            |                      |             | X      |
| 92       | 67   |   | Excessive combustibles         |            |                      |             | X      |
| 92       | 68   |   | Fire extinguisher not by range |            |                      |             | X      |
| 92       | 69   | OK                                      |                                |            |                      |             |        |
| 92       | 70   | OK                                      |                                |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** March 11, 2014


Fire Drill Log:    
 Drills Performed: 6

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency                  | Facilities | Information Services | Maintenance | School |
|----------|------|---|---|------------|----------------------|-------------|--------|
| 1        |      |   | General: Fire extinguishers out of date |            |                      | X           |        |
| 2        | 209  |   | Fire sprinkler riser red tagged         |            |                      | X           |        |
| 3        |      | OK                                      |   |            |                      |             |        |
| 4        |      | OK                                      |   |            |                      |             |        |
| 5        |      | OK                                      |   |            |                      |             |        |
| 92       | 1    | OK                                      |   |            |                      |             |        |
| 92       | 2    | OK                                      |   |            |                      |             |        |
| 92       | 3    | OK                                      |   |            |                      |             |        |
| 92       | 4    | OK                                      |   |            |                      |             |        |
| 92       | 5    |   | Emergency light out                     |            |                      | X           |        |
| 92       | 6    | Projector plug above ceiling            |   | X          |                      |             |        |
| 92       | 7    | OK                                      |   |            |                      |             |        |
| 92       | 8    | OK                                      |   |            |                      |             |        |
| 92       | 9    | OK                                      |   |            |                      |             |        |
| 92       | 10   | Projector plug above ceiling            |   | X          |                      |             |        |
| 92       | 11   | OK                                      |   |            |                      |             |        |
| 92       | 12   | OK                                      |   |            |                      |             |        |
| 92       | 13   | OK                                      |   |            |                      |             |        |
| 92       | 14   | OK                                      |   |            |                      |             |        |
| 92       | 15   | OK                                      |   |            |                      |             |        |
| 92       | 16   | OK                                      |   |            |                      |             |        |

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON ELEMENTARY - 0491  
 4965 COUNTY ROAD 218 W.  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** March 11, 2014

Fire Drill Log:    
 Drills Performed: 6

| Building | Room | Casualty Safety & Sanitation Deficiency | Fire Safety Deficiency | Facilities | Information Services | Maintenance | School |
|----------|------|---|------------------------|------------|----------------------|-------------|--------|
| 92       | 17   | OK                                      |                        |            |                      |             |        |
| 92       | 18   | OK                                      |                        |            |                      |             |        |
| 92       | 20   | OK                                      |                        |            |                      |             |        |
| 92       | 21   | OK                                      |                        |            |                      |             |        |
| 92       | 31   | OK                                      |                        |            |                      |             |        |
| 92       | 33   | OK                                      |                        |            |                      |             |        |
| 92       | 34   | OK                                      |                        |            |                      |             |        |
| 92       | 35   | OK                                      |                        |            |                      |             |        |
| 92       | 36   | OK                                      |                        |            |                      |             |        |
| 92       | 37   | OK                                      |                        |            |                      |             |        |
| 92       | 38   | OK                                      |                        |            |                      |             |        |
| 92       | 39   | OK                                      |                        |            |                      |             |        |
| 92       | 40   | OK                                      |                        |            |                      |             |        |
| 92       | 41   | OK                                      |                        |            |                      |             |        |
| 92       | 42   | OK                                      |                        |            |                      |             |        |
| 92       | 43   | OK                                      |                        |            |                      |             |        |
| 92       | 44   | OK                                      |                        |            |                      |             |        |
| 92       | 45   | OK                                      |                        |            |                      |             |        |
| 92       | 46   | OK                                      |                        |            |                      |             |        |
| 92       | 47   | OK                                      |                        |            |                      |             |        |
| 92       | 48   | OK                                      |                        |            |                      |             |        |
| 92       | 49   | OK                                      |                        |            |                      |             |        |
| 92       | 50   | OK                                      |                        |            |                      |             |        |
| 92       | 51   | OK                                      |                        |            |                      |             |        |
| 92       | 52   | OK                                      |                        |            |                      |             |        |



