


**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** GREEN COVE SPRINGS JUNIOR HIGH - 0021  
 1220 BONAVENTURE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 5, 2013


Fire Drill Log:    
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	1	Wire mold not secured correctly				X	
1	2	Wire mold not secured correctly				X	
1	3	Wire mold not secured correctly				X	
1	4	Wire mold not secured correctly				X	
1	5	Wire mold not secured correctly				X	
1	6	Wire mold not secured correctly				X	
1	10	Wire mold not secured correctly				X	
1	11	Wire mold not secured correctly				X	
1	12	Wire mold not secured correctly				X	
1	13	Wire mold not secured correctly				X	
1	14	Wire mold not secured correctly				X	

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** GREEN COVE SPRINGS JUNIOR HIGH - 0021  
 1220 BONAVENTURE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 5, 2013


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	7		Emergency exit blocked				X
1	11	Electrical knockout missing in panduit				X	
2		OK					
3	30	Wire mold not secured correctly				X	
3	32	Wire mold not secured correctly				X	
3	33	Wire mold not secured correctly				X	
4	411		Fire extinguisher not within 15ft. of stove				X
4	422	Remove old parts				X	
5	425	Ceiling tiles damaged					X
5	511	Health department permit expired 9/30/13				X	
6	117	Replace stained ceiling tiles					X
7		OK					
8	831	Lift permit expired				X	
9	908	License cover missing					X
9	909	Ceiling tiles missing					X
92	70	OK					
92	71	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** November 7, 2013

Fire Drill Log:    
 Drills Performed: 3


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	105	Light over vanities out					X
1	105	Replace stained ceiling tiles					X
1	105		Remove combustible materials				X
1	108	Replace stained ceiling tiles					X
2		OK					
3		OK					
5		OK					
6		OK					
7	706	Clean return air grill					X
7	709		Clear exit				X
8		OK					
92	390		Emergency light out				X
92	391	OK					
92	392	OK					
92	393	OK					
92	394	OK					
92	401	OK					
92	402	Change AC filters					X
92	403	OK					
92	404	OK					
92	405	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** November 12, 2013

Fire Drill Log:   
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	801	Handrail at mid landing too low				X	
1	21		Exit lights missing at smoke doors			X	
2	800	Handrail at mid landing too low				X	
2	802	Handrail at mid landing too low				X	
2	803	Handrail at mid landing too low				X	
2	45		Exit lights missing at smoke doors			X	
3	803	Handrail at mid landing too low				X	
3	804	Handrail at mid landing too low				X	
3	72		Exit lights missing at smoke doors			X	
5	218	Broken outlet by Room 246				X	
5	226	AC condensation leak				X	
8	824	Excessive erosion at door				X	
8	804	Crack in wall getting larger				X	

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 12, 2013

Fire Drill Log:   ✓    
 Drills Performed:   4  

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
8	814	Crack in wall getting larger				X	
92	701	Exhaust fan in restroom not working				X	
92	702	OK					
92	703	OK					
92	704	OK					
92	705	OK					
92	706	OK					
92	707		Emergency light out			X	
92	708	OK					
92	710	OK					
92	721	OK					
92	722	OK					
92	723	OK					
92	731		Emergency light out			X	
92	732		Emergency light out			X	
92	733	OK					
92	734		Open slot in electric panel			X	
92	735	OK					
92	737	OK					
92	745		Emergency light out			X	
92	791	Lens cover missing in restroom					X






**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEARD  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** November 14, 2013

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		OK					
2		OK					
3	311		Emergency evacuation sheet missing				X
4	401		Emergency evacuation sheet missing				X
4	416		Emergency evacuation sheet missing				X
5		OK					
92	601	OK					
92	602	OK					
92	603	OK					
92	604	OK					
92	605	OK					
92	606	OK					
92	607	OK					
92	608	OK					
92	609	OK					
92	610	OK					
92	612	OK					
92	618	OK					
92	619	OK					
92	701	OK					
92	702	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEARD  
 ORANGE PARK, FL 32066

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 14, 2013

Fire Drill Log:   
 Drills Performed: 3


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	703	OK					
92	704	OK					
92	705	OK					
92	706	OK					
92	707	OK					
92	709	OK					
92	710	OK					
92	711	OK					
92	712	OK					
92	713	OK					
92	715	OK					
92	716	OK					
92	801	OK					
92	807	OK					
92	809	OK					
92	910	OK					
92	811	OK					
92	823	OK					
92	824	OK					
92	611		Emergency light not working				X
92	613	Toilet leaking/replace stained ceiling tiles				X	X



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK JUNIOR HIGH - 0361  
 1500 GANO AVENUE  
 ORANGE PARK, FL 32078

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** November 19, 2013

Fire Drill Log:  4  
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	101		Remove gas grill				X
1	122	Paint blistering on wall				X	
2	216		Lens missing on light			X	
3	303		No evacuation sheet				X
3	316		Exit light broken			X	
3	365		Outlet cover missing				X
4	454		No evacuation sheet				X
4	456		Wires exposed in fixture			X	
4	455B (staining)	Replace ceiling tiles (staining)					X
5	517		Exit light broken			X	
5	524	Threshold trip hazard				X	
6	604		Broken outlet cover				X
6	614		Several outlet cover broken				X
92	501	Ramp handrail too close to door				X	
92	503		Emergency disconnect switch broken			X	
92	504		No emergency light			X	
92	505	OK					
92	507	OK					
92	508	OK					
92	509	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON JUNIOR HIGH - 0371  
 5025 COUNTY ROAD 248  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** NOVEMBER 21, 2013

Fire Drill Log:    
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		OK					
2		OK					
3		OK					
4	407		Electrical outlets with improper connection - repair or remove			X	
5		OK					
6	607		Emergency evacuation sheet missing				X
6	608		Emergency evacuation sheet missing				X
7	716		Emergency evacuation sheet missing				X
7	738	Heat detector loose				X	
8	814	Broken outlet cover					X
9		OK					
11			Girls restroom emergency light out				X
16		Both restroom exhaust fans do not work				X	
92	2	OK					
92	3	OK					
92	4	OK					
92	5	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** WILKINSON JUNIOR HIGH - 0371  
 5025 COUNTY ROAD 218  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** NOVEMBER 21, 2013

Fire Drill Log:    
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	6	OK					
92	7	OK					
92	8	OK					
92	9	OK					
92	12	OK					
92	17	OK					
92	18	OK					
92	22	OK					
92	23	OK					
92	24	OK					
92	25	OK					
92	26	OK					
92	27	OK					
92	30	OK					
92	40	OK					
92	41	OK					
92	42	OK					
92	43	OK					
92	46	OK					
92	48	OK					
92	96	OK					
92	10		Emergency light out				X
92	11	Siding in bad shape long side				X	





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** BANNERMAN LEARNING CENTER - 0111  
 608 MILL STREET  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 29, 2013

Fire Drill Log:   
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		OK					
2		OK					
3		OK					
92	1	OK					
92	2	OK					
92	3	OK					
92	4	OK					
92	5	OK					
92	6 A&B	OK					
92	7	OK					
92	8	OK					
92	9	OK					
92	10	OK					
92	11	OK					
92	12	OK					
92	13	OK					
92	14	OK					
92	30	OK					
92	32	OK					
92	33	OK					
92	34	OK					
92	35	OK					
92	36	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HIGH SCHOOL - 0341  
2025 HIGHWAY 16 WEST  
GREEN COVE SPRINGS, FL 30243

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 14, 2013


Fire Drill Log:   
Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	102	Remove old fire extinguisher cabinet					X
4		OK					
5		OK					
6		OK					
7	776	Replace ceiling tile					X
7	779	Replace ceiling tile					X
7	789	Replace ceiling tile					X
8	835	Red tag riser				X	
8	836	Remove old parts				X	
9	905	Repair ceiling tile sag					X
9	920	Remove old parts				X	
11	1104	Outlet cover missing by projector					X
11	1103	Boys restroom sign missing					X
11	1108	Remove chair from exit					X
30		Electric panel blocked - move equipment					X
35		OK					
29		Broken outlet cover behind ice maker					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30243

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 14, 2013

Fire Drill Log:   
 Drills Performed: 4


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	5	OK					
92	7	OK					
92	8	OK					
92	17	OK					
92	18	OK					
92	19	OK					
92	20	OK					
92	31	OK					
92	32	OK					
92	33	OK					
92	40	OK					
92	41	Move cabinet from in front of electrical panel					X
92	42	Replace emergency light weak battery				X	
92	43	OK					
92	44	OK					
92	45	OK					
92	46	OK					
92	47	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003


**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 10, 2013

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>		Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	048				Remove gas and gas powered equipment				X
1	085				Elevator certification out of date			X	
1	110	Corners broken on drywall						X	
1	134	Projector not installed properly				X			
1	146				No evacuation sheet				X
1	146	Mold on ceiling tiles							X
1	146	Lenses missing on lights							X
1	140	Mold on ceiling tiles							X
1	168	Mold on ceiling tiles							X
1	220	Stained ceiling tile							X
1	221				Cover off electric panel			X	
1	224				Door sticks			X	
2	204	Mold on ceiling tiles							X
2	206	Mold on ceiling tiles							X
2	228	Ceiling tile missing							X
2	231	Lenses missing on lights							X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 10, 2013

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
2	245	Mold on ceiling tiles					X
2	218	Mezzanine condensate overflow to lower level				X	
10	1002		No evacuation sheet				X
10	1005		Material stored in electrical room				X
10	1022		Door sticks			X	
92	10		Trophies in front of electrical panel				X
92	11	Projector not installed properly		X			
92	12	Projector not installed properly		X			
92	13	West side of building joint alignment				X	
92	14		Exit light out			X	
92	15		Emergency light out			X	
92	20	OK					
92	21		Broken switch plate by door				X
92	22	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**

STATE BOARD OF EDUCATION

ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION

F.S. 1013.12, 1013.20 & NFPA 101

AND

FIRE SAFETY INSPECTION REPORT

F.S. 1013.12, 1013.20 & RULE 69A-58


FISCAL YEAR: 2013/2014

DISTRICT: CLAY

FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551

2233 VILLAGE SQUARE PARKWAY

FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE: 

INSPECTION DATE: October 10, 2013

Fire Drill Log:   
 Drills Performed: 2


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	23	OK					
92	24	Projector not installed properly		X			
92	25	OK					
92	26	OK					
92	30	Corner pier by ramp out		X			
92	31		Emergency light out			X	
92	32	OK					
92	33	OK					
92	34	OK					
92	35		Emergency light out			X	
92	40		Emergency light out			X	
92	41		Emergency light out			X	
92	41	Pier support needs work				X	
92	42	OK					
92	43	Pier support needs work				X	
92	44	OK					
92	45	Pier support needs work				X	
92	46	End of ramp needs work				X	
92	47		Emergency light out			X	
92	48		Emergency light out			X	
92	49	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 10, 2013


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	50		Emergency light out			X	
92	51		Emergency light out			X	
92	51	Stained tile in restroom					X
92	52		Emergency light out			X	
92	52		Smart board blocking exit				X
92	53		Emergency light out			X	
92	60		Emergency light out			X	
92	61	OK					
92	62	OK					
92	63		Emergency light out			X	
92	64	OK					
92	70	Platform loose at ramp				X	
92	71	OK					
92	72	Replace tile in closet				X	
92	73	OK					
92	80		Emergency light out			X	
92	81	OK					
92	82	OK					
92	83	OK					
92	84	OK					
92	85	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
900 S. ORCHID AVENUE  
KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 17, 2013

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>		Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	160				Plastic floor outlet cover cracked or broken			X	
1	171				Exposed wire at ceiling			X	
1	173				Remove trash				X
1	173				Replace ceiling diffuser			X	
1	188				Light fixture missing - wires exposed			X	
1	190				Material stored too close to ceiling				X
2	70				Remove trash				X
2	73	Replace ceiling tile							X
4	403				No evacuation sheet				X
4	412C				Remove Christmas lights				X
4	412D				Remove equipment				X
5	537	Door sticks						X	
5	505	OK			Remove stored materials				X
6		OK							
7	700				Exit light out			X	
7	709	Remove stored materials							X
8		OK							

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS FL 32656

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 17, 2013

		Fire Drill Log: <input checked="" type="checkbox"/> <u>1</u> Drills Performed: <u>2</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
9	905	Replace ceiling tile					X
9	912	Secure TV bracket					X
9	917	Secure TV bracket					X
9	909		Open junction box			X	
92	1	OK					
92	2	OK					
92	3	OK					
92	4		Emergency light out			X	
92	5	Ceiling tiles damaged					X
92	6	OK					
92	7	OK					
92	8		No room number				
92	9	OK					
92	10	OK					
92	11	OK					
92	12	OK					
92	13		Emergency light out			X	
92	14	OK					
92	15	OK					
92	16		No evacuation sheet				X
92	17	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**


**FISCAL YEAR:** 2013/2014

**DISTRICT:** CLAY

**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311

900 S. ORCHID AVENUE

KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 17, 2013

Fire Drill Log:   
Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	18	OK					
92	19	OK					
92	20	OK					
92	21	OK					
92	22	OK					
92	23	OK					
92	24	OK					
92	25	OK					
92	26		Switch cover missing under data box				X
92	27	OK					
92	28	OK					
92	29		Emergency light out			X	
92	50	OK					
92	51	OK					
92	52	OK					
92	53	OK					
92	54	OK					
92	55	OK					
92	56		Emergency light out			X	
92	57	OK					
92	58	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT  
STATE BOARD OF EDUCATION  
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION  
F.S. 1013.12, 1013.20 & NFPA 101  
AND  
FIRE SAFETY INSPECTION REPORT  
F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391  
3750 COUNTY ROAD 220  
MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 16, 2013

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
**			All fire extinguishers need to be replaced			X	
1	157		Emergency evacuation sheet missing				X
1	241		Emergency evacuation sheet missing				
1	254		Emergency evacuation sheet missing				
1	254		Exposed wires where old clock was on wall				X
1	229B		Exposed wires where old clock was on wall				
1	282		Exposed wires where old clock was on wall				
1	312		Exposed wires where old clock was on wall				
1	302		Exposed wires where old clock was on wall				
1	293		Exposed wires where old clock was on wall				
1	335	Secure TV to shelf					X
1	285	Cover missing on box at North end of gym					X
1	286	Ceiling tiles					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**


**FISCAL YEAR:** 2013/2014

**DISTRICT:** CLAY

**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391

3750 COUNTY ROAD 220

MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 16, 2013

Fire Drill Log:   
 Drills Performed: 2


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	227		Need flammable storage cabinet				X
1	294	Replace stained ceiling tiles					X
1	373		Remove LP tank from custodial room				X
1	340		Exposed wires where old clock was on wall				X
1	341		Exposed wires where old clock was on wall				X
1	369		Exposed wires where old clock was on wall				X
92	001		Emergency light not working				X
92	7	Trip hazard at base of ramp					X
**			Fire extinguishers not current				X
92	59	OK					
92	32	OK					
92	33	OK					
92	36	OK					
92	42	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 16, 2013

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	43	OK					
92	44	OK					
92	45	OK					
92	47	OK					
92	51	OK					
92	52	OK					
92	53	OK					
92	54A	OK					
92	54B	OK					
92	55	OK					
92	60	OK					
92	61	OK					
92	62	OK					
92	63	OK					
92	64	OK					
92	65	OK					
92	66	OK					
92	67	OK					
92	74	OK					
92	76	OK					
92	78	OK					
92	79	OK					
92	81	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014

**DISTRICT:** CLAY

**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391

3750 COUNTY ROAD 220

MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 16, 2013

Fire Drill Log:   ✓    
 Drills Performed:   2  

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	82	OK					
92	83	OK					
92	86	OK					
92	88	OK					
92	34		Printer too close to electrical panel - move				X
92	31		Emergency light not working				X
92	35		Emergency light not working				X
92	70		Emergency light not working				X
92	72		Emergency light not working				X
92	41	Covers of light bulbs missing					X
92	46		Outlet cover missing outside electric panel				X
92	69		Outlet cover missing outside main panel				X
92	69		Emergency light not working				X



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 24, 2013

Fire Drill Log:   
 Drills Performed: 1


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
5	505		Fire extinguisher missing at oven cook top				X
92	10	OK					
92	11	OK					
92	15	OK					
92	16	OK					
92	20	Boys restroom out of order				X	
92	21	OK					
92	22	OK					
92	23	OK					
92	24	OK					
92	25	OK					
92	26		Emergency light out			X	
92	30	OK					
92	31	OK					
92	32	OK					
92	33	OK					
92	34	OK					
92	35	OK					
92	36	Floor damaged at rear door				X	
92	40	Grab bar missing in restroom					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 23, 2013

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1			General: Corridors on first and second floor do not meet fire safety standards	X			
1			General: Emergency evacuation sheets are missing in most classrooms				X
1	100		Southeast corridor exit light out			X	
1	160C		Elevator certification overdue			X	
1	102A		Clock wires exposed			X	
1	116		Clock wires exposed			X	
1	117		Clock wires exposed			X	
1	128		Clock wires exposed			X	
1	129		Clock wires exposed			X	
1	130		Clock wires exposed			X	
1	800		North corridor exit light out			X	
1	800		Add exit light east end			X	


**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014

**DISTRICT:** CLAY

**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 23, 2013


Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		General: Second floor stair landing rails too short				X	
2	7		Cover plate missing on outlet				X
2	7		Electrical wires exposed on ceiling			X	
2	9		No evacuation sheet				X
2	9		Exit light out			X	
4	1		Exit lights out or broken at main entrance			X	
4	1	Broken floor tile at main entrance doors				X	
4	5		Exit light falling			X	
4	17H		Add exit lights at exit doors			X	
4	21A		Add exit lights at exit stair			X	
4	22A	Lens missing on light					X
10	102		Broken outlet cover plate				X
10		General: Clean A/C diffusers					X
10	124	Mold on ceiling tile					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 23, 2013

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
24	14	Light fixture broken				X	
24	26	Lens missing on light					X
51		General: Clean A/C filters					X
51	2		Fire alarm panel not certified			X	
92	13	OK					
92	35		Emergency light out			X	
92	35	Hole in wall by electric panel				X	
92	35		Exit light missing at ramp door			X	
92	36		Emergency light out			X	
92	36	Door hits platform				X	
92	37	OK					
92	38	OK					
92	39		Emergency light out			X	
92	40		Emergency light out			X	
92	45		Emergency light out			X	
92	48		Emergency light out			X	
92	49		Emergency and exit light pulling off wall			X	
92	50		Desk blocking exit				X



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 23, 2013

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	51	OK					
92	52		Emergency light not working			X	
92	52	Doorknob broken at closet				X	
92	53		Emergency light out			X	
92	54	OK					
92	55	OK					
92	56	OK					
92	59		Excessive combustibles on walls				X
92	60		Stairs exit into A/C unit				X
92	61	Light out in time out room					X
92	61	Data cord runs across floor					X
92	62	OK					
92	63		Electric panel blocked				X
92	63	Hole in wall by restroom				X	
92	63	Drinking fountain broken				X	
92	64	OK					
92	65	Lock on electrical panel broken				X	



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 24, 2013


Fire Drill Log:    
 Drills Performed:  2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	149		Exit light out				X
2		OK					
3	353		No emergency evacuation sheet				X
3	353		Outlet cover plate missing				X
5	526		No emergency evacuation sheet				X
5	526		Outlet cover plate missing				X
5	530		No emergency evacuation sheet				X
5	535		No emergency evacuation sheet				X
5	557		No emergency evacuation sheet				X
5	525	Stained ceiling tile by Room 530					X
5	534	Stained ceiling tile by Room 541					X
6	689		sheet				X
6	684	Roof leak/stained ceiling by exit doors					X
6	629		No emergency evacuation sheet				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** 


**INSPECTION DATE:** October 24, 2013

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
7	705		No emergency evacuation sheet				X
7	714		No emergency evacuation sheet				X
8	801	Roof leak				X	
8	814	Remove barricade at exit					X
8	819	Remove barricade at exit					X
9	926	Remove paint from mechanical room					X
9	**	Clean all AC grills					X
9	925	Replace stained ceiling					X
9	916	Lens cover missing					X
9	924		Exit light out by Room 928				X
9	941		2 exit lights out				X
9	936	Replace ceiling tiles					X
10	36		Exit light out				X
10	4	Repair soffit outside					X
11	Concession	OK					
12	Concession	OK					
13	Concession	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 24, 2013

Fire Drill Log:    
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
96	2	Open fire alarm box at entrance				X	
96	2	Sink running. Toilet will not flush					X
92	1	OK					
92	4	OK					
92	5	OK					
92	7	OK					
92	8	OK					
92	10	OK					
92	11	OK					
92	12	OK					
92	13	OK					
92	24	OK					
92	25	OK					
92	29	OK					
92	32	OK					
92	33	OK					
92	34	OK					
92	41	OK					
92	43	OK					
92	45	OK					
92	47	OK					
92	48	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** *Ted J. Keating*

**INSPECTION DATE:** October 24, 2013


Fire Drill Log:    
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	49	OK					
92	50	OK					
92	52	OK					
92	53	OK					
92	61	OK					
92	62	OK					
92	64	OK					
92	65	OK					
92	66	OK					
92	69	OK					
92	70	OK					
92	72	OK					
92	81	OK					
92	82	OK					
92	85	OK					
92	86	OK					
92	87	OK					
92	88	OK					
92	89	OK					
92	90	OK					
92	91	OK					
92	92	OK					
92	103	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2013/2014  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 24, 2013

		Fire Drill Log: <input checked="" type="checkbox"/> <u>2</u> Drills Performed: <u>2</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	3	Drywall ceiling separating at hall				X	
92	6	Light cover missing and bulbs					X
92	9	Projector plug above ceiling		X			
92	21		Emergency light out				X
92	22		Excessive combustibles/drama storage.				X
92	23		Emergency light out				X
92	26		No emergency evacuation sheet				X
92	27	Light covers missing and broken					X
92	28						
92	30						
92	30						
92	31						
92	31						
96	42	Light covers broken on boys side					X
96	44	Switch cover broken					X









