

925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Location Code Set

HC Long Admin

Inspection Date:

2/15/2024

Address:

23 South Green Street

InspectionType:

Annual Fire Safety Inspection

Bldg 2

Inspected By:

Stephanie Raucci

Suite:

Green Cove Springs

Code

Room

FL NFPA 01 2021

201

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: 2ND YEAR VIOLATION: Fire extinguisher certification tag is expired. Have tested and

recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephanie Francci

Signature valid only in mobile-eyes documents:

Stephanie Raucci

2/15/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

HC Long Admin

Inspection Date:

2/15/2024

Address:

23 South Green Street

InspectionType:

Annual Fire Safety Inspection

Suite: Bldg 3

Inspected By:

Stephanie Raucci

Green Cove Springs

Location

Code Set

Code

R-300 Hallway at R-315

FL State Requirements for Educational Facilities

FL State Requirements for Educational Facilities 2014

5.16 - Mechanical.

Inspector Comments: Drinking fountain not working. Repair as needed.

R-303 Office

FL NFPA 01 2021

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher certification tag is expired. Have tested and recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

2/15/2024 1:04/36 PM

Signature valid only in mobile eyes documents

Stephanie Raucci

2/15/2024

Mephinne Ra



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

HC Long Admin

Inspection Date:

2/15/2024

Address:

23 South Green Street

InspectionType:

Annual Fire Safety Inspection

Suite:

Bldg 4

Inspected By:

Stephanie Raucci

Green Cove Springs

Code

Location

Code Set

FL State Requirements for Educational Facilities

R-401 Entry Hallway

FL State Requirements for Educational Facilities 2014

5.17 - Electrical.

Inspector Comments: Electrical cover plate is missing at the center doors. Replace as

required.

FL NFPA 01 2021

13.6.3.1.2 - Extinguisher Readiness.

R-411 Corridor

Chapter 13 Fire Protection Systems

Inspector Comments: Fire extinguisher certification is expired. Have tested and recertified.

R-413 Corridor

FL NFPA 01 2021

13.6.3.1.2 - Extinguisher Readiness.

Chapter 13 Fire Protection Systems

Inspector Comments: Fire extinguisher certification is expired. Have tested and recertified.

R-415 at South door

FL State Requirements for Educational Facilities

5.1 - Operational

FL State Requirements for Educational Facilities 2014 Inspector Comments: Repair leak and replace water damaged ceiling tile.

R-415 Overflow Room

FL NFPA 01 2021

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher certification is expired. Have tested and recertified.

R-416 Multipurpose

Room

FL NFPA 01 2021

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher certification is expired. Have tested and recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephanie 1041 SECT 25

Signature valid only in mobile eyes documents

Stephanie Raucci

2/15/2024



925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

HC Long Admin

Bldg 5

Inspection Date:

2/15/2024

Address:

Suite:

23 South Green Street

Green Cove Springs

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

2/16/2<del>021 12/3</del>0/26 PM

Signature valid only in mobile-eyes documents

Stephanie Raucci

Slaphame Baucu

2/15/2024



925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

HC Long Portable

23 South Green Street

Address: Suite:

B-95, R-001

Green Cove Springs

Inspection Date:

2/15/2024

InspectionType: Inspected By:

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephanie Raucci 110

Signalure valid only in mobile eyes documents

Stephanie Raucci 2/15/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Food Services Storage Building

8300 Green Street

**Green Cove Springs** 

Suite:

Address:

Inspection Date: InspectionType:

2/2/2024 Relocatables

Inspected By:

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Inspector Comments: Exterior AC housing is rusting on lower right side. There is also condensation build up dripping from the bottom of unit.

Remove storage from areas within 2 feet of ceiling per FFPC-NFPA 1 10.18.3.1.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Signatura valid only to mobile eyes documents Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

School Board Main Office

900 Walnut Street

Bldg 3

Green Cove Springs

Inspection Date:

2/15/2024

InspectionType: Inspected By:

Annual Fire Safety Inspection

Stephanie Raucci

Location

Address:

Suite:

Code Set

Code

Mechanical Room 1st

Floor

FL NFPA 01 2021

Chapter 10 General Safety Requirements

10.19.5.1 - Excerpt: [Combustible material shall not

be stored in boi...]

Inspector Comments: Remove all storage in boiler rooms, mechanical rooms, or electrical

equipment rooms.

FL State Requirements for Educational

Facilities

R-14 Hallway (1st FI)

FL State Requirements for Educational

Facilities 2014

5.16 - Mechanical.

Inspector Comments: Drinking fountain has low water flow.

R-2 Superintendent's Office Corridor

FL NFPA 01 2021

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher tag is expired. Have tested and recertified.

FL State Requirements for Educational

**Facilities** 

R-61 Hallway (2nd FI) FL State Requirements for Educational 5.16 - Mechanical.

Facilities 2014

Inspector Comments: Drinking fountain has low water flow.

FL State Requirements for Educational

**Facilities** 

FL State Requirements for Educational

5.10 - Specialties.

Facilities 2014

Inspector Comments: 2nd year violation: Remove all storage items under the stainwell. The

space under stairs and ramps shall be kept free of any storage or other purpose.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stairwell

Rayco : Stepharn 106 2/15/2024 T35555 AM Signature valid only in mobile-eyes documents

Stephanie Raucci

2/15/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Vacant

Bldg 2

Inspection Date:

2/15/2024

Address:

Suite:

900 Walnut Street

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

Location

Gree

Green Cove Springs

Code

R-17

FL NFPA 01 2021

Code Set

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher certification tag is expired. Have tested and recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

· Štephurile Ráucci.

Signature valid only in mobile eyes documents

Stephanie Raucci

2/15/2024

100.



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Main Office Portable

**Green Cove Springs** 

Inspection Date:

2/15/2024

Address:

Suite:

900 Walnut Street

InspectionType:

Annual Fire Safety Inspection

B-95, R-001

Inspected By:

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

, Stephanie Raud . 109

Signature valid only in mobile-eyes documents

Stephanie Raucci

2/15/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Main Office Portable

Green Cove Springs

Inspection Date:

2/15/2024

Address:

Suite:

900 Walnut Street B-95, R-002

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

海塘 hanle Raud

Signature valid only in mobile-eyes documents

Stephanie Raucci 2/15/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services Complex

Inspection Date:

2/2/2024

Address:

925 Center Street

InspectionType:

Annual Fire Safety Inspection

Suite:

Bldg 1

Inspected By:

Stephanie Raucci

oune.

play i

Green Cove Springs

Location

Code Set

Code

2nd Floor Police Dept

FL NFPA 01 2018

Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: 2 fire extinguishers on the 2nd floor are expired. Have tested and recertified.

R-152 Multi-Purpose

FL NFPA 01 2018

Chapter 13 Fire Protection Systems

13,6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher by the exit door is expired. Have tested and recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

2023 24 (1/22 2) AM

Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services

Inspection Date:

2/22/2024

Address:

925 Center Street

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

Suite:

Bldg 2

Green Cove Springs

Code

Location

Code Set

¢4α. Ø Λ. (f.

444 C. C. C. C.

R-110

FL NFPA 01 2021


Chapter 14 Means of Egress

14.13 - Emergency Lighting.

Inspector Comments: Emergency light in last bay is not working. Repair or replace as needed.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:



Signature valid only in mobile-eyes documents

Stephanie Raucci

2/22/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services

925 Center Street

Address: Suite:

Bldg 4

Green Cove Springs

Inspection Date:

InspectionType:

Inspected By:

2/22/2024

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Sisphante Paucol
123
2225/024 155 15 FM

Signature valid only in mobile-eyes documents

Stephanie Raucci 2/22/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Maintenance

925 Center Street

Suite:

Address:

Bldg 5

Green Cove Springs

Inspection Date:

InspectionType:

Inspected By:

2/22/2024

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safel If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephanie Raudo

Signature valid only in mobile eyes documents

Stephanie Raucci

2/22/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services

Inspection Date:

2/16/2024

Address:

925 Center Street

InspectionType: Inspected By: Annual Fire Safety Inspection

Stephanie Raucci

Suite:

Gree

Bldg 6

Green Cove Springs

Code

Location

Code Set

000

R-3 Office

FL NFPA 01 2021 Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher certification tag is expired. Have tested and recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephanie Rauck

2016/2024 1: 14:30 FM

Signature valid only in mobile eyes documents

Stephanie Raucci

2/16/2024



925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

**Support Services** 

Inspection Date:

2/2/2024

Address:

925 Center Street

InspectionType:

Annual Fire Safety Inspection

Suite: Bldg 9

Inspected By:

Stephanie Raucci

Location

Green Cove Springs

Code

R-901

Code Set

FL NFPA 01 2018 Chapter 13 Fire Protection Systems 13.6.3.1.2 - Extinguisher Readiness.

Inspector Comments: Fire extinguisher next to exterior door is expired. Have tested and certified.

R-908 Hallway

FL NFPA 01 2021

Chapter 14 Means of Egress

14.13 - Emergency Lighting.

Inspector Comments: Emergency light not functional. Repair/replace as required.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Sci

Signature valid only in mobile eyes documents

Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services

Address:

925 Center Street

2/2/2024

Suite:

Bldg 10

Annual Fire Safety Inspection

Green Cove Springs

Stephanie Raucci

Location

Code Set

Code

Hallway by R-

FL NFPA 01 2018

110

Chapter 10 General Safety

10.18.3.1 - Ceiling clearance from storage (non-sprinklered

Requirements

areas).

Inspector Comments: Remove storage from areas within 2 feet of ceiling.

Inspection Date:

InspectionType:

Inspected By:

R-103

FL NFPA 01 2018

10.18.3.1 - Ceiling clearance from storage (non-sprinklered

Chapter 10 General Safety

areas).

Requirements

Inspector Comments: Remove storage from areas within 2 feet of ceiling.

Thank you for your cooperation in keeping our school community safel If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Signature valid only in mobile-eyes documents

Stephanie Raucci

-Stephanie Rauge

2/2/2024



925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services

925 Center Street

Address: Suite:

Bldg 11

Green Cove Springs

Inspection Date:

Inspected By:

.

2/2/2024

InspectionType:

Annual Fire Safety Inspection

Stephanie Raucci

Location

Code Set

e Sef

Code

Throughout

FL NFPA 01 2018


Chapter 13 Fire Protection Systems

13.6.3.1.2 - Extinguisher Readiness.

**Inspector Comments:** All 3 fire extinguishers in the building on 1 & 2 floors are expired. Have tested and recertified.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:



Signalure valid only in mobile-eyes documents

Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Support Services

Inspection Date:

2/2/2024

Address: Suite: 925 Center Street

InspectionType: Inspected By:

Annual Fire Safety Inspection

Bldg 12

Green Cove Springs

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephanie Flaula 98 2/2/2024 | Freda per

Signature valid only in mobile eyes documents

Stephanie Raucci

2/2/2024



925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Middleburg Transportation

3674 County Road 220

Address: Suite:

Bld 1-Vehicle Maintenance

Middleburg

Inspection Date:

11/2/2023

InspectionType: Inspected By:

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

· SUL

Soneture valid only in trabile eyes docume

Stephanie Raucci

11/2/2023



925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Middleburg Transportation

Address:

3674 County Road 220

Suite:

Bld 3-Vehicle Fuel Station/Maintenance

Middleburg

Inspection Date:

11/2/2023

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

19202023 ID 14 58 M3 Signature yalld only in mobile eye's documents

Stephanie Raucci

11/2/2023



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Middleburg Transportation

Address:

3674 County Road 220

Suite:

15-Workshop

Middleburg

Location

**Code Set** 

V9.43 69.72 163.32 16

Building 15

FL NFPA 01 2018

Chapter 13 Fire Protection Systems

Code

13.6.2.1.1 - Installation and maintenance of portable fire extinguishers

11/2/2023

Stephanie Raucci

Annual Fire Safety Inspection

Inspector Comments: Hang the fire extinguisher on the wall at proper height with an approved bracket.

Inspection Date:

InspectionType:

Inspected By:

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

NC.

11/2/2023 9/59/21 AM

Signature valid only in mobile eyes documents

Stephanie Raucci

11/2/2023



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Middleburg Transportation

Address:

3674 County Road 220

R-201-Bus Driver Office Suite: Middleburg

**Inspection Date:** Inspected By:

11/2/2023

InspectionType:

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Signature yalid only in mobile-eyes documents

Stephanie Raucci

11/2/2023



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Middleburg Transportation

Address:

3674 County Road 220

Suite:

R-202 & 203-Bus Driver Training

Middleburg

Inspection Date:

InspectionType: Inspected By:

11/2/2023

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

nature valld only in mobile eyes documents

Stephanie Raucci

11/2/2023



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Middleburg Transportation

Address:

3674 County Road 220

Suite:

R-401,402, & 403-Administration

Middleburg

Location

Code Set

FL NFPA 01 2018

R-401,402, & 403-Administration

Chapter 13 Fire Protection

Systems

Inspection Date:

11/2/2023

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

Code

13.6.2.1.1 - Installation and maintenance of portable fire

extinguishers

Inspector Comments: Fire extinguishers are expired in these buildings. Have serviced

immediately.

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

nature velid only is mobile eyes documents

Stephanie Raucci 11/2/2023



925 Center St, Green Cove Springs; FL 32043 (904) 336-0636

Occupant Name:

R-501,502,503,504, & 505-

Middleburg Transportation

Address:

3674 County Road 220

Suite:

R-501,502,503,504, & 505-Administration

Middleburg

Location

Administration

Code Set

FL NFPA 01 2018

Chapter 13 Fire Protection

Systems

Code

13.6.2.1.1 - Installation and maintenance of portable fire

11/2/2023

Stephanie Raucci

Annual Fire Safety Inspection

extinguishers

Inspector Comments: Fire extinguishers are expired in these buildings. Have

Inspection Date:

InspectionType:

Inspected By:

serviced immediately.

Inspector Comments: Passed annual firesafety inspection.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

alure valid only in mobile eyes documents

Stephanie Raucci

11/2/2023

#### 2023 - 2024 KEYSTONE TRANSPORTATION CORRECTION LIST

QUANTY	Room Number	DGA Prefbi	DCA Number	THEMS THAT NEED TO BE CORRECTED
2	2	II-B	10964	Transport and the Commission was produced to the sale of the Commission of the Society and the Commission of the Commiss
(12) Elizabether menter management etteran	002A	II-B	10964	Company of the Compan
3	760	V	002061	

TOTAL 2

#### CCSB KEYSTONE TRANSPORTATION — KEYSTONE TRANSPORTATION

6842 County Rd 315C, Keystone Heights, FL 32656, USA



KEYSTONE TRANSPORTATION PORTABLE ANNUAL INSPECTION #2

Description

RM 2 MB E 10964 KEYSTONE TRANSPORTATION PORTABLE INSPECTION

Status

**APPROVED** 

Assignee

Larry Paterson (LPA)

Date

11-20-2023

SCHOOLS 中,但我就是她的一种,我们就是我们的,我们就是我们,我们就是我们,我们是我们的,我们是我们的,我们是我们的,我们是我们的,我们是我们的,我们也是我们的,我们也是

BLD/FISH ID # INSIGNIA #

t makaya wasa ann kanasanan pagamanan sanasa ahan ahan danah soo kanasan manasan masan masan magaasan ando an k

DATE OF CONSTRUCTION

KEYSTONE

SCHOOLS

TRANSPORTATION

MB-E 10964

PORTABLE BUILDING INFO

TYPE OF CONSTRUCTION **ROOF TYPE** 

ANCHORS AND BLOCKS

LOW SLOPE

GOOD CONDITION

DOORS

IIB

NUMBER OF EXITS DIRECTION OF

SWING

**ACCESSIBLE HARDWARE** 

**CLOSERS** 

TWO

OUTSWING

YES

YES

ELECTRICAL

PANEL LABELED

YES

ARE THE OUTLET COVERS AND LIGHT FIXTURES INTACT AND

**OPERATIONAL?** 

YES

IS THE GFCI FUNCTIONING

PROPERLY?

YES

IS THE ELECTRICAL PANEL

ACCESSIBLE?

YES

COMMENTS

MECHANICAL

IS THE HVAC SYSTEM IN WORKING

ORDER?

ARE THE FILTERS CLEAN?


YES

COMMENTS

PLUMBING						
pring parmine and statemented from an exception of statement of the second control of	VEC	reigh denge a le boar ephrées er	per supply opening before the entire entre	NA JOSEPH CONTRACTOR OF A COMPANY OF A COMPA	in pulsar have a credit of the property of the open society and of	gingapa ng manakan garan
IS THE PORTABLES BATHROOM IN OPERATION?	YES					
ARE THE SUPPLY AND DRAIN CONNECTIONS COMPLETE AND FREE OF LEAKS?	YES					
ARE THE FIXTURES IN WORKINMG ORDER AND FREE OF LEAKS?	YES					
EXHAUST FAN INTACT AND OPERATIONAL?	YES					
SINK HANDICAPPED	YES					
HANDICAPPED TOILET	YES					
SIDE OF TOILET GRAB BAR	YES					
BACK OF TOILET GRAB BAR	YES					
COMMENTS						
LIFE SAFETY					,	a grant more
FIRE ALARM PRESENT	YES	t is account to the County Special Property (1992) for 1 kind	ৰ general অৰ্থা সংগ্ৰাহণ কৰে মুখ্য ছবলে চীন । — বিষ্ণান কৰে বিৰুদ্ধ কৰে বিৰুদ্ধ কৰে । সং	- 1997年 - 19		
INTERCOM/PHONE PRESENT	YES					
FIRE EXTINGUISHER PRESENT AND WITHIN 5' OF DOOR	YES					
SMOKE DETECTORS/CLASSROOM PRESENT	YES					
HEAT DETECTORS/STORAGE ROOMS PRESENT	YES					
EMERGENCY LIGHT'S PRESENT AND WORKING	YES					
EXIT SIGN/EXIT LIGHT PRESENT	YES					
STEPS/RAMPS/5'X5' PLATFORM AT ALL DOORS	YES					
EMERGENCY EVACUATION SHEET PROPERLY PLACED BY DOOR	YES					
COMMENTS						

PHOTOS







#### THIS BUILDING MEETS THE SREF STANDARDS, FS SECTION 1013.20 AND FLORIDA BUILDING CODE FOR SATISFACTORY RELOCATABLE CLASSROOM

APPROVED:

INSPECTED BY: LARRY PATERSON, BUILDING OFFICIAL

YES

#### CCSB KEYSTONE TRANSPORTATION — KEYSTONE TRANSPORTATION

6842 County Rd 315C, Keystone Heights, FL 32656, USA



KEYSTONE TRANSPORTATION ANNUAL PORTABLE INSPECTION #3

Description

RM 760 MB E 002061 KEYSTONE TRANSPORTATION PORTABLE INSPECTION

Status

**APPROVED** 

Assignee

Larry Paterson (LPA)

Date

11-20-2023

SCHOOLS

BLD/FISH ID #

INSIGNIA #

DATE OF CONSTRUCTION

KEYSTONE

SCHOOLS

760

002061

TRANSPORTATION

PORTABLE BUILDING INFO

TYPE OF

ROOF TYPE

ANCHORS AND BLOCKS

CONSTRUCTION

GABLE

GOOD CONDITION

DOORS

NUMBER OF EXITS DIRECTION OF

ACCESSIBLE

SWING

HARDWARE

**CLOSERS** 

OWT

OUTSWING

YES

YES

ELECTRICAL

PANEL LABELED

YES

ARE THE OUTLET COVERS AND

LIGHT FIXTURES INTACT AND

**OPERATIONAL?** 

YES

IS THE GFCI FUNCTIONING

PROPERLY?

YES

IS THE ELECTRICAL PANEL

ACCESSIBLE?

YES

COMMENTS

MECHANICAL

IS THE HVAC SYSTEM IN WORKING ORDER?


- ..... was track a amount of a country and arrangly

ARE THE FILTERS CLEAN?

COMMENTS

ŧ							
, PLUMBING		ر الشرائع و المتعدد ال	kan no a grapasa da rekeronak so koste sekanisi daki se	es postpanna han reconstructivos curtos de	ellergresstad gibrer for weap with a like of traditional color listens.	enne alle vije (miller) e der delt stedel i endler	aa
IS THE PORTABLES BATHROOM IN OPERATION?	YES	and the second s					
ARE THE SUPPLY AND DRAIN CONNECTIONS COMPLETE AND FREE OF LEAKS?	YES						
ARE THE FIXTURES IN WORKINMG ORDER AND FREE OF LEAKS?	YES						
EXHAUST FAN INTACT AND OPERATIONAL?	YES						
SINK HANDICAPPED	YES						
HANDICAPPED TOILET	YES						
SIDE OF TOILET GRAB BAR	YES						
BACK OF TOILET GRAB BAR	YES						
COMMENTS							
LIFE SAFETY						e e e e e e e e e e e e e e e e e e e	つれ エンル 編 面がが続き マン・・5、赤竿
FIRE ALARM PRESENT	YES	унев 2000 жылы анына таккоо шалауындан — Бак ж	antic yearned Constantion - EN Contractor M	N. HATEL BURNE SELECTIONS OF LEAST			
INTERCOM/PHONE PRESENT	YES						
FIRE EXTINGUISHER PRESENT AND WITHIN 5' OF DOOR	YES						•
SMOKE DETECTORS/CLASSROOM PRESENT	YES						
HEAT DETECTORS/STORAGE ROOMS PRESENT	YES						
EMERGENCY LIGHTS PRESENT AND WORKING	YES						
EXIT SIGN/EXIT LIGHT PRESENT	YES						
STEPS/RAMPS/5'X5' PLATFORM AT ALL DOORS	YES						
EMERGENCY EVACUATION SHEET PROPERLY PLACED BY DOOR	YES						
COMMENTS							

PHOTOS



#### THIS BUILDING MEETS THE SREF STANDARDS, FS SECTION 1013.20 AND FLORIDA BUILDING CODE FOR SATISFACTORY RELOCATABLE CLASSROOM

APPROVED:

INSPECTED BY: LARRY PATERSON, BUILDING OFFICIAL

#### 2023 - 2024 GCS SCJHOOL BUS GARAGE CORRECTION LIST

QUANTY	Room Number	DCA Prefix	DCA Number	ITEMS THAT NEED TO BE CORRECTED
2	002	II-B	007455	GFCI IN RR WOULD NOT RESET

800 Center St, Green Cove Springs, FL 32043, USA



GCS SCHOOL BUS GARAGE PORTABLE ANNUAL INSPECTION #2

Description

RM 002 MB E 007455 GCS SCHOOL BUS GARAGE PORTABLE INSPECTION

Status

**APPROVED** 

Assignee

Larry Paterson (LPA)

Date

12-12-2023

**SCHOOLS** 

**SCHOOLS** BLD/FISH ID # INSIGNIA #

DATE OF CONSTRUCTION

GCS SCHOOL BUS 002

**GARAGE** 

MB E 007455

PORTABLE BUILDING INFO

TYPE OF

**ROOF TYPE** 

ANCHORS AND BLOCKS

CONSTRUCTION

**LOW SLOPE** 

GOOD CONDITION

**DOORS** 

NUMBER OF EXITS DIRECTION OF

**SWING** 

**ACCESSIBLE** HARDWARE

**CLOSERS** 

TWO

IIB

**OUTSWING** 

YES

YES

ELECTRICAL

PANEL LABELED

YES

ARE THE OUTLET COVERS AND LIGHT FIXTURES INTACT AND

**OPERATIONAL?** 

YES

IS THE GFCI FUNCTIONING

PROPERLY?

YES

IS THE ELECTRICAL PANEL

ACCESSIBLE?

YES

COMMENTS

MECHANICAL

IS THE HVAC SYSTEM IN WORKING

**ORDER?** 

YES


ARE THE FILTERS CLEAN?


YES


COMMENTS


LUMBING	
S THE PORTABLES BATHROOM IN OPERATION?	YES
ARE THE SUPPLY AND DRAIN CONNECTIONS COMPLETE AND FREE OF LEAKS?	YES
ARE THE FIXTURES IN WORKINMG ORDER AND FREE OF LEAKS?	YES
EXHAUST FAN INTACT AND OPERATIONAL?	YES
SINK HANDICAPPED	YES
HANDICAPPED TOILET	YES
SIDE OF TOILET GRAB BAR	YES
BACK OF TOILET GRAB BAR	YES
COMMENTS	
LIFE SAFETY	
FIRE ALARM PRESENT	YES
INTERCOM/PHONE PRESENT	YES
FIRE EXTINGUISHER PRESENT AND WITHIN 5' OF DOOR	YES
SMOKE DETECTORS/CLASSROOM PRESENT	YES
HEAT DETECTORS/STORAGE ROOMS PRESENT	YES
EMERGENCY LIGHTS PRESENT AND WORKING	YES
EXIT SIGN/EXIT LIGHT PRESENT	YES
STEPS/RAMPS/5'X5' PLATFORM AT ALL DOORS	YES
EMERGENCY EVACUATION SHEET PROPERLY PLACED BY DOOR	YES
COMMENTS	GFCI in bathroom would not reset
PHOTOS	











#### THIS BUILDING MEETS THE SREF STANDARDS, FS SECTION 1013.20 AND FLORIDA BUILDING CODE FOR SATISFACTORY RELOCATABLE CLASSROOM

APPROVED:

INSPECTED BY: LARRY PATERSON, BUILDING OFFICIAL

YES



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Green Cove Springs Transportation

Inspection Date:

2/2/2024

Address:

800 Center Street

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

Suite:

**Green Cove Springs** 

Location

Code Set

Code

R-11 Bus Garage

NFPA 70 2017

Chapter 4 Equipment for General Use

408.7 - Unused Openings. (see photo 1.1)

Inspector Comments: Install cover over empty opening in the panel box on the west wall.

R-16 Storage Area

FL NFPA 01 2018

Chapter 10 General Safety


10.18.3.1 - Ceiling clearance from storage (non-sprinklered

Requirements

Inspector Comments: Remove storage from the top of the shelving cabinets.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:




Signature valid only in mobile eyes documents

Stephanie Raucci

2/2/2024

1.1 - 408.7.





925 Čenter St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Transportation

800 Center Street

Suite:

Address:

Bld 3-Vehicle Fuel Station

Green Cove Springs

Inspection Date:

2/2/2024

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

Location Code Set

FL NFPA 01 2021 Chapter 42 Refueling Code

42.7.2.6.4\* - Signs.

**Inspector Comments:** Existing signage is old and hard to read or missing. Replace signage at the fuel station and emergency shut off locations to be in compliance with NFPA 30A-9.2.5.4 & 9.5.3.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

State | State

S'neature valid only in mobile eyes document

Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Fuel Station Bldg

Inspection Date:

2/2/2024

Address: Suite:

800 Center Street

InspectionType:

Annual Fire Safety Inspection

B-90, R-001

Inspected By:

Stephanie Raucci

Green Cove Springs

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

. Stepnomie Kauddi

: 2/2/2004 12:16:08 PM

Signature valid only in mobile eyes documents

Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Address:

Suite:

Portable-Bus Drivers

800 Center Street

B-92, R-002

**Green Cove Springs** 

Inspection Date:

InspectionType:

Inspected By:

2/2/2024

Annual Fire Safety Inspection

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

Stephande 5 91 2/2/2024 1:05:33 F

Signature valid only in mobile eyes documents

Stephanie Raucci

2/2/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Keystone Transportation

Address:

6800 County Road 315 C

Suite:

B-95, R-2

Keystone Heights

Inspection Date:

3/1/2024

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

Code

Location

Code Set

FL State Requirements for Educational Facilities

FL State Requirements for Educational Facilities 2014

5.17 - Electrical.

Inspector Comments: Lighting was not working on half of the room. Repair as needed.

Thank you for your cooperation in keeping our school community safel If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

MAGGOROL PERENTE

Stephanie Raucci

3/1/2024



925 Center St, Green Cove Springs, FL 32043 (904) 336-0636

Occupant Name:

Keystone Transportation

Address:

6800 County Road 315 C

Suite:

Keystone Heights

B-92, R-760

Inspection Date:

3/1/2024

InspectionType:

Annual Fire Safety Inspection

Inspected By:

Stephanie Raucci

No violations noted at this time. If you have any questions, please contact our office.

Thank you for your cooperation in keeping our school community safe! If you have any questions, please contact the inspector listed at the top of this report.

Inspector:

SR

1012024 (634 04 FII)

Stephanie Raucci

3/1/2024