

FISCAL YEAR 2012-2013

**COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY: 0033

FACILITY: MIDDLEBURG TRANSPORTATION
3674 COUNTY ROAD 220
MIDDLEBURG, FLORIDA 32043

INSPECTION DATE: MARCH 7, 2013

3-7-13

DATE

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	1-2	PAINT PEELING	X							
1	102	CEILING TILE STAINED	X							
3		OK								
92	201	OK								

FISCAL YEAR 2012-2013

**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY: 0027

FACILITY: H. C. LONG ADMINISTRATION
 23 SOUTH GREEN STREET
 GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: APRIL 11, 2013

INSPECTOR'S SIGNATURE: *[Signature]* DATE: 4-11-13

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	100	BOTH EMERGENCY LIGHTS OUT		X						
2	201B	ROMEX WIRE LEAVING PANEL GOING UP INTO CEILING - REMOVE	X							
3	300	BOTH EMERGENCY LIGHTS OUT		X						
4	404A	ADD EMERGENCY LIGHTS	X							
4	407A	OUTLET COVER MISSING OVER PANEL	X							
4	416	EMERGENCY LIGHT OUT		X						
4	416	EQUIPMENT IN FRONT OF ELECTRIC PANEL		X						

FISCAL YEAR 2012-2013

**COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY: 0003

FACILITY: SUPPORT SERVICES
925 WEST CENTER STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: APRIL 11, 2013

Ed McCallister
INSPECTOR'S SIGNATURE

4-11-13
DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	13A	EMERGENCY LIGHT OUT		X						
1	34	EMERGENCY LIGHT OUT		X						
2		OK								
4		EQUIPMENT TOO CLOSE TO PANEL		X						
5	21	EMERGENCY LIGHT OUT		X						
6		OK								
9	104	EMERGENCY LIGHT OUT		X						
9	107	EMERGENCY LIGHT OUT		X						
9	115	EMERGENCY LIGHT OUT		X						
9	911	EMERGENCY LIGHT OUT		X						
9	911A	EMERGENCY LIGHT OUT		X						
11		OK								
12		OK								

FISCAL YEAR 2012-2013

**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY: 0036

FACILITY: SCHOOL BOARD MAIN OFFICE
900 WALNUT STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: APRIL 11, 2013

INSPECTOR'S SIGNATURE: *Ed McArthur* DATE: 4-11-13

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
2		OK								
3	30	LENSE MISSING CORRIDOR		X						
95	1	OK								
95	2	OK								

FISCAL YEAR 2012-2013

**COMPREHENSIVE SAFETY & SANITATION
 INSPECTION REPORT
 STATE BOARD OF EDUCATION
 ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
 "CASUALTY SAFETY & SANITATION INSPECTION"
 IN COMPLIANCE WITH
 F.S. 1013.12, 1013.20 & NFPA 101**



DISTRICT: CLAY FACILITY: 0030

FACILITY: SCHOOL BUS GARAGE - TRANSPORTATION
800 CENTER STREET
GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: APRIL 11, 2013

INSPECTOR'S SIGNATURE: *John Swearingen*

DATE: 4-11-13

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	11	EMERGENCY LIGHT OUT BY BACK DOOR		X						
1	11	KNOCK-OUT MISSING PAN-DUIT UNDER PANELS	X							
1	6	EMERGENCY LIGHT OUT		X						
1	200	ALL THREE (3) EMERGENCY LIGHTS OUT		X						
1	200	CEILING TILE MISSING		X						
90	1	FUEL PUMP BUILDING - OK								
95	2	OK								
91	3	EMERGENCY LIGHT OUT		X						