

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:	0003

FACILITY: BANNERMAN LEARNING CENTER

608 MILL STREET

GREEN COVE SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBE	R 4, 2011
RIA	11-4-11
recent /	
INSPECTOR'S SIGNATURE	/DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	109	PLUG ABOVE CEILING TO PROJECTOR			Х	10.00				
2	208	TOO MUCH STORAGE BLOCKING ELECTRIC PANELS		X						NFPA 70-160.26
3	319	LIGHT OUT - MECHANICAL ROOM		Х						FBC 1006.3.1
3	319	WEEDS GROWN UP @ AC YARD	X							The state of the s



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY: 0003
FACILITY: BANNERMAN L	EARNING CENTER
608 MILL STRE	
GREEN COVE	SPRINGS, FLORIDA 32043

INSPÉCTION DATE: NOVEMBER 4, 2011

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac.	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	1	ок				12 to 2 to	TO 1 1 14 PAGE 1	*		
92	2	OK								
92	3	OK								
92	4	OK								
92	5	OK								
92	6	oK					Anne de la company		**************************************	
92	7	ок								
92	- 8	OK								
92	9	ОК								
92	10	ок								
92	11	ОК								
92	12	ok								
92	13	ок								

•	-	
1		
	`	

FISCAL YEAR <u>2011-2012</u>



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:0003	
FACILITY:		N LEARNING CENTER	
	608 MILL STR	REET	
	GREEN COV	/E SPRINGS, FLORIDA 32043	

INSPECTION DATE: NOVEMBER 4, 2011

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper: "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	30	ОК								
92	31	OK								
92	32	ОК	·					4847 (1992	Alek See Lar	
92	33	ΘK								
92	34	ок					<u> </u>			
92	35	ok								
92	36	ок								
92	37	ок								
92	38	ок								
92	39	OK							At an A comme	
92	40	ОК								
92	42	ОК								
92	43	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY	FACILITY:0003
FACILITY:	BANNERMAN	LEARNING CENTER
	608 MILL STR	EET
	GREEN COVE	SPRINGS, FLORIDA 32043

INSPECTION DATE: NOVEMBER 4, 2011

INSPECTOR'S SIGNATURE

				Def. Cited	Correction	
Х	Х					
		X				
l						



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

4.4	and the state of t		title in the territory	
mio-mmi	OT 01 A37	PAOII ITY.	0004	
DISTRI	LICHAY	FACILITY:	111111	
DIO 1111	O 1 . O L./ \ / 1	 	000.	
and the second second	and the second second			

FACILITY: GREEN COVE SPRINGS JUNIOR HIGH SCHOOL
1220 BONAVENTURE AVENUE

GREEN COVE SPRINGS, FLORIDA 32043

Hauff	11-10-11
INSPECTOR'S SIGNATURE	DATE

INSPECTION DATE: NOVEMBER 10, 2011

Building	Room (Deficiency Description and Corrective Action Required:	Maint. "M"	Oper "O"	Pac "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		OK		le gallane						
	1,002/24/2014	OK		arregay para Palatina keph						
2 1		OK)								
3	34	EMERGENCY LIGHT OUT	Χ			Page 10 Control of the Control of th	Section 1 hand on them in the	and Marchines, 2007 Service Sci.	n antere mane es anterangua	FBC 423.17.1
4	403	EXTENSION CORD ABOVE CEILING		Χ						NFPA 70 400-8
4	404	PROJECTOR NOT INSTALLED PROPERLY	Х							NFPA 70 110.12
5	501	EXIT SIGNS BROKEN	X							NFPA1
5	501	NO MAXIMUM OCCUPANCY SIGN		Х						FBC 423.14.2.2
54	10	PROJECTOR NOT INSTALLED PROPERLY	X							NFPA 70-110:12
5	12	PROJECTOR NOT INSTALLED PROPERLY	Х							NFPA 70-110.12
(5)	14A	FOURISTOVES - NO HOODS	· X							NFPA 1 10.4.1
8		ОК								
7		OK								
. 9	931	CHECK TV BRACKET	Х							NFPA 70-110.12
31	1, 1	REMOVE PROPANE TANK		X						NFPA 1.21.3.3.5



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CL	AY FAC	ILITY: 0001
		and the second of the second o
FACILITY: GRE	EN COVE SPRING	SS JUNIOR HIGH SCHOOL
	BONAVENTURE	
GRE	EN COVE SPRING	GS, FLORIDA 32043
INSPECTION DA	TE: NOVEMBE	R 10, 2011
M		11 6 11
/ Kelef f		11-1071
	ICMATURE	DATE


Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rulė
92	70	PROJECTOR NOT INSTALLED PROPERLY	Χ							NFPA 70-110.12
92	70		X ,							NEPA(101.7.9
92	71	OK	400000 CONTRACTOR (1990) CONTR	Anti-one Beauty	(2010-05-04-05-05-010-	arangan dan kananan dan kerab	F. C.	ENERGY PERSONS	The Control of the Co	Carlot to the control of the carlot transfer and the control of the carlot transfer and transfe
92	74	PROJECTOR NOT INSTALLED PROPERLY	X							NFPA 70-110.12
92	75	ок								
92	76	OK 100 Marin 1997								
92	103	ОК								
92	104	ŌΚ								
92	105	ок								
92	106	ΘK.								
92	107	PROJECTOR NOT INSTALLED PROPERLY	Х						·	NFPA 70-110.12
. 92	112	ÖK								
92	113	ОК								



	DISTRICT: CLAY FACILITY: 0025
	FACILITY: LAKE ASBURY JUNIOR HIGH SCHOOL 2851 SANDRIDGE ROAD
	INSPECTION DATE: NOVEMBER 17, 2011
7	Todheattand Nov 17, 2011
	INSPECTOR'S SIGNATURE DATE


1 .										
Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Hac. "G"	Info. Serv "I.S."	Cost	No: of times Def. Cited	:Scheduled for Correction	'Kulė
1	111	FIRE EXTINGUISHER NOT SIGNED		. X		ALCOHOLOGICAL CONTRACTOR	ementarias (Sa	enangan selebah		69A-58.008
1	139	FIRE ALARMIFLOW SWITCH BOX OPEN	X							NEPA 70-110-26
3	343	PIRE EXTINGUISHER NOT SIGNED		X		ESTERVIEN AGE	rundschen Sal	enter volution		69A-58.008
3	344	ELECTRICAL PANEL KNOCKOUT MISSING	X							NEPA/70(99) 410-4(A)
8	8096	OUTLET FOR PROJECTOR ABOVE CEILING	and the state of t		X	北京部外加速時期	usomvistili est	Markat Mark		NFPA 70-110.12
- F2E8	8019	OUTLETFOR PROJECTOR ABOVE CEILING			X					NEPA 70-110-12
8	8056	OUTLET FOR PROJECTOR ABOVE CEILING	и останательный дина	e vestavevese <i>di</i>	X		7656598A	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		NFPA 70-110.12
										7751
								V8: 111		
		· 特别的 1.2 在 1.1 的 1.2								

FISCAL YEAR <u>2011-2012</u>




DISTRICT:_	CLAY	FACIL	_ITY:0025
FACILITY:	2851 SAN	IDRIDGE RO	R HIGH SCHOOL AD GS, FLORIDA 32043
INSPECTION	ON DATE: _	NOVEMBE	ER 17, 2011
INSPECTO	Aveou R's SIGNA	Long TURE	Mov 17,2011 DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac: "C"	Info. Serv. "IS:"	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	390	ОК	Name to see a consession	School Employees	9479126912JULIJE	102 TANGS MENGAGO (**)	verel decreta	a seriolest	83.4-14.2-15.2-16.16.16.16.16.16.16.16.16.16.16.16.16.1	
92	391	OK								
92	392	ОК				THE STATE OF THE S	SUPPRANTACIONES (S	caracina ang ara-ara-ara-ara-ara-ara-ara-ara-ara-ara	PARAMETOR MINERAL	
92	393	PROJECTOR INSTALLED IMPROPERLY			X					NFPA 70-110.12
92	394	ОК							and the second Laboratory of the Heaville	TOTAL PROPERTY OF THE SECRET PROPERTY PROPERTY OF THE SECRET PROPERTY PROPERTY OF THE SECRE
92	401	ΘK								
92	402	PROJECTOR INSTALLED IMPROPERLY			Х					NFPA 70-110.12
92	403	OK.								
92	404	OK								
	405	PROJECTOR INSTALLED IMPROPERLY			X					NFPA 70-110.12
92	Section Contests of the Contests	Publicated Control of the Control of Control	- 54-500-000 attached (1704)	costs of established a con-	American and basel sectors	, , , , , , , , , , , , , , , , , , , ,				
92	406	OK								
-92	407	OK	1975	10.500 (D	加州斯特斯	中的學家	的問題問題	建筑财务标约	Control of the Contro	Entre de Merchen des controls de la control



DISTRICT:_	CLAY	FACILITY:	0025
FACILITY:	LAKE ASBUF	RY JUNIOR HIGH	I SCHOOL
	2851 SANDR	IDGE ROAD	
	GREEN COV	E SPRINGS, FLO	ORIDA 32043
INSPECTION	N DATE: N	OVEMBER 17, 2	2011
(ad)	Weatters)	Nov 17, 2011
INCRECTO	D'S SIGNATIE) = 1	DATE

		The second secon	P4601620016448	(EKYESKISKI)	AND IESO MARIO	25 行动数据			建筑是建筑建筑	
Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac. "C"	Info Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
			KEEP WEEP	TO COLUMN TO STATE OF THE STATE	Carlo martine salah salah					
92	408	OK	en al december	SANTONIA CONTRACTOR	maranganang	SH-SVESSTATE	39307426	O SACATOD		
92	410	EMERGENCY LIGHT OUT	X							FBC 423.17 1
	Teach process the section of the	OK								
92	421					11515	洪州旗			
92	422	OK				MARKED E	92910600	网络密沙斯多 拉	Environmentalismos	
92	423	ОК							Income and the second second second	ordania da ordina produce e produce de la compaña de l
92	425	OUT OF SERVICE								
92	427	OK								
				12 (13 7/4)						
92	428	OUT OF SERVICE		E MAN				STATE HAVE TO	Projectic Composition	
92	430	ок							oomen oo ee ka oo saaree saaree	recover tractions was tractived by the contract
ASSESSMENT FOR THE STATE OF THE	(Facilities Assistant 25/25/2	parametric and process of the annual control								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY: 0014
FACILITY: LAKESIDE JUNIOR HIGH SCHOOL
2750 MOODY ROAD

ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 29, 2011

SPECTOR'S SIGNATURE DATE

Building	Room	Deficiency, Description and Corrective Action Required:	Maint.	Oper "O"	Fac. "C"	Info Serv "I S:"	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	18	OUTLET FOR PROJECTOR ABOVE CEILING			Х				ned in the Draw employed (CATER)	NFPA 70-110.12
1	19	OUTLET-FOR PROJECTOR ABOVE GEILING			X					NEPA 70-110-12
1	29	OUTLET FOR PROJECTOR ABOVE CEILING			Х				description of the only configurations	NFPA 70-110.12
2 -	31	OUTLET FOR PROJECTOR ABOVE CEILING			X					NEPA 70-110-12
2	54	OUTLET FOR PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
3		REMOVE UNPLUGGED EXTENSION CORDS		X						NFPA 70-400.8
5	116	CEILING TILES MISSING		Х						FBC 804.2.3
8 line	814	REPLACE OUTLET COVER BETWEEN 818-819		X						NFPA 70-410 1/2
9	919	TWO BULBS OUT		Х						FBC 1006.3.1
			15065							
**************************************	PROFESSION FOR THE	enderstellte state der state der state state state state in der state in der state in der state state in der s Bestellt der state state state state state state state state in der state state state state state state state s							:	
Children Children 1989										



administrative rules s.k.e.f. - Chapter 3

"Casualty Safety & Sanitation Inspection"

In Compliance with

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY	FACILITY:	0014
FACILITY: LAKESIDE JUNIO	R HIGH SCH	OOL
2750 MOODY RC	AD	

ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 29, 2011

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper. "O"	Fac. "G"	Info: Serv. "I'S:"	Cost	No. of times Defi Cited	Scheduled for Correction	Rule
92	701	ок					15.11 (M. 1.15.20°) 1.24(30)	ngaga erherar (d. 1889/1.1.) (0.0)	aranggan sa anggangan dag	
92	702	OK								
92	703	ОК						Southernest war was strong	o walka wa kafanina maraka maka ma ka ma wa ka	
92	704	,oK								
92	705	ОК							a prestrucción de planetes (h.) 2000	naturin kali izangan okumpala kali izang disebut bila izang disebut bila izang disebut bila izang disebut bila
92	706	OK								
92	707	ок								Danis dan Bertan dan dan dan dan dan dan dan dan dan d
92	708	OK								
92	710	ОК						UE william de l'Original de l'Artic	en orthold are uporthologistics.	algoriosen perminalalentaturarian kalinenakia
92	721	©K ³								
92	722	ОК					Construence on the state of the sa	scoppropriasi se englises e	Francia espera naturale de la consta	Proposition of the Mark Control Contro
,92	723	OK								
92	731	ок								

and the firm and the state of				2.75	and the second of
A Committee of the Committee of the	and the second second				
	O1 437		FACILIT	v.	0014
STRICT:	CLAY	1 17	₩ A3 € . 11	Y	111114
JINUI.	ULAI	The state of the s		the state of the s	



COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

FACILITY:	LAKESIDE JUNIOR HIGH SCHOOL
•	2750 MOODY ROAD
	ORANGE PARK, FLORIDA 32073

INSPECTION DATE: NOVEMBER 29, 2011

Aug | 1 - 79 - 1 |
INSPECTOR'S SIGNATURE DATE

Building.	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def Cited	Scheduled for Correction	Rule.
		性性 (A. B.				746				
92	732	ОК	Parameter with a Walder	nassanaryanan ne	STATE OF THE SHEET OF THE	ANGEN GERRALE	eledektekkirk	251094201(07:12:38)	Samual de Charles	
92	738	OK								
92	734	LIGHT COVER MISSING		Х						NFPA 708-401.3
92	737	LIGHT COVER MISSING		X						NEPA 708-401.3
92	735	ОК								Constitution of the Consti
92	745	EMREGENCY LIGHT OUT		X						FBC 423 17.1
92	791	ОК								contribution to the sequence of the sequence o
7 - (92) 。	792	(oK)								
92	793	ОК								annungara kina paratawan baharinga palawa (kinika 1166) ka 11885.
/92	794	OK								
										Marchan Carles Company



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY FACILITY: 0048
FACILITY:	OAKLEAF JUNIOR HIGH SCHOOL
	410 OAKLEAF VILLAGE PARKWAY
	ORANGE PARK, FLORIDA 32065
INCRECTION	DN DATE: DECEMBED 9 2011

ISPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint "M"	Oper. "O"	Fac:	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction.	Rule
1	209	BATHROOM SIGN MISSING – BOYS		Х						FBC 423.14.2.3
16 5 Th	522	REPLACE STAINED CEILING TILES		X						FBC 804:2.3
WEST STREET, SERVICE STREET,		SOMETIME STATE OF THE STATE OF								
37 - 24 - 24 - 24 - 24 - 24 - 24 - 24 - 2										
	10.41									
<u> </u>										



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:	0048	عنسست
FACILITY:	OAKLEAF JUNIOI	R HIGH SCHO	OL	
	410 OAKLEAF VII			
	ORANGE PARK,	FLORIDA 320	65	

Building	Room	Deficiency Description and Corrective Action Required:	Maint: "M"	Oper "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Gorrection	Rule
92	601	ОК								
92	602	OK								
92	604	ок								
• 92	605	OK:								
92	607	ОК								
92	.608	OK								
92	609	ок								
. 92	, -610	OK								
92	611	ок								
rii 92 🗀 r	5 612	OK								
92	613	ОК								
92	614	iOK _{II}								
92	615	ОК								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

"CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:	CLAY		FACILITY	0048	
7.7 11 11 1 		<u> </u>			

FACILITY: OAKLEAF JUNIOR HIGH SCHOOL 410 OAKLEAF VILLAGE PARKWAY

ORANGE PARK, FLORIDA 32065

INSPECTION-DATE: DECEMBER 8, 2011

Jey///	18-8-11
SPÉCTOR'S SIGNATURE	DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Operi "O"	Fac:	Info: Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	616	ок								
92	617	I@K								
92	618	ОК								
92	619	OK //								
92	620	ОК								
92 11	622	OK								
92	704	ОК								
92	705	ÖK								
92	706	ОК								
92:5	707	ЮК.								
92	708	ок								
92 :	709:	ЮК								
92	710	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

			and the last of the second		360 to 200 to 100 to 10	100
DISTRICT	CLAY	and the state of the state of the	TACIL IT	T'\/.	0040	
DISTRICT	CLAY.		FACILI	I I	0048	 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
						-
		the second of the second	10. 5. 5. 5.		and the second of the second o	and the second second

FACILITY: OAKLEAF JUNIOR HIGH SCHOOL
410 OAKLEAF VILLAGE PARKWAY
ORANGE PARK, FLORIDA 32065

INSPECTION DATE: DECEMBER 8, 2011

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper "O"	Fact. "C"	Info. Serv. "I.S."	Cost	No. of times Defi Cited	Scheduled for Correction	Rule
92	711	ОК					:			
92.	712	ΘK:								
92	603	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
92:	606	LIGHT LOOSE AT CEILING		X						
92	713	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
. 92	714	OK:								
92	715	ОК								
92	716	OK								
92	807	ОК								
92	809	ЮK								
92	810	ок								
92	821	OK.								
92	823	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

EACH ITV.	OVRIEVE TRIVIOD FIGH SCHOOL	
FACILITY:	OAKLEAF JUNIOR HIGH SCHOOL	
FACILITY:	OAKLEAF JUNIOR HIGH SCHOOL 410 OAKLEAF VILLAGE PARKWAY	

INSPECTION DATE: DECEMBER 8, 2011

'ŎR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper: "O"	Fac: "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	824	ОК								
92	808	TOLET DIVIDER RUSTING OUT	X							
92	811	LIGHT COVER MISSING		Х						



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"


IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY	FACILITY:	0016	
FACILITY:	ORANGE PA	ARK JUNIOR HIGH	I SCHOOL	
		ARK, FLORIDA 32	073	
	OKANGE FA	ANN, FLONIDA JE	0/0	
$1 \wedge 1$				

INSPECTION DATE: _	DECEMBER 1, 2011
$+$ $(u)^{-}$	
1) 11/19	- 15.1-1

INSPECTOR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1		ок								
2		OK								
3		ОК								
4		OK								
5		ОК								
6		OK								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

FACILITY:	ORANGE PARK JUNIOR HIGH SCHOOL
	2750 MOODY ROAD
	ORANGE PARK, FLORIDA 32073

FACILITY:

0016

CLAY

DISTRICT:

INSPECTION DATE: DECEMBER 1, 2011

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper.	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	501	ок								
92	503	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
92	504	ОК								
92	505	EMERGENCY LIGHT OUT	×							FBC 423:17.1
92	506	ок								
92	507	NO CONCRETE @ BASE OF RAMP	X							
92	507	EMERGENCY LIGHT OUT	Х							FBC 423.17.1
92	508	OK								
92	509	TRIP HAZARD @ BASE OF RAMP	Х							
92	510	OK								
92	511	ок								
92	514.	OK								
92	515	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION"

IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT	CLAY	FACILITY: 0016	
		K HINDS HIGH COHOO!	· · · · · · · · · · · · · · · · · · ·
FACILITY:	ORANGE PAR	K JUNIOR HIGH SCHOOL	
	2750 MOODY	ROAD	
	ORANGE PAR	K, FLORIDA 32073	

INSPECTION DATE: DECEMBER 1, 2011

SPECTOR'S SIGNATURE DAT

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "1.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	516	LENS MISSING ON LIGHT		Х						
92	702	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	702	MATERIAL STORED TOO CLOSE TO CEILING		Х						NFPA 1 12.1
92	703	OK								
92	704	ок								
92	706	ok								
92	708	ок								
92	710	EMERGENCY LIGHT OUT	X							FBC 423.17.1
92	712	ок								



Comprehensive Safety & Sanitation Inspection Report State Board of Education

ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"

in compliance with f.s. 1013.12, 1013.20 & NFPA 101

DISTRICT	CLAY	FACILITY: 0017	ينند
그래 기본 중	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		

FACILITY: WILKINSON JUNIOR HIGH SCHOOL

5025 COUNTY ROAD 218
MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: NOVEMBER 16, 2011

INSPECTOR'S SIGNATURE

11-16-11

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O") Fac Ç	Info: Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	101	STAINED CEILING TILES REPLACED		Х						FBC 804.2.3
# 2	203	LOOSE:WIRES = HOOD = SHUT DOWN	X							
3	301	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
4	414	PLUG-TO-PROJECTOR ABOVE GEILING			X					NFPA 70-1110:12
4	418	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
4	416	NO EMERGENCY EVACUATION SHEET		X						
5		ок								
6	606	LIGHT MISSING ON LENS COVER		- X1						NFPA 708 401.3
6	608	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
7	730	CEILING TILES MISSING		X						
7	775	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
8 223		OK								
9		ок								



DISTRICT:_	CLAY	FACILITY:_	0017
<u></u>	<u>epiliti, yi Balija i Nazita a Kak BA Barasa ya ka</u>		<u>and a second and the second and the</u>
FACILITY:	WILKINSON JUI	<u>VIOR HIGH S</u>	SCHOOL
_	5025 COUNTY F	ROAD 218	
•	MIDDLEBURG,	FLORIDA 32	2068
INSPECTIO		/EMBER 16,	
INSPECTO	R'S SIGNATURE		DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint! "M"	Oper. "O"	Fac.	Info: Serv "I'S:"	Cost	No. of times Def Gited	Scheduled for Correction	Rüle
92	2	ОК								
#£# 92	3	OK								
92	4	ОК								
#### (92	5 ,	OK								
92	6	ок								
(s, 92)	7	ÖK-							9	
92	8	ок								
92	93	OK								
92	10	ОК								
92	41	OK Company of the Com								
92	12	ОК								
92	17	OK								
92	18	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

그는 문문에 가장하다 하는 사람들은 사람들이 되었다. 그는 사람들이 가장 그리고 모르고 보고 보고 보고 있다.	الشداد بشيدا	
DISTRICT: CLAY FACILITY:	0017	
DISTRICT: CLAY FACILITY:	. 0017	
510111101		

FACILITY: WILKINSON JUNIOR HIGH SCHOOL 5025 COUNTY ROAD 218

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: NOVEMBER 16, 2011

NSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac.	Info. Serv. 'IS."	Cost	No. of times Def. Cited	Scheduled for Correction	Rüle
92	21	OK				PSTRIATUSALDITS-SII	va yan kana a rayan K	en per consumprime	nevernous some consecution was	avarencaese successor (Nearesy art 1870) e e l'Alexa
92	22	OK								
92	23	ок						Part and desired	contributed for the northead (2014)	
92	24	OK								
92	25	ок						•		
1 192	26	OK								
92	27	ОК								
. 92-≟	30	OK.								
92	40	ок								
92	F 41	OK Participation of the Control of t							e de la companya de	
92	42	ОК						ton they wright a supplement	er hag samman daga tempanyang	
92	43	IOK								
92	44	ок								

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION

ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY: 0017
	FACILITY: WILKINSON JUNIOR HIGH SCHOOL
	5025 COUNTY ROAD 218
	MIDDLEBURG, FLORIDA 32068
79	INSPECTION DATE: NOVEMBER 16, 2011

NSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Faci.	Info. Servi "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	46	OK			50.00	n i i i i i i i i i i i i i i i i i i i				
92	89/(300)///950/5/CDVA	©K								
92	96	OK			**************************************	- 1 American Mark St. 1				
								in School and the second		Total transport the country of the Total transport of the Total tran
						-17:48-18:70-18:0-11:10	ar makatanga kan hasing dalaman	are in the their Good and the second	recension versionini	overte gester historie area el decado restreolar e tras persente
		THE RESERVE OF THE PROPERTY OF THE RESERVE OF THE RESERVE OF THE PROPERTY OF T	HERSENBERGER	20 500 14000 00000	NAMES AND SERVICE AND A	Alleninevation	SERVICE SERVICE SERVICE	\$05777.B.2779.B	enting assertion and approxi-	
					2000					
Janaca de la composito de la c	Kentalasaharakasa		nama-wayota	a service entre e	USTANAS USTANA	SECURIE DE LA				



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY: 0017	٠.
FACILITY: WILKINSON JUNIOR HIGH SCHOOL	
5025 COUNTY ROAD 218	_
MIDDLEBURG, FLORIDA 32068	-

INSPECTION DATE: NOVEMBER 16, 2011

INSPECTOR'S SIGNATURE

// "/ ©

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Y Fact. "G"	Info. Serv. "I.S."	Cost	No. of times Def. Cired	Scheduled for Correction	Rule
1	101	STAINED CEILING TILES REPLACED		Х						FBC 804.2.3
2.51	203	LOOSE WIRES HOOD SHUT DOWN	X							
3	301	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
4	414	PLUGTO PROJECTOR ABOVE CEILING			X					NFPA-70-110-12
4	418	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
4.	416 - (NO EMERGENCY EVACUATION SHEET.		X						FBC=423.171
5		ок								
6 90	606	LIGHT MISSING ON LENS COVER		X						NFPA 708 401 3
6	608	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
7	730	CEILING TILES MISSING		1.X						
7	775	PLUG TO PROJECTOR ABOVE CEILING			Х					NFPA 70-110.12
8		OK								
9		ок								