


COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: THUNDERBOLT ELEMENTARY - 0531
 2020 THUNDERBOLT ROAD
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE: 
INSPECTION DATE: 3/8/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>5</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
1	111	Power strip to full/add outlets, so breaker not overloaded							
1	118	Excessive storage in closet/to high					X		X
**		Storage to high in closets ** must be down 18" from ceiling							
92	701	OK							
92	702	OK							
92	703	OK							
92	704	OK							
92	705	OK							
92	706	OK							
92	707	OK							
92	708	OK							
92	709	OK							
92	710	OK							
92	711		Emergency light out						X
92	712	OK							
92	713	OK							
92	721		Emergency light out						X

92	722	OK								
92	723	OK								
92	724	OK								
92	725	OK								
92	726	OK								
92	727	OK								
92	728	OK								
92	729	OK								
92	730	OK								
92	731		Electric panel blocked by cabinet							X
92	732	Foundation block broken							X	
92	733		Emergency light out							X
92	734	OK								
92	735	OK								
92	736	OK								
92	737	OK								
92	738	OK								
92	739	OK								
92	740	OK								
92	741	OK								
92	742	OK								
92	743	OK								
92	744	OK								

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: W. E. CHERRY ELEMENTARY - 0241
 420 EDSON DRIVE
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: 
INSPECTION DATE: 2/12/2016


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>5</u>					
1		OK						
2	77		Remove storage by exits					X
3	63		Emergency light out				X	
4	25		No emergency evacuation sheet					X
92	26	OK						
92	27	OK						
92	29	OK						
92	30	OK						
92	31	OK						
92	32	OK						
92	33	OK						
92	34	OK						
92	36	OK						
92	37	OK						
92	38	OK						
92	39	OK						
92	40	OK						
92	41	OK						
92	42A&B	OK						
92	43	OK						
92	47	OK						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: WILKINSON ELEMENTARY - 0491
 4965 COUNTY ROAD 218 W
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/10/2016

Fire Drill Log:
 Drills Performed: 6

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2		OK						
3		OK						
4		OK						
5		OK						
92	1	OK						
92	2	OK						
92	3	OK						
92	4	OK						
92	5	OK						
92	6	OK						
92	7	OK						
92	8	OK						
92	9	OK						
92	10	OK						
92	11	OK						
92	12	OK						
92	13	OK						
92	14	OK						
92	15	OK						
92	16	OK						
92	17	OK						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: GREEN COVE SPRINGS JUNIOR HIGH - 0021
 1200 BONAVENTURE AVENUE
 GREEN COVE SPRINGS, FL 32043


INSPECTOR SIGNATURE: 
INSPECTION DATE: 11/4/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
1		OK							
2	800		Emergency light out						X
3		OK							
4		OK							
5		OK							
6		OK							
7		OK							
8		OK							
9	908		Remove racks in exit		X				X
31		OK							
32		OK							
92	70	OK							
92	71	OK							
92	74	OK							
92	75	OK							
92	76	OK							
92	103	OK							
92	104	OK							
92	105	OK							
92	106	OK							
92	107	OK							
92	112	OK							
92	113	OK							

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: LAKE ASBURY JUNIOR HIGH - 0481
 2851 SANDRIDGE ROAD
 GREEN COVE SPRINGS, FL 32043


INSPECTOR SIGNATURE: 
INSPECTION DATE: 11/10/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Fire Drill Log: Drills Performed: <u>3</u>	Deficiency Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	139	Clogged drain						X	
2		OK							
3		OK							
5		OK							
6		OK							
7	703		Remove storage						X
8	8133	OK	Remove storage						X
92	390		Emergency light out					X	
92	391	OK							
92	392		Emergency light out					X	
92	393	OK							
92	394	OK							
92	401	OK							
92	402	OK							
92	403	OK							
92	404		Exit door drags					X	
92	405	OK							
92	406		Emergency light out					X	
92	407	OK							
92	408	OK							
92	409		Emergency light out					X	
92	410	OK							

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: LAKESIDE JUNIOR HIGH - 0351
 2750 MOODY AVENUE
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: 
INSPECTION DATE: 11/12/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>	Fire Safety Deficiency	Deficiency Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	21			Emergency light out					X
1	23			Emergency light out					X
2	40			Emergency light out					X
2	48			Emergency light out	X				X
3	59			Emergency light out					X
3	72			Emergency light out					X
3	75			Emergency light out					X
5		OK							
8	819	Remove bar at door and storage							X
9	901			Exit light out					X
9	917			Emergency light out					X
92	701	OK							
92	702	OK							
92	703	OK							
92	704	OK							
92	705	OK							
92	706	OK							
92	707	OK							
92	708	OK							
92	710	OK							
92	721	OK							

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: OAKLEAF JUNIOR HIGH SCHOOL
 4085 PLANTATION OAKS BOULEVARD
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 
INSPECTION DATE: 12/3/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>4</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
1		OK							
2		OK							
3		OK							
4		OK							
5		OK							
92	601		Emergency light out	X					X
92	602	OK							
92	603		Emergency light out	X					X
92	604	OK							
92	605	OK							
92	606	OK							
92	607	OK							
92	608		Emergency light out						X
92	609	OK							
92	610	OK							
92	611		Emergency light out	X					X
92	612	OK							
92	613	OK							
92	614	OK							
92	615	OK							
92	616	OK							
92	617	OK							

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: ORANGE PARK JUNIOR HIGH - 0361
 1500 GANO AVENUE
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: *[Signature]*
INSPECTION DATE: 11/17/2015


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>								
1	128	Lens cover missing						X
1	139A		Remove gas bottle and grill from stairs					X
1	162	Lens cover missing						X
1	181	Bulb & lens cover missing						X
1	190		Remove storage from electric closet					X
2	214	Floor drain strainer missing						X
2	252		Evacuation sheet missing	X				X
3	364		Emergency light out					X
4	417A	Lens cover missing						X
4	417B	Replace ceiling tiles by light						X
4	454		Evacuation sheet missing	X				X
5		OK						
6	625	Roof leak-replace tiles if fixed						X
6	629	Light out						X
92	501	OK						
92	503	OK						
92	504	OK						

92	505		Emergency light out						X
92	506	OK							
92	507	OK							
92	508	OK							
92	509A/B	OK							
92	510		Emergency light out						X
92	511	OK							
92	515	Out of Service							
92	516		Emergency light out						X
92	516	Lens missing							X
92	702	OK							
92	703	OK							
92	704	OK							
92	706	OK							
92	708	OK							
92	710	OK							
92	712	OK							

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: WILKINSON JUNIOR HIGH - 0371
 5025 COUNTY ROAD 218
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 
INSPECTION DATE: 11/30/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2	220		Emergency light out				X	
3		OK						
4	407	Repair strip electrical outlets with strain connectors					X	
4	414	Replace stained ceiling tiles						X
5	510		Emergency light out				X	
6		OK						
7	749	Exhaust hood not working					X	
7	767	Replace fire blanket if used as science room					X	
8	808	Clear hallway						X
8	829		Emergency light out				X	
9	901		Exit and Emergency light out				X	
32		Football concession	Emergency light out				X	
92	2	OK						
92	3	OK						
92	4	OK						
92	5	OK						

Fire Drill Log:
 Drills Performed: 2

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: BANNERMAN LEARNING CENTER - 0111
 608 MILL STREET
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: *[Signature]*
INSPECTION DATE: 11/3/2015


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>						
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1		OK						
2		OK						
3	319	Attach drains to air handlers					X	
3	319	Repair light						X
92	1	OK						
92	2	OK						
92	3	OK						
92	4	OK						
92	5	OK						
92	6	OK						
92	7	OK						
92	8		Emergency light out				X	
92	9	OK						
92	10	OK						
92	11	OK						
92	12	OK						
92	13	OK						
92	14	OK						
92	30	OK						
92	31	OK						
92	32	OK						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND

FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: CLAY HIGH SCHOOL - 0341
 2025 HIGHWAY 16 WEST
 GREEN COVE SPRINGS, FL 32043

INSPECTOR SIGNATURE: 

INSPECTION DATE: 10/15/2015

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>								
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School		
1	111		Emergency light out					X		
1	116	Ceiling in shower needs to be cleaned and repainted w/mold resistant paint						X		
2	207	Hood not cleaned		X			X			
2	208		Emergency evacuation sheet missing					X		
	228		Emergency evacuation sheet missing					X		
3	383		Emergency light out					X		
4	402	Light lens cover missing						X		
4	407	Light lens cover missing						X		
4	410	Light lens cover missing						X		
5		OK								
6		OK								
7		OK								
8		OK								
9		OK								
11	1119	Outlet cover missing						X		
11	1104	Wood risers being built-not complete						X		

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: FLEMING ISLAND HIGH SCHOOL - 0551
 2233 VILLAGE SQUARE PARKWAY
 FLEMING ISLAND, FL 32003

INSPECTOR SIGNATURE:

INSPECTION DATE: October 16, 2015


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>1</u>								
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School		
1	81	Exit light out					X			
1	44	Leak from 2nd floor					X			
1	173	Lens cover missing on light						X		
92	10	OK								
92	11	OK								
92	12		Excessive combustables on walls and ceiling. Remove secondary projector from ceiling	X				X		
92	13	OK								
92	14		Emergency light out					X		
92	15	OK								
92	20		Emergency light out					X		
92	21	OK								
92	22	OK								
92	23	OK								
92	24	OK								
92	25	OK								
92	27	OK								
92	30	OK								
92	31	OK								
92	32	OK								

92	93	OK								
92	94	OK								
92	95		Emergency light out							X
92	96		Excessive combustibles on walls and ceiling							X
92	97	OK								

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: KEYSTONE HEIGHTS HIGH SCHOOL - 0311
 900 S.W. ORCHID AVENUE
 KEYSTONE HEIGHTS, FL 32656

INSPECTOR SIGNATURE: 
INSPECTION DATE: October 20, 2015

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: _____						
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	109	Replace ceiling tiles by Room 110						X
2		OK						
4	412		Emergency evacuation sheet missing					X
5	538	Very hot - check exhaust fan						X
6	606		Emergency evacuation sheet missing					X
7		OK						
8		OK						
9		OK						
18	17		Emergency evacuation sheet missing					X
20		OK						
35			Remove propane bottles from concession. Move appliance from top of transformer.					X
92	1	OK						
92	2		Emergency light out					X
92	4	OK						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: MIDDLEBURG HIGH SCHOOL - 0391
 3750 COUNTY ROAD 220
 MIDDLEBURG, FL 32068

INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/29/2015

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>											
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School					
1	51		Emergency light out				X						
1	51		Tamper switch on fire sprinkler				X						
1	144	Exit light on switch					X						
1	212	Cover missing on water fountain					X						
1	221	Outlet covers missing					X						
9	1		Refrigerator blocking panel									X	
10	1	Remove extension cord from ceiling											X
92	1	OK											
92	5	OK											
92	31		Emergency light out				X						
92	32	OK											
92	33	OK											
92	34	OK											
92	35	OK											
92	36	OK											
92	41	OK											
92	42	OK											
92	43	OK											

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: OAKLEAF HIGH SCHOOL - 0661
 4035 PLANTATION OAKS BOULEVARD
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/22/2015


Fire Drill Log: ✓
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	252	Sink broken					X	
1	328	Evacuation sheet missing						X
1	538C		Excessive combustibles on walls					X
6	601		Gas powered equipment inside				X	
7	703		Propane tanks stored inside	X				X
7	704		Fire alarm panel not current				X	
92	10	OK						
92	11	OK						
92	15	OK						
92	16	OK						
92	20	OK						
92	21	OK						
92	22	OK						
92	23	OK						
92	24	OK						
92	25	OK						
92	26	OK						
92	30	OK						

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: ORANGE PARK HIGH SCHOOL - 0252
 2300 KINGSLEY AVENUE
 ORANGE PARK, FL 32073

INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/30/2015

Fire Drill Log:
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	near 155		Exit light out					X
1	116B	Electrical outlet cover missing						X
1	130		Evacuation sheet missing				X	X
1	181A	Roof leak						
1	216	2x2 lights not working. Cannot get bulbs, may need to replace w/2x4's.					X	
1	226		Evacuation sheet missing					X
1	209	Remove paper decoration from hallway-Halloween						X
1		Elevator missing certification						X
2	2		Exit light out					X
3		OK						
4		OK						
10	122	Door very hard to open-Fire sprinkler room					X	
12	137	Lenze cover missing						X
12	152	Broken glass in door					X	

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: RIDGEVIEW HIGH SCHOOL 0431
 466 MADISON AVENUE
 ORANGE PARK, FL 32065

INSPECTOR SIGNATURE: 

INSPECTION DATE: 11/16/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>2</u>	Fire Safety Deficiency	Deficiency Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
1	102			Exit light out				X	
1	102A			Fire alarm trouble				X	
1	135	Replace stained ceiling tile							X
1	149			Exit light out				X	
2	201	Broken floor tile						X	
2	218	Newspaper stored in electric room							X
2	234	Floor chemicals stored in electric room							X
3	301			Exit light out				X	
5	553			Exit light out				X	
6		OK							
7		OK							
8				Remove bar on exit doors while school is in session					X
9	903	Outlet cover missing							X
9	904			Emergency light out				X	
9	910			Emergency light gone				X	
9	930			Exit lights broken				X	
9	941			Exit lights broken				X	
10	4			No evacuation sheet					X

10	37		Exit light out						X	
11	GEN		No room numbers						X	
11	1102		Emergency light out						X	
11	1105		Equipment stored in electric room							X
12	1203	Outlet cover broken								X
13		OK								
15		OK								
92	1	OK								
92	2	OK								
92	3	OK								
92	4	OK								
92	5	OK								
92	6	OK								
92	7	OK								
92	8	OK								
92	9		Emergency light out						X	
92	10	OK								
92	11		Emergency light out						X	
92	12	OK								
92	21		Emergency light out						X	
92	22		Excessive combustables							X
92	23	OK								
92	24	OK								
92	25		Emergency light out			X				
92	26	OK							X	
92	27	OK								
92	28	OK								
92	29	OK								
92	30		Emergency light out			X				X
92	31	OK								
92	32		Emergency light out						X	
92	33	OK								
92	34		Emergency light out						X	
92	41		Emergency light out			X				X
92	42	OK								
92	43	OK								

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: ORANGE PARK ANNEX (FACILITY #0034)
 2300 KINGSLEY AVENUE
 ORANGE PARK, FL 32073


INSPECTOR SIGNATURE: 
INSPECTION DATE: 10/30/2015

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>		Deficiency Not Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
			Fire Safety Deficiency						
16		OK							
17		OK							
18	All Rooms		Maintain clear space at emergency window escape						X
19	All Rooms		Maintain clear space at emergency window escape						X
20	All Rooms		Maintain clear space at emergency window escape						X
21	All Rooms		Maintain clear space at emergency window escape						X

COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5

CASUALTY SAFETY & SANITATION INSPECTION
F.S. 1013.12, 1013.20 & NFPA 101
AND
FIRE SAFETY INSPECTION REPORT
F.S. 1013.12, 1013.20 & RULE 69A-58

FISCAL YEAR: 2015/2016
DISTRICT: CLAY
FACILITY: ANCILLARY BUILDINGS

INSPECTOR SIGNATURE: 

INSPECTION DATE: 3/1/2016

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>N/A</u>	Fire Safety Deficiency	Deficiency Corrected from Previous Inspection	Facilities	Information Services	Maintenance	School
School District Main Office:									
2		OK							
3	7			Emergency light out				X	
3	30	Lens cover missing			X			X	
3	62			Emergency light out				X	
		City Electric Company needs to fix "guy wire" at sidewalk near corner of Walnut and Roderigo Avenue							
IS Portable									
95	1	OK							
95	2	OK							
Support Services:									
1	32	Replace handrail (ext. stairs)						X	
2	34	Stairs not to code							
4		OK							
4		OK							

5	14	Repaint "Yellow" warning lines on floor							
6		OK							
9		OK							
10		OK							
11		OK							
12	206		Emergency light out					X	
95	12	OK							
Green Cove Transportation:									
1		OK							
95	3	OK							
Middleburg Transportation:									
1		OK							
3	2		Emergency light out						X
3	6		Emergency light out						X
8			Emergency light out - 2nd floor						X
95	201	OK							
95	402		Emergency light out						X
95	403		Emergency light out						X
95	501	OK							
95	502	OK							
95	503	OK							
95	504	OK							
Keystone Heights Transportation:									
95	1	OK							
95	2	OK							
H. C. Long:									
1	100		Emergency light out				X		
2		OK							
3		OK							
4	404A	Floor has several loose areas	Add Emergency light				X		X

4	413		Replace exit light						X	
4	415	Replace ceiling tile by back door								X
5		OK								