
Amistrie Cir

OMB LANGES





COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT:_	CLAY FACILITY#: 0034	
EACH ITV:	ADMINISTRATIVE OFFICE ORANGE DARK ANNEX	,

FACILITY: ADMINISTRATIVE OFFICE ORANGE PARK ANNEX
2300 KINGSLEY AVENUE
ORANGE PARK, FLORIDA 32073

INSPECTION DATE: OCTOBER 30, 2008


INSPECTOR'S SIGNATURE


NATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint, "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
16	11	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
17	9	CEILING TILES MISSING		Х						
						for William				
en de la propieta de la composición de La composición de la composición de la La composición de la										
		·								

ADMINISTRATIVE OFFICES ORANGE PARK ANNEX 2008-09 SREF INSPECTION

Siperintents Office





COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY #: 0036
	FACILITY: CLAY SUPERINTENDENT'S OFFICE
	900 WALNUT AVENUE GREEN COVE SPRINGS, FLORIDA 32043
1	INSPECTION DATE: FEBRUARY 2, 2009
,	Xunt 2.2.08

DATE

Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
*	OK								
7	EMERGENCY LIGHT OUT		Х						FBC 423.17.1
7A	CLEAR PATH TO EXIT		Х						
48	BULB WITH NO PROTECTION / GLOBE MISSING		X						NFPA 70
	. 7 7A	Required: OK THE EMERGENCY LIGHT OUT TA CLEAR PATH TO EXIT	Required: "M" OK THE EMERGENCY LIGHT OUT TA CLEAR PATH TO EXIT	Required: "M" "O" . OK X 7 EMERGENCY LIGHT OUT X 7A CLEAR PATH TO EXIT X	OK X 7 EMERGENCY LIGHT OUT X 7A CLEAR PATH TO EXIT X	Room Required: "M" Oper. "C" Serv. "I.S." OK THEREGENCY LIGHT OUT TA CLEAR PATH TO EXIT Required: "M" Oper. "C" Serv. "I.S."	Room Required: "M" Oper Cost Serv. Cost Maint. Oper Cost Cost Maint. Oper Cost Cost Cost Cost Cost Cost Cost Cost	Room Deficiency Description and Corrective Action Required: Maint. "M" Oper. "C" Fac. "C" Intro. Serv. "I.S." Cost Def. Cited . OK X X X 7 EMERGENCY LIGHT OUT X X X 7A CLEAR PATH TO EXIT X X X	Room Deficiency Description and Corrective Action Required: Maint. "M" Oper. "C" Fac. "C" Into. Serv. "I.S." Cost Def. Cited Scheduled for Correction . OK X




COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH

F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY #: 0037
	FACILITY: FOOD SERVICE STORAGE
	720 CENTER STREET GREEN COVE SPRINGS, FLORIDA 32043
9	INSPECTION DATE: FEBRUARY 9, 2009
7	3-9.03

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
95	1	OK			. As in table of the control of the	A GATACLE AND		The Control of the Co		

RODA DEDICES





COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

*****	DISTRICT: CLAY FACILITY #: 0037
	FACILITY: FOOD SERVICE STORAGE
	720 CENTER STREET GREEN COVE SPRINGS, FLORIDA 32043
	INODECTION DATE. FEDDUADVO 2000
,	INSPECTION DATE: FEBRUARY 9, 2009
	INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
95	1	ок								



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

	DISTRICT: CLAY FACILITY #: 0027
	FACILITY: HARRIS C. LONG ADMINISTRATION
١	23 SOUTH GREEN STREET
l	GREEN COVE SPRINGS, FLORIDA 32043
ı	

INSPECTION DATE: FEBRUARY 9, 2009

INSPECTOR'S SIGNATURE

5-9-09 DATE

No. of Info. Scheduled **Deficiency Description and Corrective Action** Fac. times Rule Maint. Oper. Serv. Cost Building Room for Required: "M" "O" Def. "I.S." Correction Cited FBC 423.17.1 1 100 **BOTH EMERGENCY LIGHTS OUT** Х STORAGE IN RESTROOM (MAINTAIN 36" WIDE PATH) Χ 1 127 OK 2 Х FBC 423.17.1 BOTH EMERGENCY LIGHT OUT 3 300 NFPA 70 **OUTLET COVER MISSING** Х 3 309 4

TESTOR TESTS





COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101


DISTRICT: CLAY FACILITY #. 0037
FACILITY: KEYSTONE HEIGHTS TRANSPORTATION
6800 COUNTY ROAD 315
KEYSTONE HEIGHTS, FLORIDA 32656
INSPECTION DATE: FEBRUARY 13, 2009

NSPECTOR'S SIGNATURE

2-13-08

No. of Info. Scheduled **Deficiency Description and Corrective Action** Fac. times Rule Maint. Oper. Serv. Cost Building Room for "C" Required: "M" "O" Def. "I.S." Correction Cited 802 OK





COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

EACH ITV.	******	DUDG TDA	NODODI	- 4 - 1 - 0 - 1		
DISTRICT:	CLAY	FA	CILITY#	t: <u>00</u>	33	

FACILITY: MIDDLEBURG TRANSPORTATION
3674 COUNTY ROAD 220

MIDDLEBURG, FLORIDA 32068

INSPECTION DATE: FEBRUARY 16, 2009

INSPECTOR'S SIGNATURE

5-16-09

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	102	EXTERIOR WALL AT CORNER HAS WATER DAMAGE WATCH MAY BE LEAKY DOWNSPOUT		х						
- 2		OK								
11		ОК								
. 15		OK								
	1 .			l				1	l	l
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70
3	4	ELECTRIC PANEL MISSING KNOCKOUTS	X							NFPA 70

MIDDLEBURG TRANSPORTATION 2008-09 SREF INSPECTION

CAROOL IBAS

FISCAL YEAR <u>2008-2009</u>



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY#: 0030
FACILITY: SCHOOL BUS GARAGE – TRANSPORTATION
800 CENTER STREET
GREEN COVE SPRINGS, FLORIDA 32043
INSPECTION DATE: FEBRUARY 9, 2009

TØR'S SIGNATURE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "Č	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	8	CEILING TILES STAINED / REPLACE		Х						
1	200	EMERGENCY LIGHT OUT		X						FBC 423.17.1
				East S						
						71				



COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

DISTRICT: CLAY FACILITY #: 0030
FACILITY: SCHOOL BUS GARAGE – TRANSPORTATION
800 CENTER STREET
GREEN COVE SPRINGS, FLORIDA 32043


INSPECTION DATE: FEBRUARY 9, 2009

INSPECTOR'S SIGNATURE

DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv: "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
92	3	TWO LIGHTS OUT		Х						FBC 423.17.1
95	2	OΚ								
							70 7 3 3 3			
					- N. 21 - N 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	a de la companya de				

Supple Seves ACC CA





COMPREHENSIVE SAFETY & SANITATION
INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5
"CASUALTY SAFETY & SANITATION INSPECTION"
IN COMPLIANCE WITH
F.S. 1013.12, 1013.20 & NFPA 101

ואוניו	FAUILIT	7. 0020	


FACILITY: SUPPORT SERVICES AG LOT
ROBERTS STREET
GREEN COVE SPRINGS, FLORIDA 32043


INSPECTION	DATE:	FEBRUARY 6, 2009
		· mortoristi oj modo

INSPECTOR'S SIGNATURE DATE

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper. "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
90	1	ОК							<u> </u>	
95	2	NOT OCCUPIED								
95	3	NOT OCCUPIED								
95	4	NOT OCCUPIED								
95	5	NOT OCCUPIED				:				
95	6	NOT OCCUPIED								

OUDOIL OEDS





COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5 "CASUALTY SAFETY & SANITATION INSPECTION" IN COMPLIANCE WITH F.S. 1013.12, 1013.20 & NFPA 101

Participation of the court of the con-	
- 4 OH 1737	OUDDODT OFDWOED OFNIED
FACILITY:	SUPPORT SERVICES CENTER
	925 WEST CENTER STREET
	925 WEST CENTER STREET
	GREEN COVE SPRINGS, FLORIDA 32043
l	CITELIA COAL CI ITHACO, I LOITIDA CECTO

FACILITY #:

INSPECTION DATE: FEBRUARY 6, 2009

INSPECTOR'S SIGNATURE

DISTRICT: CLAY

2-6.09

Building	Room	Deficiency Description and Corrective Action Required:	Maint. "M"	Oper: "O"	Fac. "C"	Info. Serv. "I.S."	Cost	No. of times Def. Cited	Scheduled for Correction	Rule
1	*	NO HANDICAPPED PARKING SPACE		Х						FBC
1	20	NO BULB PROTECTION		×						
1	32	EXIT STAIRS REPLACE HANDRAILS / SOME STEPS	Х							
1	4C	EXIT LIGHT BULBS OUT		X						FBC 1006.3.1
1	11A	EMERGENCY LIGHT WEAK		Х						FBC 432.17.1
2		OK								
4		ок								
5	* .									
6		ок								
9		OK								
10		ОК								
11		ÓK					A/2001			
12		ОК								