

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** GREEN COVE SPRINGS JUNIOR HIGH - 0021  
 1220 BONAVENTURE AVENUE  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 4, 2014

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>							
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School		
1	11	Knockouts missing pan-duit. Electrical covers required.				X			
3	31		Emergency evacuation sheet missing				X		
3	106	Restroom out of order					X		
5	501		Maximum occupancy sign not posted. Max occupancy 800.					X	
8	820	Ceiling grid rusty - repair/replace.				X			
9	908		Remove rack from exit corridor					X	
9	901	Foyer floor tile missing - north side.				X			
92	70		OK						
92	71		OK						
92	74		OK						
92	75		Emergency light out					X	
92	76		OK						
92	103		OK						
92	104		OK						
92	105		OK						





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** LAKE ASBURY JUNIOR HIGH - 0481  
 2851 SANDRIDGE ROAD  
 GREEN COVE SPRINGS, FL 32043

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 6, 2014


Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	390	OK					
92	391	OK					
92	392	OK					
92	393	OK					
92	394	OK					
92	401	OK					
92	402	OK					
92	403	OK					
92	404		Stair door drags			X	
92	405	OK					
92	406	OK					
92	407	OK					
92	408		Emergency light out			X	
92	409	OK					
92	410	OK					
92	421		Emergency light out			X	
92	422	OK					
92	423	OK					
92	425	OK					
92	427	OK					
92	428	OK					
92	430		Emergency light out			X	

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** LAKESIDE JUNIOR HIGH -0351  
 2750 MOODY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** November 14, 2014

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		OK					
2	46	Replace stained tile					X
2	48		Emergency light out			X	
3	72	Patch wall and vinyl base				X	
5	138	Patch wall by urinal				X	
92	701	OK					
	702	OK					
	703	OK					
	704	OK					
	705	OK					
	706	OK					
	707	OK					
	708	OK					
	710	OK					
	721	OK					
	722	OK					
	723	OK					
	731		Broken lens cover			X	
	732	OK					
	733	OK					
	734		Covers missing on lights				X
	735	OK					
	737	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND


**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58

**FISCAL YEAR:** 2014/2015

**DISTRICT:** CLAY

**FACILITY:** OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** November 13, 2014

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	229	Fire sprinkler red tag, FDC sign missing				X	
5	521	Fire sprinkler red tag, FDC sign missing				X	
92	601		Emergency light out			X	
92	602	OK					
92	603	OK					
92	604	OK					
92	605	OK					
92	606	OK					
92	607		Emergency light out			X	
92	608	OK					
92	609	OK					
92	610	OK					
92	611		Emergency light out			X	
92	612	OK					
92	613	OK					
92	614	OK					
92	615	OK					
92	616	OK					
92	617	OK					
92	618	OK					
92	619	OK					
92	620	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF JUNIOR HIGH SCHOOL  
 4085 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** November 13, 2014

Fire Drill Log:    
 Drills Performed: 3


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	622	OK					
92	701	OK					
92	702	OK					
92	703	OK					
92	704	OK					
92	705	OK					
92	706	OK					
92	707	OK					
92	708	OK					
92	709	OK					
92	710	OK					
92	711		Emergency light out			X	
92	712		Emergency light out			X	
92	713	OK					
92	714	OK					
92	715	OK					
92	716	OK					
92	801	OK					
92	802	OK					
92	802	OK					
92	807	Floor not screwed down by entry at stairs					X
92	808	OK					
92	810	OK					





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK JUNIOR HIGH - 0361  
 1500 GANO AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** December 2, 2014


Fire Drill Log:    
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	OK						
2		All view panels into classrooms are covered. Need to leave small area to see in or out.					X
2	206		No emergency evacuation sheet				X
2	252		No emergency evacuation sheet				X
3		All view panels into classrooms are covered. Need to leave small area to see in or out.					X
4		All view panels into classrooms are covered. Need to leave small area to see in or out.					X
4	408		No emergency evacuation sheet				X
4	454		No emergency evacuation sheet				X
5	OK						

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK JUNIOR HIGH - 0361  
 1500 GANO AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** December 2, 2014

Fire Drill Log:   
 Drills Performed: 4

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
6	604	2 cracked outlet covers. Double doors need adjustment to lock properly. Cannot use metal across the doors to hold shut.					X
92	501	OK					
92	503	OK					
92	504	OK					
92	505	OK					
92	506	OK					
92	507	OK					
92	508	OK					
92	509	OK					
92	510	OK					
92	511	OK					
92	515	OK					
92	516		Emergency light out			X	
92	702	OK					
92	703	OK					
92	704	OK					
92	708		Emergency light out			X	
92	710	OK					
92	712	OK					









**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30245

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 7, 2014


		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>4</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	118		Install exit light @ rear door			X	
2	207		Hood not cleaned				X
3A		OK					
3B	315		Move file cabinet by door				X
3C		OK					
3D	396	Emergency light out				X	
4		OK					
5	510B		Install exit light at door				
6		OK					
7A		OK					
7B		OK					
8	835		Red tag on gauges (Sprinkler)			X	
8	842	Paint peeling on walls				X	
9	903	Urinal out of order				X	
11	110B		Drums blocking exit				X
29		OK					
30		OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** CLAY HIGH SCHOOL - 0341  
 2025 HIGHWAY 16 WEST  
 GREEN COVE SPRINGS, FL 30243

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 7, 2014

Fire Drill Log:   
 Drills Performed: 4


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
35		OK					
44		OK					
45		OK					
46		OK					
47		OK					
48		OK					
49		OK					
54		OK					
56		OK					
5		OK					
7		OK					
8		OK					
17		OK					
18		OK					
19		OK					
20		OK					
31		OK					
32		OK					
33		OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 


**INSPECTION DATE:** October 9, 2014

Fire Drill Log:   
 Drills Performed: 1

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	44	Leak stained ceiling tile and damaged light				X	
1	176	Fire sprinkler riser 2 red tags				X	
1	237	Lense cover and bulbs missing					X
1	253	Stained ceiling tiles					X
1	268	Rooms very warm - AC issue					X
1	303	No emergency evacuation sheet					X
2	220	Fie sprinkler riser 2 red tags					X
2	207	Replace ceiling tiles - stained					X
2	205	Replace ceiling tiles - adjust sprinkler so that it is below ceiling				X	
2	227	Replace ceiling tiles					X
2	228	Replace ceiling tiles					X
2	218	Patch holes in wall from switch repair				X	
2	253		Remove all storage from electrical room				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 9, 2014

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>1</u>							
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School		
2	267		Remove all storage from electrical room - no flammables allowed!!!				X		
10	1002	Replace stained ceiling tiles					X		
92	10		Move refrigerator from in front of electrical panel				X		
92	11	OK							
92	12		Excessive combustibles on walls and ceiling. Remove second projector from ceiling.				X		
92	13	OK							
92	14	OK							
92	15	OK							
92	20	OK							
92	22	OK							
92	23	OK							
92	24	OK							
92	27	OK							
92	30	OK							
92	31	OK							
92	32	OK							

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:** *[Signature]*

**INSPECTION DATE:** October 9, 2014

Fire Drill Log:   
 Drills Performed: 1

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	33	OK					
92	34	OK					
92	42	OK					
92	43	OK					
92	44	OK					
92	45	OK					
92	46	OK					
92	49	OK					
92	21	Replace broken switch plate at rear door					X
92	25	Smoke detector hanging from ceiling					X
92	35		Emergency light not working				X
92	40		Emergency light not working				X
92	41		Emergency light not working				X
92	47		Emergency light not working				X
92	48		Emergency light not working				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** FLEMING ISLAND HIGH SCHOOL - 0551  
 2233 VILLAGE SQUARE PARKWAY  
 FLEMING ISLAND, FL 32003

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 9, 2014

Fire Drill Log:   
 Drills Performed: 1


Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	50		Emergency light not working				X
92	51		Emergency light not working				X
92	52		Emergency light not working				X
92	53		Emergency light not working				X
92	60		Emergency light not working				X
92	61	Replace AC filter					X
92	62	OK					
92	64	OK					
92	70	OK					
92	71	OK					
92	72	OK					
92	73	OK					
92	80	OK					
92	81	OK					
92	82	OK					
92	85	OK					
92	86	OK					
92	90	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 14, 2014

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		OK					
2		OK					
4	411		No evacuation sheet				X
5		OK					
6	611B	Replace water heater thermostat				X	
7	Exterior	Erosion at walkways				X	
8		OK					
18		OK					
20	17		Move equipment by exit storage. Broken outlet				X
35							X
92	1	OK					
92	2	OK					
92	4		Emergency light out			X	
92	6	OK					
92	8		Emergency light out			X	
92	9	OK					
92	10	OK					
92	11		Cabinets blocking electric panel				X
92	12	OK					
92	13	OK					




**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015

**DISTRICT:** CLAY

**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 14, 2014

Fire Drill Log:    
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	14		Door at stair drags			X	
92	15	OK					
92	16	OK					
92	17	OK					
92	18	OK					
92	19		Emergency light out			X	
92	20		Storage cabinet blocking electric panel				X
92	21		Emergency light out			X	
92	22	OK					
92	23	OK					
92	24		Stair door sticks			X	
92	25	OK					
92	26		Switch cover missing by panel				X
92	27	OK					
92	28	Replace wood stair and ramp				X	
92	29	Stained ceiling				X	
92	50	OK					
92	51	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** KEYSTONE HEIGHTS HIGH SCHOOL - 0311  
 900 S. ORCHID AVENUE  
 KEYSTONE HEIGHTS, FL 32656

**INSPECTOR SIGNATURE:** *[Signature]*  
**INSPECTION DATE:** October 14, 2014

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	52	OK					
92	53	OK					
92	54	OK					
92	55	OK					
92	56	OK					
92	57	OK					
92	58		Emergency light out			X	
92	59	OK					
92	60	OK					
92	61	OK					
92	62	Replace wood ramp				X	
92	63	OK					
92	64	OK					
92	65	OK					
92	72	OK					
92	74	OK					
92	76	OK					
92	78	OK					
92	80	OK					
92	82	OK					
92	84	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 16, 2014

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>1</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	51		Excessive storage around fire sprinkler - remove				X
1	51		2 red tag on fire sprinkler riser - 5 year gauge			X	
1	119		Emergency evacuation sheet missing				X
1	122	Ceiling tile miss placed					X
1	154		Remove paper from doorway - all				X
1	148	Occupancy load sign missing - maximum 150					X
1	260		2 red tags fire sprinkler riser			X	
1	263		Emergency evacuation sheet missing				X
1	250	Repair roof leak - replace ceiling tiles					X
1	253	Repair roof leak - replace ceiling tiles					X
1	227	Lock not working				X	
1	196		2 red tag on fire sprinkler riser			X	
1	215	Storage too high - lower 18" from ceiling					X


**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**

**AND**

**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 16, 2014

Fire Drill Log:   
 Drills Performed: 1

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	297	Cloths was machine backs up into shower				X	
9	1		Move shelf from in front of electrical panel				X
92	1	OK					
92	5	OK					
92	7	OK					
92	9	OK					
92	31	OK					
92	32	OK					
92	33	OK					
92	34	OK					
92	35	OK					
92	36	OK					
92	41	OK					
92	42	OK					
92	43	OK					
92	44	OK					
92	45	OK					
92	46	OK					
92	51	OK					
92	52	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** MIDDLEBURG HIGH SCHOOL - 0391  
 3750 COUNTY ROAD 220  
 MIDDLEBURG, FL 32068

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 16, 2014


Fire Drill Log:    
 Drills Performed: 1

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	54 A&B	OK					
92	55	OK					
92	60	OK					
92	61	OK					
92	62	OK					
92	63	OK					
92	64	OK					
92	65	OK					
92	66	OK					
92	67	OK					
92	69	OK					
92	70	OK					
92	71	OK					
92	72	OK					
92	73	OK					
92	74	OK					
92	75	OK					
92	76	OK					
92	77	OK					
92	78	OK					
92	79	OK					
92	80	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**  
  
**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** OAKLEAF HIGH SCHOOL - 0661  
 4035 PLANTATION OAKS BOULEVARD  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 21, 2014

Fire Drill Log:    
 Drills Performed: 1

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1		OK					
4		OK					
6	601		Remove stored materials				X
6	603		Red tags on fire sprinkler			X	
7	703		Remove propane tanks				X
11	1101		Remove oil, etc. from transformer room				X
92	10	OK					
92	11	OK					
92	15	OK					
92	16	OK					
92	20	OK					
92	21	OK					
92	22	OK					
92	23	OK					
92	24	OK					
92	25	OK					
92	26	OK					
92	30	OK					
92	31	OK					
92	32	OK					





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**

F.S. 1013.12, 1013.20 & NFPA 101

AND

**FIRE SAFETY INSPECTION REPORT**

F.S. 1013.12, 1013.20 & RULE 69A-58


**FISCAL YEAR:** 2014/2015

**DISTRICT:** CLAY

**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252

2300 KINGSLEY AVENUE

ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 23, 2014

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	107		Emergency evacuation sheet missing				X
1	120		Emergency evacuation sheet missing				X
1	121		Emergency evacuation sheet missing				X
1	205		Emergency evacuation sheet missing				X
1	206		Emergency evacuation sheet missing				X
1	224		Emergency evacuation sheet missing				X
1	230		Emergency evacuation sheet missing				X
1	222		Emergency evacuation sheet missing				X
1	100		Exit light out by entrance to cafeteria				X
1	181		Emergency light out				X
1	217		Emergency light out				X
1	219		Emergency light out				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 23, 2014

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	220		Emergency light out				X
1	201		Remove paper from door and entry space				X
1	203		Remove paper from door and entry space				X
1	224	Replace stained ceiling tiles					X
1	231	Replace stained ceiling tiles					X
1	166	Move cabinet from in front of electrical panel					X
1	253	Move cabinet from in front of electrical panel					X
2	1.9		Emergency light out				X
4	1		Emergency light out				X
10	122		2 red tags fire sprinkler riser			X	
10	115		Emergency light out				X
10	112		Emergency light out				X
24		OK					
25		OK					
22		OK					
27		OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 23, 2014

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
51			No emergency evacuation sheet				X
51	8	Electrical outlet pulled out of wall					X
51	13	Light switch knockouts missing					X
51	12	Cover plate missing outlet S.W. corner					X
51	2	Fire alarm not certified since July 2013				X	
12	102		No emergency evacuation sheet				X
12	116		No emergency evacuation sheet				X
12	110		No emergency evacuation sheet				X
12	135		No emergency evacuation sheet				X
12	134		No emergency evacuation sheet				X
12	140		No emergency evacuation sheet				X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 23, 2014

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
12	139		No emergency evacuation sheet				X
12	141		No emergency evacuation sheet				X
12	157		No emergency evacuation sheet				X
12	161		No emergency evacuation sheet				X
12	110		Emergency exit sign missing				X
12	115		Emergency exit sign missing				X
12	101	By 106 and 164 by 134 - replace stained ceiling tiles					X
12	161C		Materials blocking electrical panel				X
12	161A	Cover missing lights - Stain relief connection missing outlet strip				X	
48		Remove gas bottles from concession					X

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 23, 2014


Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	13A&B		No emergency evacuation sheet				X
92	35		No emergency evacuation sheet				X
92	36		No emergency evacuation sheet				X
92	37		No emergency evacuation sheet				X
92	38		No emergency evacuation sheet				X
92	39		No emergency evacuation sheet				X
92	40		No emergency evacuation sheet				X
92	48		No emergency evacuation sheet				X
92	53		No emergency evacuation sheet				X
92	54		No emergency evacuation sheet				X
92	60		No emergency evacuation sheet				X
92	45	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ORANGE PARK HIGH SCHOOL - 0252  
 2300 KINGSLEY AVENUE  
 ORANGE PARK, FL 32073

**INSPECTOR SIGNATURE:** 

**INSPECTION DATE:** October 23, 2014

Fire Drill Log:   
 Drills Performed: 2

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	49	OK					
92	50	OK					
92	52	OK					
92	55	OK					
92	56	OK					
92	58	OK					
92	62	OK					
92	64	OK					
92	65	OK					
92	66	OK					
92	67	OK					
92	51		Remove excessive combustibles on walls. No emergency evacuation sheet.				X
92	59		Remove excessive combustibles on walls. No emergency evacuation sheet.				X
92	61	Data cord run across floor - trip hazard.					X





**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 28, 2014

		Fire Drill Log: <input checked="" type="checkbox"/> Drills Performed: <u>3</u>					
Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
1	102		Exit light out			X	
2		OK					
3	346		Rescue window blocked				X
3	346		Turn off power to stove				X
5	501		Exit blocked - remove decorations				X
6	633		Excessive combustibles in hall				X
7	710	Remove extension cord - add outlet				X	
8		OK					
9	908	Door drags				X	
9	910	Replace air grills				X	
9	941		Exit light out			X	
10	12	Remove desk					X
10	35		Exit light out			X	
12			Boys room: emergency light out			X	
13			Girls room: emergency light out			X	
92	1	OK					
92	2	OK					
92	3	OK					
92	4	OK					

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 28, 2014

Building		Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	92	25		Emergency light out			X	
92	92	26		No evacuation sheet				X
92	92	27	OK					
92	92	28	OK					
92	92	29	OK					
92	92	30		Emergency light out			X	
92	92	31	OK					
92	92	32	OK					
92	92	33	OK					
92	92	34	OK					
92	92	41		Emergency light out			X	
92	92	42	OK					
92	92	43	OK					
92	92	44	OK					
92	92	45	OK					
92	92	46	OK					
92	92	47		Emergency light out			X	
92	92	48	OK					
92	92	49	OK					
92	92	50	OK					
92	92	51	OK					
92	92	52	OK					
92	92	53		Electric panel blocked				
92	92	54		Emergency light out			X	X

Fire Drill Log:   
 Drills Performed: 3

**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** RIDGEVIEW HIGH SCHOOL - 0431  
 466 MADISON AVENUE  
 ORANGE PARK, FL 32065

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** October 28, 2014

Fire Drill Log:   
 Drills Performed: 3

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
92	61	OK					
92	62	OK					
92	64	OK					
92	65	OK					
92	66	Wood splinters on handrail				X	
92	67	OK					
92	68	OK					
92	69	OK					
92	70	OK					
92	71	OK					
92	72	OK					
92	73		Emergency light out			X	
92	81	OK					
92	82	OK					
92	83	OK					
92	84		Emergency light out			X	
92	85	OK					
92	86	OK					
92	87	OK					
92	88	OK					
92	89	OK					
92	90	OK					
92	91	OK					



**COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT**  
**STATE BOARD OF EDUCATION**  
**ADMINISTRATIVE RULES S.R.E.F. - CHAPTER 5**

**CASUALTY SAFETY & SANITATION INSPECTION**  
**F.S. 1013.12, 1013.20 & NFPA 101**  
**AND**  
**FIRE SAFETY INSPECTION REPORT**  
**F.S. 1013.12, 1013.20 & RULE 69A-58**

**FISCAL YEAR:** 2014/2015  
**DISTRICT:** CLAY  
**FACILITY:** ANCILLARY BUILDINGS

**INSPECTOR SIGNATURE:**   
**INSPECTION DATE:** March 4, 2014

Building	Room	Casualty Safety & Sanitation Deficiency	Fire Safety Deficiency	Facilities	Information Services	Maintenance	School
<b>School District Main Office:</b>							
3	30	Lense cover missing					X
3	48	Landing for exit needs repair				X	
2		OK					
95	1, 2	OK					
<b>Support Services:</b>							
1	20	Repair flo lights or remove - under shelf				X	
1	2	OK					
4	2		Emergency light out over electric panel				X
5	31B	Outlet cover missing on floor by stairs					X
5	35		Emergency light out rear of room				X
6	1, 2		Emergency light out - both rooms				X
9		OK					
10		OK					
11		OK					
12		OK					
95	12	OK					

Fire Drill Log: N/A  
 Drills Performed: \_\_\_\_\_









