92	92	92	92	92	92	92	92	92	92	92	92	92	92	ဝ	5	4	4	သ	2	1	Building		СОМР
805	804	802	802	801	714	713	711	706	705	704	703	702	701	611		433	408				Room		ADMI
CR	CR.	CR		OK		OK		OK			OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58							
					Emergency light out									Evacuation sheet missing		Evacuation sheet missing	Evacuation sheet missing				Fire Safety Deficiency	Fire Drill Log: \(\square\) Drills Performed: \(4 \)	N INSPECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																					Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR
																					Information Services		RICT: CLAY ILITY: ARGYLE ELEMENTARY SCHOO 2625 SPENCER PLANTATION BOOK ORANGE PARK, FL 32673 INSPECTOR SIGNATURE: ALAM HINSPECTION DATE: December 1,
					×																Maintenance		INTARY SCHOO PLANTATION B FL 32073 Qualification
												×		×		×	×				School		OULEVARD

						92	92	92	92	92	92	92	92	92	Building		СОМР
						906	905	904	903	902	901	808	807	806	Room		REHEN
							OK	OK	OK		Ceiling tile out of grid	OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
						Emergency light out									Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:4	N INSPECTION REPORT CATION F CHAPTER 5 ON INSPECTION FPA 101 I REPORT LE 69A-58
															Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
	AND THE RESIDENCE OF THE PROPERTY AND TH														Information Services		FEAR: 2014/2015 CLAY ARGYLE ELEMENTARY S 2625 SPENCER PLANTAT ORANGE PARK, FL 32073 ECTOR SIGNATURE: INSPECTION DATE: Decemb
						×									Maintenance		EAR: 2014/2015 CLAY ARGYLE ELEMENTARY SCHOOL 2625 SPENCER PLANTATION BOULEVARD ORANGE PARK, FL 32073 CCTOR SIGNATURE:
											×				School		LEVARD

92	76	92	93	92	92	92	92	92	92	92	92	92	92	92	92	92	92	16	14	11	10	9	5	4	Building		COMP
57	S	200	77	54	53	52	51	50	49	48	47	46	45	43	42	41	40								Room		ADM
OK	CX		OK.	OK	OK .	OK	OX.	OX.	OK .	OK.	OK.			OK	OK .	OK.	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58						
				The state of the s														Red tag on fire riser	Red tag on fire riser						Fire Safety Deficiency	Fire Drill Log: Drills Performed:	N INSPECTION REPORT CATION F CHAPTER 5 DN INSPECTION FPA 101 I REPORT LE 69A-58
	The state of the s							· · ·																	Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
								-																	Information Services		'EAR: 2014/2015 CLAY CHARLES E. BENNETT ELEME 1 SOUTH OAKRIDGE AVENUE GREEN COVE SPRINGS, FL 32 ECTOR SIGNATURE: INSPECTION DATE: December 2
																		×	Х						Maintenance		2014/2015 CLAY CHARLES E. BENNETT ELEMENTARY - 0071 1 SOUTH OAKRIDGE AVENUE GREEN COVE SPRINGS, FL 32043 SIGNATURE: SIGNATURE: December 4, 2014
															7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1										School		ARY - 0071

							92	92	92	92	92	92	92	92	92	92	2.6	Building								COMP
							803	703	702	605	604	603	602	503	502	501	59	Room				CASU		ADMI		REHEN
)						OK .	OK	OK.	OK	OK.	CK	OK	OK	OK	OK	CR	Casualty Safety & Sanitation Deficiency		AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	F.S. 1013.12, 1013.20 & NFPA 101	CASUALTY SAFETY & SANITATION INSPECTION		ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
												The state of the s		- Annual Annual -	The second secon			Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:2	REPORT _E 69A-58	FPA 101	N INSPECTION		CHAPTER 5	ATION	INSPECTION REPORT
																		Facilities		INSPECTOR				FACILITY:	DISTRICT:	FISCAL YEAR:
																		Information Services		ECTOR SIGNATURE:		GREEN COVE S	1 SOUTH OAKRIDGE AVENUE	CHARLES E. BE	CLAY	2014/2015
														· · · · · · · · · · · · · · · · · · ·				Maintenance		INSPECTION DATE: December 4, 2014	2/1/	GREEN COVE SPRINGS, FL 32043	DGE AVENUE	CHARLES E. BENNETT ELEMENTARY - 0071		
	-													THE STATE OF THE S				School)14	/ · · · · · · · · · · · · · · · · · · ·	9		\RY - 0071		

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	4	3	2		Building		COM
50	49	48	47	43	42	41	40	39	38	37	36	34	33	31	30	29	28	27	26				47	Room		COMPREHENSIVE S' ADMINIST CASUALT' F.S. F.S.
OK	OK	OK	OK.	OK.	OK	OK	OK .	OK .	OK	OK .	OK .	OK		Casualty Safety & Sanitation Deficiency		EHENSIVE SAFETY & SANITATION INSPECTION F STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58										
																							Emergency light out	Fire Safety Deficiency	Fire Drill Log: Drills Performed:	SAFETY & SANITATION INSPECTION REPORT TATE BOARD OF EDUCATION RATIVE RULES S.R.E.F CHAPTER 5 Y SAFETY & SANITATION INSPECTION S. 1013.12, 1013.20 & NFPA 101 E SAFETY INSPECTION REPORT 1013.12, 1013.20 & RULE 69A-58
																								Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																								Information Services		EAR: 2014/2015 CLAY W. E. CHERRY ELE 420 EDSON DRIVE ORANGE PARK, FI ECTOR SIGNATURE: INSPECTION DATE: M
																							×	Maintenance		EAR: 2014/2015 CLAY W. E. CHERRY ELEMENTARY - 0241 420 EDSON DRIVE ORANGE PARK, FLORIDA/32073 CTOR SIGNATURE: INSPECTION DATE: March 5, 2015
																								School		

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	Building			COMP
70	69	68	67	66	65	64	63	62	61	60	59	58	57	56	55	54	53	51	Room		CASU	REHENS
OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT							
																			Fire Safety Deficiency	Fire Drill Log: Drills Performed:	ATION : - CHAPTER 5 INSPECTION =PA 101 REPORT _E 69A-58	INSTECTION RETORT
							The state of the s											-	Facilities		FACILITY: FACILITY: INSPECTOR	HISCAL YEAR:
ı																			Information Services		ILITY: W. E. CHERRY ELEMENTARY - 0 420 EDSON DRIVE ORANGE PARK, FLORIDA 32073 INSPECTOR SIGNATURE: INSPECTION DATE: March 5, 2018	2014/2015
																			Maintenance		CLAY W. E. CHERRY ELEMENTARY - 0241 420 EDSON DRIVE ORANGE PARK, FLORIDA 32073 SIGNATURE: SIGNATURE: March 5, 2015	
																			School			

		Г	_	T	т—	T		_			T		T			_	,				_								
92	92	92	92	92	92	92	92	92	92	92	92	92	92	7	6	Çī	3&4				2	1	Building						COMF
762	760	712	710	709	708	707	706	705	704	703	702	701	682									125	Room			CASU	ADMI		REHENS
OK	OK	OK	OK	OX.	OK	OK .	OK	OK	OK.	around it.	off or concrete poured	hazard and needs to be cut	Pipe in parking lot is a trip	OK	Remove electrical plug that is run through ceiling	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	CASUALTY SAFETY & SANITATION INSPECTION	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT							
																				×			Fire Safety Deficiency	Fire Drill Log: \(\frac{1}{2} \) Drills Performed: \(\frac{5}{2} \)	=PA 101 REPORT .E 69A-58	N INSPECTION	: - CHAPTER 5	ATION	INSPECTION REPORT
																							Facilities	·	INSPECTOR		FACILITY:	DISTRICT:	FISCAL YEAR:
																							Information Services		INSPECTOR SIGNATURE: INSPECTION DATE:	JACKSONVILLE, FL 32234	CLAY HILL ELEI	CLAY	2014/2015
												-					×					×	Maintenance		CTOR SIGNATURE:	OAD 218 , FL 32234	CLAY HILL ELEMENTARY - 0411		
								-															School)14				

													92	92	Building		COMP
													766	764	Room	:	ADM
The second secon													OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
										. Company and the company and					Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:5_	N INSPECTION REPORT ATION : CHAPTER 5 IN INSPECTION FPA 101 REPORT LE 69A-58
					-										Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
								,							Information Services		EAR: 2014/2015 CLAY CLAY HILL ELEMENTARY - 0411 6345 COUNTY ROAD 218 JACKSONVILLE, FL 32234 ECTOR SIGNATURE: December 5,
									-						Maintenance		MENTARY - 0411 OAD 218 FL 32234 December 5, 2014
															School)14

						92	92	92	92	92	92	92	92	92	92	92	_	Building		COM
						520	518	516	514	513	512	511	504	503	502	501		Room		PREHEN: ADM CASU
						OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58										
				THE REAL PROPERTY AND ADDRESS OF THE PARTY AND									c c					Fire Safety Deficiency	Fire Drill Log:√_ Drills Performed:5	N INSPECTION REPORT CATION F CHAPTER 5 DN INSPECTION FPA 101 I REPORT LE 69A-58
																		Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																		Information Services		EAR: 2014/2015 CLAY COPPERGATE ELEMENTAR 2250 COUNTY ROAD 209-N. MIDDLEBURG, FL 32068 ECTOR SIGNATURE:
																		Maintenance		CLAY CCPPERGATE ELEMENTARY - 0601 2250 COUNTY ROAD 209 N. MIDDLEBURG, FL 32068 CTOR SIGNATURE: INSPECTION DATE: December 8, 2014
																		School		01

92	76	3	92	92	92	92	92	92	92	92	92	92	92	92	92	မ	8	7	l	6		5	4	Building		COM
874	0/3	872	872	871	870	869	849	847	849	845	842	840	838	837	836			710		601A			124	Room		PREHEN
OK	CA	OK .	OK	OK	OK	OK	OK	OK .	OK	Lens cover missing	OK	OK	OK	OK	OK		OX.	column	Repair tile by toilet/paint	FRP	Seal tile in corners at wall to	OK		Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
																Exit light very dim/add different bulbs							Emergency light out	Fire Safety Deficiency	Fire Drill Log:/ Drills Performed:5	N INSPECTION REPORT ATION F CHAPTER 5 ON INSPECTION FPA 101 REPORT LE 69A-58
			***************************************																					Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
							·					1010000	-											Information Services		EAR: 2014/2015 CLAY DOCTORS INLET ELEME 2634 COUNTY ROAD 220 MIDDLEBURG, FL 32068 ECTOR SIGNATURE: INSPECTION DATE: Decem
																		×		×				Maintenance		EAR: 2014/2015 CLAY DOCTORS INLET ELEMENTARY - 0261 2634 COUNTY ROAD 228 MIDDLEBURG, FL 32068 CTOR SIGNATURE: INSPECTION DATE: December 10, 2014
																×							×	School		0261

																				Bu		
						92	92	92	92	92	92	92	92	92	92	92	92	92	92	Building		COMP
				·		923	921	899	897	896	895	894	893	892	891	890	889	888	876	Room		CASL
						OX	OK	OK	OK	Lens cover missing	OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58						
				THE THE PARTY OF T		The section of the se							i i i i i i i i i i i i i i i i i i i							Fire Safety Deficiency	Fire Drill Log: _ \/ _ Drills Performed: _ 5	N INSPECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
	THE WATER AND THE PARTY OF THE																			Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
					, ·	- Transaction												The delication of the second		Information Services		RICT: CLAY RICT: CLAY ILITY: DOCTORS INLET ELEME 2634 COUNTY ROAD 220 MIDDLEBURG, FL 32068 INSPECTOR SIGNATURE: Decem
																				Maintenance		EAR: 2014/2015 CLAY DOCTORS INLET ELEMENTARY - 0261 2634 COUNTY ROAD 220 MIDDLEBURG, FL 32068 CTOR SIGNATURE: December 10, 2014
		Market and a second a second and a second an														×				School		0261

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	7	ე	4	ω	2		Building		COMP
824	821	812	807	806	805	804	803	802	801	608	607	606	605	604	603	602	601				323			Room		ADM
OK		OK	OK	OK	OK		OK .	OK.	OK.		OK	OK	OK	OK		OK	OK	OK	OK	OK		OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
	Emergency light out					Emergency light out				Emergency light out					Emergency light out						Exit light out			Fire Safety Deficiency	Fire Drill Log:/ Drills Performed:4_	N INSPECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
											5													Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																								Information Services		EAR: 2014/2015 CLAY FLEMING ISLAND ELEMENT 4425 LAKESHORE DRIVE FLEMING ISLAND, FL 32003 ECTOR SIGNATURE: Decemb
																			7.00			TO POPPER AND		Maintenance		2014/2015 CLAY FLEMING ISLAND ELEMENTARY - 0521 4425 LAKESHORE DRIVE FLEMING ISLAND, FL 32003 SIGNATURE: SIGNATURE: December 18, 2014
	×														×						×			School		0521

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	Building		COMI
910	909	908	908	907	906	905	904	903	901	862	861	860	850	848	846	844	843	842	841	832	830	828	826	Room		ADM
OK	OK	OK .	OK	OK		OK	OK.	OK	OK	OK	OK	OK	OK		OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58								
					Emergency light out									Emergency light out										Fire Safety Deficiency	Fire Drill Log: Drills Performed:4	N INSPECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																			•					Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
													•											Information Services		EAR: 2014/2015 CLAY FLEMING ISLAND ELEMENT 4425 LAKESHORE DRIVE FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 ECTOR SIGNATURE: INSPECTION DATE: Decemb
																								Maintenance		2014/2015 CLAY FLEMING ISLAND ELEMENTARY - 0521 4425 LAKESHORE DRIVE FLEMING ISLAND, FL/32003 SIGNATURE: December 18, 2014
					×				-					×										School		2014

92	92	92	92	92	92	26	3	92		92	92	92	92	92	92	92	9		ω	7	6	2		Building		
504	501	500	71	44	31	واد	30	29		27	10	9	8	7	6	5	142				611			Room		ADM
OK	CK	QX	OK	OK	OK	CA	OK .		Replace blocks under stair	OK	OK.	OK .	OK .	OK	OK.	OK	order alrady in	Urinal being repaired. Work	OK			OK	OK	Casualty Safety & Sanitation Deficiency		STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
									THE PROPERTY OF THE PROPERTY O											Extension cord crossing exit door path	Emergency light out			Fire Safety Deficiency	Fire Drill Log:	CATION F CHAPTER 5 ON INSPECTION FPA 101 I REPORT LE 69A-58
																								Facilities		FACILITY: INSPECTOR
		-					-					-												Information Services		ILITY: GROVE PARK ELEMENTA 1643 MILLER STREET ORANGE PARK, FL 32073 INSPECTOR SIGNATURE: INSPECTION DATE: Decemb
																			The state of the s					Maintenance		GCLAY GROVE PARK ELEMENTARY - 0232 1643 MILLER STREET ORANGE PARK, FL 32073 CTOR SIGNATURE: INSPECTION DATE: December 15, 2014
								×												×	×			School		2014

								92	92	92	92	92	92	92	92	92	Building						COMP
								528	527	525	524	523	522	521	520	506	Room				CASU	ADM	RETEN
								OK.	OK	OK	OK	OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & RULE 69A-58	F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE CAFFETY WORKSTON SERVED	CASUALTY SAFETY & SANITATION INSPECTION	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION
				The state of the s								The second secon	The state of the s				Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:4	LE 69A-58	FPA 101	ON INSPECTION	F CHAPTER 5	N INSPECTION REPORT
																	Facilities		INSPI	INSPECTOR		FACILITY:	FISCAL YEAR: DISTRICT:
																	Information Services		ECTION DATE:	INSPECTOR SIGNATURE:	ORANGE PARK, FL 3/2073	GROVE PARK E	2014/2015 CLAY
		The state of the s									Marian and the second s						Maintenance		INSPECTION DATE: December 15, 2014	Jaul H	FL 3/207/3	GROVE PARK ELEMENTARY - 0232	
										1				77774188644184477			School		2014			ž	

92 44 OK	43	92 42 OK	39	37	92 36 OK	35	32		92 30 OK	29	92 28 OK	92 27 OK	26	9 OK	8 OK	7 OK			4 OK	3 OK	1 OK	Building Room Sanitat		FIRE SAFI F.S. 1013.	F.S. 1010	CASUALTY SAF	AUMINISTRATIO	STATE
							re	0									With a state of the state of th					Casualty Safety & Sanitation Deficiency	Fir Dr	FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	F.S. 1013.12, 1013.20 & NFPA 101 AND	CASUALTY SAFETY & SANITATION INSPECTION	AUMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION
	The state of the s						relief connector.	Outlet strips missing. Strain								##1000.						Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:7_	EPORT 69A-58	A 101	INSPECTION	CHAPIERS	TATE BOARD OF EDUCATION
																	**************************************	*				Facilities		INSPE	INSPECTOR		FACILITY:	DISTRICT:
																						Information Services			NSPECTOR SIGNATURE:	ORANGE PARK, FLORIDA 32073	S. BRYAN JENNINGS	CLAY
							×															Maintenance		February 9, 2015	X	FLORIDA 32073	S. BRYAN JENNINGS ELEMENTARY - 0331 215 CORONA DRIVE	
																						School		15			?Y - 0331	

										92	92	92	92	92	92	92	ing		СОМР
										81	80	79	78	77	76	75	Room		REHENS
		1 1112 112 11			The state of the s					OK	OK	OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
	-																Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:7	INSPECTION REPORT ATION
		THE PERSON NAMED AND PASSED OF															Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																	Information Services		/EAR: 2014/2015 f: CLAY f: S. BRYAN JENNINGS 215 CORONA DRIVE ORANGE PARK, FLC ORANGE PARK, FLC INSPECTION DATE: Fel
					Mayor and a second seco												Maintenance		EAR: 2014/2015 CLAY S. BRYAN JENNINGS ELEMENTARY - 0331 215 CORONA DRIVE ORANGE PARK, FLORIDA 32973 CTOR SIGNATURE: INSPECTION DATE: February 9, 2015
				-									1777				School		Y - 0331

92	92	92	92	92	92	92	92	4	12	1	10	9	œ	7	6	5	4	ω	1	2		Building		CONT
707	706	705	704	703	702	701														811		Room		ADMI
OK	OK	OK	OK.	OX.	OX	OK	OK	OK to be renovated	OK to be renovated	OK to be renovated	OK .	OK	OK	OK	OK.	OK.	OK	OK	OK	playground	Remove rusted railing by	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFELY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
																						Fire Safety Deficiency	Fire Drill Log: _ √_ Drills Performed:	ATION SATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																						Facilities		FISCAL TEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																						Information Services		ILITY: CLAY CLAY CLAY KEYSTONE HEIGHTS EI 335 SW PECAN STREET KEYSTONE HEIGHTS, F
																				×		Maintenance		CLAY KEYSTONE HEIGHTS ELEMENTARY - 0301 335 SW PECAN STREET KEYSTONE HEIGHTS, FL 32656 CTOR SIGNATURE: January 20, 2015 INSPECTION DATE: January 20, 2015
							-															School		?Y - 0301

92	92	92	92	92	92	92	92		92	92	92	92	92	92	92	92	92	92	92	Building										COMF
773	772	770	760	751	750	724	A&B	722	721	719	718	717	716	715	714	713	710	709	708	Room							CASU	ADM		REHEN
OK	OK.	OK	OK .	OK	OK	OK	OK .		OK	Casualty Safety & Sanitation Deficiency		TO THE PROPERTY OF THE PROPERT	F.S. 1013.12, 1013.20 & RULE 69A-58	FIRE SAFETY INSPECTION REPORT	AND	F.S. 1013.12, 1013.20 & NFPA 101	CASUALTY SAFETY & SANITATION INSPECTION	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT										
																				Fire Safety Deficiency	Fire Drill Log: Drills Performed:		_E 69A-58	REPORT		FPA 101	ON INSPECTION	: - CHAPTER 5	ATION	INSPECTION REPORT
																				Facilities		THE RESERVE AND THE RESERVE AN	INSPE		INSPECTOR			FACILITY:	DISTRICT:	FISCAL YEAR:
																				Information Services			ECTION DATE:		ECTOR SIGNATURE:		KEYSTONE HEIGHTS, FL 32656	KEYSTONE HEIG	CLAY	2014/2015
																				Maintenance			INSPECTION DATE: January 20, 2015		Tangle Committee of the		STREET 3HTS, FL 32656	KEYSTONE HEIGHTS ELEMENTARY - 0301		
																				School			15		Tables 1924 - Commission of the Commission of th			የY - 0301	1	

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	7	0		5		3	2	_	Building			COMP
48	46	45	44	43	42	41	40	39	18	16	14	13	12	11	9		629		536					Room		CASU	REHENS
OK	OK.	OX.	OX.	OK	OK.	OK	OK	OK	OK	OK	OK .	OK	OK.	OK.	OK.	OK			leaking	Boy's restroom urinal	OK	OK	OK	Casualty Safety & Sanitation Deficiency		CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5
														1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			exit	Extension cords to computers crosses floor to						Fire Safety Deficiency	Fire Drill Log: \ Drills Performed:5	INSPECTION FPA 101 REPORT LE 69A-58	N INSPECTION REPORT SATION F CHAPTER 5
											-											-		Facilities		INSPECTOR	FISCAL YEAR: DISTRICT: FACILITY:
						-													The state of the s					Information Services		GREEN COVE S PECTOR SIGNATURE: INSPECTION DATE:	2014/2015 CLAY LAKE ASBURY ELEMEN 2901 SANDRIDGE ROAD
				,															×		-			Maintenance		PRINGS/FL 3204 January 15,	2014/2015 CLAY LAKE ASBURY ELEMENTARY - 0451 2901 SANDRIDGE ROAD
																2	×							School		2015	51

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	ing								(COMPREHENSIVE
71	15	10	79	96	95	93	91	90	88	87	86	85	84 4	81	80	77	76	75	74	73	72	70	69	Room					CASU		ADMI	Í	HEN
			Light out in electric closet	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & RULE 69A-58	FIRE SAFETY INSPECTION REPORT	F.S. 1013.12, 1013.20 & NFPA 101	CASUALTY SAFETY & SANITATION INSPECTION		ADMINISTRATIVE RULES S.R.E.F CHAPTER 5											
Emergency light out	Emergency light out	Emergency light out																						Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:5_	LE 69A-58	REPORT	FPA 101	ON INSPECTION		F CHAPTER 5	ATION	SAFETY & SANITATION INSPECTION REPORT
																						and the same of th		Facilities		INSPE					FACILITY:	DISTRICT:	FISCAL YEAR.
																								Information Services		ECTION DATE	Y OLONAL ONE.	ECTOR SIGNATURE!	GREEN COVE S	2901 SANDRIDGE ROAD	LAKE ASBURY	CLAY	2014/2015
																			,					Maintenance		INSPECTION DATE: January 15, 2015	and 1171		GREEN COVE SPRINGS, FL 32043	E ROAD	LAKE ASBURY ELEMENTARY - 0451		
×	×	×	×								-													School		15		3.00			51		

2014/2015 CLAY LAKE ASBURY ELEN 2901 SANDRIDGE RO GREEN COVE SPRIN SIGNATURE: Jan Services Ma											92 94 Emergency light out	0	82	ing Room Casualty Safety & Sanitation Deficiency	Fire Drill Log: Drills Performed:5	N REPORT FISCAL YE DISTRICT: FACILITY:
																SCAL YEAR: 2014/2015 STRICT: CLAY CILITY: LAKE ASBURY ELEMENTARY - 0451 2901 SANDRIDGE ROAD GREEN COVE SPRINGS, FL 32043 INSPECTOR SIGNATURE: January 15, 2015

92		92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	8	7	o	2	_	Building		СОМР
43	42A&B	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10					115	Room		COMPREHENSIVE S ADMINIST CASUALT F.S. FIRE
OK	OK	OK	OK	OK	OX.	OX.	OX.	OX.	OK	OK	OK	OK	OK .	OK		OK		Casualty Safety & Sanitation Deficiency		EHENSIVE SAFETY & SANITATION INSPECTION F STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58							
															Emergency light out									Emergency light out	Fire Safety Deficiency	Fire Drill Log:/ Drills Performed:5_	SAFETY & SANITATION INSPECTION REPORT TATE BOARD OF EDUCATION IRATIVE RULES S.R.E.F CHAPTER 5 Y SAFETY & SANITATION INSPECTION S. 1013.12, 1013.20 & NFPA 101 AND E SAFETY INSPECTION REPORT 1013.12, 1013.20 & RULE 69A-58
										,		-													Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
															TOTAL CONTRACTOR OF THE PARTY O										Information Services		FEAR: 2014/2015 CLAY LAKESIDE ELEMENTARY 2752 MOODY ROAD ORANGE PARK, FL 32073 ECTOR SIGNATURE: INSPECTION DATE: January
									Will all the second sec																Maintenance		2014/2015 CLAY CLAY LAKESIDE ELEMENTARY - 0352 2752 MOODY ROAD ORANGE PARK, FL 32073 SIGNATURE: SIGNATURE: STION DATE: January 22, 2015
								,	-		-				×									×	School		15

	Т	_	 	_	_	. T	_	- 1			f	_	_						_		r	_								
					92	82	03	97	92	92	92	92	92	92	92	92	92	92	92	92	92	92	Building							COMI
		-			63	32	3 5	61	60	59	57	56	55	54	53	52	51A&B	48	47	46	45	44	Room				CASU	ADMI		REHENS
					OR		OK .	OK.	OK	OK	OK	OK	OK		Casualty Safety & Sanitation Deficiency		FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	F.S. 1013.12, 1013.20 & NFPA 101	CASUALTY SAFETY & SANITATION INSPECTION	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT								
																	,					Emergency light out	Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:5	REPORT _E 69A-58	FPA 101	N INSPECTION	CHAPTER 5	ATION	INSPECTION REPORT
															·								Facilities		INSPE			FACILITY:	DISTRICT:	FISCAL YEAR:
																							Information Services		INSPECTION DATE:		ORANGE PARK, EL 32073	LAKESIDE ELEMEN	CLAY	2014/2015
																							Maintenance		INSPECTION DATE: Japuary 22, 2014		EL 32073	LAKESIDE ELEMENTARY - 0352		
																						×	School		14	7				

\·`\ * ~ 5 Z Z
EAR: 2014/2015 CLAY MCRAE ELEMEN 6770 COUNTY R KEYSTONE HEIC KEYSTONE HEIC INSPECTION DATE:
2014/2015 CLAY MCRAE ELEMENTARY - 0511 6770 COUNTY ROAD 3/5 C KEYSTONE HEIGHTS/ FL/32656 KEYSTONE ### AND AUTOMOTION DATE: January 20, 2015

					92	92	92	92	92	92	92	92	92	92	92	92	92	Building		
		-			828	827	826	825	824	823	821	806	804	803	802	801	708	Room		ADM
				The state of the s		OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
			The state of the s		Excessive combustibles											j		Fire Safety Deficiency	Fire Drill Log: _ \/_ Drills Performed: _ 5_	CATION F CHAPTER 5 ON INSPECTION FPA 101 I REPORT LE 69A-58
																		Facilities		PACILITY: FACILITY: INSPECTOR INSPE
										The state of the s								Information Services		ILITY: MCRAE ELEMENTARY - 0511 6770 COUNTY ROAD 315 C KEYSTONE HEIGHTS, FL 32656 INSPECTOR SIGNATURE: INSPECTION DATE: January 20, 2
																		Maintenance		MCRAE ELEMENTARY - 0511 6770 COUNTY ROAD 315 C KEYSTONE HEIGHTS, FL 32656 CTOR SIGNATURE: INSPECTION DATE: January 20, 2015
																		School		15

92	92	92	92	92	92	92	92	92	92	92	92	9	7			6	4	ω	ω	2		Building		COM
43	41	40	39	38	37	35	29	26	25	24	23		747									Room		ADM
OK	OK	OK	OK	OK .	OK	OK	OK	OK	OK	OK .	OK	OK				OK	OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
													elevator.	Expired inspection on	No evacuation sheet.							Fire Safety Deficiency	Fire Drill Log: _\ Drills Performed:7_	N INSPECTION REPORT CATION F CHAPTER 5 ON INSPECTION FPA 101 I REPORT LE 69A-58
																			-			Facilities		FACILITY: FACILITY: INSPECTOR
																						Information Services		EAR: 2014/2015 CLAY MIDDLEBURG ELEMENT 3958 MAIN STREET MIDDLEBURG, FL 32068 ECTOR SIGNATURE: INSPECTION DATE: Januar
															,				·			Maintenance		2014/2015 CLAY MIDDLEBURG ELEMENTARY - 0271 3958 MAIN STREET MIDDLEBURG, FL 32068 SIGNATURE: SIGNATURE: January 22, 2015
			,		-								×									School		15

									92	92	92	92	92	92	92	Building		COMP
				-					69	68	65	64	65	57	55	Room		PREHENS ADM CASU
					The state of the s				OK	OK	OK	OK	ОК	ОК	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
																Fire Safety Deficiency	Fire Drill Log: _ \/ _ Drills Performed: _ 7	N INSPECTION REPORT SATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
		٠				m Trond and the second and the secon	To the second of									Information Services		AL YEAR: 2014/2015 TRICT: CLAY ILITY: MIDDLEBURG ELEMENT 3958 MAIN STREET MIDDLEBURG, FL 32068 INSPECTOR SIGNATURE: INSPECTION DATE: Januar
												ACAD AND AND AND AND AND AND AND AND AND A				Maintenance		EAR: 2014/2015 CLAY MIDDLEBURG ELEMENTARY - 0271 3958 MAIN STREET MIDDLEBURG, FL 32068 CTOR SIGNATURE: INSPECTION DATE: January 22, 2015
					,											School		15

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	5	4	2		Building		
38	37	36A&B	35	34	33	32	<u>3</u>	30	29	28	27	26	25	24	23	22	21	8				103	Room		ADMI
OK	OK	OK	OK	OK	OK .	OK	OK	OK	OK	OK .	OK .	OK	OK	OK	OK.	OK	OK.	OK	OK	OK	OK	Floor drain broken	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFE IT & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
We will be a second of the sec																							Fire Safety Deficiency	Fire Drill Log: Drills Performed:4_	E CHAPTER 5 F CHAPTER 5 ON INSPECTION FPA 101 I REPORT LE 69A-58
																							Facilities		FACILITY: FACILITY: INSPECTOR
																							Information Services		RICT: CLAY LITY: MONTCLAIR ELEMENTAR 2398 MOODY ROAD ORANGE PARK, FL 32073 NSPECTOR SIGNATURE: INSPECTION DATE: January
																		TO COMPANY COM				×	Maintenance		MONTCLAIR ELEMENTARY - 0381 2398 MOODY ROAD ORANGE PARK, FL 32073 CTOR SIGNATURE: INSPECTION DATE: January 22, 2015
																			3				School		15

										92	92	92	92	92	Building		COMI
										46	45	41	40	39	Room		ADM
								The state of the s		OK	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
															Fire Safety Deficiency	Fire Drill Log:/ Drills Performed:4	N INSPECTION REPORT SATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
															Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
															Information Services		YEAR: 2014/2015 T: CLAY Y: MONTCLAIR ELEMENTAR 2398 MOODY ROAD ORANGE PARK, FL 32073 PECTOR SIGNATURE: INSPECTION DATE: January
															Maintenance		EAR: 2014/2015 CLAY MONTCLAIR ELEMENTARY - 0381 2398 MOODY ROAD ORANGE PARK, FL 32073 CTOR SIGNATURE: INSPECTION DATE: January 22, 2015
															School		15

			92	92	92	92	92	92	92	92	92	92	25	25		Building		СОМР
			914	913	912	911	910	909	908	907	906	905	1105	1102	118	Room		REHENS
			OK	OK	OK .	OK	OK	OK	OK	OK	OK	OK .				Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
							0.0000000000000000000000000000000000000						No exit light	No exit light	Red tag fire riser	Fire Safety Deficiency	Fire Drill Log:/ Drills Performed:	N INSPECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR
																Information Services		ECTOR SIGNATURE: INSPECTION DATE: January
·													×	×	×	Maintenance		2014/2015 CLAY OAKLEAF VILLAGE ELEMENTARY - 0621 410 OAKLEAF VILLAGE PARKWAY ORANGE PARK, FL 32065 SIGNATURE:
																School		0621

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	7	51	4	ω	2	_	Building		
54	53	52	51	50	45	44	43	42	41	39	38	37	35	34	24	23	22	21	1		85				Room		ADM
OK	OK	OK	OK	OK	OK	OK	OK	OX.	OX	OK	OK	OK.	OK	OK	OK	OK	OK .	OK		OK		OK	OK	OK	Casualty Safety & Sanitation Deficiency		STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
																			No evacuation sheet		Switch cover broken			•	Fire Safety Deficiency	Fire Drill Log: \(\square\) Drills Performed: 4	CATION F CHAPTER 5 ON INSPECTION IFPA 101 I REPORT ILE 69A-58
																									Facilities		FACILITY: FACILITY: INSPECTOR
	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4																								Information Services		INSPECTION DATE: January
	and the second s																								Maintenance		ORANGE PARK ELEMENTARY - 0201 1401 PLAINFIELD AVENUE ORANGE PARK, FL 32073 CTOR SIGNATURE: INSPECTION DATE: January 26, 2015
												-							×		×				School		201

92	92	92	92	92	92	92	92	92	92	92	92	92	92	6	57	4	ω	2	_	Building		CO CO
22	21	16	15	14	13	11	8	6	5	4	3	2	1					208		Room		ADMI
ОК	OK	OK	OK	OX	OK	OK	OK	OK	OK		OK		OK	OK	OK	OK	OK		OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFELY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
										Emergency light out		Exit blocked						Red tag on fire riser		Fire Safety Deficiency	Fire Drill Log:/ Drills Performed:6_	ATION E CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																				Facilities		FISCAL TEAR: DISTRICT: FACILITY: INSPECTOR INSPI
						-										111				Information Services		CLAY PATTERSON ELEMENTARY - 047 5400 PINE AVENUE FLEMING ISLAND, FL 32003 ECTOR SIGNATURE: INSPECTION DATE: January 28, 2015
										×								×		Maintenance		2014/2015 CLAY PATTERSON ELEMENTARY - 0471 5400 PINE AVENUE FLEMING ISLAND, FL 32003 SIGNATURE: SIGNATURE: January 28, 2015
												×								School		

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	Building		uta i i			
53	52	51	50	49	48	47	46	45	44	43	42	41	28	27	26	25	24	23	Room			CASL	ADM	
OK		OK	OK	OK	OK		OK	OK			OK	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58	CASUALTY SAFETY & SANITATION INSPECTION	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION							
	Emergency light out					Emergency light out			Emergency light out	Emergency light out									Fire Safety Deficiency	Fire Drill Log: \(\square\) Drills Performed: 4	IFPA 101 N REPORT ILE 69A-58	ON INSPECTION	.F CHAPTER 5	CATION
								THE PROPERTY OF THE PROPERTY O											Facilities		INSPECTOF		FACILITY:	DISTRICT:
							-												Information Services		NSPECTOR SIGNATURE:	5400 PINE AVENUE FLEMING ISLAND,/FL 32003	PATTERSON EL	CLAY
	×					×			×	×									Maintenance		January 28, 2015	IUE D,/FL 32003	PATTERSON ELEMENTARY - 0471	
																			School	-			·	

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	25	25		Building		
916	915	914	913	912	911	910	909	908	907	906	905	904	903	902	901	1106	1103	413	Room		ADMI
OK	OK	OK	OK	OK	OK	OK	OK	OK			Door stick - hinge loose	Casualty Safety & Sanitation Deficiency		COMPRESSIVE SAFETY & SANITATION INSPECTION STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58							
																No exit light	No exit light		Fire Safety Deficiency	Fire Drill Log: \(\frac{1}{2}\) Drills Performed: \(\frac{5}{2}\)	ATION STECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 FPA 101 REPORT LE 69A-58 LE 69A-58
		-										·							Facilities		FACILITY: FACILITY: INSPECTOR
									1										Information Services		ICT: CLAY ICT: PLANTATION OAKS ELEMENTAR 4150 PLANTATION OAKS BOULE ORANGE PARK, FL 32065 INSPECTION DATE: January 13, 2015
						-										×	×	×	Maintenance		CLAY PLANTATION OAKS ELEMENTARY - 0651 4150 PLANTATION OAKS BOULEVARD ORANGE PARK, FL 32065 SIGNATURE: SIGNATURE: January 13, 2015
							- construction and the		-										School		Y - 0651 /ARD

					92	92	92	92	92	92	92	92	92	_						Building							COME
					25	24	23A&B	22	21	20	13	11	10	413						Room				CASU	ADMI		REHENS
					CK	OK	OK OK	classroom.	swing or not use as	room. Need to change door	Originally a teacher planning	direction for classroom.	Doors swing in wrong	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & RULE 69A-58	F.S. 1013.12, 1013.20 & NFPA 101 AND	CASUALTY SAFETY & SANITATION INSPECTION	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	STATE BOARD OF EDUCATION	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT						
																				Fire Safety Deficiency	Fire Drill Log: Drills Performed:6	E 69A-58	=PA 101	N INSPECTION	: - CHAPTER 5	ATION	INSPECTION REPORT
														×						Facilities		INSPE	INSPECTOR		FACILITY:	DISTRICT:	FISCAL YEAR:
			THE PROPERTY OF THE PROPERTY O														٠.			Information Services		INSPECTION DATE: January 27, 2015	INSPECTOR SIGNATURE:	MIDDLEBURG, FL 32068	RIDEOUT ELEMENTARY - 0541	CLAY	2014/2015
																				Maintenance		January 27, 2015	Taul O	MIDDLEBURG, FL 32068	ENTARY - 0541		
																				School			MAGO:				

92 735 OK	92 734 OK	733	92 732 OK	731	730	!	92 728 OK	92 718 OK	92 717	92 715 OK	92 714 OK	92 713 OK	92 712 OK	711	7 712 Light out	o OK	4 OK	3 OK	209	1 121		Building Room Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & STATE BOA ADMINISTRATIVE R CASUALTY SAFETY F.S. 1013.12, 1
					Emergency light out				Emergency light out										Exit light out	Exit light out	dated		Fire Drill Log: Drills Performed:4	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
																						Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR
																						Information Services		EAR: 2014/2015 CLAY RIDGEVIEW ELEMENTARY 421 JEFFERSON AVENUE ORANGE PARK, FL 32065 CCTOR SIGNATURE: INSPECTION DATE: February
					×				X										×	×	×	Maintenance		2014/2015 CLAY RIDGEVIEW ELEMENTARY - 0401 421 JEFFERSON AVENUE ORANGE PARK, FL 32665 SIGNATURE: SIGNATURE: February 23, 2015
															×							School		

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92		Building								COMF
772	760	759	758	756	755	755	754	751	750	749	748	747	746	745	744	743	742	741	738	737		Room					CASU			REHEN
OK	Lens cover missing	OK	OK			Light lens missing				OK .	OK	OK	OK	OK .	OK.	OK	OK	OK	OK	box by ramp	Cover missing on junction	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & RULE 69A-58	AND FIRE SAFETY INSPECTION REPORT	F.S. 1013.12, 1013.20 & NFPA 101	CASUALTY SAFETY & SANITATION INSPECTION	COMMINSTRACTION OF STREET OF STREET		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
				Light lens missing. Electric panel blocked	Electric panel blocked		Emergency light out	Emergency light out	Emergency light out													Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:4	LE 69A-58	IREPORT	FPA 101	ON INSPECTION	7. * (127 177 0	CALON	N INSPECTION REPORT
																						Facilities		INSPE	INSPECTOR			TACIEII.	יייייייייייייייייייייייייייייייייייייי	FISCAL YEAR:
																						Information Services		ECTION DATE:	INSPECTOR SIGNATURE:		ORANGE PARK, FL 32065	421 JEFFERSON AVENUE	CLAY	2014/2015
	×			×	×	X	X	X	X											×		Maintenance		INSPECTION DATE: Pebruary 23, 2015	Jede M.	X ////	FL 32065	KIUGEVIEW ELEMENTARY - 0401 421 JEFFERSON AVENIJE		
																						School								

									92	92	20	20		Building		СОМ
					,				902	901	2505	2502	204	Room		PREHENS
		The second secon							OK	OK			Mildew on wall of IDF Room	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
											Add exit lights	Add exit lights		Fire Safety Deficiency	Fire Drill Log: Drills Performed:5	N INSPECTION REPORT CATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
														Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
			* 1							1				Information Services		AL YEAR: 2014/2015 RICT: CLAY ILITY: SHADOWLAWN ELEMEN 2945 COUNTY ROAD 218 GREEN COVE SPRINGS; INSPECTOR SIGNATURE: Jan
							i				×	×	×	Maintenance	-	2014/2015 CLAY SHADOWLAWN ELEMENTARY - 0631 2945 COUNTY ROAD 218 GREEN COVE SPRINGS; FL 32043 SIGNATURE: January 14, 2015
														School	·	331

		remove (Max 20% coverage).		000	26
		Excessive combustibles -		808	3
			OK	806	92
			OK	804	92
			OX.	803	92
			OK .	801	92
			OX	708	92
			OK	708	92
			OK	706	92
			OX	705	92
			OK	704	92
			OK	703	92
		20% coverage).		702	92
	· ·	Emergency light out. Excessive			
		Emergency light out		701	92
			OK		6
			OK		5
			OK		4
			OK		3
			OK		2
			stained.	115	
			Replace ceiling tiles -		
Information Services	Facilities	Fire Safety Deficiency	Casualty Safety & Sanitation Deficiency	Room	Building
,		Fire Drill Log: Drills Performed:6_			
INSPECTOR SIGNATURE: January 27, 2015	INSPECTOR	=PA 101 REPORT _E 69A-58	F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58		
1630 WOODPECKER LANE MIDDLEBURG, FL 32068		N INSPECTION	CASUALTY SAFETY & SANITATION INSPECTION	CASU	
2014/2015 CLAY SWIMMING PEN CREEK ELEMENTARY - 0571	PISCAL YEAR: DISTRICT: FACILITY:	: - CHAPTER 5	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	ADMI	COMP

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92		Building		COMP
732	731	730	729	728	727	726	725	724	723	722	721	713	711	710	709	708	707	706	705	704	703	702	701		Room		PREHENS
OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58																							
																									Fire Safety Deficiency	Fire Drill Log: Drills Performed:5	N INSPECTION REPORT ATION CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
												:													Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																									Information Services		TEAR: 2014/2015 THUNDERBOLT ELEMENTARY 2020 THUNDERBOLT ROAD FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003
																									Maintenance		2014/2015 CLAY THUNDERBOLT ELEMENTARY - 0531 2020 THUNDERBOLT ROAD FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 SIGNATURE: February 12, 2015
																							:		School		-0531

					92	92	92	92	92	92	92	92	92	92	92	92	Building	Building		СОМР
					744	743	742	741	740	739	738	737	736	735	734	733	Room	Room		REHENS
					OK	OK .	OK	OK	OK	Casualty Safety & Sanitation Deficiency	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58							
																	Fire Safety Deficiency	Fire Safety Deficiency	Fire Drill Log: _ \/ Drills Performed: _ 5	I INSPECTION REPORT ATION : - CHAPTER 5 N INSPECTION PA 101 REPORT E 69A-58
																	Facilities	Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																	Information Services	Information Services		ECTOR SIGNATURE: CLAY CLAY THUNDERBOLT ELEMENTA 2020 THUNDERBOLT ROAD FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 FLEMING ISLAND, FL 32003 FEBRUARY FEBRUARY
																	Maintenance	Maintenance		ELEMENTARY 30LT ROAD D, FL 32003 Pauf February 12,
																	School	School		2015

			OK	30	92
	THE PARTY NAMED IN COLUMN TO THE PARTY NAMED		OK		92
			OK	28	92
			OK		92
			OK		92
			OK		92
			OK	25	92
			OK		92
			OK		92
			OK		92
			OK	10	92
			OK		92
			OK .	∞	92
			OK	7	92
			OK		92
			OK	3	92
			OK		92
			OK .	_	92
			OK .		တ
			OK.		51
			OK		4
			OK		သ
		Red tag fire sprinkler riser - "pump is out of service."		203	2
			OK		
Information Services	Facilities	Fire Safety Deficiency	Casualty Safety & Sanitation Deficiency	Room	Building
		Fire Drill Log: Drills Performed:5			
IGNA TION	INSPECTOR SIGNATURE: July H	FPA 101 REPORT E 69A-58	F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58		
1550 TYNES BOULEVARD MIDDLEBURG, FL 32068		ON INSPECTION	CASUALTY SAFETY & SANITATION INSPECTION	CASU	
TYNES ELEMENTARY - 0501	FACILITY:	F CHAPTER 5	ADMINISTRATIVE RULES S.R.E.F CHAPTER 5	ADMI	
CLAY	-	TATE BOARD OF EDUCATION	STATE BOARD OF EDUCATION		
04 4 750	EVD:	N INSBECTION BEBORT	SIVE CAEETY & CANITATION	COMPREHENSIVE	COME

		92	92	92	92		92	92	92	92	92	92	92	96	92	92	92	92	92	Building								
		68	67	66	65		64	63	62	61	49	48	47	46	45	44	43	42	41	Room					CASU	į	ADM	XIT III N
Commission and the commission of the commission		OX.	OX	OK	sharp edges - repaint	Front door has rust and	OK	OK	OK .	OK .	OK.	OK	OK	OK .	OK .	OK .	OK	OK	OK	Casualty Safety & Sanitation Deficiency		F.S. 1013.12, 1013.20 & RULE 69A-58	AND AND	F.S. 1013.12, 1013.20 & NFPA 101	CASUALTY SAFETY & SANITATION INSPECTION		ADMINISTRATIVE RUI ES S.R.F.F CHAPTER 5	COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT
																				Fire Safety Deficiency	Fire Drill Log: Drills Performed:5	LE 69A-58		FPA 101	ON INSPECTION		E - CHAPTER 5	N INSPECTION REPORT
																				Facilities		INSPI	INSPECTOR				FACII ITY:	DISTRICT:
		Management of the state of the		7.7.00.7.00.00.00.00.00.00.00.00.00.00.0																Information Services		ECTION DATE:	ECTOR SIGNATURE:		MIDDLEBURG, FL 32068	1550 TYNES BOULEVARD	TYNES EI EMENTARY - 0501	2014/2015 CLAY
																				Maintenance		INSPECTION DATE: February 11, 2015	July #		L 32068	ULEVARD	TARY - 0501	
					×															School)15	When the state of					

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	5	4	ω	2	2		Building		COMP
20	18	17	14	13	12	1	10	9	8	7	6	51	4	ω	2	_				219	208		Room		REHENS
OK	OX	OX.	OX	OK.	OK			OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58														
																				When generation goes on, it sets off hood alarm	Red tag on fire riser gauges		Fire Safety Deficiency	Fire Drill Log: Drills Performed:4	N INSPECTION REPORT ATION F CHAPTER 5 DN INSPECTION FPA 101 REPORT LE 69A-58
																							Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR
																							Information Services		EAR: 2014/2015 CLAY WILKINSON ELEMENTARY 4965 COUNTY ROAD 218-W MIDDLEBURG, FL 32968 ECTOR SIGNATURE: March 2,
																				×	×		Maintenance		2014/2015 CLAY WILKINSON ELEMENTARY - 0491 4965 COUNTY ROAD 218 W. MIDDLEBURG, FL 32968 SIGNATURE: March 2, 2015
																							School		

92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	92	Building		CO
52	51	50	49	48	47	46	45	44	43	42	41	40	39	38	37	36	35	34	33	31	22	Room		ADMI
OK	OK	OK	OK	OK	OK.	OK	OK	OK	OK .		OK		OK	OK	OK .	OK	OK.	OK	OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION IN STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
										Emergency light out		Cabinet blocking rear exit										Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:4	& SANITATION INSPECTION REPORT ARD OF EDUCATION RULES S.R.E.F CHAPTER 5 Y & SANITATION INSPECTION 2, 1013.20 & NFPA 101 AND Y INSPECTION REPORT 1013.20 & RULE 69A-58
																						Facilities		FACILITY: FACILITY: INSPECTOF
																						Information Services		EAR: 2014/2015 CLAY WILKINSON ELEMENTARY - 4965 COUNTY ROAD 218 W. MIDDLEBURG, FL 32968 ECTOR SIGNATURE: March 2, 2
										×												Maintenance		WILKINSON ELEMENTARY - 0491 4965 COUNTY ROAD 218 W. MIDDLEBURG, FL 32968 CTOR SIGNATURE: MARCH 2, 2015
												×										School		

										92	92	92	92	92	92	Building		COMP
										68	66	64	63	62	61	Room		REHENS
										OK	OK		OK	OK	OK	Casualty Safety & Sanitation Deficiency		COMPREHENSIVE SAFETY & SANITATION INSPECTION REPORT STATE BOARD OF EDUCATION ADMINISTRATIVE RULES S.R.E.F CHAPTER 5 CASUALTY SAFETY & SANITATION INSPECTION F.S. 1013.12, 1013.20 & NFPA 101 AND FIRE SAFETY INSPECTION REPORT F.S. 1013.12, 1013.20 & RULE 69A-58
												Emergency light out				Fire Safety Deficiency	Fire Drill Log:/_ Drills Performed:4	N INSPECTION REPORT CATION F CHAPTER 5 DN INSPECTION FPA 101 I REPORT LE 69A-58
															:	Facilities		FISCAL YEAR: DISTRICT: FACILITY: INSPECTOR INSPE
																Information Services		FEAR: 2014/2015 T: CLAY T: WILKINSON ELEMENTARY - 0491 4965 COUNTY ROAD 218 W. MIDDLEBURG, FL 32068 PECTOR SIGNATURE: Warch 2, 2015
												×				Maintenance		2014/2015 CLAY WILKINSON ELEMENTARY - 0491 4965 COUNTY ROAD 218 W. MIDDLEBURG, FL 32068 SIGNATURE: SIGNATURE: CTION DATE: March 2, 2015
																School		